
Model:

iR5055
iR5055N
iR5065
iR5065N
iR5075
iR5075N

Ref No.:

iR5075-006 Rev. 1
(F1-T01-N03-10021-02)

Date:

September, 2007

Revised:

Revision: Notification of the serial numbers of affected machines

Location:


Reader/ ADF Assembly

Subject:

Prevention of breakage of DDI-S Serial Cable

Detail:

Since cables such as the DDI-S Serial Cable are sticking out from the back of the machine, the Connector area [1] may be broken when the cables hit against something accidentally during relocation.



P-1 Back view of the machine

[1] Connector area


Factory measures

Include the Cable Cover as a content of the machine.

Servicing work:

Attach the included Cable Cover [2] when installing the product.

For a machine that has a serial number earlier than the ones listed below and is often relocated, it is recommended to attach the Cable Cover that has been newly set up as a service part.



P-2 Cable Cover attached

[2] Cable Cover

Points to note about Service work:

Before attaching the Cable Cover, clean the surface of the machine to which the Cover is attached with a sheet moistened with alcohol. The Cable Cover has strong adhesion and therefore, it cannot be repositioned once it is attached.

Service parts:

	Parts Number	Description	Q'ty	P.C. page
Old				001
New	FL2-9160-000	Cover, Cable	0->1	

Affected machines:

iR5075 120V	TVP02143 and later
iR5075 230V	TVR00059 and later
iR5065 120V	TVW03399 and later
iR5065 230V	TVY00123 and later
iR5055 120V	MAS05085 and later
iR5055 230V	MAU00348 and later