

Issued by Canon Europa N.V.

Copier B/W

Hardware

Model:

iR5055
iR5055N
iR5065
iR5065N
iR5075
iR5075N

Ref No.:

iR5075-003
(F1-T01-N03-10011-01)

Date:

June, 2007

Location:


Developing Assembly

Subject:

Countermeasure against lines in the sub scanning direction due to the poor positioning of the Terminal Plate

Detail:

With the Developing Assembly which lot no. is 70401XXX through 70523XXX, lines may appear in the sub scanning direction due to the poor positioning of the Terminal Plate. (P-1)



P-1 Image with lines


[1] Lines [A] Feeding direction

Servicing work:

When mounting the Developing Assembly to the machine, check the lot no. of it. If the Fixing Screw [2] of the Terminal Plate [1] is fully displaced to right side [3], or lines appear in the sub scanning direction, be sure to perform the following operation.

Target lot: 70401XXX through 70523XXX

-Loosen the Fixing Screw [2] of the Terminal Plate and retighten the it at the appropriate point where the plate is magnetically locked [4].



P-2 Area around the Terminal Plate

[1] Terminal Plate

[3] Fully displaced to right side (poor positioning)

[2] Terminal Plate Fixing Screw

[4] Range of magnetically locked position

Points to note about Service Work:

Be sure to secure the Terminal Plate at the magnetically locked position when tightening the screw.