

---

**Model:**

imageRUNNER 1133  
imageRUNNER 1133A  
imageRUNNER 1133iF

**Ref No.:**

F9-T01-M21-10012-02

**Date:**

August 27, 2012

**Approved by:**

Ishioka Jun-ichi

MF5940dn

MF5980dw

**Revised:**

Addition of Affected Machines

---

**Location:**

Software

**Subject:**

MF5900 Series/D1300 Series, iR1133 Series ENGINE CONTROLLER v02.13

**Reason:**

Version up

**[New Version Configuration]**

The operating guarantee is undertaken for the following combinations.

| Bootable | Language | ENGINE CONTROLLER |
|----------|----------|-------------------|
| v13.05   | v01.58   | v02.13            |

**[System CD-ROM No.]**

None

**[CDS]**

None

**Details:**

## 1. Changes made when upgrading ENGINE CONTROLLER v02.12 to v02.13.

| No. | Description  |
|-----|--|
| 1-1 | [Specification change]<br>Flash ROM of ENGINE CONTROLLER is changed to Mask ROM. |

**Affected Machines:**

| <b>ENGINE CONTORLLER v02.13</b> |      |                                       |
|---------------------------------|------|---------------------------------------|
| MF5930DN 120V US                | :HPN | To be informed as soon as identified. |
| MF5930DN 120V CND LTN           | :HPP | To be informed as soon as identified. |
| MF5940DN 230V EU1               | :HPQ | 20001 or later                        |
| MF5940DN 230V EU2               | :HPR | 20079 or later                        |
| MF5940DN 230V EU3               | :HPX | 20001 or later                        |
| MF5950DW 120V US                | :HPY | 15364 or later                        |
| MF5950DW 120V CND LTN           | :HQA | To be informed as soon as identified. |
| MF5950DW 220V KR                | :HQC | To be informed as soon as identified. |
| MF5950DW 220V CN                | :HQE | 02721 or later                        |
| MF5960DN 120V US                | :HQG | To be informed as soon as identified. |
| MF5960DN 120V CND LTN           | :HQH | To be informed as soon as identified. |
| MF5980DW 120V US                | :HQJ | To be informed as soon as identified. |
| MF5980DW 230V EU1               | :HQB | 20001 or later                        |
| MF5980DW 230V EU2               | :HQL | 05982 or later                        |
| MF5980DW 230V EU3               | :HQM | 20001 or later                        |
| MF5980DW 230V AU                | :HQP | 04468 or later                        |
| MF5980DW 230V AE                | :HQN | To be informed as soon as identified. |
| MF5980DW 120V CND LTN           | :HQY | To be informed as soon as identified. |
| MF5930DN 220V CN                | :KWK | 02044 or later                        |
| D1320 120V US                   | :HQR | 10992 or later                        |
| D1350 120V US                   | :HQS | 06633 or later                        |
| D1350 120V CND LTN              | :HQT | To be informed as soon as identified. |
| D1350 115V TW                   | :HQU | To be informed as soon as identified. |
| D1370 120V US                   | :HQV | 03402 or later                        |

| ENGINE CONTORLLER v02.13 |      |                                       |
|--------------------------|------|---------------------------------------|
| D1380 220V CN            | :HQX | To be informed as soon as identified. |
| iR 1133 EU               | :NZR | 20129 or later                        |
| iR 1133A EU              | :Nzs | 21185 or later                        |
| iR 1133IF EU             | :HTC | 15024 or later                        |

### History of Release:

| Service Info. No.<br>/<br>System CD-ROM No.<br>/<br>Date | Version No. /<br>Modifications  |
|--|---|
| F9-T01-M21-10012-02<br>/<br>-<br>/<br>August 24, 2012    | ENGINE CONTROLLER v02.13<br><br>-Addition of Affected Machines  |
| F9-T01-M21-10012-01<br>/<br>-<br>/<br>March 27, 2012     | ENGINE CONTROLLER v02.13<br><br><ENGINE CONTROLLER><br>-[Specification change]<br>Flash ROM of ENGINE CONTROLLER is changed to Mask ROM.  |
| F9-T01-M21-10011-01<br>/<br>-<br>/<br>March 7, 2012      | Bootable v13.05<br><br><Bootable><br>-[Specification change]<br>Specification change is made to the number of FAX received jobs from 10 to 30.<br>-[Modification of field claim]<br>Modification of the error that abnormal image occurs upon FAX receiving JBIG image from some competitor's device.           |
|  | -[Modification of field claim]<br>Modification of the error that wireless LAN access is sometimes unavailable.<br>(C-Walk No. F9C02M171003601)<br>-[Modification of field claim]<br>Modification of the error that SEND to SMB server in a clustered environment is impossible.<br>(C-Walk No. F1C01N001006001) |

| <b>Service Info. No.</b><br>/<br><b>System CD-ROM No.</b><br>/<br><b>Date</b>  | <b>Version No. /</b><br><b>Modifications</b>   |
|--|--|
| F9-T01-M21-10009-01<br>/<br>-<br>/<br>January 12, 2012                         | Bootable v12.03/Language v1.58<br><br><Bootable><br>-[Modification of field claim]<br>Modification of the error that the FAX broadcasting terminates after sending to about 20 destinations when the FAX broadcasting is performed to more than 50 destinations from PC FAX.<br>(C-Walk No. F9C01M171004701)   |
| F9-T01-M21-10007-01<br>/<br>-<br>/<br>December 16, 2011                        | Bootable v11.02/Language v1.57<br><br><Bootable><br>-<Only North America model is subjected><br>[Modification of field claim]<br>Modification of the error that no access point is displayed in the access point list of the operation panel if access point could not be detected automatically with Wifi.<br>(C-Walk No. F9C01M171006001)  |
|  | -[Modification of field claim]<br>Following spelling mistake is corrected.<br>(C-Walk No. F9C01M211000101)<br>"System Settings" ><br>"Store/Print when Forwarding" to "Print when Forwarding"  |
| F9-T01-M20-10001-01<br>/<br>-<br>/<br>September 28, 2011                       | Bootable v11.01 (iR1133 Series Only)<br><br><Bootable><br>-[Modification of error]<br>In a state in which an IC card reader and a USB memory are being connected to the USB-HUB on the device, if the USB memory is disconnected without performing the unmount process, the device becomes to fail in the recognition of IC card. This error is modified.<br><br>(Example case)<br>In expanding uniFLOW, the connection mode mentioned above occurs, and in some case, IC card authentication becomes impossible. |
| F9-T01-M21-10003-03<br>/<br>GM11-1130(FY9-4451-002)<br>/<br>September 28, 2011 | Bootable v10.24/Language v1.55<br><br>-Addition of the modification items (Details: 1-9)   |

| <b>Service Info. No.</b><br>/<br><b>System CD-ROM No.</b><br>/<br><b>Date</b>  | <b>Version No. /</b><br><b>Modifications</b>   |
|--|--|
| F9-T01-M21-10003-02<br>/<br>GM11-1130(FY9-4451-002)<br>/<br>September 16, 2011 | Bootable v10.24/Language v1.55<br><br>-Minor adjustment of wording (Details: 1-2)  |
| F9-T01-M21-10003-01<br>/<br>GM11-1130(FY9-4451-002)<br>/<br>September 2, 2011  | Bootable v10.24/Language v1.55<br><br><Bootable><br>-[New function]<br>uniFLOW function is added.  |
|  | -[Modification of field claim]<br>For models that are sold in a single country, it make unnecessary to set the display language in the initial setting screen upon installation.<br>(Affected models: Japan model, China model, Korean model and Taiwanese Model)<br>(C-Walk No. F9C02M191000901)  |
|  | -[Quality improvement]<br>Modification of the failure that a printer cannot be browsed from Bojour network when its mDNS name includes ". (dot)".<br>-[Quality improvement]<br>Modification of the failure that re-registration of PushScan driver becomes impossible when the lease period of DHCP expires.   |
|  | -[Quality improvement]<br>When "No" is selected as the answer to the question "Memory full Scanning Canceled Print?" at Memory Full, if the color copy is performed in the next job, incorrect image is output. This failure is modified.<br>-[Quality improvement]<br>Modification of the error that the device does not go into Sleep after ADF jam is cleared.                                |
|  | -[Quality improvement]<br>Modification of garbage characters that appear on received images (sender information, address, subject, body text) when a mail is sent after the display language is set to English on US and UK models.<br>-[Quality improvement]<br>Modification of the error that the power save key on the control panel occasionally locks after the device has gone into Sleep. |
| F9-T01-M20-10000-01<br>/<br>-<br>/<br>August 17, 2011                          | Bootable v1.57 (iR1133 Series Only)<br><br><Bootable><br>-[Modification of error]<br>Modification of the error that the device freezes infrequently during continuous copying.   |

| <b>Service Info. No.</b><br>/<br><b>System CD-ROM No.</b><br>/<br><b>Date</b>          | <b>Version No. /</b><br><b>Modifications</b>                           |
|--|--|
| F9-T01-M21-10001-01<br>/<br>GM11-0934(FY9-4451-001)(China/Korea)<br>/<br>July 22, 2011 | Bootable v1.55<br><br>-Modification for improvement in factory process |
| -  | Bootable v1.54/LANG.v1.49/DCON v2.12<br><br>-First release             |