

LAND ROVER													
1,8 18K16	86-88 kW (117-120 PS)	FREELANDER 16V	02/98-10/06	 02-34835-04 ¹² 08-36343-01 ¹³	61-34835-20 LVB500190 MLS 	14-32100-01 WAN2293L (10x) 	71-34837-00 LVP100630L 	12-34836-01 LUB100350L (16x)	71-34838-00 		71-34839-00 LKG100551 		81-34842-00 N ← 30x40x7 A SL RD FPM 81-38342-00 N → LUC100220L 30x40x7 A SL LD FPM
2,0 M 47 M 47 R	80-85 kW (109-116 PS)			 02-40452-01 ¹² 08-36219-01 ¹³ LVQ101240L	61-36455-00 LVB101820L 1,45 mm 1 MLS 61-36455-10 LVB101830L 1,55 mm 2 MLS 61-36455-20 LVB000100L 1,65 mm 3 MLS 		71-40452-00 LVP100620L 	12-35172-01 LGP100310L	71-33109-10 8510218 4x 		71-33027-00 LR020102 2x 	71-36219-00 LVF100420L 71-37004-00 LVF100430L 	81-37002-00 K ← LUF100530L 55x68x8 AB RD PTFE 81-20745-50 K → LUF100540L 90x110x12 AB SL LD PTFE ACM
2,0 14TCIE	72 kW (98 PS)	FREELANDER DI	02/98-11/00	 01-35496-01 ¹² ¹³ 02-35496-02 ¹²	61-35360-00 LVB100910 85,5 Ø 1,05 mm 1 61-35360-10 LVB100920 85,5 Ø 1,2 mm 2 61-35360-20 LVB100930 85,5 Ø 1,35 mm 3 	14-32007-01 LDG100040L (10x) 	71-35496-00 LVP100400 	12-35493-01 LJQ100680L (8x)		71-35492-00 ⁷ LKJ100790 	71-37037-00 WCM100480	71-35495-00 ERR7029 	81-35497-00 K → WZX1915 35x45x7 A SL RD FPM 81-90028-00 K → LUF100420 LD 81-15999-30 N
2,0 20T4	99 kW (135 PS)	DISCOVERY 16V	06/89-10/98	02-35365-01 08-35507-01 ¹⁴ STC848	61-35365-00 LVB101000 87 Ø MLS 		71-35503-00 ES GUG705026VC 71-35504-00 AS LVP100170 	12-37052-01 LUB10009 (16x) Mot.→20T101828 12-37053-01 LJQ100560 (16x) Mot.20T101829→ 70-37052-00 LUB10009 Mot.→20T101828 70-37053-00 LJQ100560 Mot.20T101829→ 16x 16x	71-35499-00 LKJ10027 		71-35501-00 LKG100290L 	71-35502-00 LVF10005 	81-35506-00 K ← ADU8891 35x47x7 A SL RD FPM 81-35498-00 K → LUL10007L
2,0 204PT	177 kW (241 PS)	FREELANDER 2 RANGE ROVER EVOQUE	06/11→	01-36290-02 ¹² ¹³ 02-36290-02 ¹²	61-36290-00 LR024975 MLS 	14-32207-01 LR025253 (10x) 	15-42391-01 LR025664 	12-35546-01 LR025006 (8x) +LR025018 (8x)	15-40257-01 LR024991 (4x) 		71-40262-00 LR025852 	70-31414-10 	81-42449-00 K ← LR043291 37x50x6 A SL RD FPM 81-90012-00 K → LR041995 PTFE

LAND ROVER												
Ltr. 2,2 DW12BTED4 110-140 kW FREELANDER 224DT (150-190 PS) 2 RANGE ROVER EVOQUE	10/06→	02-39244-03 ¹² 08-39246-01 ¹³	61-35805-00 LR017303 85,9 Ø 1,25 mm 1 MLS 61-35805-10 LR017304 85,9 Ø 1,3 mm 2 MLS 61-35805-20 LR017305 85,9 Ø 1,35 mm 3 MLS 61-35805-30 LR017307 85,9 Ø 1,4 mm 4 MLS 	14-35774-01 LR001222 (10x) 	15-38554-01 LR009411 +LR009412 (2x) +LR002834 	12-38539-01 LR001242 (16x) 70-38539-00 LR001242 16x 	11-38553-01 LR005364 16x 	71-42393-00 LR022333 	70-31414-10 	81-36557-00 K ← LR000673 42x62x7 A SL RD PTFE 81-36556-00 K → LR000674 90x110x7 A SL LD PTFE 81-34144-00 N LR000659 27x47x7 A SL RD FPM		
2,4 244DT 90 kW (122 PS)		01-33758-01 ¹² ¹³ 02-33758-05 ¹² 	61-35420-00 LR004418 91 Ø 1,1 mm 1 MLS 61-35420-10 LR004419 91 Ø 1,15 mm 2 MLS 61-35420-20 LR004420 91 Ø 1,2 mm 3 MLS 	14-32204-01 LR004369 (10x) +LR004370 (8x) 	71-33758-00 LR004440 	12-35549-01 LR005901 (16x) 70-35549-00 LR005901 16x 	71-35539-00 LR018370 8x 	71-33894-00 LR004393 	15-35536-01 LR006957 70-31414-10 	81-90014-00 K ← LR029318 PTFE 81-90013-00 K → LR020609 PTFE		
2,5 KV6 129-130 kW FREELANDER 25 K4F (175-177 PS) V6	11/00→	02-35355-02 ¹² 08-35408-01 ¹³ ³⁵	61-35355-00 2x LVB101630L 81 Ø MLS 	14-55070-01 2x 	71-39082-00 2x LVP100470L 	12-35406-01 LUB100350L (24x)	71-39081-00 2x LKJ100992L 	71-35403-00 2x LKG100290L 	70-31414-10 	81-38343-00 K ← LQX100070L 32x45x6,8 A RD MVQ 81-90049-00 K → LUF100300L 81-34842-00 N V 2x 30x40x7 A SL RD FPM 81-38342-00 N H 4x LUC100220L 30x40x7 A SL LD FPM		

LAND ROVER												
Ltr.												
2,5 Td5	102 kW (139 PS)	DISCOVERY Td5	01/99-06/04	<p>02-36824-01 ¹² Mot.→1A736339</p> <p></p> <p>02-36826-01 ¹² Mot.2A736340→</p> <p></p> <p>08-36674-01 ¹³</p>	<p>61-36300-00 LVB000240 86 Ø 1,2 mm 2 </p> <p>MLS</p> <p>61-36300-10 LVB000250 86 Ø 1,27 mm 1 </p> <p>MLS</p> <p>61-36300-20 LVB000260 86 Ø 1,35 mm 3 </p> <p>MLS</p> <p></p>	<p>14-32008-01 ERR5384 (12x)</p> <p></p>	<p>71-36824-00 ERR7094 Mot.→1A736339</p> <p></p> <p>71-36826-00 LVP000020 Mot.2A736340→</p> <p></p>	<p>12-37101-02 LJQ100940 (10x)</p> <p>70-37101-00 LJQ100940</p> <p>10x</p>	<p>71-36672-00 LKJ000010</p> <p></p>	<p>71-36673-00 LKG100470</p> <p>71-38291-00 ¹³ ESR3737</p> <p></p>	<p>71-36674-00 LVF500040</p> <p></p>	<p>81-36671-00 K ← ERR5992 50x65x8 AB SL RD FPM</p> <p>81-90028-00 K → </p> <p>LUF100420 LD</p>
2,5 200TDi	83 kW (113 PS)	DEFENDER TDI DISCOVERY TDI	10/89→	<p>02-35518-01 ¹² STC362</p> <p></p> <p>08-35521-01 ¹³ STC363</p> <p></p>	<p>61-34465-00 ERR5261 92 Ø 1,42 mm 1 </p> <p>61-34465-10 ERR5262 92 Ø 1,52 mm 2 </p> <p>61-34465-20 ERR5263 92 Ø 1,62 mm 3 </p> <p>61-34465-30 ERR7154 92 Ø 1,71 mm 0</p> <p></p> <p>61-36655-00 LVB500200 92 Ø 1,3 mm MLS</p> <p>61-36655-10 LVB500210 92 Ø 1,4 mm MLS</p> <p>61-36655-20 LVB500220 92 Ø 1,5 mm MLS</p> <p>61-36655-30 LVB500230 92 Ø 1,6 mm MLS</p> <p></p>	<p>14-32256-01 ETC8808 (4x) +ETC8809 (10x) +ETC8810 (4x)</p> <p></p>	<p>71-35518-00 ERR2393</p> <p></p>	<p>12-26545-01</p>	<p>71-35517-00 ⁷ ERR1208</p> <p></p>	<p>70-31414-10</p> <p></p>	<p>81-35519-00 K ← 516028 48,6x63,65 RD</p> <p>81-35521-00 K → ERR2532 100x120x12</p> <p>81-15999-30 N</p>	

LAND ROVER												
Ltr.												
2,5 25 6T (BMW) 100 kW 256TM (136 PS)	RANGE ROVER D	07/94-03/02	<p>02-31296-02 ¹² STC2033</p> <p>08-31298-02 ¹³ STC2012</p>	<p>61-31335-10 STC2031 80 Ø 1,87 mm 3 </p>	<p>14-32004-01 STC2023</p>	<p>71-31296-00 STC4177</p>	<p>12-31306-08 LDY000060 (12x) 70-31306-00 LDY000060</p> <p>12x</p>	<p>71-29398-10 STC2203</p> <p>6x</p>	<p>71-29396-00 STC3697</p> <p>4x</p> <p>71-29399-00 STC3696</p>	<p>71-31298-00 STC2036</p>	<p>81-17404-50 K ← LUF000010 48x65x10 81-20745-40 K → STC4283 90x110x12 A SL LD FPM</p>	
2,5 300TDi	DEFENDER TDI DISCOVERY TDI	10/89-12/98	<p>02-35511-01 ¹² STC2802</p> <p>08-35513-01 ¹³ ³⁸ STC2801</p>	<p>61-34465-00 ERR5261 92 Ø 1,42 mm 1 </p> <p>61-34465-10 ERR5262 92 Ø 1,52 mm 2 </p> <p>61-34465-20 ERR5263 92 Ø 1,62 mm 3 </p> <p>61-34465-30 ERR7154 92 Ø 1,71 mm 0</p> <p>61-36655-00 LVB500200 92 Ø 1,3 mm MLS</p> <p>61-36655-10 LVB500210 92 Ø 1,4 mm MLS</p> <p>61-36655-20 LVB500220 92 Ø 1,5 mm MLS</p> <p>61-36655-30 LVB500230 92 Ø 1,6 mm MLS</p>	<p>14-32259-01 ERR1939 (10x) +ETC8808 (4x) +ETC8810 (4x)</p>	<p>71-35511-00 ERR2409</p>	<p>12-26545-01</p>	<p>71-35509-00 ⁷ ERR3785</p>	<p>70-31414-10</p>	<p>81-35512-00 K ← 47x62 RD 81-90029-00 K → LUF100430 81-35514-00 N 40x56x7</p>		

LAND ROVER													
2,7 276DT	140 kW (190 PS)	DISCOVERY TD RANGE ROVER TDVM	07/04→	<p> 02-38558-03 ¹²</p> <p> 08-38527-03 ^{13 35}</p>	<p>61-34875-10 2x LR009719 82,5 Ø 1,17 mm 2 MLS</p> <p>61-34875-20 2x LR009721 82,5 Ø 1,22 mm 3 MLS</p> <p>61-34875-30 2x LR009722 82,5 Ø 1,27 mm 4 MLS</p> <p>61-34875-40 2x LR009723 82,5 Ø 1,32 mm 5 MLS</p>	<p>14-32344-01 2x 1331316 (8x)</p>	<p>71-38558-00 2x LR029132</p>	<p>12-38546-01 24x 1311285 (24x)</p> <p>70-38546-00 24x 1311285</p>		<p>71-34888-00 2x 1336543</p>	<p>71-38527-00 2x LR005994</p> <p>71-41252-00 1365260</p>	<p>81-34316-00 K ← 1102415 35x50x7 A SL RD PTFE ACM</p> <p>81-90050-00 K → LR036542</p> <p>81-38536-00 N 3x 1311318 26x45x8 A SL WD FPM</p>	
3,0 30DDTX 306DT	155-250 kW (211-340 PS)	DISCOVERY SDV6 DISCOVERY TD RANGE ROVER IV TD Hybrid 4x4 RANGE ROVER IV TD 4x4 RANGE ROVER SPORT TD RANGE ROVER SPORT TD Hybrid 4x4 RANGE ROVER SPORT TD 4x4	09/09→	<p> 02-38558-02 ¹²</p> <p> 08-38527-02 ¹³</p>	<p>61-36610-00 2x LR013063 85 Ø 1,17 mm 2 MLS</p> <p>61-36610-10 2x LR013066 85 Ø 1,22 mm 3 MLS</p> <p>61-36610-20 2x LR013070 85 Ø 1,27 mm 4 MLS</p> <p>61-36610-30 2x LR013073 85 Ø 1,32 mm 5 MLS</p>	<p>14-32344-01 2x 1331316 (8x)</p>	<p>71-38558-00 2x LR029132</p>	<p>12-38546-01 24x 1311285 (24x)</p> <p>70-38546-00 24x 1311285</p>		<p>71-34888-00 2x 1336543</p>	<p>71-38527-00 2x LR005994</p>	<p>81-34316-00 K ← 1102415 35x50x7 A SL RD PTFE ACM</p> <p>81-90050-00 K → LR036542</p> <p>81-38536-00 N 3x 1311318 26x45x8 A SL WD FPM</p>	
3,2 i6	170 kW (231 PS)			<p>02-37620-01 ¹²</p> <p>08-39587-01 ¹³</p>	<p>61-37620-00 LR006664 84,85 Ø MLS</p>	<p>14-32306-01 LR002553 (14x)</p>	<p>15-39299-01 LR001808 (6x) +LR001978</p> <p></p>	<p>12-31306-05 24x LR002556 (24x)</p> <p>70-31306-00 24x LDY000060</p>	<p>71-39303-00 6x LR001454</p>	<p>71-39332-00 2x LR001455</p>	<p>70-31414-10 </p>	<p>81-39311-00 K ← 19x38,5x8 A SL RD PTFE</p> <p>81-39337-00 K → LR001418 98x118x10 A SL LD PTFE ACM</p>	
3,5 22 D 22D	107-113 kW (146-154 PS)	DISCOVERY (SALLJG) RANGE ROVER	01/87-06/94	<p> 02-35370-01 ¹² STC1566</p> <p> 08-35523-01 ¹³ STC1639</p>	<p>61-35370-00 2x GEG340 92,2 Ø</p>		<p>71-36379-00 2x GEG436 Kork</p>		<p>71-35528-00 LKJ500020</p>		<p>71-35527-00 8x ERC3605</p>	<p>71-35531-00 8x 602087 Kork</p>	<p>81-35519-00 K ← 516028 48,6x63,65 RD</p> <p>81-35523-00 K → 611409 82x98,5 LD</p>

LAND ROVER												
3,9 SEV8 V06VEi 3.9V8EFI 42 D	136-140 kW (185-190 PS)	RANGE ROVER	07/94→	02-35380-01 ⑫ STC2822 08-35523-02 ⑬ STC2823	61-35380-00 2x LVB500030 95,6 Ø 		71-35524-10 2x LVC100260 Gummi 	12-36903-01 ERR1782 (16x) 70-36903-00 16x ERR1782 	71-35528-00 LKJ500020 	71-35532-00 4x ERR6733 	71-35531-00 602087 Kork 	81-35519-00 K ← 516028 48,6x63,65 RD 81-35523-00 K → 611409 82x98,5 LD
3,9 35 D	134 kW (182 PS)	DISCOVERY V8	09/93-10/98	02-35375-01 ⑫ STC1641 Mot.→35D08927B 02-35380-01 ⑫ STC2822 Mot.35D08928B→ 08-35523-01 ⑬ STC1639 Mot.→35D08927B 08-35523-02 ⑬ STC2823 Mot.35D08928B→	61-35375-00 2x ETC7819 91,5 Ø MLS Mot.→35D08927B 61-35380-00 2x LVB500030 95,6 Ø Mot.35D08928B→ 		71-35524-10 2x LVC100260 Gummi 	71-35528-00 LKJ500020 	71-35527-00 8x ERC3605 Mot.→35D08927B 71-35532-00 4x ERR6733 Mot.35D08928B→ 	71-35531-00 602087 Kork 	81-35519-00 K ← 516028 48,6x63,65 RD 81-35523-00 K → 611409 82x98,5 LD	
3,9 35 D	134 kW (182 PS)	RANGE ROVER	11/88-07/94	02-35375-01 ⑫ STC1641 Mot.→35D08927B 02-35380-01 ⑫ STC2822 Mot.35D08928B→ 08-35523-01 ⑬ STC1639 Mot.→35D08927B 08-35523-02 ⑬ STC2823 Mot.35D08928B→	61-35375-00 2x ETC7819 91,5 Ø MLS Mot.→35D08927B 61-35380-00 2x LVB500030 95,6 Ø Mot.35D08928B→ 		71-35524-10 2x LVC100260 Gummi 	12-36903-01 ERR1782 (16x) Mot.35D08928B→ 70-36903-00 16x ERR1782 Mot.35D08928B→ 	71-35528-00 LKJ500020 	71-35527-00 8x ERC3605 Mot.→35D08927B 71-35532-00 4x ERR6733 Mot.35D08928B→ 	71-35531-00 602087 Kork 	81-35519-00 K ← 516028 48,6x63,65 RD 81-35523-00 K → 611409 82x98,5 LD
3,9 36 D	134 kW (182 PS)	DISCOVERY V8	09/93-10/98	02-35375-01 ⑫ STC1641 Mot.→36D25154B 02-35380-01 ⑫ STC2822 Mot.36D25155B→ 08-35523-01 ⑬ STC1639 Mot.→36D25154B 08-35523-02 ⑬ STC2823 Mot.36D25155B→	61-35375-00 2x ETC7819 91,5 Ø MLS Mot.→36D25154B 61-35380-00 2x LVB500030 95,6 Ø Mot.36D25155B→ 		71-35524-10 2x LVC100260 Gummi 	71-35528-00 LKJ500020 	71-35527-00 8x ERC3605 Mot.→36D25154B 71-35532-00 4x ERR6733 Mot.36D25155B→ 	71-35531-00 602087 Kork 	81-35519-00 K ← 516028 48,6x63,65 RD 81-35523-00 K → 611409 82x98,5 LD	
3,9 36 D	134 kW (182 PS)	RANGE ROVER	11/88-07/94	02-35375-01 ⑫ STC1641 Mot.→36D25154B 02-35380-01 ⑫ STC2822 Mot.36D25155B→ 08-35523-01 ⑬ STC1639 Mot.→36D25154B 08-35523-02 ⑬ STC2823 Mot.36D25155B→	61-35375-00 2x ETC7819 91,5 Ø MLS Mot.→36D25154B 61-35380-00 2x LVB500030 95,6 Ø Mot.36D25155B→ 		71-35524-10 2x LVC100260 Gummi 	12-36903-01 ERR1782 (16x) Mot.36D25155B→ 70-36903-00 16x ERR1782 Mot.36D25155B→ 	71-35528-00 LKJ500020 	71-35527-00 8x ERC3605 Mot.→36D25154B 71-35532-00 4x ERR6733 Mot.36D25155B→ 	71-35531-00 602087 Kork 	81-35519-00 K ← 516028 48,6x63,65 RD 81-35523-00 K → 611409 82x98,5 LD

LAND ROVER												
3,9 37 D	127 kW (173 PS)	RANGE ROVER	11/88-07/94	02-35375-01 ⑫ STC1641 Mot.→37D02931B 02-35380-01 ⑫ STC2822 Mot.37D02932B→ 08-35523-01 ⑬ STC1639 Mot.→37D02931B 08-35523-02 ⑬ STC2823 Mot.37D02932B→	61-35375-00 2x ETC7819 91,5 Ø MLS Mot.→37D02931B 61-35380-00 2x LVB500030 95,6 Ø Mot.37D02932B→ 		71-35524-10 2x LVC100260 Gummi 	12-36903-01 ERR1782 (16x) Mot.37D02932B→ 70-36903-00 16x ERR1782 Mot.37D02932B→	71-35528-00 LKJ500020 		71-35527-00 8x ERC3605 Mot.→37D02931B 71-35532-00 4x ERR6733 Mot.37D02932B→ 	71-35531-00 602087 Kork 81-35519-00 K ← 516028 48,6x63,65 RD 81-35523-00 K → 611409 82x98,5 LD
3,9 38 D	127 kW (173 PS)	RANGE ROVER	11/88-07/94	02-35375-01 ⑫ STC1641 Mot.→38D27237B 02-35380-01 ⑫ STC2822 Mot.38D27238B→ 08-35523-01 ⑬ STC1639 Mot.→38D27237B 08-35523-02 ⑬ STC2823 Mot.38D27238B→	61-35375-00 2x ETC7819 91,5 Ø MLS Mot.→38D27237B 61-35380-00 2x LVB500030 95,6 Ø Mot.38D27238B→ 		71-35524-10 2x LVC100260 Gummi 	12-36903-01 ERR1782 (16x) Mot.38D37238B→ 70-36903-00 16x ERR1782 Mot.38D37238B→	71-35528-00 LKJ500020 		71-35527-00 8x ERC3605 Mot.→38D27237B 71-35532-00 4x ERR6733 Mot.38D27238B→ 	71-35531-00 602087 Kork 81-35519-00 K ← 516028 48,6x63,65 RD 81-35523-00 K → 611409 82x98,5 LD
3,9 3.9V8EFI	127 kW (173 PS)	RANGE ROVER	11/88-07/94	02-35375-01 ⑫ STC1641 →12/93 02-35380-01 ⑫ STC2822 01/94→ 08-35523-02 ⑬ STC2823 01/94→ 08-35523-01 ⑬ STC1639	61-35375-00 2x ETC7819 91,5 Ø MLS →12/93 61-35380-00 2x LVB500030 95,6 Ø 01/94→ 		71-35524-10 2x LVC100260 Gummi 	12-36903-01 ERR1782 (16x) →12/93 70-36903-00 16x ERR1782	71-35528-00 LKJ500020 		71-35527-00 8x ERC3605 →12/93 71-35532-00 4x ERR6733 01/94→ 	71-35531-00 602087 Kork 81-35519-00 K ← 516028 48,6x63,65 RD 81-35523-00 K → 611409 82x98,5 LD
4,0 MGRV8	136 kW (185 PS)	DISCOVERY V8	11/98-06/04	02-35380-01 ⑫ STC2822 08-35523-02 ⑬ STC2823	61-35380-00 2x LVB500030 95,6 Ø 		71-35524-10 2x LVC100260 Gummi 	12-36903-01 ERR1782 (16x) 70-36903-00 16x ERR1782	71-35528-00 LKJ500020 		71-35532-00 4x ERR6733 71-35531-00 602087 Kork 71-39086-00 LVF100400 Gummi 	81-35519-00 K ← 516028 48,6x63,65 RD 81-35523-00 K → 611409 82x98,5 LD
4,3 40 D	149 kW (203 PS)	RANGE ROVER	09/92-07/94	02-35380-01 ⑫ STC2822 08-35523-02 ⑬ STC2823	61-35380-00 2x LVB500030 95,6 Ø 		71-35524-10 2x LVC100260 Gummi 		71-35528-00 LKJ500020 		71-35532-00 4x ERR6733 71-35531-00 602087 Kork 	81-35519-00 K ← 516028 48,6x63,65 RD 81-35523-00 K → 611409 82x98,5 LD

LAND ROVER													
Ltr.													
4,3 4.2V8EFI	149 kW (203 PS)	RANGE ROVER	09/92-07/94	02-35380-01 ¹² STC2822 08-35523-02 ¹³ STC2823	61-35380-00 2x LVB500030 95,6 Ø 		71-35524-10 2x LVC100260 Gummi 	12-36903-01 ERR1782 (16x) 70-36903-00 ERR1782 16x 	71-35528-00 LKJ500020 		71-35532-00 4x ERR6733 	71-35531-00 602087 Kork 	81-35519-00 K ← 516028 48,6x63,65 RD 81-35523-00 K → 611409 82x98,5 LD
4,4 M62 B44	210 kW (286 PS)			02-33396-01 ¹² LVQ00020 08-31828-03 ¹³	61-31370-00 L LVB000360 93 Ø 1,74 mm MLS Zyl. 1 - 4 61-31370-10 L LVB000370 93 Ø 2,07 mm MLS Zyl. 1 - 4 61-31375-00 R LVB000340 93 Ø 1,74 mm MLS Zyl. 5 - 8 61-31375-10 R LVB000350 93 Ø 2,07 mm MLS Zyl. 5 - 8 	14-32005-01 2x LYG000200 	15-33396-01 L LR003813 +LVP000030 Zyl. 1 - 4 15-33397-01 R LR003812 +LVP000030 Zyl. 5 - 8 	12-31306-12 LDY000060 (16x) 70-31306-00 LDY000060 32x	71-31853-00 4x LKJ000040 		71-31834-10 3x LKG000100 71-31836-10 LKG000100 	71-31828-00 LVF000030 71-40369-00 ¹¹ LVF000040 	81-17404-50 K ← LUF000010 48x65x10 AB SL RD FPM 81-27373-00 K → LUF000020 100x125x13 A SL LD FPM
4,6 46 D	165 kW (224 PS)	RANGE ROVER	07/94-03/02	02-35380-01 ¹² STC2822 08-35523-02 ¹³ STC2823	61-35380-00 2x LVB500030 95,6 Ø 		71-35524-10 2x LVC100260 Gummi 		71-35528-00 LKJ500020 		71-35532-00 4x ERR6733 	71-35531-00 602087 Kork 	81-35519-00 K ← 516028 48,6x63,65 RD 81-35523-00 K → 611409 82x98,5 LD