

HONDA														
1,0 ECA1	50-56 kW (68-76 PS)	INSIGHT INSIGHT VTEC	04/00-12/06	<b>02-53715-01</b> <sup>12</sup> 06110-PHM-000 <b>08-53609-01</b> <sup>13</sup> 06111-PHM-000	<b>61-53715-00</b> 12251-PHM-004 73 Ø MLS 		<b>71-53757-00</b> 12341-PHM-000 	<b>12-53547-02</b> 12210-PZ004 (6x) +12211-PZ1-004 (6x)	<b>71-53753-00</b> 17106-PHM-006 3x  <b>71-53754-00</b> <sup>10</sup> 17146-PHM-004 		<b>71-53756-00</b> 18115-PHM-004 	<b>10-53609-01</b> 11251-PHM-000 +11252-PHM-000 	<b>81-53272-00 K</b> ← 91212-PWA-003 40x55x8 A SL RD MVQ <b>81-53758-00 K</b> → 91214-PHM-003 65x88x10 A SL LD	
1,2 ER1 ER2 ER4	33-41 kW (45-56 PS)	JAZZ	10/83-10/86	<b>01-52349-01</b> <sup>12</sup> <sup>13</sup> 061A1-PE8-000 +061B1-PC0-020 <b>02-52349-01</b> <sup>12</sup> 061A1-PE8-000	<b>61-52349-00</b> 12251-PC0-010 61,9 Ø 		<b>71-52313-00</b> 12341-PC1-010 			<b>71-52351-00</b> <sup>7</sup> 18115-PC0-014 		<b>71-52352-00</b> 11251-PC0-014 	<b>81-53246-00 K</b> ← 91213-PH1-003 35x50x8 A SL RD NBR <b>81-53308-00 K</b> → 91214-634-004 74x98x12 A SL RD MVQ <b>81-53219-00 N</b> 91203-PG6-003 27x43x9 A SL LD NBR	
1,2 L12A1	57-58 kW (78-79 PS)	CIVIC JAZZ	04/01-07/08	<b>02-37065-01</b> <sup>12</sup> 06110-PWA-030 <b>08-40019-01</b> <sup>13</sup> 06111-PWA-010 +06114-PWA-000	<b>61-37065-00</b> 12251-PWA-J01 MLS 	<b>14-32335-01</b> 90008-PWA-003 (10x) 	<b>15-39874-01</b> 12341-PWA-000 	<b>12-53547-04</b> 12210-PZ1-003 (4x) +12211-PZ1-003 (4x)	<b>11-39877-01</b> 17105-PWA-007 (4x)  <b>71-39878-00</b> <sup>10</sup> 17146-PWA-004 		<b>71-39879-00</b> 18115-PWA-003 	<b>70-31414-10</b>  <b>71-39882-00</b> 11252-PWA-000 	<b>81-53272-00 K</b> ← 91212-PWA-003 40x55x8 A SL RD MVQ <b>81-53338-00 K</b> → 91214-PWA-003 80x98x10 A SL LD NBR	
1,2 L12A2 L12A3	58-61 kW (79-83 PS)	CITY	05/03→	<b>02-37755-01</b> <sup>12</sup> 06110-REA-Z00 <b>08-40019-01</b> <sup>13</sup> 06111-PWA-010 +06114-PWA-000	<b>61-37755-00</b> 12251-REA-Z01 MLS 	<b>14-32335-01</b> 90008-PWA-003 (10x) 	<b>15-39874-01</b> 12341-PWA-000 	<b>12-53547-04</b> 12210-PZ1-003 (4x) +12211-PZ1-003 (4x)	<b>11-39877-01</b> 17105-PWA-007 (4x)  <b>71-39878-00</b> <sup>10</sup> 17146-PWA-004 		<b>71-39879-00</b> 18115-PWA-003 	<b>70-31414-10</b>  <b>71-39882-00</b> 11252-PWA-000 	<b>81-53272-00 K</b> ← 91212-PWA-003 40x55x8 A SL RD MVQ <b>81-53338-00 K</b> → 91214-PWA-003 80x98x10 A SL LD NBR	
1,2 L12B1	66 kW (90 PS)	JAZZ	07/08→	<b>02-54085-01</b> <sup>12</sup> <sup>19</sup> 06110-RB0-010 <b>08-40019-01</b> <sup>13</sup> 06111-PWA-010 +06114-PWA-000	<b>61-54085-00</b> 12251-RB0-004 0,65 mm MLS 	<b>14-32335-01</b> 90008-PWA-003 (10x) 	<b>71-54146-00</b> 12341-RB0-003 ACM 	<b>12-53547-01</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) <b>70-53547-00 ES</b> 12210-PZ1-004 <b>70-53547-10 AS</b> 12211-PZ1-004	<b>71-54147-00</b> 17105-RB0-004 8x <b>11-54149-01</b> <sup>10</sup> 17115-RB0-007 (4x) 8x		<b>71-54148-00</b> 18115-RB0-007 	<b>70-31414-10</b>  <b>71-39882-00</b> 11252-PWA-000 	<b>81-53272-00 K</b> ← 91212-PWA-003 40x55x8 A SL RD MVQ <b>81-53338-00 K</b> → 91214-PWA-003 80x98x10 A SL LD NBR	
1,2 ZA2	40 kW (54 PS)	CIVIC	01/84-10/87	<b>02-52295-04</b> <sup>12</sup> 061A1-PE3-020 <b>08-52284-01</b> <sup>13</sup> 061B1-PE0-010	<b>61-52295-10</b> 12251-PE3-014 74,5 Ø 		<b>71-52289-00</b> 12341-PE0-000 			<b>71-52377-00</b> 17105-PE1-650 		<b>71-52378-00</b> 18110-PE0-010 	<b>71-52284-00</b> 11251-PE0-020 2x 	<b>81-53233-00 K</b> ← 91212-PD6-A01 31x46x8 A SL LD NBR <b>81-53323-00 K</b> → 91214-PH1-004 80x100x10 A SL RD MVQ <b>81-53224-00 N</b> 91213-PE1-721 29x45x8 A SL LD NBR

HONDA													
Ltr.													
1,3 D13B1 D13B2	55 kW (75 PS) CIVIC	10/87-11/95	<b>01-52355-01</b> <sup>(12)</sup> <sup>(13)</sup> 061A1-PM3-000 +061B14-PM3-000 <b>02-52355-01</b> <sup>(12)</sup> 061A1-PM3-000	<b>61-52355-00</b> 12251-PM3-003 75,5 Ø 	<b>71-52357-00</b> 12341-PM6-010 	<b>12-53539-01</b> 12210-PT2-004 (8x) +12211-PT2-004 (8X)	<b>71-52356-00</b> 17105-PM3-004 		<b>71-52354-00</b> 18115-PM3-003 	<b>71-52284-00</b> 11251-PE0-020 	<b>81-53233-00</b> K ← 91212-PD6-A01 31x46x8 A SL LD NBR <b>81-53323-00</b> K → 91214-PH1-004 80x100x10 A SL RD MVQ <b>81-53224-00</b> N 91213-PE1-721 29x45x8 A SL LD NBR		
1,3 D13B7	48 kW (65 PS) LOGO	03/99-03/02	<b>02-53735-01</b> <sup>(12)</sup> 06110-P7A-G00 <b>08-53782-01</b> <sup>(13)</sup> 06111-P7A-G00	<b>61-53735-00</b> 12251-P7A-G01 76 Ø 0,65 mm MLS 	<b>15-52543-01</b> 12030-P2A-000 		<b>71-53778-00</b> 17105-P7A-004 		<b>71-53779-00</b> 18115-PEJ-004 	<b>71-53794-00</b> 11251-P1J-E00 	<b>81-53726-00</b> K ← 91212-P7A-004 31x46x7 A SL LD NBR <b>81-53323-00</b> K → 91214-PH1-004 80x100x10 A SL RD MVQ <b>81-53224-00</b> N 91213-PE1-721 29x45x8 A SL LD NBR		
1,3 EN1 EN2 EN4	33-52 kW (45-71 PS) CIVIC	09/79-12/84	<b>02-52273-06</b> <sup>(12)</sup> 061A1-PA1-026 <b>08-52284-01</b> <sup>(13)</sup> 061B1-PE0-010	<b>61-52273-10</b> 12251-642-020 74 Ø 	<b>71-52283-00</b> 12341-PA1-000 		<b>71-52278-00</b> 2x 17105-634-000 		<b>71-52276-00</b> 4x 18110-PA1-000 	<b>71-52284-00</b> 11251-PE0-020 	<b>81-53246-00</b> K ← 91213-PH1-003 35x50x8 A SL RD NBR <b>81-53308-00</b> K → 91214-634-004 74x98x12 A SL RD MVQ <b>81-53219-00</b> N 91203-PG6-003 27x43x9 A SL LD NBR		
1,3 EV2	52 kW (71 PS) CIVIC CRX	08/83-12/87	<b>02-52295-04</b> <sup>(12)</sup> 061A1-PE3-020 <b>08-52284-01</b> <sup>(13)</sup> 061B1-PE0-010	<b>61-52295-10</b> 12251-PE3-014 74,5 Ø 	<b>71-52289-00</b> 12341-PE0-000 		<b>71-52377-00</b> 17105-PE1-650 		<b>71-52378-00</b> 2x 18110-PE0-010 	<b>71-52284-00</b> 11251-PE0-020 	<b>81-53233-00</b> K ← 91212-PD6-A01 31x46x8 A SL LD NBR <b>81-53323-00</b> K → 91214-PH1-004 80x100x10 A SL RD MVQ <b>81-53224-00</b> N 91213-PE1-721 29x45x8 A SL LD NBR		
1,3 L13A1 L13A7 L13A8	61-85 kW (83-116 PS) CITY CIVIC FIT JAZZ JAZZ DSI	03/02→	<b>02-37065-01</b> <sup>(12)</sup> 06110-PWA-030 <b>08-40019-01</b> <sup>(13)</sup> 06111-PWA-010 +06114-PWA-000	<b>61-37065-00</b> 12251-PWA-J01 MLS 	<b>14-32335-01</b> 90008-PWA-003 (10x) 	<b>15-39874-01</b> 12341-PWA-000 	<b>12-53547-04</b> 12210-PZ1-003 (4x) +12211-PZ1-003 (4x)	<b>11-39877-01</b> 17105-PWA-007 (4x) 	<b>71-39878-00</b> <sup>(10)</sup> 17146-PWA-004 	<b>71-39879-00</b> 18115-PWA-003 	<b>70-31414-10</b> 	<b>71-39882-00</b> 11252-PWA-000 	<b>81-53272-00</b> K ← 91212-PWA-003 40x55x8 A SL RD MVQ <b>81-53338-00</b> K → 91214-PWA-003 80x98x10 A SL LD NBR
1,3 L13A3 L13A5	60-65 kW (82-88 PS) CITY	10/05→	<b>02-37755-01</b> <sup>(12)</sup> 06110-REA-Z00 <b>08-40019-01</b> <sup>(13)</sup> 06111-PWA-010 +06114-PWA-000	<b>61-37755-00</b> 12251-REA-Z01 MLS 	<b>14-32335-01</b> 90008-PWA-003 (10x) 	<b>15-39874-01</b> 12341-PWA-000 	<b>12-53547-04</b> 12210-PZ1-003 (4x) +12211-PZ1-003 (4x)	<b>11-39877-01</b> 17105-PWA-007 (4x) 	<b>71-39878-00</b> <sup>(10)</sup> 17146-PWA-004 	<b>71-39879-00</b> 18115-PWA-003 	<b>70-31414-10</b> 	<b>71-39882-00</b> 11252-PWA-000 	<b>81-53272-00</b> K ← 91212-PWA-003 40x55x8 A SL RD MVQ <b>81-53338-00</b> K → 91214-PWA-003 80x98x10 A SL LD NBR

HONDA												
Ltr.												
1,3 L13Z1	73 kW (100 PS) JAZZ	07/08→		<b>02-54085-01</b> <sup>12</sup> <sup>19</sup> 06110-RB0-010 <b>08-40019-01</b> <sup>13</sup> 06111-PWA-010 +06114-PWA-000	<b>61-54085-00</b> 12251-RB0-004 0,65 mm MLS 	<b>14-32335-01</b> 90008-PWA-003 (10x) 	<b>71-54146-00</b> 12341-RB0-003 ACM 	<b>12-53547-01</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) <b>70-53547-00</b> ES 12210-PZ1-004 <b>70-53547-10</b> AS 12211-PZ1-004	<b>71-54147-00</b> 17105-RB0-004 8x  <b>11-54149-01</b> <sup>10</sup> 17115-RB0-007 (4x) 8x 	<b>71-54148-00</b> 18115-RB0-007 	<b>70-31414-10</b>  <b>71-39882-00</b> 11252-PWA-000 	<b>81-53272-00</b> K ← 91212-PWA-003 40x55x8 A SL RD MVQ <b>81-53338-00</b> K → 91214-PWA-003 80x98x10 A SL LD NBR
1,4 D14A3 D14A4 D14Z1	55-66 kW (75-90 PS) CIVIC	11/95-02/01		<b>02-53690-01</b> <sup>12</sup> 06110-P2A-030	<b>61-53690-00</b> 12251-P2J-004 76 Ø 0,7 mm MLS 		<b>15-52543-01</b> 12030-P2A-000 	<b>12-53547-01</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) <b>70-53547-00</b> 12210-PZ1-004 <b>70-53547-10</b> 12211-PZ1-004	<b>71-53723-00</b> 17105-P2A-014 8x  8x 	<b>71-53724-00</b> 18115-P2A-004 	<b>71-53794-00</b> 11251-P1J-E00 	<b>81-53233-00</b> K ← 91212-PD6-A01 31x46x8 A SL LD NBR <b>81-53323-00</b> K → 91214-PH1-004 80x100x10 A SL RD MVQ <b>81-53224-00</b> N 91213-PE1-721 29x45x8 A SL LD NBR
1,4 D14A7 D14A8	55-66 kW (75-90 PS) CIVIC CONCERTO	08/89-02/01		<b>02-53690-02</b> <sup>12</sup> 06110-P1J-E00 <b>08-53794-02</b> <sup>13</sup> 06111-P2A-010	<b>61-53690-00</b> 12251-P2J-004 76 Ø 0,7 mm MLS 		<b>15-52543-01</b> 12030-P2A-000 	<b>12-53547-01</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) <b>70-53547-00</b> 12210-PZ1-004 <b>70-53547-10</b> 12211-PZ1-004	<b>11-40398-01</b> 17105-P1J-E01 (3x) +17106-P1J-E01 (1x) 8x  8x 	<b>71-53724-00</b> 18115-P2A-004 	<b>71-53794-00</b> 11251-P1J-E00 	<b>81-40389-00</b> K ← 91212-PD6-A01 31x46x8 A SL LD <b>81-53323-00</b> K → 91214-PH1-004 80x100x10 A SL RD MVQ <b>81-53224-00</b> N 91213-PE1-721 29x45x8 A SL LD NBR
1,4 D14Z5 D14Z6	55-66 kW (75-90 PS) CIVIC	12/00-09/05		<b>02-53705-03</b> <sup>12</sup> 06110-PSM-E00 <b>08-53794-01</b> <sup>13</sup> 06111-PSG-Y10	<b>61-53705-00</b> 12251-PLC-003 76 Ø 0,73 mm MLS 		<b>15-53736-01</b> 123030-PLC-010 	<b>12-53547-01</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) <b>70-53547-00</b> 12210-PZ1-004 <b>70-53547-10</b> 12211-PZ1-004	<b>71-53796-00</b> 4x 17105-PLA-G01 8x  8x <b>71-53784-00</b> <sup>10</sup> 17055-PLD-004 	<b>71-53734-00</b> 18115-PLC-J01 	<b>71-53794-00</b> 11251-P1J-E00 	<b>81-53323-00</b> K → 91214-PH1-004 80x100x10 A SL RD MVQ <b>81-53224-00</b> N 91213-PE1-721 29x45x8 A SL LD NBR
1,4 L13Z1	73 kW (99-100 PS) CITY CIVIC	09/08→		<b>02-54085-01</b> <sup>12</sup> <sup>19</sup> 06110-RB0-010 <b>08-40019-01</b> <sup>13</sup> 06111-PWA-010 +06114-PWA-000	<b>61-54085-00</b> 12251-RB0-004 0,65 mm MLS 	<b>14-32335-01</b> 90008-PWA-003 (10x) 	<b>71-54146-00</b> 12341-RB0-003 ACM 	<b>12-53547-01</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) <b>70-53547-00</b> ES 12210-PZ1-004 <b>70-53547-10</b> AS 12211-PZ1-004	<b>71-54147-00</b> 17105-RB0-004 8x  <b>11-54149-01</b> <sup>10</sup> 17115-RB0-007 (4x) 8x 	<b>71-54148-00</b> 18115-RB0-007 	<b>70-31414-10</b>  <b>71-39882-00</b> 11252-PWA-000 	<b>81-53272-00</b> K ← 91212-PWA-003 40x55x8 A SL RD MVQ <b>81-53338-00</b> K → 91214-PWA-003 80x98x10 A SL LD NBR
1,5 D15A1	63 kW (86 PS) INTEGRA	10/85-08/89		<b>02-52295-04</b> <sup>12</sup> 061A1-PE3-020 <b>08-52284-01</b> <sup>13</sup> 061B1-PE0-010	<b>61-52295-10</b> 12251-PE3-014 74,5 Ø 		<b>71-52289-00</b> 12341-PE0-000 		<b>71-52377-00</b> 17105-PE1-650 	<b>71-52378-00</b> 18110-PE0-010 2x 	<b>71-52284-00</b> 11251-PE0-020 	<b>81-53233-00</b> K ← 91212-PD6-A01 31x46x8 A SL LD NBR <b>81-53323-00</b> K → 91214-PH1-004 80x100x10 A SL RD MVQ <b>81-53224-00</b> N 91213-PE1-721 29x45x8 A SL LD NBR

HONDA													
Ltr.	Power	Model	Year	Part 1	Part 2	Part 3	Part 4	Part 5	Part 6	Part 7	Part 8	Part 9	Part 10
1,5 D15B2	61-74 kW (83-101 PS)	CIVIC CONCERTO	10/87-12/95	<b>01-52355-02</b> <sup>(12)</sup> <sup>(13)</sup> 061A1-PM6-000 +061B1-PM3-000 <b>02-52355-02</b> <sup>(12)</sup> 061A1-PM6-000	<b>61-52355-00</b> 12251-PM3-003 75,5 Ø 		<b>71-52357-00</b> 12341-PM6-010 	<b>12-53539-01</b> 12210-PT2-004 (8x) +12211-PT2-004 (8X)	<b>71-52358-00</b> 17105-PG6-010 		<b>71-52354-00</b> 18115-PM3-003 	<b>71-52284-00</b> 11251-PE0-020 	<b>81-53233-00</b> K ← 91212-PD6-A01 31x46x8 A SL LD NBR <b>81-53323-00</b> K → 91214-PH1-004 80x100x10 A SL RD MVQ <b>81-53224-00</b> N 91213-PE1-721 29x45x8 A SL LD NBR
1,5 D15B7	74 kW (101 PS)	CIVIC	08/93-11/95	<b>01-52680-01</b> <sup>(12)</sup> <sup>(13)</sup> 06110-PO3-000 +06111-PO7-000 <b>02-52680-01</b> <sup>(12)</sup> 06110-PO3-000	<b>61-52680-00</b> 12251-PM5-S02 75,5 Ø 		<b>15-52384-01</b> 	<b>12-53547-01</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) <b>70-53547-00</b> 12210-PZ1-004 <b>70-53547-10</b> 12211-PZ1-004	<b>71-52381-00</b> 17105-PO0-T02 		<b>71-52382-00</b> 18115-PO0-004  <b>71-52281-00</b> <sup>(10)</sup> 18212-SA0-003 	<b>71-52284-00</b> 11251-PE0-020 	<b>81-53233-00</b> K ← 91212-PD6-A01 31x46x8 A SL LD NBR <b>81-53323-00</b> K → 91214-PH1-004 80x100x10 A SL RD MVQ <b>81-53224-00</b> N 91213-PE1-721 29x45x8 A SL LD NBR
1,5 D15Z1	69 kW (94 PS)	CIVIC	10/91-11/95	<b>01-52685-01</b> <sup>(12)</sup> <sup>(13)</sup> 06110-PO8-000 +06111-PO8-000 <b>02-52685-01</b> <sup>(12)</sup> 06110-PO8-000	<b>61-52685-00</b> 12251-PO8-004 75,8 Ø MLS 		<b>71-52543-00</b> 12341-PO8-000 	<b>12-53539-01</b> 12210-PT2-004 (8x) +12211-PT2-004 (8X)	<b>71-52541-00</b> 17105-PO7-004  <b>71-52542-00</b> <sup>(10)</sup> 17105-PO8-004 		<b>71-52382-00</b> 18115-PO0-004 	<b>71-52284-00</b> 11251-PE0-020 	<b>81-53233-00</b> K ← 91212-PD6-A01 31x46x8 A SL LD NBR <b>81-53323-00</b> K → 91214-PH1-004 80x100x10 A SL RD MVQ <b>81-53224-00</b> N 91213-PE1-721 29x45x8 A SL LD NBR
1,5 D15Z3	66 kW (90 PS)	CIVIC VTEC-E	09/94-01/97	<b>02-53690-01</b> <sup>(12)</sup> 06110-P2A-030	<b>61-53690-00</b> 12251-P2J-004 76 Ø 0,7 mm MLS 		<b>15-52543-01</b> 12030-P2A-000 	<b>12-53547-01</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) <b>70-53547-00</b> 12210-PZ1-004 <b>70-53547-10</b> 12211-PZ1-004	<b>71-53723-00</b> 17105-P2A-014 		<b>71-53724-00</b> 18115-P2A-004 	<b>71-53794-00</b> 11251-P1J-E00 	<b>81-53233-00</b> K ← 91212-PD6-A01 31x46x8 A SL LD NBR <b>81-53323-00</b> K → 91214-PH1-004 80x100x10 A SL RD MVQ <b>81-53224-00</b> N ← 91213-PE1-721 29x45x8 A SL LD NBR
1,5 EW2	63 kW (86 PS)	CIVIC	10/83-10/87	<b>02-52295-04</b> <sup>(12)</sup> 061A1-PE3-020 <b>08-52284-01</b> <sup>(13)</sup> 061B1-PE0-010	<b>61-52295-10</b> 12251-PE3-014 74,5 Ø 		<b>71-52289-00</b> 12341-PE0-000 	<b>12-53037-01</b> 12211-PE0-004 (12x)	<b>71-52377-00</b> 17105-PE1-650 		<b>71-52378-00</b> 18110-PE0-010 	<b>71-52284-00</b> 11251-PE0-020 	<b>81-53233-00</b> K ← 91212-PD6-A01 31x46x8 A SL LD NBR <b>81-53323-00</b> K → 91214-PH1-004 80x100x10 A SL RD MVQ <b>81-53224-00</b> N 91213-PE1-721 29x45x8 A SL LD NBR



HONDA													
1.5 EW3 EW4	66-74 kW (90-101 PS)	CIVIC CRX	10/83-10/87	<b>02-52295-03</b> <sup>(12)</sup> 061A1-PE7-020	<b>61-52295-10</b> 12251-PE3-014 74,5 Ø		<b>71-52304-00</b> 12341-PE2-003		<b>71-52377-00</b> 17105-PE1-650		<b>71-52378-00</b> 18110-PE0-010	2x <b>71-52284-00</b> 11251-PE0-020	<b>81-53233-00</b> K ← 91212-PD6-A01 31x46x8 A SL LD NBR <b>81-53323-00</b> K → 91214-PH1-004 80x100x10 A SL RD MVQ <b>81-53224-00</b> N 91213-PE1-721 29x45x8 A SL LD NBR
1.5 L15A1	70-79 kW (95-107 PS)	CITY	09/04→	<b>02-54080-01</b> <sup>(12)</sup> <sup>(19)</sup> 06110-REB-Z01 <b>08-40019-01</b> <sup>(13)</sup> 06111-PWA-010 +06114-PWA-000	<b>61-54080-00</b> 12251-REB-Z01 0,85 mm MLS	<b>14-32335-01</b> 90008-PWA-003 (10x)	<b>15-54144-01</b> 12030-PWC-000 ACM	<b>12-53547-01</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) <b>70-53547-00</b> ES 12210-PZ1-004 <b>70-53547-10</b> AS 12211-PZ1-004	8x <b>11-39877-01</b> 17105-PWA-007 (4x) <b>71-39878-00</b> <sup>(10)</sup> 17146-PWA-004		<b>71-39879-00</b> 18115-PWA-003	<b>70-31414-10</b> <b>71-39882-00</b> 11252-PWA-000	<b>81-53272-00</b> K ← 91212-PWA-003 40x55x8 A SL RD MVQ <b>81-53338-00</b> K → 91214-PWA-003 80x98x10 A SL LD NBR
1.5 L15A2 L15A3	81-88 kW (110-120 PS)	JAZZ	07/08→	<b>02-37755-01</b> <sup>(12)</sup> 06110-REA-Z00 <b>08-40019-01</b> <sup>(13)</sup> 06111-PWA-010 +06114-PWA-000	<b>61-37755-00</b> 12251-REA-Z01 MLS	<b>14-32335-01</b> 90008-PWA-003 (10x)	<b>15-39874-01</b> 12341-PWA-000	<b>12-53547-04</b> 12210-PZ1-003 (4x) +12211-PZ1-003 (4x) <b>70-53547-00</b> 12210-PZ1-004 <b>70-53547-10</b> AS 12211-PZ1-004	4x <b>11-39877-01</b> 17105-PWA-007 (4x) <b>71-39878-00</b> <sup>(10)</sup> 17146-PWA-004		<b>71-39879-00</b> 18115-PWA-003	<b>70-31414-10</b> <b>71-39882-00</b> 11252-PWA-000	<b>81-53272-00</b> K ← 91212-PWA-003 40x55x8 A SL RD MVQ <b>81-53338-00</b> K → 91214-PWA-003 80x98x10 A SL LD NBR
1.5 L15A7	88 kW (120 PS)	CITY JAZZ	07/08→	<b>02-54085-01</b> <sup>(12)</sup> <sup>(19)</sup> 06110-RB0-010 <b>08-40019-01</b> <sup>(13)</sup> 06111-PWA-010 +06114-PWA-000	<b>61-54085-00</b> 12251-RB0-004 0,65 mm MLS	<b>14-32335-01</b> 90008-PWA-003 (10x)	<b>71-54146-00</b> 12341-RB0-003 ACM	<b>12-53547-01</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) <b>70-53547-00</b> ES 12210-PZ1-004 <b>70-53547-10</b> AS 12211-PZ1-004	8x <b>11-54147-00</b> 17105-RB0-004 <b>11-54149-01</b> <sup>(10)</sup> 17115-RB0-007 (4x)		<b>71-54148-00</b> 18115-RB0-007	<b>70-31414-10</b> <b>71-39882-00</b> 11252-PWA-000	<b>81-53272-00</b> K ← 91212-PWA-003 40x55x8 A SL RD MVQ <b>81-53338-00</b> K → 91214-PWA-003 80x98x10 A SL LD NBR
1.6 B16A1	110 kW (150 PS)	CIVIC VTEC CRX VTEC	10/89-02/92	<b>02-53335-01</b> <sup>(12)</sup> 061A1-PR3-305	<b>61-53335-00</b> 12251-P30-014 81,5 Ø 0,6 mm MLS		<b>15-53546-01</b> 12030-PR3-000	<b>12-53547-01</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) <b>70-53547-00</b> 12210-PZ1-004 <b>70-53547-10</b> 12211-PZ1-004	8x <b>71-53543-00</b> 17105-P30-004		<b>71-53544-00</b> 18115-P30-003		<b>81-53219-00</b> N 2x 91203-PG6-003 27x43x9 A SL LD NBR
1.6 D16A6 D16A7	79-96 kW (107-130 PS)	CIVIC CRX	09/87-10/95	<b>01-52680-01</b> <sup>(12)</sup> <sup>(13)</sup> 06110-P03-000 +06111-PO7-000 <b>02-52680-01</b> <sup>(12)</sup> 06110-P03-000	<b>61-52680-00</b> 12251-PM5-S02 75,5 Ø		<b>15-52384-01</b>	<b>12-53547-01</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) <b>70-53547-00</b> 12210-PZ1-004 <b>70-53547-10</b> 12211-PZ1-004	8x <b>71-52381-00</b> 17105-PO0-T02		<b>71-52354-00</b> 18115-PM3-003	<b>71-52284-00</b> 11251-PE0-020	<b>81-53233-00</b> K ← 91212-PD6-A01 31x46x8 A SL LD NBR <b>81-53323-00</b> K → 91214-PH1-004 80x100x10 A SL RD MVQ <b>81-53224-00</b> N 91213-PE1-721 29x45x8 A SL LD NBR
1.6 D16A8 D16A9 D16Z5	90-96 kW (122-131 PS)	CIVIC CONCERTO CRX	09/87-03/95	<b>01-52690-01</b> <sup>(12)</sup> <sup>(13)</sup> 061A1-PM7-G00 +061B1-PM7-000 <b>02-52690-01</b> <sup>(12)</sup> 061A1-PM7-G00	<b>61-52690-00</b> 12251-PM7-003 75,5 Ø		<b>71-52544-00</b> 12341-PM7-000	<b>12-53593-01</b> 12210-PT2-004 (8x) +12211-PT2-004 (8x) <b>70-53593-00</b> 12210-PT2-004 <b>70-53593-10</b> 12211-PT2-004	8x 8x		<b>71-52354-00</b> 18115-PM3-003	<b>71-52284-00</b> 11251-PE0-020	<b>81-53219-00</b> N 91203-PG6-003 27x43x9 A SL LD NBR

HONDA														
Ltr.			<b>1</b>											
1,6 D16B2	85 kW (116 PS)			<b>02-53690-01</b> <sup>12</sup> 06110-P2A-030	<b>61-53690-00</b> 12251-P2J-004 76 Ø 0,7 mm MLS 		<b>15-52543-01</b> 12030-P2A-000 	<b>12-53547-01</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) <b>70-53547-00</b> 12210-PZ1-004 <b>70-53547-10</b> 12211-PZ1-004	8x 	<b>71-53723-00</b> 17105-P2A-014 		<b>71-53724-00</b> 18115-P2A-004 	<b>70-31414-10</b> 	<b>81-53224-00 N</b> ← 91213-PE1-721 29x45x8 A SL LD NBR
1,6 D16V1	81 kW (110 PS)	CIVIC	02/01-12/05	<b>02-53705-03</b> <sup>12</sup> 06110-PSM-E00 <b>08-53323-01</b> <sup>13</sup> 06111-PMM-A01	<b>61-53705-00</b> 12251-PLC-003 76 Ø 0,73 mm MLS 		<b>15-53736-01</b> 123030-PLC-010 	<b>12-53547-01</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) <b>70-53547-00</b> 12210-PZ1-004 <b>70-53547-10</b> 12211-PZ1-004	8x 	<b>71-53796-00</b> 17105-PLA-G01 4x 		<b>71-53734-00</b> 18115-PLC-J01 	<b>70-31414-10</b> 	<b>81-40303-00 K</b> ← 91212-PLC-003 38x50x7 A SL LD <b>81-53323-00 K</b> → 91214-PH1-004 80x100x10 A SL RD MVQ <b>81-53224-00 N</b> 91213-PE1-721 29x45x8 A SL LD NBR
1,6 D16W5	91 kW (124 PS)	HR-V	10/99→	<b>02-53690-01</b> <sup>12</sup> 06110-P2A-030 01/03→	<b>61-53690-00</b> 12251-P2J-004 76 Ø 0,7 mm MLS 		<b>15-52543-01</b> 12030-P2A-000 	<b>12-53547-01</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) <b>70-53547-00</b> 12210-PZ1-004 <b>70-53547-10</b> 12211-PZ1-004	8x 	<b>71-53723-00</b> 17105-P2A-014 		<b>71-53724-00</b> 18115-P2A-004 		<b>81-53233-00 K</b> ← 91212-PD6-A01 31x46x8 A SL LD NBR →07/00 <b>81-53323-00 K</b> → 91214-PH1-004 80x100x10 A SL RD MVQ <b>81-53224-00 N</b> 91213-PE1-721 29x45x8 A SL LD NBR
1,6 D16Y7	77-79 kW (105-107 PS)	CIVIC	01/94-03/00	<b>02-53690-01</b> <sup>12</sup> 06110-P2A-030	<b>61-53690-00</b> 12251-P2J-004 76 Ø 0,7 mm MLS 		<b>15-52543-01</b> 12030-P2A-000 	<b>12-53547-01</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) <b>70-53547-00</b> 12210-PZ1-004 <b>70-53547-10</b> 12211-PZ1-004	8x 	<b>71-53723-00</b> 17105-P2A-014 		<b>71-53724-00</b> 18115-P2A-004 	<b>71-53794-00</b> 11251-P1J-E00 	<b>81-40389-00 K</b> ← 91212-P01-003 31x46x7 A SL LD <b>81-53323-00 K</b> → 91214-PH1-004 80x100x10 A SL RD MVQ <b>81-53224-00 N</b> ← 91213-PE1-721 29x45x8 A SL LD NBR
1,6 D16Z2	81-82 kW (110-112 PS)	CIVIC CONCERTO DOMANI	10/87-12/97	<b>02-52355-02</b> <sup>12</sup> 061A1-PM6-000	<b>61-52355-00</b> 12251-PM3-003 75,5 Ø 		<b>71-52357-00</b> 12341-PM6-010 	<b>12-53539-01</b> 12210-PT2-004 (8x) +12211-PT2-004 (8x)		<b>71-52358-00</b> 17105-PG6-010 		<b>71-52354-00</b> 18115-PM3-003 	<b>71-52284-00</b> 11251-PE0-020 	<b>81-53233-00 K</b> ← 91212-PD6-A01 31x46x8 A SL LD NBR <b>81-53323-00 K</b> → 91214-PH1-004 80x100x10 A SL RD MVQ <b>81-53224-00 N</b> 91213-PE1-721 29x45x8 A SL LD NBR

HONDA												
Ltr.			<b>1</b>									
1,6 D16Z6 D16Z7 D16Z9	92 kW (125 PS) CIVIC CIVIC VTEC CRX	10/91-12/98	<b>01-52685-01</b> <sup>12</sup> <sup>13</sup> 06110-PO8-000 +06111-PO8-000 <b>02-52685-01</b> <sup>12</sup> 06110-PO8-000	<b>61-52685-00</b> 12251-PO8-004 75,8 Ø MLS 	<b>15-52543-01</b> 12030-P2A-000 	<b>12-53547-01</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) <b>70-53547-00</b> 12210-PZ1-004 <b>70-53547-10</b> 12211-PZ1-004	<b>71-52541-00</b> 17105-PO7-004 8x <b>71-52542-00</b> <sup>10</sup> 17105-PO8-004 8x 	<b>71-52382-00</b> 18115-PO0-004 	<b>71-52284-00</b> 11251-PE0-020 	<b>81-53233-00</b> K ← 91212-PD6-A01 31x46x8 A SL LD NBR <b>81-53323-00</b> K → 91214-PH1-004 80x100x10 A SL RD MVQ <b>81-53224-00</b> N 91213-PE1-721 29x45x8 A SL LD NBR		
1,6 EY EZ	65 kW (88 PS) ACCORD	09/83-12/89	<b>01-52305-03</b> <sup>12</sup> <sup>13</sup> 061A1-PC7-660 +061B1-PC7-660 <b>02-52305-03</b> <sup>12</sup> 061A1-PC7-660 <b>08-52353-01</b> <sup>13</sup> 061B1-PD2-000	<b>61-52305-10</b> 12251-PD6-013 81 Ø 	<b>71-52361-00</b> 12341-PH4-000 			<b>71-52658-00</b> 18115-PD2-000 	<b>71-52659-00</b> 18116-PD2-000 2x 	<b>71-52353-00</b> 11251-PC6-010 	<b>81-53249-00</b> K ← 91212-PC6-003 35x54x8 A SL LD MVQ <b>81-53323-00</b> K → 91214-PH1-004 80x100x10 A SL RD MVQ <b>81-53224-00</b> N 91213-PE1-721 29x45x8 A SL LD NBR	
1,6 ZC1	92 kW (125 PS) CRX	03/86-10/87	<b>02-52360-01</b> <sup>12</sup> 061A1-PJ1-000	<b>61-52360-00</b> 12251-PG6-003 	<b>71-52544-00</b> 12341-PM7-000 	<b>12-53593-01</b> 12210-PT2-004 (8x) +12211-PT2-004 (8x)	<b>71-52358-00</b> 17105-PG6-010 	<b>71-52354-00</b> 18115-PM3-003 		<b>81-53233-00</b> K ← 91212-PD6-A01 31x46x8 A SL LD NBR <b>81-53323-00</b> K → 91214-PH1-004 80x100x10 A SL RD MVQ <b>81-53219-00</b> N 91203-PG6-003 27x43x9 A SL LD NBR		
1,7 D17A2	92 kW (125 PS) EDIX FR-V STREAM	05/01→	<b>02-53705-02</b> <sup>12</sup> 06110-RJH-000 <b>08-53323-01</b> <sup>13</sup> 06111-PMM-A01	<b>61-53705-00</b> 12251-PLC-003 76 Ø 0,73 mm MLS 	<b>15-53736-01</b> 123030-PLC-010 	<b>12-53547-01</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) <b>70-53547-00</b> 12210-PZ1-004 <b>70-53547-10</b> 12211-PZ1-004	<b>71-53752-00</b> 4x 17105-PMR-A01 8x <b>71-53784-00</b> <sup>10</sup> 17055-PLD-004 8x 	<b>71-53734-00</b> 18115-PLC-J01 	<b>70-31414-10</b> 	<b>81-40303-00</b> K ← 91212-PLC-003 38x50x7 A SL LD <b>81-53323-00</b> K → 91214-PH1-004 80x100x10 A SL RD MVQ <b>81-53224-00</b> N 91213-PE1-721 29x45x8 A SL LD NBR		
1,7 D17A5	92 kW (125 PS) CIVIC VTEC	05/01-12/05	<b>02-53705-01</b> <sup>12</sup> 06110-PLL-Y01 <b>08-53794-01</b> <sup>13</sup> 06111-PSG-Y10	<b>61-53705-00</b> 12251-PLC-003 76 Ø 0,73 mm MLS 	<b>15-53736-01</b> 123030-PLC-010 	<b>12-53547-01</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) <b>70-53547-00</b> 12210-PZ1-004 <b>70-53547-10</b> 12211-PZ1-004	<b>71-53733-00</b> 4x 17055-PLC-004 8x <b>71-53752-00</b> 4x 17105-PMR-A01 8x 	<b>71-53734-00</b> 18115-PLC-J01 	<b>71-53794-00</b> 11251-P1J-E00 	<b>81-40303-00</b> K ← 91212-PLC-003 38x50x7 A SL LD <b>81-53323-00</b> K → 91214-PH1-004 80x100x10 A SL RD MVQ <b>81-53224-00</b> N 91213-PE1-721 29x45x8 A SL LD NBR		

HONDA												
Ltr.												
1,7 D17A8	88 kW (120 PS) CIVIC	05/01-12/05	02-53705-01 <sup>12</sup> 06110-PLL-Y01 08-53323-01 <sup>13</sup> 06111-PMM-A01	61-53705-00 12251-PLC-003 76 Ø 0,73 mm MLS 	15-53736-01 123030-PLC-010 	12-53547-01 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) 70-53547-00 12210-PZ1-004 70-53547-10 12211-PZ1-004	71-53733-00 17055-PLC-004 8x 71-53752-00 17105-PMR-A01 4x 	71-53734-00 18115-PLC-J01 	70-31414-10 	81-40303-00 K ← 91212-PLC-003 38x50x7 A SL LD 81-53323-00 K → 91214-PH1-004 80x100x10 A SL RD MVQ 81-53224-00 N 91213-PE1-721 29x45x8 A SL LD NBR		
1,7 4EE-2	74 kW (100 PS) CIVIC CTDi	01/02-09/05	02-36081-01 <sup>12</sup>  08-38447-01 <sup>13</sup>	61-53245-00 12251-PLZ-D00 80 Ø 1,45 mm 1 □ MLS 61-53245-10 12251-PLZ-D10 80 Ø 1,5 mm 2 □ MLS 61-53245-20 12251-PLZ-D20 1,55 mm 3 □ MLS 	14-32160-01 	71-36081-00 12341-PLZ-D00 	12-31306-01 12211-PLZ-D00 (16x) 70-31306-10 12211-PLZ-D00 16x 	71-35562-00 17105-PLZ-D00 	71-36303-00 18115-PLZ-D00 2x 	70-31414-10 	81-35144-00 K ← 91220-PLZ-D00 40x52x6 A SL RD FPM 81-53299-00 K → 91220-PLZ-D10 87x100x8,5 A SL LD FPM 81-28236-00 N 91214-PLZ-D00 38x50x8 A SL RD FPM	
1,8 B18C4 B18C6	124-140 kW (169-190 PS) CIVIC INTEGRA Type-R	01/97-10/01		61-53335-00 12251-P30-014 81,5 Ø 0,6 mm MLS 	15-53546-01 12030-PR3-000 			71-53544-00 18115-P30-003 		81-53321-00 K → 80x100x10 A SL LD MVQ		
1,8 ET1	74 kW (101 PS) ACCORD	09/83-10/85	01-52305-03 <sup>12</sup> <sup>13</sup> 061A1-PC7-660 +061B1-PC7-660 02-52305-03 <sup>12</sup> 061A1-PC7-660 08-52353-01 <sup>13</sup> 061B1-PD2-000	61-52305-10 12251-PD6-013 81 Ø 	71-52361-00 12341-PH4-000 	12-52819-01 12210-PC1-003 (4x) +12211-PE0-004 (8x)		71-52658-00 18115-PD2-000 71-52659-00 18116-PD2-000 2x 	71-52353-00 11251-PC6-010 	81-53249-00 K ← 91212-PC6-003 35x54x8 A SL LD MVQ 81-53323-00 K → 91214-PH1-004 80x100x10 A SL RD MVQ 81-53224-00 N 91213-PE1-721 29x45x8 A SL LD NBR		
1,8 ET2 ET3 ET4	74-77 kW (101-105 PS) PRELUDE	11/83-04/87	01-52305-03 <sup>12</sup> <sup>13</sup> 061A1-PC7-660 +061B1-PC7-660 02-52305-03 <sup>12</sup> 061A1-PC7-660	61-52305-10 12251-PD6-013 81 Ø 	71-52361-00 12341-PH4-000 	12-52819-01 12210-PC1-003 (4x) +12211-PE0-004 (8x)	71-52666-00 17105-PC7-000 	71-52658-00 18115-PD2-000 71-52659-00 18116-PD2-000 2x 	71-52353-00 11251-PC6-010 	81-53249-00 K ← 91212-PC6-003 35x54x8 A SL LD MVQ 81-53323-00 K → 91214-PH1-004 80x100x10 A SL RD MVQ 81-53224-00 N 91213-PE1-721 29x45x8 A SL LD NBR		



HONDA													
Ltr.	Power	Model	Year	Part 1	Part 2	Part 3	Part 4	Part 5	Part 6	Part 7	Part 8	Part 9	Part 10
1,8 F18B2	100 kW (136 PS)	ACCORD	10/98-12/02	<b>02-53720-02</b> <sup>12</sup> 06110-PDA-E00 <b>08-53764-01</b> <sup>13</sup> 06111-PAA-A01 	<b>61-53720-00</b> 12251-P0A-004 86 Ø 0,7 mm MLS 	<b>14-32337-01</b> 90005-PAA-A01 (9x) +90006-PAA-A01 (1x) 	<b>15-53777-01</b> 12030-P0A-000 	<b>12-53547-01</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) <b>70-53547-00</b> 12210-PZ1-004 <b>70-53547-10</b> 12211-PZ1-004 8x 	<b>71-53841-00</b> 17105-P0A-A02 	<b>71-54081-00</b> 18115-PAA-L21 	<b>70-31414-10</b> 	<b>81-53273-00</b> K ← 91212-PAA-A02 40x52x7,1 A SL LD MVQ <b>81-53323-00</b> K → 91214-PH1-004 80x100x10 A SL RD MVQ <b>81-53222-00</b> N 91213-PT0-003 28x42x8 A SL LD MVQ	
1,8 R18A1 R18A2	103 kW (140 PS)	CIVIC CROSSROAD FR-V STREAM VTEC	09/05→	<b>02-37760-01</b> <sup>12</sup> 06110-RNA-000 +06114-RNA-010 	<b>61-37760-00</b> 12251-RNA-A02 MLS 	<b>14-32339-01</b> 90005-RNA-A01 (10X) 	<b>71-40021-00</b> 12341-RNA-A01 	<b>12-53547-01</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) 	<b>11-40022-01</b> 17105-RNA-A01 (4x) +17106-RNA-A01 (1x)  <b>11-40269-01</b> <sup>10</sup> 17103-RNA-A01 (2x) +17104-RNA-A01 (4x) 	<b>71-40024-00</b> 18115-RNA-004 	<b>70-31414-10</b> 	<b>81-40028-00</b> K ← 91212-RNA-A01 43x58x7 A SL RD FPM <b>81-53338-00</b> K → 91214-PWA-003 80x98x10 A SL LD NBR	
1,8 XUD7T	58 kW (79 PS)	CITY D	02/97-11/99	<b>02-25942-06</b> <sup>12</sup>  <b>08-25918-02</b> <sup>13</sup>	<b>61-33670-00</b> 82 Ø 1,54 mm 2 <b>61-33670-10</b> 82 Ø 1,64 mm 3 	<b>14-32077-01</b> 	<b>71-25942-00</b> 	<b>12-25837-01</b> <b>70-25837-00</b> 8x 	<b>71-33683-00</b> <sup>7</sup> 	<b>50-92244-00</b> <sup>8</sup> 	<b>71-25918-30</b> 	<b>81-25926-10</b> K ← 42x62x8 A RD FPM <b>81-34456-00</b> K → 90x110x7 A SL LD FPM <b>81-21798-30</b> N 35x50x8 A SL WD ACM	
2,0 A20A1 A20A2 A20A3	75-85 kW (102-116 PS)	ACCORD	11/85-12/89	<b>02-52365-01</b> <sup>12</sup> 061A1-PJ0-000 →12/87 <b>02-52365-02</b> <sup>12</sup> 061A1-PJ0-A00 01/88→	<b>61-52365-00</b> 12251-PH4-003 86 Ø 		<b>71-52361-00</b> 12341-PH4-000 	<b>12-52819-01</b> 12210-PC1-003 (4x) +12211-PE0-004 (8x) 	<b>71-52362-00</b> 17105-PH3-000 	<b>71-52658-00</b> 18115-PD2-000  <b>71-52659-00</b> 18116-PD2-000  <b>71-52281-00</b> <sup>9</sup> 18212-SA0-003 →12/87 	<b>71-52353-00</b> 11251-PC6-010 	<b>81-53249-00</b> K ← 91212-PC6-003 35x54x8 A SL LD MVQ 01/88→ <b>81-53323-00</b> K → 91214-PH1-004 80x100x10 A SL RD MVQ <b>81-53224-00</b> N 91213-PE1-721 29x45x8 A SL LD NBR	
2,0 A20A4	90 kW (122 PS)	ACCORD	11/85-12/87	<b>02-52365-01</b> <sup>12</sup> 061A1-PJ0-000	<b>61-52365-00</b> 12251-PH4-003 86 Ø 		<b>71-52361-00</b> 12341-PH4-000 	<b>12-52819-01</b> 12210-PC1-003 (4x) +12211-PE0-004 (8x) 	<b>71-52362-00</b> 17105-PH3-000 	<b>71-52658-00</b> 18115-PD2-000  <b>71-52659-00</b> 18116-PD2-000  <b>71-52281-00</b> <sup>9</sup> 18212-SA0-003 	<b>71-52353-00</b> 11251-PC6-010 	<b>81-53249-00</b> K ← 91212-PC6-003 35x54x8 A SL LD MVQ <b>81-53323-00</b> K → 91214-PH1-004 80x100x10 A SL RD MVQ <b>81-53224-00</b> N 91213-PE1-721 29x45x8 A SL LD NBR	

HONDA													
2,0 B20A1 B20A2 B20A8	98-101 kW (133-137 PS)	ACCORD PRELUDE	04/86-12/89	<b>02-52370-01</b> ⑫ 061A1-PH3-000	<b>61-52370-00</b> 12251-PH3-023 82,5 Ø 		<b>15-52368-01</b> 12341-PK2-000 +12342-PG6-000 (4x) 		<b>71-52362-00</b> 17105-PH3-000 		<b>71-52366-00</b> 18115-PK2-000 	<b>71-52367-00</b> 11251-PH3-000 	<b>81-53323-00 K</b> → 91214-PH1-004 80x100x10 A SL RD MVQ <b>81-53219-00 N</b> 2x 91203-PG6-003 27x43x9 A SL LD NBR
2,0 B20A5 B20A7 B20A9	101-110 kW (137-150 PS)	PRELUDE	04/87-01/92	<b>01-52375-01</b> ⑫ ⑬ 061A1-PK2-660 +061B1-PK2-000 <b>02-52375-01</b> ⑫ 061A1-PK2-660	<b>61-52375-00</b> 12251-PK1-662 82 Ø 		<b>15-52368-01</b> 12341-PK2-000 +12342-PG6-000 (4x) 		<b>71-52672-00</b> 17105-PK3-A00 		<b>71-52366-00</b> 18115-PK2-000 <b>71-52303-00</b> ⑬ 2x 18212-SB2-961 	<b>71-52369-00</b> 11251-PK1-010 	<b>81-53323-00 K</b> → 91214-PH1-004 80x100x10 A SL RD MVQ <b>81-53224-00 N</b> 91213-PE1-721 29x45x8 A SL LD NBR
2,0 B20B B20B3 B20Z1	94-108 kW (128-147 PS)	CR-V	10/95→	<b>02-37765-01</b> ⑫ 06110-P3F-902	<b>61-37765-00</b> 12251-P8R-004 MLS 		<b>15-40047-01</b> 12030-PR4-000 	<b>12-53593-01</b> 12210-PT2-004 (8x) +12211-PT2-004 (8x) <b>70-53593-00 ES</b> 8x 12210-PT2-004 <b>70-53593-10 AS</b> 8x 12211-PT2-004	<b>71-40048-00</b> 17105-PHK-004 		<b>71-52668-00</b> 18115-PR3-003 	<b>71-52669-00</b> 11251-PR3-000 	<b>81-40249-00 K</b> ← 91212-PR3-003 38x50x7,4 A SL LD FPM <b>81-53323-00 K</b> → 91214-PH1-004 80x100x10 A SL RD MVQ <b>81-53219-00 N</b> 2x 91203-PG6-003 27x43x9 A SL LD NBR
2,0 F20A2 F20A4 F20A6 F20A7 F20A8 F20Z3	66-98 kW (90-133 PS)	ACCORD PRELUDE	01/90-10/00	<b>01-52695-01</b> ⑫ ⑬ 061A1-PT3-000 +061B1-PT3-000 <b>02-52695-01</b> ⑫ 061A1-PT3-000	<b>61-52695-00</b> 12251-PT0-J02 86 Ø MLS 		<b>15-53766-01</b> 12030-PT0-000 	<b>12-53547-01</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) <b>70-53547-00</b> 8x 12210-PZ1-004 <b>70-53547-10</b> 8x 12211-PZ1-004	<b>71-52661-00</b> 17105-PT2-004 		<b>71-53799-00</b> 18115-PT0-004 	<b>71-52663-00</b> 11251-PT0-000 	<b>81-53273-00 K</b> ← 91212-PAA-A02 40x52x7,1 A SL LD MVQ <b>81-53323-00 K</b> → 91214-PH1-004 80x100x10 A SL RD MVQ <b>81-53222-00 N</b> 91213-PT0-003 28x42x8 A SL LD MVQ
2,0 F20B3	100 kW (136 PS)	ACCORD	09/93-02/98	<b>02-53720-01</b> ⑫ 06110-POD-030 <b>08-53759-01</b> ⑬ 06111-PT1-010	<b>61-53720-00</b> 12251-P0A-004 86 Ø 0,7 mm MLS 	<b>14-32295-01</b> 90005-PT0-003 (9x) +90006-PT0-003 (1x)	<b>15-53766-01</b> 12030-PT0-000 	<b>12-53547-01</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) <b>70-53547-00</b> 8x 12210-PZ1-004 <b>70-53547-10</b> 8x 12211-PZ1-004	<b>71-53762-00</b> 17105-P0A-004 		<b>71-53763-00</b> 18115-P0A-003 	<b>71-52663-00</b> 11251-PT0-000 	<b>81-40328-00 K</b> ← 91233-PT0-003 27x40x8 A SL LD <b>81-53273-00 K</b> ← 91212-PAA-A02 40x52x7,1 A SL LD MVQ <b>81-53323-00 K</b> → 91214-PH1-004 80x100x10 A SL RD MVQ <b>81-53222-00 N</b> 91213-PT0-003 28x42x8 A SL LD MVQ

HONDA													
Ltr.													
2,0 F20B5	108 kW (147 PS)	ACCORD	02/98-06/03	<b>02-53720-03</b> <sup>12</sup> 06110-PAD-G00 <b>08-53764-01</b> <sup>13</sup> 06111-PAA-A01 	<b>61-53720-00</b> 12251-POA-004 86 Ø 0,7 mm MLS 	<b>14-32337-01</b> 90005-PAA-A01 (9x) +90006-PAA-A01 (1x) 	<b>15-53777-01</b> 12030-POA-000 	<b>12-53547-01</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) <b>70-53547-00</b> 12210-PZ1-004 <b>70-53547-10</b> 12211-PZ1-004 8x 	<b>71-53792-00</b> 17105-PAA-A01 		<b>71-53763-00</b> 18115-POA-003 	<b>70-31414-10</b> 	<b>81-40328-00</b> K ← 91233-PT0-003 27x40x8 A SL LD <b>81-53273-00</b> K ← 91212-PAA-A02 40x52x7,1 A SL LD MVQ <b>81-53323-00</b> K → 91214-PH1-004 80x100x10 A SL RD MVQ <b>81-53222-00</b> N 91213-PT0-003 28x42x8 A SL LD MVQ
2,0 F20B7	108 kW (147 PS)	ACCORD	02/98-06/03	<b>02-53720-03</b> <sup>12</sup> 06110-PAD-G00 <b>08-53764-01</b> <sup>13</sup> 06111-PAA-A01 	<b>61-53720-00</b> 12251-POA-004 86 Ø 0,7 mm MLS 	<b>14-32337-01</b> 90005-PAA-A01 (9x) +90006-PAA-A01 (1x) 	<b>15-53777-01</b> 12030-POA-000 	<b>12-53547-01</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) <b>70-53547-00</b> 12210-PZ1-004 <b>70-53547-10</b> 12211-PZ1-004 8x 	<b>71-53776-00</b> 17105-PAA-L01 		<b>71-53763-00</b> 18115-POA-003 	<b>70-31414-10</b> 	<b>81-40328-00</b> K ← 91233-PT0-003 27x40x8 A SL LD <b>81-53273-00</b> K ← 91212-PAA-A02 40x52x7,1 A SL LD MVQ <b>81-53323-00</b> K → 91214-PH1-004 80x100x10 A SL RD MVQ <b>81-53222-00</b> N 91213-PT0-003 28x42x8 A SL LD MVQ
2,0 F20C VTEC	177 kW (240 PS)	S2000	06/99→	<b>02-53685-01</b> <sup>12</sup> 06110-PCX-020 <b>08-53717-01</b> <sup>13</sup> 06111-PCX-020 	<b>61-53685-00</b> 12251-PCX-004 88 Ø 0,65 mm MLS 		<b>15-53722-01</b> 12040-PCX-305 	<b>12-53547-01</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) <b>70-53547-00</b> 12210-PZ1-004 <b>70-53547-10</b> 12211-PZ1-004 8x 	<b>71-53719-00</b> 17105-PCX-004 		<b>71-53721-00</b> 18115-PCX-004 	<b>70-31414-10</b> 	<b>81-53718-00</b> K ← 91212-PCX-003 43x58x8 A SL RD FPM <b>81-53717-00</b> K → 91214-PCX-003 80x98x10 A SL LD MVQ
2,0 F20C1	170 kW (231 PS)	S 2000 VTEC	03/99-10/03	<b>02-53685-01</b> <sup>12</sup> 06110-PCX-020 <b>08-53717-01</b> <sup>13</sup> 06111-PCX-020 	<b>61-53685-00</b> 12251-PCX-004 88 Ø 0,65 mm MLS 	<b>14-32337-02</b> 90005-PCX-003 (10x) 	<b>15-53722-01</b> 12040-PCX-305 	<b>12-53547-01</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) <b>70-53547-00</b> 12210-PZ1-004 <b>70-53547-10</b> 12211-PZ1-004 8x 	<b>71-53719-00</b> 17105-PCX-004 		<b>71-53721-00</b> 18115-PCX-004 	<b>70-31414-10</b> 	<b>81-53718-00</b> K ← 91212-PCX-003 43x58x8 A SL RD FPM <b>81-53717-00</b> K → 91214-PCX-003 80x98x10 A SL LD MVQ
2,0 F20Z1	96 kW (131 PS)	ACCORD	03/93-10/98	<b>02-52695-02</b> <sup>12</sup> 06110-PT5-020 <b>08-53759-01</b> <sup>13</sup> 06111-PT1-010 	<b>61-52695-00</b> 12251-PT0-J02 86 Ø MLS 		<b>15-53766-01</b> 12030-PT0-000 	<b>12-53547-01</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) <b>70-53547-00</b> 12210-PZ1-004 <b>70-53547-10</b> 12211-PZ1-004 8x 	<b>71-52661-00</b> 17105-PT2-004 		<b>71-53799-00</b> 18115-PT0-004 	<b>71-52663-00</b> 11251-PT0-000 	<b>81-40328-00</b> K ← 91233-PT0-003 27x40x8 A SL LD <b>81-53273-00</b> K ← 91212-PAA-A02 40x52x7,1 A SL LD MVQ <b>81-53323-00</b> K → 91214-PH1-004 80x100x10 A SL RD MVQ <b>81-53222-00</b> N 91213-PT0-003 28x42x8 A SL LD MVQ

HONDA													
2,0 F20Z2	85 kW (116 PS)	ACCORD	03/93-01/96	<b>02-52695-02</b> ⑫ 06110-PT5-020 <b>08-53759-01</b> ⑬ 06111-PT1-010	<b>61-52695-00</b> 12251-PT0-J02 86 Ø MLS 	<b>14-32295-01</b> 90005-PT0-003 (9x) +90006-PT0-003 (1x)	<b>15-53766-01</b> 12030-PT0-000 	<b>12-53547-01</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) <b>70-53547-00</b> 12210-PZ1-004 <b>70-53547-10</b> 12211-PZ1-004 8x 	<b>71-53797-00</b> 17105-PT2-014 	<b>71-53799-00</b> 18115-PT0-004 	<b>71-52663-00</b> 11251-PT0-000 	<b>81-40328-00</b> K ← 91233-PT0-003 27x40x8 A SL LD <b>81-53273-00</b> K ← 91212-PAA-A02 40x52x7,1 A SL LD MVQ <b>81-53323-00</b> K → 91214-PH1-004 80x100x10 A SL RD MVQ <b>81-53222-00</b> N 91213-PT0-003 28x42x8 A SL LD MVQ	
2,0 K20A1	115 kW (156 PS)	STREAM	05/01→	<b>02-53765-01</b> ⑫ 06110-PNA-020 <b>08-53807-01</b> ⑬ 06114-RBA-020 	<b>61-53765-00</b> 12251-PNA-004 86,5 Ø 0,6 mm MLS 	<b>14-32377-01</b> 90005-PNA-003 (10x) 	<b>15-53806-01</b> 12030-PNC-000 	<b>12-53547-01</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) <b>70-53547-00</b> 12210-PZ1-004 <b>70-53547-10</b> 12211-PZ1-004 8x 	<b>71-53808-00</b> 17105-PNA-J01 	<b>71-53811-00</b> 18115-PNA-004 →12/03 	<b>70-31414-10</b> 	<b>81-53807-00</b> K ← 91212-RBD-E01 43x58x7 A SL RD ACM <b>81-53338-00</b> K → 91214-PWA-003 80x98x10 A SL LD NBR	
2,0 K20A6 <b>[NEW]</b>	114 kW (155 PS)	ACCORD	02/03-05/08	<b>02-53745-01</b> ⑫ 06110-RBA-E01 <b>08-53807-01</b> ⑬ 06114-RBA-020 	<b>61-53745-00</b> 12251-RAC-004 87 Ø 0,68 mm MLS 	<b>14-32377-01</b> 90005-PNA-003 (10x) 	<b>15-53806-01</b> 12030-PNC-000 	<b>12-53547-01</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) <b>70-53547-00</b> 12210-PZ1-004 <b>70-53547-10</b> 12211-PZ1-004 8x 	<b>71-53803-00</b> 17115-RAA-A01 	<b>71-53802-00</b> 18115-PRB-A01 	<b>70-31414-10</b> 	<b>81-40028-00</b> K ← 91212-RNA-A01 43x58x7 A SL RD FPM <b>81-53338-00</b> K → 91214-PWA-003 80x98x10 A SL LD NBR	
2,0 R20A1 R20A2 R20A3	110-115 kW (150-156 PS)	ACCORD CR-V STEPWAGON	01/07→	<b>02-37760-01</b> ⑫ 06110-RNA-000 +06114-RNA-010 	<b>61-37760-00</b> 12251-RNA-A02 MLS 	<b>14-32339-01</b> 90005-RNA-A01 (10x) 	<b>71-40021-00</b> 12341-RNA-A01 	<b>12-53547-01</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) <b>70-53547-00</b> ES 12210-PZ1-004 <b>70-53547-10</b> AS 12211-PZ1-004 8x 	<b>11-40022-01</b> 17105-RNA-A01 (4x) +17106-RNA-A01 (1x) 	<b>71-40024-00</b> 18115-RNA-004 	<b>70-31414-10</b> 	<b>81-40028-00</b> K ← 91212-RNA-A01 43x58x7 A SL RD FPM <b>81-53338-00</b> K → 91214-PWA-003 80x98x10 A SL LD NBR	
2,0 20T2N	74-77 kW (101-105 PS)	ACCORD TDi CIVIC D CIVIC TDIC	04/96-12/02	<b>01-35496-01</b> ⑫ ⑬ <b>02-35496-02</b> ⑫ 	<b>61-35360-00</b> 85,5 Ø 1,05 mm 1 ■ <b>61-35360-10</b> 85,5 Ø 1,2 mm 2 ■ <b>61-35360-20</b> 85,5 Ø 1,35 mm 3 ■ 	<b>71-35496-00</b> 	<b>12-35493-01</b>	<b>71-35492-00</b> ⑦ 	<b>71-35495-00</b> 	<b>81-35497-00</b> K ← 35x45x7 A SL RD FPM <b>81-90028-00</b> K → LD <b>81-15999-30</b> N 2x			
2,2 F22A3 F22A7 F22A8	108-110 kW (147-150 PS)	ACCORD ASCOT	01/90-10/96	<b>01-52695-01</b> ⑫ ⑬ 061A1-PT3-000 +061B1-PT3-000 <b>02-52695-01</b> ⑫ 061A1-PT3-000	<b>61-52695-00</b> 12251-PT0-J02 86 Ø MLS 	<b>15-53766-01</b> 12030-PT0-000 	<b>12-53547-01</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) <b>70-53547-00</b> 12210-PZ1-004 <b>70-53547-10</b> 12211-PZ1-004 8x 	<b>71-52661-00</b> 17105-PT2-004 	<b>71-52662-00</b> 18115-PT3-A21 	<b>71-52663-00</b> 11251-PT0-000 	<b>81-53273-00</b> K ← 91212-PAA-A02 40x52x7,1 A SL LD MVQ <b>81-53323-00</b> K → 91214-PH1-004 80x100x10 A SL RD MVQ <b>81-53222-00</b> N 91213-PT0-003 28x42x8 A SL LD MVQ		



HONDA													
Ltr.			<b>1</b>										
2,2 F22B5 F22B8	110 kW (150 PS) ACCORD SHUTTLE	09/93-02/98	<b>02-53720-01</b> <sup>12</sup> 06110-POD-030 <b>08-53759-01</b> <sup>13</sup> 06111-PT1-010	<b>61-53720-00</b> 12251-P0A-004 86 Ø 0,7 mm MLS 	<b>14-32295-01</b> 90005-PT0-003 (9x) +90006-PT0-003 (1x)	<b>15-53766-01</b> 12030-PT0-000 	<b>12-53547-01</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) <b>70-53547-00</b> 12210-PZ1-004 <b>70-53547-10</b> 12211-PZ1-004	<b>71-53762-00</b> 17105-P0A-004 8x 	<b>71-53763-00</b> 18115-P0A-003 	<b>71-52663-00</b> 11251-PT0-000 	<b>81-53222-00 N</b> 91213-PT0-003 28x42x8 A SL LD MVQ		
2,2 N22A1	103 kW (140 PS) ACCORD CTDi	01/04-05/08	<b>02-53814-01</b> <sup>12</sup> →12/05  <b>08-53816-01</b> <sup>13</sup> 06111-RBD-E01 	<b>61-53750-00</b> 12251-RBD-E01 86 Ø 1,3 mm 1 MLS <b>61-53750-10</b> 12252-RBD-E01 86 Ø 1,35 mm 2 MLS <b>61-53750-20</b> 12253-RBD-E01 86 Ø 1,4 mm 0 MLS <b>61-53750-30</b> 12254-RBD-E01 86 Ø 1,45 mm 3 MLS <b>61-53750-40</b> 12255-RBD-E01 86 Ø 1,5 mm 4 MLS 	<b>15-53814-01</b> 12030-RBD-E01 →12/05 	<b>12-53547-01</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) <b>70-53547-00</b> 12210-PZ1-004 <b>70-53547-10</b> 12211-PZ1-004	<b>71-53812-00</b> 17105-RBD-E01 8x 	<b>71-53813-00</b> 18115-RBD-E01 	<b>70-31414-10</b> 	<b>81-53807-00 K</b> ← 91212-RBD-E01 43x58x7 A SL RD ACM <b>81-53816-00 K</b> → 91214-RBD-E01 87x104x10 SL LD MVQ			
2,2 N22A2	103 kW (140 PS) CIVIC CR-V CTDi	02/05→	<b>08-53816-01</b> <sup>13</sup> 06111-RBD-E01 	<b>61-53750-00</b> 12251-RBD-E01 86 Ø 1,3 mm 1 MLS <b>61-53750-10</b> 12252-RBD-E01 86 Ø 1,35 mm 2 MLS <b>61-53750-20</b> 12253-RBD-E01 86 Ø 1,4 mm 0 MLS <b>61-53750-30</b> 12254-RBD-E01 86 Ø 1,45 mm 3 MLS <b>61-53750-40</b> 12255-RBD-E01 86 Ø 1,5 mm 4 MLS 		<b>12-53547-01</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) <b>70-53547-00</b> 12210-PZ1-004 <b>70-53547-10</b> 12211-PZ1-004	<b>71-53812-00</b> 17105-RBD-E01 8x 	<b>71-53813-00</b> 18115-RBD-E01 	<b>70-31414-10</b> 	<b>81-53807-00 K</b> ← 91212-RBD-E01 43x58x7 A SL RD ACM <b>81-53816-00 K</b> → 91214-RBD-E01 87x104x10 SL LD MVQ			

HONDA												
Ltr.												
2,2 N22B1 N22B2 <b>[NEW]</b>	110-132 kW (150-180 PS) ACCORD DTEC	07/08→		<p><b>02-10039-01</b> <sup>12</sup></p> <p></p>	<p><b>61-10774-00</b> 12251-RL0-G01 86 Ø 1,25 mm MLS</p> <p><b>61-10774-10</b> 12252-RL0-G01 86 Ø 1,3 mm MLS</p> <p><b>61-10774-20</b> 12253-RL0-G01 86 Ø 1,35 mm MLS</p> <p><b>61-10774-30</b> 12254-RL0-G01 86 Ø 1,4 mm MLS</p> <p><b>61-10774-40</b> 12255-RL0-G01 86 Ø 1,45 mm MLS</p>	<p><b>14-11294-01</b> 90005-RBD-E01 (10X)</p>	<p><b>15-10039-01</b> 12030-RL0-G00</p>	<p><b>12-53547-01</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)</p> <p><b>70-53547-00</b> 12210-PZ1-004</p> <p><b>70-53547-10</b> 12211-PZ1-004</p>	<p><b>71-11265-00</b> 17105-RL0-G01</p>	<p><b>71-11266-00</b> 18115-RL0-G01</p>	<p><b>70-31414-10</b></p>	<p><b>81-53807-00 K</b> ← 91212-RBD-E01 43x58x7 A SL RD ACM</p> <p><b>81-53816-00 K</b> → 91214-RBD-E01 87x104x10 SL LD MVQ</p>
2,2 N22B3 <b>[NEW]</b>	110 kW (150 PS) CR-V	01/07→		<p><b>02-10039-01</b> <sup>12</sup> 01/10→</p> <p></p>	<p><b>61-10774-00</b> 12251-RL0-G01 86 Ø 1,25 mm MLS 01/10→</p> <p><b>61-10774-10</b> 12252-RL0-G01 86 Ø 1,3 mm MLS 01/10→</p> <p><b>61-10774-20</b> 12253-RL0-G01 86 Ø 1,35 mm MLS 01/10→</p> <p><b>61-10774-30</b> 12254-RL0-G01 86 Ø 1,4 mm MLS 01/10→</p> <p><b>61-10774-40</b> 12255-RL0-G01 86 Ø 1,45 mm MLS 01/10→</p>	<p><b>14-11294-01</b> 90005-RBD-E01 (10X) 01/10→</p>	<p><b>15-10039-01</b> 12030-RL0-G00 01/10→</p>	<p><b>12-53547-01</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) 01/10→</p> <p><b>70-53547-00</b> 12210-PZ1-004 01/10→</p> <p><b>70-53547-10</b> 12211-PZ1-004 01/10→</p>	<p><b>71-11265-00</b> 17105-RL0-G01 01/10→</p>	<p><b>71-11266-00</b> 18115-RL0-G01 01/10→</p>	<p><b>70-31414-10</b> 01/10→</p>	<p><b>81-53807-00 K</b> ← 91212-RBD-E01 43x58x7 A SL RD ACM 01/10→</p> <p><b>81-53816-00 K</b> → 91214-RBD-E01 87x104x10 SL LD MVQ 01/10→</p>

HONDA												
2,3 F23A1	113 kW (154 PS)	ACCORD	01/01-06/03	<b>02-53730-03</b> <sup>12</sup> 06110-PAB-A00 <b>08-53764-01</b> <sup>13</sup> 06111-PAA-A01 	<b>61-53730-00</b> 12251-PAA-A02 87 Ø 0,72 mm MLS 	<b>14-32337-01</b> 90005-PAA-A01 (9x) +90006-PAA-A01 (1x) 	<b>15-53777-01</b> 12030-POA-000 	<b>12-53547-01</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) <b>70-53547-00</b> 12210-PZ1-004 <b>70-53547-10</b> 12211-PZ1-004 8x 	<b>71-53776-00</b> 17105-PAA-L01 <b>71-53792-00</b> 17105-PAA-A01 8x 	<b>71-53763-00</b> 18115-POA-003 	<b>70-31414-10</b> 	<b>81-40328-00</b> K ← 91233-PT0-003 27x40x8 A SL LD <b>81-53273-00</b> K ← 91212-PAA-A02 40x52x7,1 A SL LD MVQ <b>81-53323-00</b> K → 91214-PH1-004 80x100x10 A SL RD MVQ <b>81-53222-00</b> N 91213-PT0-003 28x42x8 A SL LD MVQ
2,3 F23A3 F23A6 F23A7 F23A8	110-118 kW (150-160 PS)	ACCORD ODYSSEY SHUTTLE	10/97→	<b>02-53730-03</b> <sup>12</sup> 06110-PAB-A00 <b>08-53764-01</b> <sup>13</sup> 06111-PAA-A01 	<b>61-53730-00</b> 12251-PAA-A02 87 Ø 0,72 mm MLS 	<b>14-32337-01</b> 90005-PAA-A01 (9x) +90006-PAA-A01 (1x) 	<b>15-53777-01</b> 12030-POA-000 	<b>12-53547-01</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) <b>70-53547-00</b> 12210-PZ1-004 <b>70-53547-10</b> 12211-PZ1-004 8x 	<b>71-53792-00</b> 17105-PAA-A01 8x 	<b>71-53763-00</b> 18115-POA-003 	<b>70-31414-10</b> 	<b>81-40328-00</b> K ← 91233-PT0-003 27x40x8 A SL LD <b>81-53273-00</b> K ← 91212-PAA-A02 40x52x7,1 A SL LD MVQ <b>81-53323-00</b> K → 91214-PH1-004 80x100x10 A SL RD MVQ <b>81-53222-00</b> N 91213-PT0-003 28x42x8 A SL LD MVQ
2,3 F23A5	100-101 kW (136-137 PS)			<b>08-53764-01</b> <sup>13</sup> 06111-PAA-A01 	<b>61-53720-00</b> 12251-POA-004 86 Ø 0,7 mm MLS 	<b>14-32337-01</b> 90005-PAA-A01 (9x) +90006-PAA-A01 (1x) 	<b>15-53777-01</b> 12030-POA-000 	<b>12-53547-01</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) <b>70-53547-00</b> 12210-PZ1-004 <b>70-53547-10</b> 12211-PZ1-004 8x 	<b>71-53792-00</b> 17105-PAA-A01 8x 	<b>71-53763-00</b> 18115-POA-003 	<b>70-31414-10</b> 	<b>81-40328-00</b> K ← 91233-PT0-003 27x40x8 A SL LD <b>81-53273-00</b> K ← 91212-PAA-A02 40x52x7,1 A SL LD MVQ <b>81-53323-00</b> K → 91214-PH1-004 80x100x10 A SL RD MVQ <b>81-53222-00</b> N 91213-PT0-003 28x42x8 A SL LD MVQ
2,3 F23Z5	113 kW (154 PS)	ACCORD	11/00-06/03	<b>02-53730-03</b> <sup>12</sup> 06110-PAB-A00 <b>08-53764-01</b> <sup>13</sup> 06111-PAA-A01 	<b>61-53730-00</b> 12251-PAA-A02 87 Ø 0,72 mm MLS 	<b>14-32337-01</b> 90005-PAA-A01 (9x) +90006-PAA-A01 (1x) 	<b>15-53777-01</b> 12030-POA-000 	<b>12-53547-01</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) <b>70-53547-00</b> 12210-PZ1-004 <b>70-53547-10</b> 12211-PZ1-004 8x 	<b>71-53841-00</b> 17105-POA-A02 8x 	<b>71-53763-00</b> 18115-POA-003 	<b>70-31414-10</b> 	<b>81-40328-00</b> K ← 91233-PT0-003 27x40x8 A SL LD <b>81-53273-00</b> K ← 91212-PAA-A02 40x52x7,1 A SL LD MVQ <b>81-53323-00</b> K → 91214-PH1-004 80x100x10 A SL RD MVQ <b>81-53222-00</b> N 91213-PT0-003 28x42x8 A SL LD MVQ

HONDA													
2,3 H23A2 H23A3	116-118 kW (158-160 PS)	ACCORD PRELUDE	02/92-09/96	<b>02-53740-01</b> <sup>12</sup> 06110-P14-010 <b>08-53608-01</b> <sup>13</sup> 06111-P14-030	<b>61-53740-00</b> 12251-P14-A02 88 Ø 0,68 mm MLS 		<b>15-53801-01</b> 12030-PT2-000 	<b>12-53593-01</b> 12210-PT2-004 (8x) +12211-PT2-004 (8x) <b>70-53593-00</b> 12210-PT2-004 <b>70-53593-10</b> 12211-PT2-004 8x 	<b>71-53797-00</b> 17105-PT2-014 <b>71-53798-00</b> <sup>10</sup> 17121-PT2-003 8x 		<b>71-53799-00</b> 18115-PT0-004 	<b>71-52663-00</b> 11251-PT0-000 	<b>81-53222-00 N</b> 2x 91213-PT0-003 28x42x8 A SL LD MVQ
2,4 K24A	127-140 kW (173-190 PS)	ACCORD ODYSSEY	02/03→	<b>02-53745-01</b> <sup>12</sup> 06110-RBA-E01 <b>08-53807-01</b> <sup>13</sup> 06114-RBA-020 	<b>61-53745-00</b> 12251-RAC-004 87 Ø 0,68 mm MLS 		<b>15-53806-01</b> 12030-PNC-000 	<b>12-53547-01</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) <b>70-53547-00</b> 12210-PZ1-004 <b>70-53547-10</b> 12211-PZ1-004 8x 	<b>71-53803-00</b> 17115-RAA-A01 		<b>71-53802-00</b> 18115-PRB-A01 	<b>70-31414-10</b> 	<b>81-53807-00 K</b> ← 91212-RBD-E01 43x58x7 A SL RD ACM <b>81-53338-00 K</b> → 91214-PWA-003 80x98x10 A SL LD NBR
2,5 C25A1 C25A2	110-127 kW (150-173 PS)	LEGEND V6	01/86-06/88	<b>01-52380-01</b> <sup>12</sup> <sup>13</sup> 061A1-PH7-660 +061B1-PH7-660 <b>02-52380-01</b> <sup>12</sup> 061A1-PH7-660	<b>61-52380-00</b> 2x 12251-PH7-004 85 Ø 		<b>71-52374-00</b> 2x 12341-PH7-000 	<b>12-52819-03</b> 12210-PD2-004 (12x) +12211-PH7-004 (12x)	<b>71-52371-00</b> 2x 18115-PH7-003 		<b>71-52372-00</b> 2x 17105-PH7-003 	<b>71-52373-00</b> 2x 11251-PH7-000 	<b>81-53246-00 N</b> 2x 91213-PH1-003 35x50x8 A SL RD NBR
2,7 C27A1	124 kW (169 PS)	LEGEND V6	10/87-12/90	<b>01-52385-01</b> <sup>12</sup> <sup>13</sup> 061A1-PL2-000 +061B1-PH7-000 <b>02-52385-01</b> <sup>12</sup> 061A1-PL2-000	<b>61-52385-00</b> 2x 12251-PL2-003 88 Ø 		<b>71-52374-00</b> 2x 12341-PH7-000 	<b>12-52819-03</b> 12210-PD2-004 (12x) +12211-PH7-004 (12x)	<b>71-52371-00</b> 2x 18115-PH7-003 		<b>71-52372-00</b> 2x 17105-PH7-003 	<b>71-52373-00</b> 2x 11251-PH7-000 	<b>81-53246-00 N</b> 91213-PH1-003 35x50x8 A SL RD NBR
3,0 J30A1	147 kW (200 PS)	ACCORD VTEC ACCORD V6 24v	03/97-12/03	<b>02-53725-01</b> <sup>12</sup> R 06120-P8A-A13 <b>02-53725-02</b> <sup>12</sup> L 06110-P8A-A21 <b>08-53717-02</b> <sup>13</sup> 06111-P8A-A01 	<b>61-53725-00</b> 2x 12251-P8A-A01 87 Ø 0,7 mm MLS 		<b>15-53773-01</b> 2x 12030-P8A-A00 	<b>12-53547-03</b> 12210-PZ1-A01 (12x) +12211-PZ1-004 (12x)	<b>71-53769-00 R</b> 17065-P8A-A01 		<b>71-53767-00</b> 2x 18115-P8A-A01 	<b>70-31414-10</b> 	<b>81-53772-00 N</b> 2x 91213-P8A-A01 39x53x8