

PEUGEOT													
Ltr.													
1,1 TU1JP (HFX) 44 kW (60 PS)	PARTNER	06/96→	02-35060-01 <sup>12</sup> 08-31859-02 <sup>13</sup>	61-35060-00 0209.Y0 73,5 Ø 1,25 mm 	14-32075-01 0204.83 (10x) 	71-31146-00 0249.54 	12-26058-02 0956.19 (8x) 70-26058-00 0956.19	71-35247-00 0342.E0 8x 	71-33774-00 <sup>51</sup> X 0349.J6 71-35068-00 0349.K1 71-36469-00 <sup>51</sup> 1709.25 	71-33674-00 <sup>51</sup> 	81-31863-00 K ← 0514.38 42x66x6 A SL RD FPM 81-23708-50 K → 0514.74 85x105x8 A SL LD FPM 81-34403-00 N 0236.44 36x50x7 A SL RD FPM		
1,1 TU1M (HDZ) 44 kW (60 PS)	PARTNER	06/96→	02-31146-01 <sup>12</sup> 0197.A7  02-31200-01 <sup>12</sup> <sup>51</sup> 0197.H8 +0209.CJ 08-33674-01 <sup>13</sup> <sup>51</sup>	61-33715-00 <sup>51</sup> 0209.CJ 76 Ø 1,3 mm 61-33715-10 <sup>51</sup> 0209.W7 76 Ø 1,5 mm 	14-32075-01 0204.83 (10x) 	71-31146-00 0249.54 	12-26058-02 0956.19 (8x) 70-26058-00 0956.19	71-38817-00 8x 	71-31147-00 0349.A6 2x 71-31862-00 <sup>51</sup> 1709.10 	71-33674-00 <sup>51</sup> 	81-31863-00 K ← 0514.38 42x66x6 A SL RD FPM 81-23708-50 K → 0514.74 85x105x8 A SL LD FPM 81-26244-10 N 0236.21 36x50x8 A RD ACM		
1,4 TU3JP (KFW) 54-55 kW (73-75 PS)	PARTNER	06/96→	02-31146-01 <sup>12</sup> 0197.A7  02-31200-01 <sup>12</sup> <sup>51</sup> 0197.H8 +0209.CJ 08-33674-01 <sup>13</sup> <sup>51</sup>	61-33715-00 <sup>51</sup> 0209.CJ 76 Ø 1,3 mm 61-33715-10 <sup>51</sup> 0209.W7 76 Ø 1,5 mm 	14-32075-01 0204.83 (10x) 	71-31146-00 0249.54 	12-26058-02 0956.19 (8x) 70-26058-00 0956.19	71-35247-00 0342.E0 8x 	71-31147-00 0349.A6 2x 71-33774-00 <sup>51</sup> X 0349.J6 71-35068-00 <sup>51</sup> X 0349.K1 	71-33674-00 <sup>51</sup> 	81-31863-00 K ← 0514.38 42x66x6 A SL RD FPM 81-23708-50 K → 0514.74 85x105x8 A SL LD FPM 81-26244-10 N 0236.21 36x50x8 A RD ACM		
1,6 TU5JP4 (NFU) 80 kW (109 PS)	PARTNER PARTNER 16V	09/00→	02-35055-01 <sup>12</sup> 08-35253-01 <sup>13</sup>	61-35055-10 98 045 482 80 79,8 Ø 0,6 mm MLS 	14-32139-01 0204.81 (10x) 	71-35251-00 0249.A9 2x Mot.→2336722 71-42166-00 <sup>51</sup> X 2x Mot.2336723→ 	12-33512-02 0956.40 (16x) 70-33512-00 0956.40	11-35246-01 0348.Q5 16x 	71-35067-00 0349.L3 71-36469-00 <sup>51</sup> 1709.25 	71-35253-00 0304.55 	81-31863-00 K ← 0514.38 42x66x6 A SL RD FPM 81-23708-50 K → 0514.74 85x105x8 A SL LD FPM 81-34146-00 N 0807.24 38x50x6 A SL RD FPM		
1,6 1580 SPI (222A2) 58 kW (79 PS)	EXPERT	02/96→	01-31755-03 <sup>12</sup> <sup>13</sup> 02-31755-06 <sup>12</sup> 0197.V3	61-31755-00 0209.P9 87,3 Ø 		71-31729-00 0 71-31732-00 U 	12-25837-01 0956.22 (8x) 70-25837-00 0956.22	8x 	71-35716-00 <sup>7</sup> 2x 	71-31742-00 0304.49 	81-35883-00 N 30x52x7 AB SL RD FPM		

PEUGEOT												
Ltr.												
1,8 XUD7 (A9A) 43-44 kW (58-60 PS)	PARTNER D	06/96→	<p><b>02-25942-03</b> 0197.37</p> <p><del></del></p> <p><b>02-25942-04</b> <sup>12</sup> 0197.37 +0956.22 (8x)</p> <p><del></del></p> <p><b>08-25918-02</b> <sup>13</sup></p>	<p><b>61-29145-10</b> 0209.F9 82 Ø 1,6 mm 2 </p> <p><b>61-29145-20</b> 0209.G0 82 Ø 1,7 mm 3 </p> <p><b>61-31060-00</b> 0209.S0 82 Ø 1,4 mm 1 </p> <p><b>61-31060-10</b> 0209.S1 82 Ø 1,45 mm 2 </p> <p><b>61-31060-20</b> 0209.S2 82 Ø 1,5 mm 3 </p> <p><b>61-31060-30</b> 0209.S3 82 Ø 1,55 mm 4 </p> <p><b>61-31060-40</b> 0209.S4 82 Ø 1,6 mm 5 </p>	<p><b>14-32077-01</b> 0204.65 (10x)</p>	<p><b>71-25942-00</b> 0249.46</p>	<p><b>12-25837-01</b> 0956.22 (8x)</p> <p><b>70-25837-00</b> 0956.22</p>	<p><b>71-33156-00</b> 0348.98</p> <p>8x </p> <p><b>71-33157-00</b> 0348.99</p> <p>2x </p>	<p><b>71-25919-30</b> 0349.47</p> <p>2x </p>	<p><b>71-25918-30</b> 0304.34</p>	<p><b>81-25926-10 K</b> ← 0326.12 42x62x8 A RD FPM</p> <p><b>81-34456-00 K</b> → 0127.28 90x110x7 A SL LD FPM</p> <p><b>81-21798-30 N</b> 0236.14 35x50x8 A SL WD ACM</p>	
1,8 XU7JB (LFX) 66 kW (90 PS)	PARTNER	05/97→	<p><b>02-25415-09</b> <sup>12</sup></p> <p><b>08-25918-05</b> <sup>13</sup></p>	<p><b>61-25415-30</b> 0209.E1 84 Ø 1,3 mm</p> <p><b>61-25415-40</b> 0209.L3 84 Ø 1,5 mm</p>	<p><b>71-33664-00</b> 0249.71</p>	<p><b>12-25837-01</b> 0956.22 (8x)</p> <p><b>70-25837-00</b> 0956.22</p>	<p><b>71-34418-00</b> 0348.L7</p> <p>8x </p>	<p><b>71-35364-00</b> 1723.63</p>	<p><b>71-25918-30</b> 0304.34</p>	<p><b>81-25926-10 K</b> ← 0326.12 42x62x8 A RD FPM</p> <p><b>81-34456-00 K</b> → 0127.28 90x110x7 A SL LD FPM</p> <p><b>81-26244-10 N</b> 0236.21 36x50x8 A RD ACM</p>		

PEUGEOT												
Ltr.												
1,9 DW8 (WJZ) DW8B (WJY)	51 kW (69 PS) EXPERT D PARTNER D	06/96→	1	<p><b>01-34356-01</b> <sup>12</sup> <sup>13</sup> 0197.X6 +0127.28 +0326.22 +0807.14</p> <p></p> <p><b>02-34356-01</b> <sup>12</sup> 0197.X5 +0807.14</p> <p></p>	<p><b>61-33720-00</b> 0209.X0 84 Ø 1,26 mm 3 </p> <p>MLS</p> <p><b>61-33720-10</b> 0209.X1 84 Ø 1,3 mm 4 </p> <p>MLS</p> <p><b>61-33720-20</b> 0209.X2 84 Ø 1,34 mm 5 </p> <p>MLS</p> <p><b>61-33720-30</b> 0209.X3 84 Ø 1,38 mm 6 </p> <p>MLS</p> <p><b>61-33720-40</b> 0209.X4 84 Ø 1,42 mm 7 </p> <p>MLS</p> <p><b>61-33720-50</b> 0209.1C 84 Ø 1,47 mm 4 </p> <p>MLS</p> <p></p>	<p><b>14-32077-01</b> 0204.65 (10x) Mot.→08469</p> <p></p> <p><b>14-32116-01</b> 0204.97 (10x) Mot.08470→</p> <p></p>	<p><b>15-34356-01</b> 0249.95 +0249.97</p> <p><b>71-34353-00 U</b> 0249.97</p> <p></p> <p><b>71-34356-00 O</b> 0249.95</p> <p></p>	<p><b>12-25837-01</b> 0956.22 (8x)</p> <p><b>70-25837-00</b> 0956.22</p>	<p><b>71-34997-00</b> 0348.N1</p> <p>8x </p> <p><b>71-34998-00</b> 0348.N2</p> <p></p> <p>2x</p>	<p><b>71-29465-00</b> 0349.H7</p> <p></p> <p>2x</p>	<p><b>71-25918-30</b> 0304.34</p> <p></p>	<p><b>81-25926-10 K</b> ← 0326.12 42x62x8 A RD FPM</p> <p><b>81-34456-00 K</b> → 0127.28 90x110x7 A SL LD FPM</p> <p><b>81-25451-10 N</b> 0807.14 35x50x7 A SL RD FPM</p>
1,9 XDP88	40 kW (55 PS) J7 Bus D J7 D	08/68-07/78		<p><b>02-50919-10</b> <sup>12</sup> 0197.08 Mot.4586484→</p> <p></p> <p><b>08-25857-01</b> <sup>13</sup> <sup>16</sup> Mot.4586484→</p>	<p><b>61-23635-10</b> 0203.70 94 Ø 1,5 mm</p> <p>Mot.4586484→</p> <p><b>61-23635-20</b> 79 32 566 274 94 Ø 1,8 mm</p> <p>Mot.4586484→</p> <p></p>	<p><b>71-50919-10</b> 0249.25 Mot.4586484→</p> <p></p>	<p><b>12-77023-01</b> 0956.01 (8x)</p> <p>Mot.4586484→</p> <p><b>40-77023-00</b> 0956.01</p> <p>Mot.4586484→</p> <p>8x</p>	<p><b>71-50920-10</b> 0349.08 Mot.4586484→</p> <p></p> <p><b>71-24581-10</b> <sup>16</sup> 1710.19 Mot.4586484→</p> <p></p>	<p>2x <b>71-25857-10</b> 0313.19 Mot.4586484→</p> <p></p>	<p><b>81-27333-00 K</b> ← 0514.11 42x60x8 A RD ACM</p> <p>Mot.4586484→</p> <p><b>71-25853-10 K</b> → 2x 0119.03 Mot.4586484→</p>		

PEUGEOT												
Ltr.												
1.9 XUD9A (DJY) 50-51 kW XUD9A (D9B) (68-70 PS) XUD9AU (D8C)	BOXER Bus D BOXER D EXPERT D J5 Bus D J5 D PARTNER D	10/90→	 02-25942-05 <sup>12</sup>  08-25918-02 <sup>13</sup>	 61-29165-10 0209.K0 84 Ø 1,6 mm 2 61-29165-20 0209.K1 84 Ø 1,7 mm 3 61-31065-00 0209.S5 84 Ø 1,4 mm 1 61-31065-10 0209.S6 84 Ø 1,45 mm 2 61-31065-20 0209.S7 84 Ø 1,5 mm 3 61-31065-30 0209.S8 84 Ø 1,55 mm 4 61-31065-40 0209.S9 84 Ø 1,6 mm 5	14-32077-01 0204.65 (10x) 	71-25942-00 0249.46 	12-25837-01 0956.22 (8x) 70-25837-00 0956.22 8x		71-33682-00 <sup>7</sup> 0348.89 	50-92244-00 1721.01 	71-25918-30 0304.34 	81-25926-10 K ← 0326.12 42x62x8 A RD FPM 81-34456-00 K → 0127.28 90x110x7 A SL LD FPM 81-21798-30 N 0236.14 35x50x8 A SL WD ACM
1.9 XUD9TE 66-68 kW XUD9TE (90-92 PS) (DHX) XUD9TE (DHY) XUD9TE (D8B) XUD9UTF (D8C)	BOXER BOXER Bus TD BOXER TD EXPERT TD	03/94→	 02-25942-06 <sup>12</sup>  08-25918-02 <sup>13</sup>	 61-33155-00 0209.Q8 84 Ø 1,36 mm 1 MLS 61-33155-10 0209.Q9 84 Ø 1,4 mm 2 MLS 61-33155-20 0209.R0 84 Ø 1,44 mm 3 MLS 61-33155-30 0209.R1 84 Ø 1,48 mm 4 MLS 61-33155-40 0209.R2 84 Ø 1,53 mm 5 MLS 61-33155-50 0209.T7 84 Ø 1,59 mm MLS 61-33155-60 84 Ø 1,7 mm MLS 	14-32177-01 0204.73 (10x) 	71-25942-00 0249.46 	12-25837-01 0956.22 (8x) 70-25837-00 0956.22 8x		71-33683-00 <sup>7</sup> 0348.J0 	50-92244-00 1721.01 	71-25918-30 0304.34 	81-25926-10 K ← 0326.12 42x62x8 A RD FPM 81-34456-00 K → 0127.28 90x110x7 A SL LD FPM 81-21798-30 N 0236.14 35x50x8 A SL WD ACM

PEUGEOT												
Ltr.												
2,0 DW10ATED (RHZ) DW10BTED (RHX) DW10TD (RHY)	66-80 kW (90-109 PS) EXPERT HDI PARTNER HDI	02/00→	<b>01-34398-01</b> <sup>12</sup> <sup>13</sup> 0197.X4 +0249.99   <b>02-34398-01</b> <sup>12</sup> 0197.X3 +0249.99 	<b>61-35815-00</b> 0209.X5 86 Ø 1,3 mm 1 MLS <b>61-35815-10</b> 0209.X6 86 Ø 1,35 mm 2 MLS <b>61-35815-20</b> 0209.X7 86 Ø 1,4 mm 3 MLS <b>61-35815-30</b> 0209.X8 86 Ø 1,45 mm 4 MLS <b>61-35815-40</b> 0209.X9 86 Ø 1,5 mm 5 MLS 	<b>14-35774-01</b> 0204.A6 (10x) 	<b>71-34398-00</b> 0249.99 	<b>12-31306-07</b> 0956.38 (8x) Mot.→08331 <b>12-34399-01</b> 0956.48 (8x) Mot.08332→ <b>70-31306-00</b> 0956.38 Mot.→08331 <b>70-34399-00</b> 0956.48 Mot.08332→	8x 8x	<b>71-34401-00</b> 0348.N4 	<b>71-34402-00</b> 0349.H4 	<b>70-31414-10</b> 	<b>81-25926-10 K</b> ← 0326.12 42x62x8 A RD FPM <b>81-34456-00 K</b> → 0127.28 90x110x7 A SL LD FPM <b>81-34144-00 N</b> 0807.28 27x47x7 A SL RD FPM
2,0 DW10ATED4 (RHW)	80 kW (109 PS) EXPERT EXPERT HDI	07/00→	<b>01-34404-01</b> <sup>12</sup> <sup>13</sup> 0197.Y6   <b>02-34404-01</b> <sup>12</sup> 0197.Y7 +0249.A6 	<b>61-34370-00</b> 0209.AV 86 Ø 1,25 mm 2 MLS <b>61-34370-10</b> 0209.AW 86 Ø 1,3 mm 3 MLS <b>61-34370-20</b> 0209.AX 86 Ø 1,35 mm 4 MLS <b>61-34370-30</b> 0209.AY 86 Ø 1,4 mm 5 MLS 	<b>14-32233-01</b> 0204.96 (10x) 	<b>71-34404-00</b> 0249.A6 	<b>12-34399-02</b> 0956.48 (16x) <b>70-34399-00</b> 0956.48	16x	<b>71-33223-00</b> 0349.J2 	<b>70-31414-10</b> 	<b>81-25926-10 K</b> ← 0326.12 42x62x8 A RD FPM <b>81-34456-00 K</b> → 0127.28 90x110x7 A SL LD FPM <b>81-34144-00 N</b> 0807.28 27x47x7 A SL RD FPM	

PEUGEOT													
Ltr.													
2,0 DW10UTD (RHV)	62 kW (84 PS) BOXER Bus HDI BOXER HDI	04/02→	1	<p><b>01-34398-01</b> ⑫ ⑬ 0197.X4 +0249.99</p> <p></p> <p><b>02-34398-01</b> ⑫ 0197.X3 +0249.99</p> <p></p>	<p><b>61-35815-00</b> 0209.X5 86 Ø 1,3 mm 1 □ MLS</p> <p><b>61-35815-10</b> 0209.X6 86 Ø 1,35 mm 2 □ MLS</p> <p><b>61-35815-20</b> 0209.X7 86 Ø 1,4 mm 3 □ MLS</p> <p><b>61-35815-30</b> 0209.X8 86 Ø 1,45 mm 4 □ MLS</p> <p><b>61-35815-40</b> 0209.X9 86 Ø 1,5 mm 5 □ MLS</p> <p></p>	<p><b>14-35774-01</b> 0204.A6 (10x)</p> <p></p>	<p><b>71-34398-00</b> 0249.99</p> <p></p>	<p><b>12-34399-01</b> 0956.48 (8x)</p> <p><b>70-34399-00</b> 0956.48</p>	<p><b>71-34401-00</b> 0348.N4</p> <p>8x </p>		<p><b>71-34402-00</b> 0349.H4</p> <p></p>	<p><b>70-31414-10</b></p> <p></p>	<p><b>81-25926-10 K</b> ← 0326.12 42x62x8 A RD FPM</p> <p><b>81-34456-00 K</b> → 0127.28 90x110x7 A SL LD FPM</p> <p><b>81-34144-00 N</b> 0807.28 27x47x7 A SL RD FPM</p>
2,0 DW10UTED4 (RHK)	88 kW (120 PS) EXPERT HDI EXPERT TEPEE HDI	01/07→		<p><b>02-36571-02</b> ⑫ 0197.AN +0348.S3</p> <p></p>	<p><b>61-34370-00</b> 0209.AV 86 Ø 1,25 mm 2 ■ MLS</p> <p><b>61-34370-10</b> 0209.AW 86 Ø 1,3 mm 3 ■ MLS</p> <p><b>61-34370-20</b> 0209.AX 86 Ø 1,35 mm 4 ■ MLS</p> <p><b>61-34370-30</b> 0209.AY 86 Ø 1,4 mm 5 ■ MLS</p> <p></p>	<p><b>14-35774-01</b> 0204.A6 (10x)</p> <p></p>	<p><b>15-36571-01</b> 0348.S3</p> <p></p>	<p><b>12-34399-02</b> 0956.48 (16x)</p> <p><b>70-34399-00</b> 0956.48</p> <p>16x</p>		<p><b>71-36124-00</b> 0349.L9</p> <p></p>	<p><b>70-31414-10</b></p> <p></p>	<p><b>81-36557-00 K</b> ← 0127.47 42x62x7 A SL RD PTFE</p> <p><b>81-36556-00 K</b> → 0127.45 90x110x7 A SL LD PTFE</p> <p><b>81-34144-00 N</b> 0807.28 27x47x7 A SL RD FPM</p>	
2,0 EW10 (RFH)	103 kW (140 PS) EXPERT	01/07→		<p><b>01-37360-01</b> ⑫ ⑬ ⑰ <b>02-37360-01</b> ⑫ ⑰ <b>08-41188-01</b> ⑬</p> <p></p>	<p><b>61-37360-00</b> 0209.FS MLS</p> <p></p>	<p><b>14-32342-01</b> 0204.A3 (10X)</p> <p></p>		<p><b>12-34439-01</b> 0956.45 (16x)</p> <p><b>70-34439-00</b> 0956.45</p> <p>16x</p>	<p><b>71-38549-00</b> 0348.S2</p> <p>4x </p>		<p><b>71-34992-00</b> 0349.L4</p> <p></p>	<p><b>70-31414-10</b></p> <p></p>	<p><b>81-34454-10 K</b> ← 16 08 940 680 40x55x6 A SL RD PTFE</p> <p><b>81-34456-00 K</b> → 0127.28 90x110x7 A SL LD FPM</p> <p><b>81-34403-00 N</b> 0236.44 36x50x7 A SL RD FPM</p> <p><b>81-38657-00 N</b> 0236.74 39x50x7 A SL RD</p>

PEUGEOT														
2.0 EW10J4 (RFN) 100 kW (136 PS)	EXPERT	07/00→	<p><b>01-35045-01</b> <sup>12</sup> <sup>13</sup> <sup>19</sup> 0197.Y1 +0209.Z3 +0249.A4 +0249.A5</p> <p><b>02-35045-01</b> <sup>12</sup> <sup>19</sup></p> <p><b>08-37006-01</b> <sup>13</sup></p>	<p><b>61-35045-00</b> 0209.Z3 85 Ø MLS</p>	<p><b>14-32234-01</b> 0204.A7 (10x)</p>	<p><b>71-34452-00 R</b> 0249.A5</p> <p><b>71-34453-00 L</b> 0249.A4</p>	<p><b>12-34439-01</b> 0956.45 (16x)</p> <p><b>70-34439-00</b> 0956.45</p> <p>16x</p>	<p><b>71-35903-00</b> 0348.P1</p> <p>4x</p>	<p><b>71-33853-00</b> 0349.H8</p>	<p><b>70-31414-10</b></p>	<p><b>81-34454-10 K</b> ← 16 08 940 680 40x55x6 A SL RD PTFE</p> <p><b>81-34456-00 K</b> → 0127.28 90x110x7 A SL LD FPM</p> <p><b>81-34403-00 N</b> 2x 0236.44 36x50x7 A SL RD FPM</p>			
2.0 XN1P 57-58 kW (78-79 PS)	J5 J9 J9 Bus	03/80-08/90	<p><b>02-19231-01</b> <sup>12</sup></p> <p><b>02-22770-10</b> <sup>12</sup></p>	<p><b>61-22770-40</b> 0209.46 90 Ø 1,2 mm</p>	<p><b>14-32086-01</b> 0204.21 (10x) →06/85</p> <p><b>14-32087-01</b> 0204.51 (10x) 07/85→</p>	<p><b>71-19231-00</b> 0249.14</p>	<p><b>12-23062-01</b> 0956.30 (8x)</p> <p><b>70-23062-00</b> 0956.05</p> <p>8x</p>	<p><b>71-24661-10</b> 0348.33</p> <p><b>71-23049-10</b> <sup>10</sup> 0348.21</p>	<p><b>71-17538-10</b> 0349.03</p>	<p><b>71-12921-20</b> 0304.44</p>	<p><b>81-27333-00 K</b> ← 0514.11 42x60x8 A RD ACM</p>			
2.0 XN1T 55 kW (75 PS)	J5	09/87-08/90	<p><b>02-19231-01</b> <sup>12</sup></p> <p><b>02-22770-10</b> <sup>12</sup></p>	<p><b>61-22770-40</b> 0209.46 90 Ø 1,2 mm</p>	<p><b>14-32087-01</b> 0204.21 (10x) →04/89</p> <p><b>14-32079-01</b> 0204.57 (10x) 05/89→</p>	<p><b>71-19231-00</b> 0249.14</p>	<p><b>12-23062-01</b> 0956.30 (8x)</p> <p><b>70-23062-00</b> 0956.05</p> <p>8x</p>	<p><b>71-24661-10</b> 0348.33</p> <p><b>71-23049-10</b> <sup>10</sup> 0348.21</p>	<p><b>71-17538-10</b> 0349.03</p>	<p><b>71-12921-20</b> 0304.44</p>	<p><b>81-27333-00 K</b> ← 0514.11 42x60x8 A RD ACM</p>			
2.0 XN1T (170) 55-58 kW (75-79 PS)	J5 Bus XN1T (170B)	09/81-09/90	<p><b>02-19231-01</b> <sup>12</sup></p> <p><b>02-22770-10</b> <sup>12</sup></p>	<p><b>61-22770-40</b> 0209.46 90 Ø 1,2 mm</p>	<p><b>14-32086-01</b> 0204.21 (10x) →06/85</p> <p><b>14-32087-01</b> 0204.51 (10x) 07/85-04/89</p> <p><b>14-32079-01</b> 0204.57 (10x) 05/89→</p>	<p><b>71-19231-00</b> 0249.14</p>	<p><b>12-23062-01</b> 0956.30 (8x)</p> <p><b>70-23062-00</b> 0956.05</p> <p>8x</p>	<p><b>71-24661-10</b> 0348.33</p> <p><b>71-23049-10</b> <sup>10</sup> 0348.21</p>	<p><b>71-17538-10</b> 0349.03</p>	<p><b>71-12921-20</b> 0304.44</p>	<p><b>81-27333-00 K</b> ← 0514.11 42x60x8 A RD ACM</p>			
2.0 XU10J2 (RFW) 80-81 kW (109-110 PS)	BOXER BOXER Bus	03/94→	<p><b>02-33650-02</b> <sup>12</sup> 0197.T4 +0209.J8</p> <p><b>08-25918-04</b> <sup>13</sup></p>	<p><b>61-33650-00</b> 0209.J8 87 Ø 1,35 mm</p>	<p><b>14-32077-01</b> 0204.65 (10x)</p>	<p><b>71-26237-00</b> 0249.48</p>	<p><b>12-25837-01</b> 0956.22 (8x)</p> <p><b>70-25837-00</b> 0956.22</p> <p>8x</p>	<p><b>71-33663-00</b> 0348.F6</p> <p><b>71-33738-00</b> <sup>10</sup> 0348.E6</p> <p>2x</p>	<p><b>71-26236-10</b> 0349.70</p> <p>4x</p>	<p><b>70-31414-10</b></p>	<p><b>81-25926-10 K</b> ← 0326.12 42x62x8 A RD FPM</p> <p><b>81-34456-00 K</b> → 0127.28 90x110x7 A SL LD FPM</p> <p><b>81-26244-10 N</b> 0236.21 36x50x8 A RD ACM</p>			

PEUGEOT												
Ltr.												
2,1 XDPX90	41 kW (56 PS)	J9 D	03/80-06/87	<b>02-50919-10</b> <sup>12</sup> 0197.08  <b>08-25857-01</b> <sup>13 16</sup> Mot.4572282→	<b>61-23635-10</b> 0203.70 94 Ø 1,5 mm Mot.4572282→ <b>61-23635-20</b> 79 32 566 274 94 Ø 1,8 mm Mot.4572282→ 		<b>71-50919-10</b> 0249.25 →06/86 	<b>12-77023-01</b> 0956.01 (8x) <b>40-77023-00</b> 0956.01 8x		<b>71-50920-10</b> 0349.08 2x  <b>71-24581-10</b> <sup>14</sup> 1710.19 	<b>71-25857-10</b> 0313.19 	<b>81-51051-20 K</b> ← 0514.35 45x60x7 A SL RD FPM <b>71-25853-10 K</b> → 2x 0119.03
2,1 XDP90	42 kW (57 PS)	J7 Bus D J7 D	08/68-07/77	<b>02-50919-10</b> <sup>12</sup> 0197.08  <b>08-25857-01</b> <sup>13 16</sup>	<b>61-23635-10</b> 0203.70 94 Ø 1,5 mm Mot.1932463→ <b>61-23635-20</b> 79 32 566 274 94 Ø 1,8 mm Mot.1932463→ 		<b>71-50919-10</b> 0249.25 	<b>12-77023-01</b> 0956.01 (8x) <b>40-77023-00</b> 0956.01 8x		<b>71-50920-10</b> 0349.08 2x  <b>71-24581-10</b> <sup>14</sup> 1710.19 	<b>71-25857-10</b> 0313.19 	<b>81-51051-20 K</b> ← 0514.35 45x60x7 A SL RD FPM <b>71-25853-10 K</b> → 2x 0119.03
2,2 DW12UTED (4HY)	74 kW (101 PS)	BOXER Bus HDI BOXER HDI	04/02→	<b>01-34398-01</b> <sup>12 13</sup> 0197.X4 +0249.99   <b>02-34398-01</b> <sup>12</sup> 0197.X3 +0249.99 	<b>61-33875-00</b> 0209.AQ 86 Ø 1,25 mm 1 MLS <b>61-33875-10</b> 0209.AR 86 Ø 1,3 mm 2 MLS <b>61-33875-20</b> 0209.AS 86 Ø 1,35 mm 3 MLS <b>61-33875-30</b> 0209.AT 86 Ø 1,4 mm 4 MLS 	<b>14-32233-01</b> 0204.96 (10x) 	<b>71-34398-00</b> 0249.99 	<b>12-34399-01</b> 0956.48 (8x) <b>70-34399-00</b> 0956.48 8x	<b>71-34401-00</b> 0348.N4 	<b>71-34402-00</b> 0349.H4 	<b>70-31414-10</b> 	<b>81-25926-10 K</b> ← 0326.12 42x62x8 A RD FPM <b>81-34456-00 K</b> → 0127.28 90x110x7 A SL LD FPM <b>81-34144-00 N</b> 0807.28 27x47x7 A SL RD FPM
2,3 XD2PX94 XD2P94	49 kW (67 PS)	J7 Bus D J7 D J9 Bus D J9 D	07/77-07/82	<b>01-50919-08</b> <sup>12 13</sup> 0198.94  <b>02-50919-10</b> <sup>12</sup> 0197.08 	<b>61-26630-30</b> 0209.C2 96 Ø 1,5 mm 2 <b>61-26630-40</b> 0209.C4 96 Ø 1,6 mm 3 <b>61-26630-50</b> 0209.C6 96 Ø 1,7 mm 4 	<b>14-32082-01</b> 0204.54 (8x) +0204.55 (7x) +0204.56 (7x) Zyl.kopfhöhe 73 mm  <b>14-32083-01</b> 0204.55 (15x) +0204.56 (7x) Zyl.kopfhöhe 83 mm 	<b>71-50919-10</b> 0249.25 	<b>12-77023-01</b> 0956.01 (8x) <b>40-77023-00</b> 0956.01 8x		<b>71-50920-10</b> 0349.08 2x  <b>40-83824-40</b> <sup>14</sup> 1710.15 	<b>71-25857-10</b> 0313.19 	<b>81-51051-20 K</b> ← 0514.35 45x60x7 A SL RD FPM <b>71-25853-10 K</b> → 2x 0119.03



PEUGEOT													
Ltr.													
2,5 CRD93	54 kW (73 PS) J5 J5 Bus D J5 D	09/81-03/94		<b>02-24960-03</b> <del></del> <b>02-24960-04</b> 0197.K1 +0209.L5	<b>61-24960-10</b> 0209.75 95,5 Ø 1,5 mm 	<b>14-32080-01</b> 0204.41 (8x) +0204.42 (9x) 	<b>71-25612-20</b> 0249.45 	<b>12-23062-01</b> 0956.30 (8x) <b>70-23062-00</b> 0956.05	<b>50-92221-20</b> 0348.H0 8x 	4x	<b>71-25639-10</b> 0349.F0 4x 	<b>81-33859-00 K</b> ← 0514.32 75x90x11,5 A SL RD ACM FPM	
2,5 CRD93L	70 kW (95 PS) J5 DT	09/81-01/94		<b>02-24960-03</b> <del></del> <b>02-24960-04</b> 0197.K1 +0209.L5	<b>61-24960-10</b> 0209.75 95,5 Ø 1,5 mm 	<b>14-32080-01</b> 0204.41 (8x) +0204.42 (9x) 	<b>71-31131-00</b> 	<b>12-23062-01</b> 0956.30 (8x) <b>70-23062-00</b> 0956.05	<b>50-92221-20</b> 0348.H0 8x 	4x	<b>71-25639-10</b> 0349.F0 4x 	<b>81-33859-00 K</b> ← 0514.32 75x90x11,5 A SL RD ACM FPM	
2,5 CRD93LS	70 kW (95 PS) J5 Bus TD J5 DT J5 TD	09/81-03/94		<b>02-24960-02</b> <sup>12</sup> <del></del> <b>02-27015-01</b> <sup>12</sup> 0197.R9 +0209.L6	<b>61-27015-10</b> 0209.L6 95,5 Ø 1,7 mm 	<b>14-32080-01</b> 0204.41 (8x) +0204.42 (9x) 	<b>71-25612-20</b> 0249.45 	<b>12-23062-03</b> <b>70-20423-00</b> <b>70-23062-00</b> 0956.05	<b>50-92221-20</b> 0348.H0 4x 	4x	<b>71-25639-10</b> 0349.F0 4x 	<b>81-33859-00 K</b> ← 0514.32 75x90x11,5 A SL RD ACM FPM	
2,5 DJ5 (T9A) DJ5T (T8A)	63-76 kW (86-103 PS) BOXER Bus D BOXER Bus TD BOXER D BOXER TD	03/94-04/02		<b>01-29160-01</b> <sup>12</sup> <sup>13</sup> 0197.T7 +0209.R3 <b>02-29160-01</b> <sup>12</sup> 0197.T6 +0209.R3	<b>61-29160-00</b> 0209.R3 93 Ø 1,6 mm 	<b>14-32164-01</b> 0204.74 (14x) +0204.75 (8x) 	<b>71-33723-00</b> 0249.79 	<b>12-26058-01</b> 0956.19 (12x) <b>70-26058-00</b> 0956.19	<b>71-33687-00</b> 0348.K1 12x 	<b>71-33786-00</b> <sup>10</sup> 0348.F9 	<b>71-33688-00</b> 0349.E7 	<b>70-31414-10</b> 	<b>81-34457-00 K</b> ← 0326.25 64x88x6 A SL RD ACM FPM <b>81-34458-00 K</b> → 0119.14 98x120x7 A SL LD ACM FPM <b>81-25451-10 N</b> ← 0807.14 35x50x7 A SL RD FPM <b>81-34142-00 N</b> → <sup>27</sup> 0807.21 47,5x62x7 A SL LD ACM FPM <b>81-34143-00 N</b> → <sup>28</sup> 0807.15 40x62x7 A SL LD ACM FPM
2,5 DJ5TED (THX)	79 kW (107 PS) BOXER Bus TDI BOXER TDI	01/97-04/02		<b>01-34110-01</b> <sup>12</sup> <sup>13</sup> <sup>19</sup> 0197.W4 +0209.T5 <del></del> <b>02-34110-01</b> <sup>12</sup> 0197.W3 +0209.T5 <del></del>	<b>61-34110-00</b> 0209.T5 93 Ø 1,35 mm MLS 	<b>14-32156-01</b> 0204.87 (14x) +0204.88 (8x) 	<b>71-33723-00</b> 0249.79 	<b>12-26058-02</b> 0956.19 (8x) <b>70-26058-00</b> 0956.19	<b>71-37096-00</b> 0348.K4 8x 	2x	<b>71-37097-00</b> 0349.G4 	<b>70-31414-10</b> 	<b>81-34457-00 K</b> ← 0326.25 64x88x6 A SL RD ACM FPM <b>81-34458-00 K</b> → 0119.14 98x120x7 A SL LD ACM FPM <b>81-25451-10 N V</b> 0807.14 35x50x7 A SL RD FPM <b>81-17110-20 N H</b> 0807.26 32x52x7 A SL LD ACM FPM

PEUGEOT													
Ltr.													
2,5 XD3P	53 kW (72 PS)	J9 Bus D J9 D	07/82-06/87	<p><b>02-50919-09</b> <sup>12</sup> 0197.N9</p>	<p><b>61-26630-30</b> 0209.C2 96 Ø 1,5 mm 2 </p> <p><b>61-26630-40</b> 0209.C4 96 Ø 1,6 mm 3 </p> <p><b>61-26630-50</b> 0209.C6 96 Ø 1,7 mm 4 </p>	<p><b>14-32082-01</b> 0204.54 (8x) +0204.55 (7x) +0204.56 (7x) Zyl.kopfhöhe 73 mm</p> <p><b>14-32083-01</b> 0204.55 (15x) +0204.56 (7x) Zyl.kopfhöhe 83 mm</p>	<p><b>71-50919-10</b> 0249.25</p>	<p><b>12-77023-01</b> 0956.01 (8x)</p> <p><b>40-77023-00</b> 0956.01</p> <p>8x</p>		<p><b>71-25852-20</b> 0349.44</p>	<p>2x <b>70-31414-10</b></p>	<p><b>81-51051-20 K</b> ← 0514.35 45x60x7 A SL RD FPM <b>71-25853-10 K</b> → 2x 0119.03</p>	
2,8 8140.43 (F28DT)	90 kW (122 PS)			<p><b>01-33951-07</b> <sup>12 13 35</sup></p> <p><b>02-33951-07</b> <sup>12</sup></p>	<p><b>61-33950-00</b> 0209.0C 1,3 mm</p> <p><b>61-33950-10</b> 0209.0E 1,4 mm</p> <p><b>61-33950-20</b> 0209.0F 1,5 mm</p>	<p><b>14-32096-01</b></p>	<p><b>71-33951-10</b> 0249.A0</p>	<p><b>12-34914-05</b> <b>70-34914-00</b></p> <p>8x</p>	<p><b>71-33621-00</b></p>	<p>4x</p>	<p><b>71-33962-00</b></p>	<p>4x <b>71-34049-10</b></p>	
2,8 8140.43S (F28DTCR)	93-94 kW (126-128 PS)	BOXER Bus HDI BOXER HDI	10/00→	<p><b>01-33951-10</b> <sup>12 14</sup> 0197.Y2</p> <p><b>02-33951-10</b> <sup>12</sup></p>	<p><b>61-33950-00</b> 0209.0C 1,3 mm</p> <p><b>61-33950-10</b> 0209.0E 1,4 mm</p> <p><b>61-33950-20</b> 0209.0F 1,5 mm</p>		<p><b>71-33951-10</b> 0249.A0</p> <p><b>71-33956-00</b> <sup>X</sup> 0249.C3</p>	<p><b>12-34914-05</b> <b>70-34914-00</b></p> <p>8x</p>	<p><b>71-33621-00</b></p>	<p>4x</p>	<p><b>71-33654-00</b> 0349.H5</p>	<p>4x <b>71-33944-10</b> Gummi</p> <p><b>71-83048-00</b> <sup>X</sup> 500327440 NBR</p>	