


SUZUKI													
Ltr.													
0,8 AB51 F8B	25-30 kW (34-41 PS)	ALTO	06/82→	<b>02-52550-01</b> ⑫ 11100-78830	<b>61-52550-00</b> 11141-78402 68,7 Ø 		<b>71-52551-00</b> 11189-78100 	<b>12-52957-01</b> 09289-070005-000 (6x)			<b>71-52552-00</b> 14140-78100 	<b>71-52549-00</b> 11529-79110 	<b>81-53237-00 K</b> ← 09283-32016 32x47x8 A SL RD NBR <b>81-53297-00 K</b> → 09283-32042 60x80x8 A SL LD MVQ <b>81-53237-00 N</b> 09283-32016 32x47x8 A SL RD NBR
0,8 AB51	29 kW (39 PS)	ALTO	01/86-12/88	<b>01-52550-02</b> ⑫ ⑬ 11400-84824 <b>02-52550-02</b> ⑫ 11400-84824 HS	<b>61-52550-00</b> 11141-78402 68,7 Ø 			<b>12-52957-01</b> 09289-070005-000 (6x)			<b>71-52552-00</b> 14140-78100 	<b>71-52549-00</b> 11529-79110 	<b>81-53237-00 K</b> ← 09283-32016 32x47x8 A SL RD NBR <b>81-53297-00 K</b> → 09283-32042 60x80x8 A SL LD MVQ <b>81-53237-00 N</b> 09283-32016 32x47x8 A SL RD NBR
0,8 F8A	27-29 kW (37-39 PS)	ALTO CARRY LJ 80	01/80-10/85	<b>01-52553-01</b> 11400-73822	<b>61-52553-00</b> 11141-73002 64 Ø 		<b>71-52329-00</b> 11189-73001 	<b>12-52957-02</b> 09289-070007 (8x)	<b>71-52326-00</b> 2x 13119-73000 		<b>71-52324-00</b> 14140-73001 	<b>71-52328-00</b> 11529-73001 	<b>81-53237-00 K</b> ← 09283-32016 32x47x8 A SL RD NBR <b>81-53297-00 K</b> → 09283-32042 60x80x8 A SL LD MVQ <b>81-53237-00 N</b> 09283-32016 32x47x8 A SL RD NBR
1,0 F10A	30-33 kW (41-45 PS)	SAMURAI SJ 410 SUPER CARRY	09/81-12/04	<b>01-52330-03</b> ⑫ ⑬ 11400-85820 <b>02-52330-03</b> ⑫ 11100-85820	<b>61-52330-10</b> 11141-75102 67 Ø 		<b>71-52329-00</b> 11189-73001 	<b>12-52957-02</b> 09289-070007 (8x)	<b>71-52326-00</b> 2x 13119-73000 		<b>71-52324-00</b> 14140-73001 	<b>71-52548-00</b> 11529-80000 	<b>81-53237-00 K</b> ← 09283-32016 32x47x8 A SL RD NBR <b>81-53297-00 K</b> → 09283-32042 60x80x8 A SL LD MVQ <b>81-53237-00 N</b> 09283-32016 32x47x8 A SL RD NBR
1,0 G10	37 kW (50 PS)	SWIFT	10/83-03/89	<b>01-52555-02</b> ⑫ ⑬ 11400-82814 <b>02-52555-02</b> ⑫ 11100-82814	<b>61-52555-00</b> 11141-82001 75,2 Ø 		<b>71-52554-00</b> 11189-82000 	<b>12-52957-01</b> 09289-070005-000 (6x)			<b>71-52558-00</b> 14140-82000 	<b>70-31414-10</b> 	
1,0 G10A	37-40 kW (50-54 PS)	SWIFT WAGON R	10/83-12/05	<b>01-53005-01</b> ⑫ ⑬ <b>02-53005-01</b> ⑫	<b>61-53005-00</b> 75 Ø 		<b>71-52952-00</b> 	<b>12-52939-02</b> 09289-05012 (6x)	<b>71-52947-00</b> 		<b>71-52948-00</b> 	<b>70-31414-10</b> 	<b>81-53236-00 K</b> ← 09283-32042 32x47x6 A SL RD MVQ <b>81-53301-00 K</b> → 09283-68002 68x86x8 A SL LD MVQ <b>81-53236-00 N</b> 09283-32042 32x47x6 A SL RD MVQ

SUZUKI														
1,0 K10A	48-51 kW (65-69 PS)	WAGON R+	02/98-07/03	<b>02-53200-01</b> <sup>12</sup> 11401-75812-000	<b>61-53200-00</b> 11141-75F10-000 MLS 		<b>71-53152-00</b> 11189-75F01-000 	<b>12-39357-02</b> 09298-05012 (16x) <b>70-39357-00</b> 09289-05012	16x	<b>71-53148-00</b> 13119-75F00-000 		<b>71-53149-00</b> 14141-75F00-000 	<b>70-31414-10</b> 	
1,0 K10B	48-50 kW (65-68 PS)	ALTO SPLASH	01/08→	<b>02-37655-01</b> <sup>12</sup>	<b>61-37655-00</b> 11141-51K00 MLS 	<b>14-32307-01</b> 11117-69J00 (8x) 	<b>71-39373-00</b> 11189-51K00 	<b>12-39357-01</b> 09289-05012 (12x) <b>70-39357-00</b> 09289-05012	12x	<b>71-39341-00</b> 13119-51K00  <b>71-39362-00</b> <sup>10</sup> 13118-51K00 		<b>71-39342-00</b> 14140-51K00 	<b>70-31414-10</b> 	<b>81-53699-00</b> K ← 09283-41001 41x53x6 A SL RD FPM <b>81-39377-00</b> K → 09283-83002 83x97x7 A SL LD FPM
1,0 Z 10 XEP <b>[NEW]</b>	44 kW (60 PS)	WAGON R+	06/04-08/05	<b>02-37250-01</b> <sup>12</sup> <b>08-33491-02</b> <sup>13</sup>	<b>61-37250-00</b> 0,32 mm MLS <b>61-37250-10</b> × 0,57 mm MLS 	<b>14-32132-01</b> 	<b>71-34818-00</b> 	<b>12-34223-01</b> <b>70-34223-00</b>	12x	<b>71-36203-00</b> 	3x	<b>71-33509-00</b> 	<b>71-33491-00</b> 	<b>81-33489-00</b> K ← 42x55x7 A SL RD ACM FPM <b>81-24908-10</b> K → 80x98x10 A SL LD FPM
1,1 F10D F10DN <b>[NEW]</b>	46 kW (63 PS)	ALTO	09/04-12/08	<b>01-10011-01</b> <sup>12</sup> <sup>13</sup> 99000M24120-665 <b>02-10011-01</b> <sup>12</sup>	<b>61-10011-00</b> 11141M79F10 93 Ø 		<b>71-10107-00</b> 11189-79F30 	<b>12-39357-02</b> 09298-05012 (16x)		<b>71-10108-00</b> 13119M79F10 		<b>71-10109-00</b> 14141M79GA0 	<b>70-31414-10</b> 	<b>81-53236-00</b> K ← 09283-32042 32x47x6 A SL RD MVQ <b>81-53297-00</b> K → 09283-32042 60x80x8 A SL LD MVQ <b>81-10374-00</b> N 09283-35047 35x47x6 A SL RD FPM/ACM
1,2 K12A	51 kW (69 PS)	WAGON R+	02/98-05/00	<b>02-53265-01</b> <sup>12</sup>	<b>61-53265-00</b> 11141-75F30-000 MLS 		<b>71-53152-00</b> 11189-75F01-000 	<b>12-39357-02</b> 09298-05012 (16x) <b>70-39357-00</b> 09289-05012	16x	<b>71-53148-00</b> 13119-75F00-000 		<b>71-53149-00</b> 14141-75F00-000 	<b>70-31414-10</b> 	
1,2 K12B	63-69 kW (86-94 PS)	SPLASH SWIFT SWIFT IV	01/08→	<b>02-37660-01</b> <sup>12</sup>	<b>61-37660-00</b> 11141-73K00 MLS 	<b>14-32307-02</b> 117-69J00 (10x) 	<b>71-39372-00</b> 11189-73K00 	<b>12-39357-02</b> 09298-05012 (16x) <b>70-39357-00</b> 09289-05012	16x	<b>71-39347-00</b> 13119-73K00  <b>71-39363-00</b> <sup>10</sup> 13118-73K00 		<b>71-39348-00</b> 14140-73K01 	<b>70-31414-10</b> 	<b>81-53699-00</b> K ← 09283-41001 41x53x6 A SL RD FPM <b>81-39377-00</b> K → 09283-83002 83x97x7 A SL LD FPM

SUZUKI												
Ltr.												
1,2 Z 12 XEP <b>[NEW]</b>	59 kW (80 PS) WAGON R+	06/04-08/05	02-36225-01 <sup>12</sup> 08-34166-01 <sup>13</sup>	61-36225-00 0,32 mm MLS 61-36225-10 X 0,57 mm MLS	14-32132-02 	15-35888-01 	12-34223-02 70-34223-00 16x	71-36203-00 4x 	71-34157-00 71-36304-00 	71-34166-00 	81-33489-00 K ← 42x55x7 A SL RD ACM FPM 81-24908-10 K → 80x98x10 A SL LD FPM	
1,3 D13A Z13DT Z13DTJ	51-55 kW (69-75 PS) IGNIS SPLASH CDTI SWIFT WAGON R+	09/03→	02-36259-01 <sup>12</sup>  08-36261-01 <sup>13</sup> 	61-36210-00 11141N86J000A0 70,5 Ø 0,72 mm MLS 61-36210-10 11141N86J00-0B0 70,5 Ø 0,82 mm 1 MLS 61-36210-20 11141N86J00-0C0 70,5 Ø 0,92 mm 2 MLS	14-32191-01 11117N86J00 (x10) 	71-36259-00 11189N86J00 Metall 	12-31306-12 12919-84A00 (16x) 70-31306-00 12919-84A00	71-36209-00 13119N86J00 16x 	71-36322-00 14140N86J00 	70-31414-10 	81-36233-00 K ← 16115N86J00 40x52x7 AB SL RD ACM FPM 81-36232-00 K → 12361N86J00 78x100x9 A SL LD PTFE	
1,3 G13A G13B (8V) G13BA	44-59 kW (60-80 PS) BALENO SAMURAI SJ 413 SWIFT	09/84→	01-53585-02 <sup>12</sup> <sup>13</sup> 11402-61834 02-53585-02 <sup>12</sup>	61-53585-00 11141-86502-000 75 Ø 	71-52559-00 11189-82600 	12-52957-02 09289-070007 (8x)	71-52546-00 13119-63B11 	71-52547-00 14141-51G00 	71-52561-00 11510-71C01 	81-53236-00 K ← 09283-32042 32x47x6 A SL RD MVQ 81-53301-00 K → 09283-68002 68x86x8 A SL LD MVQ 81-53236-00 N 09283-32042 32x47x6 A SL RD MVQ		
1,3 G13B	74 kW (101 PS) SWIFT	08/85-05/01	01-53585-04 <sup>12</sup> <sup>13</sup> 11400-61848 02-53585-04 <sup>12</sup> 11100-86822	61-53585-00 11141-86502-000 75 Ø 	71-52566-00 11189-86500 	12-52939-01 09289-05012 (16x)	71-53626-00 13119-64B00 	71-53627-00 14141-64B00 	70-31414-10 	81-53236-00 K ← 09283-32042 32x47x6 A SL RD MVQ 81-53301-00 K → 09283-68002 68x86x8 A SL LD MVQ 81-53236-00 N 2x 09283-32042 32x47x6 A SL RD MVQ		
1,3 G13BB	56-63 kW (76-86 PS) ALTO BALENO CARRY GRAND VITARA JIMNY SWIFT WAGON R+	07/95→	01-53585-03 <sup>12</sup> <sup>13</sup> 11402-61862 02-53585-03 <sup>12</sup>	61-53585-00 11141-86502-000 75 Ø 	15-52956-01 11189-71C00 +11179-71C01 (4x) 	12-52939-01 09289-05012 (16x)	71-53458-00 14141-51G00 	71-52954-10 14140-52G00 	70-31414-10 	81-53236-00 K ← 09283-32042 32x47x6 A SL RD MVQ 81-53301-00 K → 09283-68002 68x86x8 A SL LD MVQ 81-53236-00 N 2x 09283-32042 32x47x6 A SL RD MVQ		

SUZUKI												
Ltr.												
1,3 M13A	61 kW (83 PS) GRAND VITARA	08/06-02/15		<b>61-53640-00</b> 11141-69G01 79 Ø MLS 		<b>71-53698-00</b> 11189-54GE0 	<b>12-52939-01</b> 09289-05012 (16x)	<b>71-53696-00</b> 13119-86G00 		<b>71-53697-00</b> 14140-69G01 	<b>70-31414-10</b> 	<b>81-53699-00 K</b> ← 09283-41001 41x53x6 A SL RD FPM <b>81-53701-00 K</b> → 09283-83001 83x103x8 FPM
1,3 M13A	61-69 kW (83-94 PS) IGNIS JIMNY LIANA SWIFT WAGON R+	09/00→	<b>02-53640-03</b> 11400-86875	<b>61-53640-00</b> 11141-69G01 79 Ø MLS 		<b>71-53698-00</b> 11189-54GE0 	<b>12-52939-01</b> 09289-05012 (16x)	<b>71-53696-00</b> 13119-86G00 		<b>71-53697-00</b> 14140-69G01 	<b>70-31414-10</b> 	<b>81-53699-00 K</b> ← 09283-41001 41x53x6 A SL RD FPM <b>81-53701-00 K</b> → 09283-83001 83x103x8 FPM
1,3 M13A VVT	69 kW (94 PS) IGNIS	09/03→	<b>02-53640-02</b> ⑫ 11400-69853	<b>61-53640-00</b> 11141-69G01 79 Ø MLS 		<b>71-53702-00</b> 11189-69G00 	<b>12-52939-01</b> 09289-05012 (16x)	<b>71-53703-00</b> 13119-54G00 		<b>71-53697-00</b> 14140-69G01 	<b>70-31414-10</b> 	<b>81-53699-00 K</b> ← 09283-41001 41x53x6 A SL RD FPM <b>81-53701-00 K</b> → 09283-83001 83x103x8 FPM
1,4 C 14 SE <b>[NEW]</b>	60-63 kW (82-86 PS)		<b>02-28135-02</b> ⑫ <b>08-12996-05</b> ⑬ <b>08-31226-01</b> ⑬ ⑳	<b>61-28135-00</b> 79,3 Ø 1,95 mm 	<b>14-32102-01</b> 	<b>71-29303-00</b> 	<b>12-26546-01</b> <b>70-26546-00</b> 8x	<b>71-29302-00</b> 		<b>71-24602-30</b> 	<b>71-12996-10</b> Kork  <b>71-31226-00</b> ㉑ Gummi 	<b>81-27295-00 K</b> ← 26x42x8 AB SL RD FPM <b>81-24908-10 K</b> → 80x98x10 A SL LD FPM <b>81-24909-10 N</b> 35x48x7 A SL RD MVQ
1,4 8HY	66 kW (90 PS) LIANA	04/04→	<b>02-35542-03</b> ⑫  <b>08-36869-01</b> ⑬	<b>61-35430-00</b> 75 Ø 1,25 mm 2 MLS <b>61-35430-10</b> 75 Ø 1,3 mm 3 MLS <b>61-35430-20</b> 75 Ø 1,35 mm 1 MLS <b>61-35430-30</b> 75 Ø 1,4 mm 4 MLS <b>61-35430-40</b> 75 Ø 1,45 mm 5 MLS 	<b>14-32206-01</b> 	<b>15-35542-01</b>  <b>71-35542-00</b> 	<b>12-35548-01</b> 2x <b>40-76246-00</b> 4x 		<b>71-35487-00</b> 	<b>70-31414-10</b> 	<b>81-35554-00 K</b> ← 40x55x6,4 A SL RD PTFE ACM <b>81-35553-00 K</b> → 85x105x8,8 A SL LD PTFE ACM <b>81-35552-00 N</b> ← 27x47x7 A SL RD PTFE ACM	

SUZUKI												
Ltr.												
1,5 K9K 266 K9K 700	48-63 kW (65-86 PS) JIMNY	12/03→	<b>02-36975-01</b> <sup>12</sup> 11162-84A00	<b>61-36975-00</b> 11141-84A00 77,5 Ø 0,7 mm MLS <b>61-36975-10</b> 77,5 Ø 0,9 mm MLS 	<b>14-32230-01</b> 11117-84A00 	<b>71-36442-00</b> 11179-84A00 	<b>12-31306-07</b> 12919-84A00 (8x) <b>70-31306-00</b> 12919-84A00	8x	<b>71-37214-00</b> 14140-84A00 	<b>70-31414-10</b> 	<b>81-36957-00 K</b> ← 16114-84A00 35x47x7 A SL RD NBR PTFE <b>81-35051-00 K</b> → 16121-84A00 80x100x9 A LD PTFE ACM <b>81-34408-00 N</b> 12746-84A00 28x42x5 A SL RD FPM	
1,5 M15A	73-82 kW (99-112 PS) IGNIS LIANA SWIFT SX4	09/03→	<b>02-53640-03</b> 11400-86875	<b>61-53640-00</b> 11141-69G01 79 Ø MLS 		<b>71-53698-00</b> 11189-54GE0 	<b>12-52939-01</b> 09289-05012 (16x)	<b>71-53696-00</b> 13119-86G00 	<b>71-53697-00</b> 14140-69G01 	<b>70-31414-10</b> 	<b>81-53699-00 K</b> ← 09283-41001 41x53x6 A SL RD FPM <b>81-53701-00 K</b> → 09283-83001 83x103x8 FPM	
1,6 G16A (8V) G16K-C	59-60 kW (80-82 PS) VITARA	07/88-03/98	<b>01-52645-01</b> <sup>12</sup> <sup>13</sup> 11400-60821 <b>02-52645-01</b> <sup>12</sup> 11100-60811	<b>61-52645-00</b> 11141-60A00 76 Ø 		<b>71-52559-00</b> 11189-82600 	<b>12-52957-02</b> 09289-070007 (8x)	<b>71-52638-00</b> 13119-60A00 	<b>71-52639-00</b> 14140-60A20 	<b>70-31414-10</b> 	<b>81-53236-00 K</b> ← 09283-32042 32x47x6 A SL RD MVQ <b>81-53301-00 K</b> → 09283-68002 68x86x8 A SL LD MVQ <b>81-53237-00 N</b> 09283-32016 32x47x8 A SL RD NBR	
1,6 G16B	68-73 kW (92-99 PS) ALTO BALENO GRAND VITARA GRAND VITARA SWIFT VITARA X-90	03/89-07/03	<b>01-53010-01</b> <sup>12</sup> <sup>13</sup> 11400-71812 <b>02-53010-01</b> <sup>12</sup> 11100-58810	<b>61-53010-00</b> 11141-71C00 76 Ø 		<b>71-52956-00</b> 	<b>12-52939-01</b> 09289-05012 (16x)	<b>71-52953-00</b> 	<b>71-52954-10</b> 14140-52G00 <b>71-52949-00</b> <sup>A</sup> 	<b>70-31414-10</b> 	<b>81-53236-00 K</b> ← 09283-32042 32x47x6 A SL RD MVQ <b>81-53301-00 K</b> → 09283-68002 68x86x8 A SL LD MVQ <b>81-53236-00 N</b> 09283-32042 32x47x6 A SL RD MVQ	
1,6 M16A	73-92 kW (99-125 PS) GRAND VITARA JIMNY LIANA SWIFT SX4	03/02→	<b>02-53640-02</b> <sup>12</sup> 11400-69853	<b>61-53640-00</b> 11141-69G01 79 Ø MLS 		<b>71-53702-00</b> 11189-69G00 	<b>12-52939-01</b> 09289-05012 (16x)	<b>71-53703-00</b> 13119-54G00 	<b>71-53697-00</b> 14140-69G01 	<b>70-31414-10</b> 	<b>81-53699-00 K</b> ← 09283-41001 41x53x6 A SL RD FPM <b>81-53701-00 K</b> → 09283-83001 83x103x8 FPM	



SUZUKI												
Ltr.												
1,6 9HX	66 kW (90 PS) SX4	04/07→	1	<p><b>02-36567-01</b> <sup>12</sup></p> <p><b>08-36869-01</b> <sup>13</sup></p>	<p><b>61-36265-00</b> 76 Ø 1,25 mm 4 </p> <p><b>61-36265-10</b> 76 Ø 1,3 mm 5 </p> <p><b>61-36265-20</b> 76 Ø 1,35 mm 3 </p> <p><b>61-36265-30</b> 76 Ø 1,4 mm 6 </p> <p><b>61-36265-40</b> 76 Ø 1,45 mm 7 </p>	<p><b>14-32206-01</b></p>	<p><b>71-36567-00</b></p>	<p><b>12-36587-01</b> <b>70-36587-00</b> 16x</p>	<p><b>40-76240-00</b> 4x</p> <p><b>40-76919-00</b> 4x</p>	<p><b>71-35487-00</b></p>	<p><b>70-31414-10</b></p>	<p><b>81-35554-00</b> K ← 40x55x6,4 A SL RD PTFE ACM</p> <p><b>81-35553-00</b> K → 85x105x8,8 A SL LD PTFE ACM</p> <p><b>81-35552-00</b> N 27x47x7 A SL RD PTFE ACM</p>
1,8 G18 J18A	89 kW (121 PS) BALENO GRAND VITARA	03/96-05/02		<p><b>02-53205-02</b> <sup>12</sup> 11401-77862-000</p>	<p><b>61-53205-00</b> 11141-21111-000 MLS</p>		<p><b>71-53156-00</b> 11189-77E00-000</p>	<p><b>12-52829-01</b> 09289-06003-000 (16x)</p>	<p><b>71-53153-00</b> 13119-77EA0-000</p>	<p><b>71-53179-00</b> 14140-65D01-000</p>	<p><b>70-31414-10</b></p>	<p><b>81-53236-00</b> N 09283-32042 32x47x6 A SL RD MVQ</p>
1,9 F9QB	95 kW (129 PS) GRAND VITARA	10/05-02/15		<p><b>02-34409-02</b> <sup>12</sup> 11162-67JG0</p> <p><b>08-34414-05</b> <sup>13</sup> 11299-67JG0</p>	<p><b>61-36645-00</b> 11141-67JG2 81 Ø 1,25 mm MLS</p> <p><b>61-36645-10</b> 81 Ø 1,6 mm MLS</p>	<p><b>14-32146-01</b> 11146-67JG0 (10x)</p>	<p><b>71-34409-00</b> 11179-67JG0</p>	<p><b>12-26058-02</b> 12919-67JG0 (8x) <b>70-26058-00</b> 12919-67JG0</p>	<p><b>71-38629-00</b> <sup>7</sup> 13119-67JG1</p>	<p><b>71-34414-00</b> 11515-67JG1</p>	<p><b>81-34413-00</b> K ← 11345-67JG0 42x54x6 A SL RD ACM FPM</p> <p><b>81-34417-00</b> K → 11344-67JG0 85x105x11 A SL LD FPM</p> <p><b>81-26389-30</b> N 11127-67JG0 25x42x7 A SL RD FPM</p>	
1,9 XUD9 XUD9A	46-50 kW (63-68 PS) SAMURAI TD VITARA D	01/95-12/04		<p><b>02-25942-03</b></p> <p><b>02-25942-04</b> <sup>12</sup></p> <p><b>08-25918-02</b> <sup>13</sup></p>	<p><b>61-31065-00</b> 84 Ø 1,4 mm 1 </p> <p><b>61-31065-10</b> 84 Ø 1,45 mm 2 </p> <p><b>61-31065-20</b> 84 Ø 1,5 mm 3 </p> <p><b>61-31065-30</b> 84 Ø 1,55 mm 4 </p> <p><b>61-31065-40</b> 84 Ø 1,6 mm 5 </p>	<p><b>14-32077-01</b></p>	<p><b>71-25942-00</b></p>	<p><b>12-25837-01</b></p>	<p><b>71-33156-00</b></p> <p><b>71-33157-00</b> 2x</p>	<p><b>71-25919-30</b> 2x</p>	<p><b>71-25918-30</b></p>	<p><b>81-25926-10</b> K ← 16114-66G00 42x62x8 A RD FPM</p> <p><b>81-34456-00</b> K → 16121-66G10 90x110x7 A SL LD FPM</p> <p><b>81-21798-30</b> N 35x50x8 A SL WD ACM</p>

SUZUKI													
Ltr.													
1,9 XUD9SD	55 kW (75 PS)	VITARA D	08/96-03/99	02-25942-06 <sup>12</sup>  08-25918-02 <sup>13</sup>	61-33155-00 84 Ø 1,36 mm 1 MLS 61-33155-10 84 Ø 1,4 mm 2 MLS 61-33155-20 84 Ø 1,44 mm 3 MLS 61-33155-30 84 Ø 1,48 mm 4 MLS 61-33155-40 84 Ø 1,53 mm 5 MLS 61-33155-50 84 Ø 1,59 mm MLS 61-33155-60 84 Ø 1,7 mm MLS 	14-32177-01 	71-25942-00 	12-25837-01 70-25837-00 8x		71-33683-00 <sup>7</sup> 	50-92244-00	71-25918-30 	81-25926-10 K ← 16114-66G00 42x62x8 A RD FPM 81-34456-00 K → 16121-66G10 90x110x7 A SL LD FPM 81-21798-30 N 35x50x8 A SL WD ACM
2,0 H 20 A	100 kW (136 PS)	VITARA V6	12/94-03/98	01-53025-01 <sup>12</sup> <sup>13</sup> 02-53025-01 <sup>12</sup>	61-53025-00 L 79 Ø  61-53030-00 R 79 Ø 	71-52976-00 R 11176-85FA0  71-52977-00 L 11186-85FA0 	12-52829-03 09289-06003 (24x)	71-52978-00 2x 13119-77E00 	71-52979-00 2x 14140-77E00 	70-31414-10 	81-53216-00 K ← 25x35x6 A SL RD NBR 81-53234-00 N 32x46x6 A SL RD MVQ		
2,0 J20A	94-107 kW (128-146 PS)	GRAND VITARA SX4 VITARA	12/96→	02-53205-01 <sup>12</sup> 11400-65862-000	61-53205-00 11141-21111-000 MLS 	71-53156-00 11189-77E00-000 	12-52829-01 09289-06003-000 (16x)	71-53153-00 13119-77EA0-000 	71-53154-00 11140-65D01-000 	70-31414-10 	81-53236-00 N 09283-32042 32x47x6 A SL RD MVQ		
2,0 RF	52-64 kW (71-87 PS)	GRAND VITARA TD VITARA TD	12/94-07/03	01-53115-01 <sup>12</sup> <sup>13</sup> 02-53115-01 <sup>12</sup>	61-53115-00 87,6 Ø MLS 	71-52291-00 	12-52722-01	71-52438-00 	71-52439-00 	71-52272-00 	81-53243-00 K ← 34x48x7 A SL RD MVQ 81-53342-00 K → 90x110x9 A SL LD NBR 81-53243-00 N ← 34x48x7 A SL RD NBR		

SUZUKI												
Ltr.												
2,0 RHW	80 kW (109 PS)	GRAND VITARA HDI	07/01-09/05	<p><b>01-34404-01</b> <sup>12</sup> <sup>13</sup> Mot.→4026525</p> <p></p> <p><b>02-34404-01</b> <sup>12</sup> 11162-67J00</p> <p></p>	<p><b>61-34370-00</b> 11141-67J01-001 86 Ø 1,25 mm 2 </p> <p><b>61-34370-10</b> 11141-67J01-002 86 Ø 1,3 mm 3 </p> <p><b>61-34370-20</b> 11141-67J01-003 86 Ø 1,35 mm 4 </p> <p><b>61-34370-30</b> 11141-67J01-004 86 Ø 1,4 mm 5 </p> <p></p>	<p><b>14-32233-01</b> 11117-67G01 (10x)</p> <p></p>	<p><b>71-34404-00</b> 11189-67J00</p> <p></p>	<p><b>12-34399-02</b> 12919-67G00 (16x)</p> <p><b>70-34399-00</b> 12919-67G00</p> <p>16x</p>		<p><b>71-33223-00</b> 14141-67G10</p> <p></p>	<p><b>70-31414-10</b></p> <p></p>	<p><b>81-25926-10 K</b> ← 16114-66G00 42x62x8 A RD FPM Mot.→4026525</p> <p><b>81-36557-00 K</b> ← 16114-66G01 42x62x7 A SL RD PTFE Mot.4026526→</p> <p><b>81-34456-00 K</b> → 16121-66G10 90x110x7 A SL LD FPM Mot.→4026525</p> <p><b>81-36556-00 K</b> → 16121-66G01 90x110x7 A SL LD PTFE Mot.4026526→</p> <p><b>81-34144-00 N</b> 12746-67G00 27x47x7 A SL RD FPM</p>
2,0 RHZ	80 kW (109 PS)	GRAND VITARA	07/01-09/05	<p><b>01-34398-01</b> <sup>12</sup> <sup>13</sup></p> <p></p> <p><b>02-34398-01</b> <sup>12</sup></p> <p></p>	<p><b>61-35815-00</b> 86 Ø 1,3 mm 1 </p> <p><b>61-35815-10</b> 86 Ø 1,35 mm 2 </p> <p><b>61-35815-20</b> 86 Ø 1,4 mm 3 </p> <p><b>61-35815-30</b> 86 Ø 1,45 mm 4 </p> <p><b>61-35815-40</b> 86 Ø 1,5 mm 5 </p> <p></p>	<p><b>14-35774-01</b></p> <p></p>	<p><b>71-34398-00</b></p> <p></p>	<p><b>12-31306-07</b> 12919-84A00 (8x) Mot.→08331</p> <p><b>12-34399-01</b> Mot.08332→</p> <p><b>70-31306-00</b> 12919-84A00</p> <p>8x</p> <p><b>70-34399-00</b> 12919-67G00 Mot.08332→</p> <p>8x</p>	<p><b>71-34401-00</b></p> <p></p>	<p><b>71-34402-00</b></p> <p></p>	<p><b>70-31414-10</b></p> <p></p>	<p><b>81-25926-10 K</b> ← 16114-66G00 42x62x8 A RD FPM</p> <p><b>81-34456-00 K</b> → 16121-66G10 90x110x7 A SL LD FPM</p> <p><b>81-34144-00 N</b> 12746-67G00 27x47x7 A SL RD FPM</p>



SUZUKI												
Ltr.			<b>1</b>									
2,0 XUD9TE	64 kW (87 PS) VITARA TD	12/95-03/98		<p><b>02-25942-03</b> </p> <p><b>02-25942-04</b> <sup>12</sup> </p> <p><b>08-25918-02</b> <sup>13</sup></p>	<p><b>61-33155-00</b> 84 Ø 1,36 mm 1 </p> <p><b>61-33155-10</b> 84 Ø 1,4 mm 2 </p> <p><b>61-33155-20</b> 84 Ø 1,44 mm 3 </p> <p><b>61-33155-30</b> 84 Ø 1,48 mm 4 </p> <p><b>61-33155-40</b> 84 Ø 1,53 mm 5 </p>	<p><b>14-32177-01</b> </p>	<p><b>71-25942-00</b> </p>	<p><b>12-25837-01</b></p>	<p><b>71-33156-00</b> </p> <p><b>71-33157-00</b> 2x </p>	<p><b>71-25919-30</b> </p>	<p>2x <b>71-25918-30</b> </p>	<p><b>81-25926-10 K</b> ← 16114-66G00 42x62x8 A RD FPM</p> <p><b>81-34456-00 K</b> → 16121-66G10 90x110x7 A SL LD FPM</p> <p><b>81-21798-30 N</b> 35x50x8 A SL WD ACM</p>
2,4 J24B	122-138 kW (166-188 PS) GRAND VITARA KIZASHI	01/09→		<p><b>01-10014-01</b> <sup>12</sup> <sup>13</sup> 11400-57831</p>	<p><b>61-10014-00</b> 11141-78K01 69,6 Ø</p>		<p><b>71-10124-00</b> 11189-78K00</p>	<p><b>12-39357-02</b> 09298-05012 (16x)</p>	<p><b>71-10125-00</b> 4x 13119-80J00</p>	<p><b>71-10126-00</b> 14140-78K00</p>	<p><b>70-31414-10</b> </p>	<p><b>81-10372-00 K</b> ← 11389-54L00 FPM/ACM</p> <p><b>81-10373-00 K</b> → 09283-98003 FPM/ACM</p> <p><b>81-10374-00 N</b> 09283-35047 35x47x6 A SL RD FPM/ACM</p>
2,5 H 25 A	106-116 kW (144-158 PS) GRAND VITARA V6	04/98-07/03		<p><b>02-53655-01</b> <sup>12</sup> 11400-65874</p>	<p><b>61-53655-00 L</b> 11142-86FA1 85 Ø 1,3 mm</p> <p><b>61-53660-00 R</b> 11141-86FA1 85 Ø 1,3 mm</p>		<p><b>71-52976-00 R</b> 11176-85FA0</p> <p><b>71-52977-00 L</b> 11186-85FA0</p>	<p><b>12-52829-03</b> 09289-06003 (24x)</p>	<p><b>71-52978-00</b> 2x 13119-77E00</p>	<p><b>71-53693-00</b> 2x 14140-67D03</p>	<p><b>70-31414-10</b> </p>	<p><b>81-53706-00 K</b> ← 09283-45012 45x63x7,5 A SL RD NBR</p> <p><b>81-53704-00 K</b> → 09283-98002 98x116x10 A SL LD NBR</p> <p><b>81-53234-00 N</b> 2x 32x46x6 A SL RD MVQ</p>
2,7 H 27 A	127-135 kW (173-184 PS) GRAND VITARA	09/01-07/03		<p><b>02-53645-01</b> <sup>12</sup> 11400-52823</p>	<p><b>61-53645-00 R</b> 11141-52D01 89,5 Ø 0,7 mm MLS</p> <p><b>61-53650-00 L</b> 11142-52D01 89,5 Ø 0,7 mm MLS</p>		<p><b>71-52976-00 R</b> 11176-85FA0</p> <p><b>71-52977-00 L</b> 11186-85FA0</p>	<p><b>12-52829-03</b> 09289-06003 (24x)</p>	<p><b>71-52978-00</b> 2x 13119-77E00</p>	<p><b>71-53693-00</b> 2x 14140-67D03</p>	<p><b>70-31414-10</b> </p>	<p><b>81-53706-00 K</b> ← 09283-45012 45x63x7,5 A SL RD NBR</p> <p><b>81-53704-00 K</b> → 09283-98002 98x116x10 A SL LD NBR</p> <p><b>81-53234-00 N</b> 2x 32x46x6 A SL RD MVQ</p>