

TOYOTA												
Ltr.			<b>1</b>									
1,0 EJ-VE 43 kW (58 PS)	DUET	09/98-04/04	<b>01-53280-01</b> ⑫ ⑬ 04111-97206 <b>02-53280-01</b> ⑫ 04112-97206	<b>61-53280-00</b> 11115-97201 73,8 Ø MLS 	<b>71-53373-10</b> 11213-97202 	<b>12-53129-02</b> 	<b>71-53371-00</b> 17177-97202 	<b>71-53372-00</b> 17173-87229 	<b>70-31414-10</b> 			
1,0 1E 1E-L 40 kW (54 PS)	STARLET	10/84-12/92	<b>01-52136-01</b> ⑫ ⑬ 04111-10035  <b>02-52136-01</b> ⑫ 04112-10022	<b>61-52136-00</b> 11115-10010 72 Ø 	<b>14-55001-01</b> 90105-09002 (10x) 	<b>15-52786-01</b> 11213-10011 +90210-09001 (2x) 	<b>12-52782-01</b> 90913-02089 (8x) +90913-02081 (4x) 	<b>71-52783-00</b> 17177-10020 	<b>71-52568-00</b> 17173-10021 2x 	<b>70-31414-10</b> 	<b>81-53247-00</b> K ← 90311-35040 35x49x6 A SL RD MVQ <b>81-53311-00</b> K → 90311-75009 75x100x8,5 A SL LD MVQ <b>81-53247-00</b> N 90311-35040 35x49x6 A SL RD MVQ	
1,0 1KR-FE 50-51 kW (68-69 PS)	AYGO YARIS YARIS VVT-i	07/05→	<b>01-53425-01</b> ⑫ ⑬ ⑰ 04111-0Q016 <b>02-53425-01</b> ⑫ ⑰ 04112-0Q014	<b>61-53425-00</b> 11115-40060 72 Ø 0,5 mm MLS <b>61-53425-10</b> 72 Ø 0,8 mm MLS 	<b>14-32366-01</b> 	<b>71-53503-00</b> 11213-0Q010 	<b>12-53507-01</b> 90080-31064 (6x) +90080-31065 (6x) 	<b>71-53504-00</b> 17177-0Q010 	<b>71-53506-00</b> 17173-0Q010 	<b>70-31414-10</b> 	<b>81-53508-00</b> K ← 38x50x6 A SL RD NBR <b>81-53509-00</b> K → 90311-73002 74x89x8,5 A SL LD MVQ	
1,0 1SZ-FE 48-50 kW (65-68 PS)	YARIS	04/99-09/05	<b>01-53155-01</b> ⑫ ⑬ 04111-23040 <b>02-53155-01</b> ⑫ 04112-23040	<b>61-53155-00</b> 11115-23090 70 Ø MLS 	<b>14-55036-01</b> 90910-02143 (10x) 	<b>15-53121-01</b> 11213-23020 	<b>12-53129-01</b> 90913-02120 (16x) 	<b>71-53109-00</b> 17177-23020 	<b>71-53112-00</b> 17173-23010 	<b>70-31414-10</b> 	<b>81-53252-00</b> K ← 36x49x7 A SL RD MVQ <b>81-53321-00</b> K → 80x100x10 A SL LD MVQ <b>81-53271-00</b> N 40x55x9 A SL RD MVQ	
1,2 3NR-FE <b>[NEW]</b> 63 kW (86 PS)	YARIS	10/13→	<b>01-54030-02</b> ⑫ ⑬ ⑰ 04111-47150 <b>02-54030-02</b> ⑫ ⑰ 04112-47100	<b>61-54030-00</b> 11115-47050 0,5 mm MLS 	<b>14-32328-01</b> 90910-02174 (10x) 	<b>71-54088-00</b> 11213-47020 	<b>12-54024-01</b> 90080-31084 (8x) +90080-31085 (8x) <b>70-54024-00</b> ES 90080-31084 <b>70-54026-00</b> AS 90080-31085 8x 	<b>71-54089-00</b> 17177-47010 	<b>71-54091-00</b> 17173-47021 	<b>70-31414-10</b> 	<b>81-53218-00</b> K ← 90311-25020 25,5x37,5x6 A SL RD NBR <b>81-54107-00</b> K → 90311-78003 77,5x171,5x8,7 A SL LD FPM	
1,3 K3-VE 63-67 kW (86-91 PS)	AVANZA	12/03→	<b>01-54210-01</b> ⑫ ⑬ ⑰ 04111-BZ102 <b>02-54210-01</b> ⑫ ⑰ 04112-BZ102	<b>61-54210-00</b> 11115-B1030 0,35 mm MLS 	<b>14-55036-01</b> 90910-02143 (10x) 	<b>15-53121-01</b> 11213-23020 	<b>12-53129-01</b> 90913-02120 (16x) 	<b>71-54321-00</b> 17177-B1020 	<b>71-53112-00</b> 17173-23010 	<b>70-31414-10</b> 	<b>81-53247-00</b> K ← 90311-35040 35x49x6 A SL RD MVQ <b>81-53509-00</b> K → 90311-73002 74x89x8,5 A SL LD MVQ	

TOYOTA													
1,3 1NR-FE	70-74 kW (95-101 PS)	AURIS VVTi COROLLA URBAN CRUISER URBAN CRUISER VVT-i YARIS YARIS VVT-i	01/07→	<b>01-54030-01</b> ⑫ ⑭ 04111-47073 <b>02-54030-01</b> ⑫ 04112-47033	<b>61-54030-00</b> 11115-47050 0,5 mm MLS 	<b>14-32328-01</b> 90910-02174 (10x) 	<b>71-54088-00</b> 11213-47020 	<b>12-54024-01</b> 90080-31084 (8x) +90080-31085 (8x) <b>70-54024-00</b> ES 90080-31084 <b>70-54026-00</b> AS 90080-31085 8x 8x	<b>71-54089-00</b> 17177-47010 	<b>71-54091-00</b> 17173-47021 	<b>70-31414-10</b> 	<b>81-53218-00</b> K ← 90311-25020 25,5x37,5x6 A SL RD NBR <b>81-54107-00</b> K → 90311-78003 77,5x171,5x8,7 A SL LD FPM <b>81-54108-00</b> K → (A) 90311-99012 157,5x171,5x8 A SL FPM <b>81-54109-00</b> K → (A) 90311-99011 138x153x10 AB SL LD FPM	
1,3 2A	48 kW (65 PS)	TERCEL	03/79-01/88	<b>02-52151-03</b> ⑫ 04112-14070 08/84-04/86	<b>61-52151-00</b> 11115-14031 77,3 Ø 		<b>71-52129-10</b> 11213-15020 05/82-07/84  <b>71-52570-00</b> 11213-15040 08/84-04/86 	<b>12-53029-01</b> 90913-02038 (8x)		<b>71-52571-00</b> ⑦ 17172-15010 			
1,3 2E	53-60 kW (72-82 PS)	COROLLA STARLET	05/87-10/01	<b>01-52840-02</b> ⑫ ⑬ 04111-11026 <b>02-52840-02</b> ⑫ 04112-11012	<b>61-52840-00</b> 11115-11010 74,5 Ø 	<b>14-55001-01</b> 90105-09002 (10x) 	<b>15-52786-01</b> 11213-10011 +90210-09001 (2x) 	<b>12-52851-02</b> 90913-02071 (12x) <b>70-52851-00</b> 90913-02071 12x	<b>71-52783-00</b> 17177-10020 	<b>71-52568-00</b> 17173-10021 	2x	<b>70-31414-10</b> 	<b>81-53247-00</b> K ← 90311-35040 35x49x6 A SL RD MVQ <b>81-53311-00</b> K → 90311-75009 75x100x8,5 A SL LD MVQ <b>81-53247-00</b> N 90311-35040 35x49x6 A SL RD MVQ
1,3 2E	60 kW (82 PS)	COROLLA	08/83-04/87	<b>01-52141-01</b> ⑫ ⑬ 04111-11020  <b>02-52141-01</b> ⑫ 04112-11020	<b>61-52141-10</b> 11115-11060 74,5 Ø 	<b>14-55001-01</b> 90105-09002 (10x) 	<b>15-52786-01</b> 11213-10011 +90210-09001 (2x) 	<b>12-52851-02</b> 90913-02071 (12x) <b>70-52851-00</b> 90913-02071 12x	<b>71-52783-00</b> 17177-10020 	<b>71-52568-00</b> 17173-10021 	2x	<b>70-31414-10</b> 	<b>81-53247-00</b> K ← 90311-35040 35x49x6 A SL RD MVQ <b>81-53311-00</b> K → 90311-75009 75x100x8,5 A SL LD MVQ <b>81-53247-00</b> N 90311-35040 35x49x6 A SL RD MVQ
1,3 2E-E	55 kW (75 PS)	COROLLA STARLET	08/87-03/96	<b>01-52840-01</b> ⑫ ⑬ 04111-11035  <b>02-52840-01</b> ⑫ 04112-11022	<b>61-52840-00</b> 11115-11010 74,5 Ø 	<b>14-55001-01</b> 90105-09002 (10x) 	<b>15-52786-01</b> 11213-10011 +90210-09001 (2x) 	<b>12-52782-01</b> 90913-02089 (8x) +90913-02081 (4x)	<b>71-52783-00</b> 17177-10020 	<b>71-52568-00</b> 17173-10021 	2x	<b>70-31414-10</b> 	<b>81-53247-00</b> K ← 90311-35040 35x49x6 A SL RD MVQ <b>81-53311-00</b> K → 90311-75009 75x100x8,5 A SL LD MVQ <b>81-53247-00</b> N 90311-35040 35x49x6 A SL RD MVQ



TOYOTA													
1,3 2NZ-FE	62-64 kW (84-87 PS)	YARIS YARIS VVT-i	08/99→	<b>01-53135-01</b> <sup>12</sup> <sup>13</sup> 04111-21040 <b>02-53135-01</b> <sup>12</sup> 04112-21040	<b>61-53135-00</b> 11115-21050 75,5 Ø MLS 	<b>14-55033-01</b> 90910-02126 (10x) 	<b>15-53088-01</b> 11213-21011 	<b>12-53093-01</b> 90913-02093 (8x) +90913-02092 (8x) <b>70-53093-00</b> ES 90913-02093 <b>70-54062-00</b> AS 90913-02092	8x 	<b>71-53089-00</b> 17177-21020 	<b>71-53091-00</b> 17173-21020 	<b>70-31414-10</b> 	<b>81-53218-00</b> K ← 90311-25020 25,5x37,5x6 A SL RD NBR <b>81-53313-00</b> K → 90311-75016 75x107x8 A SL LD MVQ
1,3 2SZ-FE	63-64 kW (86-87 PS)	YARIS YARIS VVT-i	11/99→	<b>01-53275-01</b> <sup>12</sup> <sup>13</sup> 04111-0J041 <b>02-53275-01</b> <sup>12</sup> 04112-B1025	<b>61-53275-00</b> 11115-97403 73,5 Ø MLS 		<b>15-53121-01</b> 11213-23020 	<b>12-53129-01</b> 90913-02120 (16x)	<b>71-53109-00</b> 17177-23020 	<b>71-53112-00</b> 17173-23010 	<b>70-31414-10</b> 		
1,3 4E-FE	55 kW (75 PS)	COROLLA STARLET	09/95-03/99	<b>01-52845-01</b> <sup>12</sup> <sup>13</sup> 04111-11141  <b>02-52845-01</b> <sup>12</sup> 04112-11121	<b>61-52845-00</b> 11115-11071 75,5 Ø 	<b>14-55029-01</b> 90910-02100 (5x) +90910-02101 (5x) 	<b>15-52791-01</b> 11213-11041 (1X) +11193-15010 (4X) +90210-06013 (5X) 	<b>12-52787-01</b> 90913-02086 (8x) +90913-02088 (8x)	<b>71-54119-00</b> 17177-11070 	<b>71-52789-00</b> 17173-11040 	<b>70-31414-10</b> 	<b>81-53247-00</b> K ← 90311-35040 35x49x6 A SL RD MVQ <b>81-53311-00</b> K → 90311-75009 75x100x8,5 A SL LD MVQ <b>81-53247-00</b> N 90311-35040 35x49x6 A SL RD MVQ	
1,3 4E-FE	65 kW (88 PS)	COROLLA TERCEL	07/92-09/99	<b>01-52845-01</b> <sup>12</sup> <sup>13</sup> 04111-11141  <b>02-52845-01</b> <sup>12</sup> 04112-11121	<b>61-52845-00</b> 11115-11071 75,5 Ø 	<b>14-55029-01</b> 90910-02100 (5x) +90910-02101 (5x) 	<b>15-52791-01</b> 11213-11041 (1X) +11193-15010 (4X) +90210-06013 (5X) 	<b>12-52787-01</b> 90913-02086 (8x) +90913-02088 (8x)	<b>71-52882-00</b> 17177-11021 →03/95  <b>71-54119-00</b> 17177-11070 04/95→ 	<b>71-52789-00</b> 17173-11040 	<b>70-31414-10</b> 	<b>81-53247-00</b> K ← 90311-35040 35x49x6 A SL RD MVQ <b>81-53311-00</b> K → 90311-75009 75x100x8,5 A SL LD MVQ <b>81-53247-00</b> N 90311-35040 35x49x6 A SL RD MVQ	
1,3 4K 4K-C	41-48 kW (56-65 PS)	COROLLA LITEACE STARLET	02/78-08/87	<b>01-52131-04</b> <sup>12</sup> <sup>13</sup> 04111-13031 <b>02-52131-05</b> <sup>12</sup> 04112-13014	<b>61-52131-10</b> 11115-13031 77,5 Ø 		<b>71-52031-00</b> 11213-22010 	<b>12-52928-01</b> 90913-02116 (8x) <b>12-52928-02</b> 90913-02117 (8x) <b>70-52928-00</b> 90913-02116 <b>70-52928-10</b> 90913-02117	8x 	<b>71-52569-00</b> <sup>7</sup> 2x 17172-13021 	<b>71-52147-10</b> 12151-13010 	<b>81-53264-00</b> K ← 90311-38013 38,5x58x11 A SL RD MVQ <b>81-53303-00</b> K → 90311-70003 70x92x12 A SL LD MVQ	
1,3 8A-FE <b>[NEW]</b>	64 kW (87 PS)	SOLUNA VIOS VVTi VIOS VVTi	07/02→	<b>01-54060-00</b> 11115-15090 1,4 mm 	<b>61-54060-00</b> 11115-15090 1,4 mm 	<b>14-55002-01</b> 90910-02120 (5x) +90910-02121 (5x) 	<b>15-54142-02</b> 11213-15071 +11193-15010 (4x) +90210-06013 (4x) 	<b>12-52806-03</b> 90913-02085 (8x) +90913-02090 (8x) <b>70-52806-00</b> AS 90913-02090 <b>70-54261-00</b> ES 90913-02089	8x 	<b>71-52808-00</b> 17173-15040 	<b>70-31414-10</b> 	<b>81-53234-00</b> K ← 90311-32017 32x46x6 A SL RD MVQ <b>81-53302-00</b> K → 90311-70004 70x92x8,5 A SL LD MVQ <b>81-53247-00</b> N 90311-35040 35x49x6 A SL RD MVQ	

TOYOTA													
Ltr.													
1,4 1ND-TV	55-66 kW (75-90 PS)	COROLLA D YARIS D-4D	12/01→	<b>01-53558-01</b> <sup>12</sup> <sup>13</sup> 04111-33022  <b>02-53558-01</b> <sup>12</sup> 04112-33021 	<b>61-53375-30</b> 11115-33022-C0 3 MLS <b>61-53375-40</b> 11115-33022-D0 4 MLS <b>61-53375-50</b> 11115-33022-E0 5 MLS 		<b>71-53558-00</b> 11213-33021 	<b>12-53457-01</b> 90913-02121 (8x) 			<b>71-53557-00</b> 17173-33010 	<b>70-31414-10</b> 	<b>81-53508-00</b> K ← 38x50x6 A SL RD NBR <b>81-53313-00</b> K → 90311-75016 75x107x8 A SL LD MVQ
1,4 2WZ-TV	40 kW (54 PS)	AYGO	07/05-08/10	<b>02-35542-01</b> <sup>12</sup>  <b>08-36869-01</b> <sup>13</sup> 	<b>61-35430-00</b> SU001-00493 75 Ø 1,25 mm 2 MLS <b>61-35430-10</b> SU001-00494 75 Ø 1,3 mm 3 MLS <b>61-35430-20</b> SU001-00495 75 Ø 1,35 mm 1 MLS <b>61-35430-30</b> SU001-00496 75 Ø 1,4 mm 4 MLS <b>61-35430-40</b> SU001-00497 75 Ø 1,45 mm 5 MLS 	<b>14-32206-01</b> SU001-00795 (10x) 	<b>15-35542-01</b> SU001-00822 +SU001-00825 (4x) +SU001-00796 (2x)  <b>71-35542-00</b> SU001-00822 	<b>12-35548-01</b> SU001-00553 (8x) <b>70-35548-00</b> SU001-00553 8x 	<b>40-76246-00</b> 4x SU001-00825 	<b>71-35487-00</b> SU001-00826 	<b>70-31414-10</b> 	<b>81-35554-00</b> K ← SU001-00818 40x55x6,4 A SL RD PTFE ACM <b>81-35553-00</b> K → SU001-00817 85x105x8,8 A SL LD PTFE ACM <b>81-35552-00</b> N SU001-00820 27x47x7 A SL RD PTFE ACM	
1,4 4E-FE	63 kW (86 PS)	COROLLA	04/97-02/00	<b>01-52845-01</b> <sup>12</sup> <sup>13</sup> 04111-11141  <b>02-52845-01</b> <sup>12</sup> 04112-11121 	<b>61-52845-00</b> 11115-11071 75.5 Ø 	<b>14-55029-01</b> 90910-02100 (5x) +90910-02101 (5x) 	<b>15-52791-01</b> 11213-11041 (1X) +11193-15010 (4X) +90210-06013 (5X) 	<b>12-52787-01</b> 90913-02086 (8x) +90913-02088 (8x) 		<b>71-54119-00</b> 17177-11070 	<b>71-52789-00</b> 17173-11040 	<b>70-31414-10</b> 	<b>81-53247-00</b> K ← 90311-35040 35x49x6 A SL RD MVQ <b>81-53311-00</b> K → 90311-75009 75x100x8,5 A SL LD MVQ <b>81-53247-00</b> N 90311-35040 35x49x6 A SL RD MVQ
1,4 4ZZ-FE	71 kW (97 PS)	COROLLA COROLLA VVT-i	02/00-07/07	<b>01-53140-01</b> <sup>12</sup> <sup>13</sup> 04111-22060 <b>02-53140-01</b> <sup>12</sup> 04112-22060 	<b>61-53140-00</b> 11115-22040 80 Ø 0,5 mm MLS <b>61-53140-10</b> 80 Ø 0,8 mm MLS 	<b>14-55035-01</b> 90910-02152 (10x) 	<b>15-53108-01</b> 	<b>12-53128-02</b> 90080-31061 (8x) +90080-31062 (8x) <b>70-53993-00</b> ES 90080-31061 <b>70-53994-00</b> AS 90080-31062 8x 8x 	<b>71-53104-00</b> 17171-22030 8x 	<b>71-53107-00</b> 17173-22010 	<b>70-31414-10</b> 	<b>81-53256-00</b> K ← 90311-38017 38x50x8 A SL RD NBR <b>81-53318-00</b> K → 90311-76001 76x94x8,5 A SL LD FPM <b>81-53256-00</b> N 90311-38017 38x50x8 A SL RD NBR	

TOYOTA													
Ltr.													
1,5 1N	40 kW (54 PS)	STARLET D	12/86-03/96	<p><b>01-52937-01</b> <sup>12</sup> <sup>13</sup> 04111-55030</p> <p><b>02-52937-01</b> <sup>12</sup> 04112-55030</p>	<p><b>61-52985-00</b> 11115-5503-01 75 Ø 1,45 mm 1 </p> <p><b>61-52985-10</b> 11115-5503-02 75 Ø 1,55 mm 2 </p> <p><b>61-52985-20</b> 11115-5503-03 75 Ø 1,65 mm 3 </p>	<p><b>14-55032-01</b> 90910-02105 (10x)</p>	<p><b>71-52937-00</b> 11273-55010</p>	<p><b>12-52806-01</b> 91913-02089 (4x) +90913-02090 (4x)</p>	<p><b>71-52933-00</b> 17177-55012</p>		<p><b>71-52934-00</b> 17173-55010</p> <p><b>71-52924-00</b> </p>	<p><b>70-31414-10</b></p>	<p><b>81-53257-00 K</b> ← 38x50x7 A SL LD NBR <b>81-53321-00 K</b> → 80x100x10 A SL LD MVQ <b>81-53247-00 N</b> 90311-35040 35x49x6 A SL RD MVQ</p>
1,5 1NZ-FE	68-110 kW (92-150 PS)	VIOS VIOS VVTi YARIS YARIS TS YARIS VVT-i	03/00→	<p><b>01-53135-01</b> <sup>12</sup> <sup>13</sup> 04111-21040</p> <p><b>02-53135-01</b> <sup>12</sup> 04112-21040</p>	<p><b>61-53135-00</b> 11115-21050 75,5 Ø MLS</p>	<p><b>14-55033-01</b> 90910-02126 (10x)</p>	<p><b>15-53088-01</b> 11213-21011</p>	<p><b>12-53093-01</b> 90913-02093 (8x) +90913-02092 (8x)</p> <p><b>70-53093-00 ES</b> 90913-02093</p> <p><b>70-54062-00 AS</b> 90913-02092</p>	<p><b>71-53089-00</b> 17177-21020</p>	<p><b>71-53091-00</b> 17173-21020</p>	<p><b>70-31414-10</b></p>	<p><b>81-53218-00 K</b> ← 90311-25020 25,5x37,5x6 A SL RD NBR <b>81-53313-00 K</b> → 90311-75016 75x107x8 A SL LD MVQ</p>	
1,5 1NZ-FXE	53-57 kW (72-78 PS)	PRIUS	05/00-03/09		<p><b>61-53135-00</b> 11115-21050 75,5 Ø MLS</p>	<p><b>14-55033-01</b> 90910-02126 (10x)</p>	<p><b>15-53088-01</b> 11213-21011</p>	<p><b>12-53093-01</b> 90913-02093 (8x) +90913-02092 (8x)</p> <p><b>70-53093-00 ES</b> 90913-02093</p> <p><b>70-54062-00 AS</b> 90913-02092</p>	<p><b>71-53643-00</b> 17177-21010</p>	<p><b>71-53091-00</b> 17173-21020</p>	<p><b>70-31414-10</b></p>		
1,5 2NR-FE <b>[NEW]</b>	66-71 kW (90-97 PS)			<p><b>01-10073-01</b> <sup>12</sup> <sup>13</sup> <sup>19</sup> 04111-47140</p> <p><b>02-10073-01</b> <sup>12</sup> <sup>19</sup> 04112-47090</p>	<p><b>61-10073-00</b> 11115-47060 0,5 mm MLS</p>	<p><b>14-32328-01</b> 90910-02174 (10x)</p>	<p><b>71-10639-00</b> 11213-47030</p>	<p><b>12-54024-01</b> 90080-31084 (8x) +90080-31085 (8x)</p> <p><b>70-54024-00 ES</b> 90080-31084</p> <p><b>70-54026-00 AS</b> 90080-31085</p>	<p><b>71-10640-00</b> 17177-47040</p>	<p><b>71-10641-00</b> 17173-0Y010</p>	<p><b>70-31414-10</b></p>	<p><b>81-10420-00 K</b> ← 90311-36007 36x48x6,5 A SL RD <b>81-10421-00 K</b> → 90311-78004 78x105,5x7,5 A SL LD</p>	
1,5 3A	52 kW (70-71 PS)	TERCEL	08/82-01/88	<p><b>01-52161-03</b> <sup>12</sup> <sup>13</sup> 04111-15060</p> <p><b>02-52161-03</b> <sup>12</sup> 04112-15050</p>	<p><b>61-52161-00</b> 11115-15060 79 Ø</p>		<p><b>71-52570-00</b> 11213-15040</p>	<p><b>12-53029-01</b> 90913-02038 (8x)</p>		<p><b>71-52571-00</b> <sup>7</sup> 17172-15010</p>	<p><b>70-31414-10</b></p>	<p><b>81-53247-00 K</b> ← 90311-35040 35x49x6 A SL RD MVQ <b>81-53303-00 K</b> → 90311-70003 70x92x12 A SL LD MVQ <b>81-53247-00 N</b> 90311-35040 35x49x6 A SL RD MVQ</p>	
1,5 3E	52 kW (71 PS)	TERCEL	10/82-01/88	<p><b>01-52141-02</b> <sup>12</sup> <sup>13</sup> 04111-11051</p> <p><b>02-52141-02</b> <sup>12</sup> 04112-11040</p>	<p><b>61-52141-10</b> 11115-11060 74,5 Ø</p>	<p><b>14-55001-01</b> 90105-09002 (10x)</p>	<p><b>15-52786-01</b> 11213-10011 +90210-09001 (2x)</p>	<p><b>12-52829-02</b> 90913-02062 (12x)</p>	<p><b>71-52783-00</b> 17177-10020</p>	<p><b>71-52572-00</b> 17173-11020</p>	<p><b>70-31414-10</b></p>	<p><b>81-53247-00 K</b> ← 90311-35040 35x49x6 A SL RD MVQ <b>81-53319-00 K</b> → 90311-80007 80x100x8,5 A SL LD FPM <b>81-53247-00 N</b> 90311-35040 35x49x6 A SL RD MVQ</p>	

TOYOTA													
Ltr.													
1,5 3SZ-VE	80 kW (109 PS)	RUSH	03/06→	<b>01-54210-01</b> <sup>12</sup> <sup>13</sup> <sup>19</sup> 04111-BZ102 <b>02-54210-01</b> <sup>12</sup> <sup>19</sup> 04112-BZ102	<b>61-54210-00</b> 11115-B1030 0,35 mm MLS 	<b>14-55036-01</b> 90910-02143 (10x) 	<b>15-53121-01</b> 11213-23020 	<b>12-53129-01</b> 90913-02120 (16x) 	<b>71-54321-00</b> 17177-B1020 		<b>71-53112-00</b> 17173-23010 	<b>70-31414-10</b> 	<b>81-53247-00 K</b> ← 90311-35040 35x49x6 A SL RD MVQ <b>81-53509-00 K</b> → 90311-73002 74x89x8,5 A SL LD MVQ
1,5 5A-FE	73-92 kW (99-125 PS)	COROLLA	08/87-08/97	<b>01-54060-01</b> <sup>12</sup> <sup>13</sup> 04111-16221 <b>02-54060-01</b> <sup>12</sup> 04112-16220	<b>61-54060-00</b> 11115-15090 1,4 mm 	<b>14-55002-01</b> 90910-02120 (5x) +90910-02121 (5x) 	<b>15-54142-01</b> 11213-15071 (1x) +0210-06010 (4x) +11193-15010 (4x) 	<b>12-52806-03</b> 90913-02085 (8x) +90913-02090 (8x) 	<b>71-52807-00</b> 17171-15030 		<b>71-52808-00</b> 17173-15040 	<b>70-31414-10</b> 	<b>81-53234-00 K</b> ← 90311-32017 32x46x6 A SL RD MVQ <b>81-53302-00 K</b> → 90311-70004 70x92x8,5 A SL LD MVQ <b>81-53247-00 N</b> 90311-35040 35x49x6 A SL RD MVQ
1,5 5E-FE	66-85 kW (90-116 PS)	PASEO	08/95-07/99	<b>01-52845-02</b> <sup>12</sup> <sup>13</sup> 04111-11150  <b>02-52845-02</b> <sup>12</sup> 04112-11130	<b>61-52845-00</b> 11115-11071 75,5 Ø 	<b>14-55029-01</b> 90910-02100 (5x) +90910-02101 (5x) 	<b>15-52791-01</b> 11213-11041 (1X) +11193-15010 (4X) +90210-06013 (5X) 	<b>12-52787-01</b> 90913-02086 (8x) +90913-02088 (8x) 	<b>71-54119-00</b> 17177-11070 		<b>71-52883-00</b> 17173-11050  <b>71-52844-00</b> <sup>12</sup> 	<b>70-31414-10</b> 	<b>81-53247-00 K</b> ← 90311-35040 35x49x6 A SL RD MVQ <b>81-53319-00 K</b> → 90311-80007 80x100x8,5 A SL LD FPM <b>81-53247-00 N</b> 90311-35040 35x49x6 A SL RD MVQ
1,5 5E-FE	70-74 kW (95-101 PS)	CORSA PASEO TERCEL	04/91-09/99	<b>01-52845-02</b> <sup>12</sup> <sup>13</sup> 04111-11150  <b>02-52845-02</b> <sup>12</sup> 04112-11130	<b>61-52845-00</b> 11115-11071 75,5 Ø 	<b>14-55029-01</b> 90910-02100 (5x) +90910-02101 (5x) 	<b>15-52791-01</b> 11213-11041 (1X) +11193-15010 (4X) +90210-06013 (5X) 	<b>12-52787-01</b> 90913-02086 (8x) +90913-02088 (8x) 	<b>71-52882-00</b> 17177-11021 →03/95  <b>71-54119-00</b> 17177-11070 04/95→ 		<b>71-52883-00</b> 17173-11050  <b>71-52844-00</b> <sup>12</sup> 	<b>70-31414-10</b> 	<b>81-53247-00 K</b> ← 90311-35040 35x49x6 A SL RD MVQ <b>81-53319-00 K</b> → 90311-80007 80x100x8,5 A SL LD FPM <b>81-53247-00 N</b> 90311-35040 35x49x6 A SL RD MVQ
1,5 5K	51-52 kW (69-71 PS)	LITEACE	10/85-01/95	<b>01-52625-01</b> <sup>12</sup> <sup>13</sup> 04111-13042 <b>02-52625-01</b> <sup>12</sup> 04112-13020	<b>61-52625-00</b> 11115-13040 82 Ø 		<b>71-52031-00</b> 11213-22010 	<b>12-52928-01</b> 90913-02116 (8x) <b>12-52928-02</b> 90913-02117 (8x) <b>70-52928-00</b> 90913-02116 <b>70-52928-10</b> 90913-02117 8x 8x 		<b>71-52569-00</b> <sup>7</sup> 2x 17172-13021 		<b>71-52623-00</b> 12151-13011 	<b>81-53302-00 K</b> → 90311-70004 70x92x8,5 A SL LD MVQ

TOYOTA												
Ltr. <b>[NEW]</b> 1,6 1WW	82 kW (112 PS)	AURIS D4-D AVENSIS D4-D VERSO D4-D	11/13→		<b>61-10049-00</b> 11115-WA010-01 78,7 Ø 0,95 mm 1 MLS <b>61-10049-10</b> 11115-WA010-02 78,7 Ø 1,05 mm 2 MLS <b>61-10049-20</b> 11115-WA010-03 78,7 Ø 1,15 mm 3 MLS 	<b>14-10398-01</b> 90069-31065 (10x) 	<b>15-41286-01</b> 11213-WA010 	<b>12-39398-01</b> 13734-WA010 <b>70-39398-00</b> 16x 	<b>71-10395-00</b> 17177-WA010 4x 	<b>71-39421-10</b> 17173-WA010 2x 	<b>70-31414-10</b> 	<b>81-39382-00 K</b> ← 90069-38023 55x68x8 RD FPM <b>81-39379-00 K</b> → 90069-38025 90x104x8,5 LD FPM
1,6 1ZR-FAE	97 kW (132 PS)	AURIS AVENSIS COROLLA VERSO	11/08→	<b>01-54025-03</b> <sup>12</sup> <sup>13</sup> <sup>19</sup> 04111-37201 <b>02-54025-03</b> <sup>12</sup> <sup>19</sup> 04112-37201 	<b>61-54025-00</b> 11115-37060 0,7 mm MLS 	<b>14-32326-01</b> 90910-02166 (10x) 	<b>15-54083-01</b> 11213-0T020 +11193-0T010 (4x) 	<b>12-54024-01</b> 90080-31084 (8x) +90080-31085 (8x) <b>70-54024-00 ES</b> 90080-31084 <b>70-54026-00 AS</b> 90080-31085 8x 	<b>71-54086-00</b> 17177-37030 8x 	<b>71-37166-00</b> 17173-0T020 8x 	<b>70-31414-10</b> 	<b>81-34146-00 K</b> ← 90311-W0012 38x50x6 A SL RD FPM <b>81-54087-00 K</b> → 90311-W0011 78x110x8,5 A SL LD FPM
1,6 1ZR-FE	91-97 kW (124-132 PS)	AURIS VVTi COROLLA COROLLA VVTi	01/07→	<b>01-54025-01</b> <sup>12</sup> <sup>13</sup> 04111-0T081 <b>02-54025-01</b> <sup>12</sup> 04112-0T011 	<b>61-54025-00</b> 11115-37060 0,7 mm MLS 	<b>14-32326-01</b> 90910-02166 (10x) 	<b>15-54083-01</b> 11213-0T020 +11193-0T010 (4x) 	<b>12-54024-01</b> 90080-31084 (8x) +90080-31085 (8x) <b>70-54024-00 ES</b> 90080-31084 <b>70-54026-00 AS</b> 90080-31085 8x 	<b>71-54086-00</b> 17177-37030 8x 	<b>71-37166-00</b> 17173-0T020 8x 	<b>70-31414-10</b> 	<b>81-34146-00 K</b> ← 90311-W0012 38x50x6 A SL RD FPM <b>81-54087-00 K</b> → 90311-W0011 78x110x8,5 A SL LD FPM
1,6 12T 12T-J 2T	54-66 kW (73-90 PS)	CARINA CELICA COROLLA	02/76-09/83	<b>01-52186-02</b> <sup>12</sup> <sup>13</sup> 04111-28014 <b>02-52186-02</b> <sup>12</sup> 04112-28014 	<b>61-52186-00</b> 11115-26024 87 Ø 		<b>71-52167-00</b> 11213-25012 	<b>12-52928-01</b> 90913-02116 (8x) <b>12-52928-02</b> 90913-02117 (8x) <b>70-52928-00</b> 90913-02116 <b>70-52928-10</b> 90913-02117 8x 	<b>71-52164-00</b> 17177-25030 8x 	<b>71-52032-00</b> 17173-25012 	<b>71-52034-00</b> 12151-25010 	<b>81-53264-00 K</b> ← 90311-38013 38,5x58x11 A SL RD MVQ <b>81-53312-00 K</b> → 75x100x13 A SL LD MVQ
1,6 3ZZ-FE	81 kW (110 PS)	AVENSIS VVT-i COROLLA COROLLA VVT-i	02/00-03/09	<b>01-53140-01</b> <sup>12</sup> <sup>13</sup> 04111-22060 <b>02-53140-01</b> <sup>12</sup> 04112-22060 	<b>61-53140-00</b> 11115-22040 80 Ø 0,5 mm MLS <b>61-53140-10</b> 80 Ø 0,8 mm MLS 	<b>14-55035-01</b> 90910-02152 (10x) 	<b>15-53108-01</b> 	<b>12-53128-02</b> 90080-31061 (8x) +90080-31062 (8x) <b>70-53993-00 ES</b> 90080-31061 <b>70-53994-00 AS</b> 90080-31062 8x 	<b>71-53104-00</b> 17171-22030 8x 	<b>71-53107-00</b> 17173-22010 	<b>70-31414-10</b> 	<b>81-53256-00 K</b> ← 90311-38017 38x50x8 A SL RD NBR <b>81-53318-00 K</b> → 90311-76001 76x94x8,5 A SL LD FPM <b>81-53256-00 N</b> 90311-38017 38x50x8 A SL RD NBR

TOYOTA													
1,6 4A-C	55-57 kW (75-78 PS)	COROLLA	05/83-08/87	02-52580-01 <sup>12</sup> 04112-16080	61-52580-00 11115-16050 82,5 Ø 		71-52570-00 11213-15040 	12-53029-01 90913-02038 (8x)		71-52571-00 <sup>7</sup> 17172-15010 	70-31414-10 	81-53234-00 K ← 90311-32017 32x46x6 A SL RD MVQ 81-53302-00 K → 90311-70004 70x92x8,5 A SL LD MVQ 81-53247-00 N 90311-35040 35x49x6 A SL RD MVQ	
1,6 4A-F 4A-FE	66-88 kW (90-120 PS)	CARINA CELICA STI COROLLA	08/87-11/93	01-52585-01 <sup>12</sup> <sup>13</sup> 04111-16120  02-52585-01 <sup>12</sup> 04112-16120	61-52585-00 11115-16082 82 Ø 	14-55002-01 90910-02120 (5x) +90910-02121 (5x) 	71-52581-00 11213-15050 	12-52851-03 90913-02062 (8x) +90913-02089 (8x)	71-52583-00 17171-16031  71-52582-00 <sup>10</sup> 17171-15020 	71-52584-00 17173-15011 	70-31414-10 	81-53234-00 K ← 90311-32017 32x46x6 A SL RD MVQ 81-53302-00 K → 90311-70004 70x92x8,5 A SL LD MVQ 81-53247-00 N 90311-35040 35x49x6 A SL RD MVQ	
1,6 4A-FE	74-84 kW (101-114 PS)	AVENSIS COROLLA	07/92-10/00	01-52870-01 <sup>12</sup> <sup>13</sup> 04111-16230  02-52870-01 <sup>12</sup> 04112-16230	61-52870-00 11115-16150 82 Ø 	14-55002-01 90910-02120 (5x) +90910-02121 (5x) 	15-52809-01 	12-52806-02 90913-02089 (8x) +90913-02090 (8x)	71-52807-00 17171-15030 	71-52808-00 17173-15040 	70-31414-10 	81-53234-00 K ← 90311-32017 32x46x6 A SL RD MVQ 81-53302-00 K → 90311-70004 70x92x8,5 A SL LD MVQ 81-53247-00 N 90311-35040 35x49x6 A SL RD MVQ	
1,6 4A-FE	76-85 kW (103-116 PS)	CARINA COROLLA	07/92-09/97	01-52870-01 <sup>12</sup> <sup>13</sup> 04111-16230 →06/94  01-52870-02 <sup>12</sup> <sup>13</sup> 04111-16300 07/94→ 02-52870-01 <sup>12</sup> 04112-16230 →06/94 02-52870-02 <sup>12</sup> 07/94→	61-52870-00 11115-16150 82 Ø 	14-55002-01 90910-02120 (5x) +90910-02121 (5x) 	15-52809-01 	12-52806-02 90913-02089 (8x) +90913-02090 (8x)	71-52807-00 17171-15030 →06/94  71-52873-00 L 17171-16051 07/94→  71-52874-00 R 17179-16021 07/94→ 	71-52808-00 17173-15040 	70-31414-10 	81-53234-00 K ← 90311-32017 32x46x6 A SL RD MVQ 81-53302-00 K → 90311-70004 70x92x8,5 A SL LD MVQ 81-53247-00 N 90311-35040 35x49x6 A SL RD MVQ	
1,6 4A-FE	77 kW (105 PS)	COROLLA	10/87-08/90	01-52585-01 <sup>12</sup> <sup>13</sup> 04111-16120  02-52585-01 <sup>12</sup> 04112-16120	61-52585-00 11115-16082 82 Ø 	14-55002-01 90910-02120 (5x) +90910-02121 (5x) 		12-52851-03 90913-02062 (8x) +90913-02089 (8x)	71-52583-00 17171-16031  71-52582-00 <sup>10</sup> 17171-15020 	71-52584-00 17173-15011 	70-31414-10 	81-53234-00 K ← 90311-32017 32x46x6 A SL RD MVQ 81-53302-00 K → 90311-70004 70x92x8,5 A SL LD MVQ 81-53247-00 N 90311-35040 35x49x6 A SL RD MVQ	



TOYOTA													
Ltr.													
1,6 4A-FE	77 kW (105 PS)	COROLLA	08/88-06/92	<b>01-52585-01</b> <sup>12</sup> <sup>13</sup> 04111-16120  <b>02-52585-01</b> <sup>12</sup> 04112-16120	<b>61-52585-00</b> 11115-16082 82 Ø 	<b>14-55002-01</b> 90910-02120 (5x) +90910-02121 (5x) 	<b>15-52809-01</b> 	<b>12-52851-03</b> 90913-02062 (8x) +90913-02089 (8x) 	<b>71-52583-00</b> 17171-16031  <b>71-52582-00</b> <sup>10</sup> 17171-15020 	<b>71-52584-00</b> 17173-15011 	<b>70-31414-10</b> 	<b>81-53234-00 K</b> ← 90311-32017 32x46x6 A SL RD MVQ <b>81-53302-00 K</b> → 90311-70004 70x92x8,5 A SL LD MVQ <b>81-53247-00 N</b> 90311-35040 35x49x6 A SL RD MVQ	
1,6 4A-FE	85 kW (115 PS)	CARINA COROLLA	04/92-09/97	<b>01-52585-01</b> <sup>12</sup> <sup>13</sup> 04111-16120 →05/92  <b>01-52870-01</b> <sup>12</sup> <sup>13</sup> 04111-16230 06/92-06/94  <b>01-52870-02</b> <sup>12</sup> <sup>13</sup> 04111-16300 07/94→ <b>02-52585-01</b> <sup>12</sup> 04112-16120 →05/92 <b>02-52870-01</b> <sup>12</sup> 04112-16230 06/92-06/94 <b>02-52870-02</b> <sup>12</sup> 07/94→	<b>61-52585-00</b> 11115-16082 82 Ø →05/92  <b>61-52870-00</b> 11115-16150 82 Ø 06/92→ 	<b>14-55002-01</b> 90910-02120 (5x) +90910-02121 (5x) 	<b>15-52809-01</b> 06/92→ 	<b>12-52851-03</b> 90913-02062 (8x) +90913-02089 (8x) →05/92 <b>12-52806-02</b> 90913-02089 (8x) +90913-02090 (8x) 06/92→ 	<b>71-52583-00</b> 17171-16031 →05/92  <b>71-52807-00</b> 17171-15030 06/92-06/94  <b>71-52873-00 L</b> 17171-16051 07/94→  <b>71-52874-00 R</b> 17179-16021 07/94→  <b>71-52582-00</b> <sup>10</sup> 17171-15020 →05/92 	<b>71-52584-00</b> 17173-15011 →05/92  <b>71-52808-00</b> 17173-15040 06/92→ 	<b>70-31414-10</b> 	<b>81-53234-00 K</b> ← 90311-32017 32x46x6 A SL RD MVQ <b>81-53302-00 K</b> → 90311-70004 70x92x8,5 A SL LD MVQ <b>81-53247-00 N</b> 90311-35040 35x49x6 A SL RD MVQ	
1,6 4A-FE Lean Burn	74 kW (101 PS)	AVENSIS	09/97-10/00	<b>01-52870-03</b> <sup>12</sup> <sup>13</sup> 04111-02022  <b>02-52870-03</b> <sup>12</sup> 04112-02022	<b>61-52870-00</b> 11115-16150 82 Ø 	<b>14-55002-01</b> 90910-02120 (5x) +90910-02121 (5x) 	<b>15-53106-01</b> 	<b>12-52806-02</b> 90913-02089 (8x) +90913-02090 (8x) 	<b>71-53102-00</b> 17171-16060 	<b>71-52808-00</b> 17173-15040 	<b>70-31414-10</b> 	<b>81-53234-00 K</b> ← 90311-32017 32x46x6 A SL RD MVQ <b>81-53302-00 K</b> → 90311-70004 70x92x8,5 A SL LD MVQ <b>81-53247-00 N</b> 90311-35040 35x49x6 A SL RD MVQ	
1,6 4A-GE 4A-GEC 4A-GEL 4A-GELC 4A-GEU	85-96 kW (115-131 PS)	CELICA COROLLA	06/83-06/93	<b>01-52573-01</b> <sup>12</sup> <sup>13</sup> 04111-16023  <b>02-52573-01</b> <sup>12</sup> 04112-16023	<b>61-52575-00</b> 11115-16070 82 Ø 	<b>14-55002-01</b> 90910-02120 (5x) +90910-02121 (5x) 	<b>71-52577-00</b> 2x 11213-16010  <b>71-52578-00</b> 11214-16020 	<b>12-52851-03</b> 90913-02062 (8x) +90913-02089 (8x) 	<b>71-52579-00</b> 17177-16012 	<b>71-52576-00</b> 17173-16011 	<b>70-31414-10</b> 	<b>81-53234-00 K</b> ← 90311-32017 32x46x6 A SL RD MVQ <b>81-53302-00 K</b> → 90311-70004 70x92x8,5 A SL LD MVQ <b>81-53247-00 N</b> 90311-35040 35x49x6 A SL RD MVQ	

TOYOTA												
Ltr.			<b>1</b>									
1,6 4A-GE (20V)	102-121 kW (118-165 PS)			<b>01-54230-01</b> <sup>12</sup> <sup>13</sup> 04111-16211 →12/95 <b>01-54230-02</b> <sup>12</sup> <sup>13</sup> 04111-16330 01/96→ <b>02-54230-01</b> <sup>12</sup> 04112-16210 →12/95 <b>02-54230-02</b> <sup>12</sup> 04112-16330 01/96→	<b>61-54230-00</b> 11115-16111 82,5 Ø 1,4 mm 		<b>15-42991-01</b> 11213-16021 (1x) +11193-16010 (4x) +90210-09016 (3x) 	<b>12-53093-02</b> 90913-02093 (12x) +90913-02092 (8x) <b>70-53093-00</b> ES 90913-02093 <b>70-54062-00</b> AS 90913-02092	<b>71-42993-00</b> 17177-16020 →12/95 12x <b>71-42997-00</b> 17177-16030 01/96→ 8x <b>71-42994-00</b> <sup>10</sup> 17179-16010 →12/95  <b>71-42998-00</b> <sup>10</sup> 17179-16030 01/96→ 	<b>71-42996-00</b> 17173-16020 →12/95  <b>71-42999-00</b> 17173-16030 01/96→ 	<b>70-31414-10</b> 	<b>81-53234-00</b> K ← 90311-32017 32x46x6 A SL RD MVQ <b>81-53302-00</b> K → 90311-70004 70x92x8,5 A SL LD MVQ <b>81-43003-00</b> N 90311-40016 40,5x54,5x7 A SL RD <b>81-53247-00</b> N 90311-35040 35x49x6 A SL RD MVQ
1,6 4A-GZE	91 kW (124 PS)	MR 2	11/84-06/90	<b>01-52575-01</b> <sup>12</sup> <sup>13</sup> 04111-16110 <b>02-52575-01</b> <sup>12</sup> 04112-16110	<b>61-52575-00</b> 11115-16070 82 Ø 	<b>14-55002-01</b> 90910-02120 (5x) +90910-02121 (5x) 	<b>71-52577-00</b> 2x 11213-16010 	<b>12-52851-03</b> 90913-02062 (8x) +90913-02089 (8x)	<b>71-52579-00</b> 17177-16012 	<b>71-52576-00</b> 17173-16011 	<b>70-31414-10</b> 	<b>81-53234-00</b> K ← 90311-32017 32x46x6 A SL RD MVQ <b>81-53302-00</b> K → 90311-70004 70x92x8,5 A SL LD MVQ <b>81-53247-00</b> N 90311-35040 35x49x6 A SL RD MVQ
1,6 4A-LC	55 kW (75 PS)	CARINA	10/83-11/87	<b>01-52156-02</b> <sup>12</sup> <sup>13</sup> 04111-16041 01/84-12/85  <b>01-52580-02</b> <sup>12</sup> <sup>13</sup> 04111-16090 01/86→  <b>02-52156-02</b> <sup>12</sup> 04112-16041 01/84-12/85 <b>02-52580-02</b> <sup>12</sup> 04112-16090 01/86→	<b>61-52156-10</b> 11115-16020 82,5 Ø 01/84-12/85  <b>61-52580-00</b> 11115-16050 82,5 Ø 01/86→ 		<b>15-52129-01</b> 01/84-12/85  <b>71-52570-00</b> 11213-15040 01/86→ 	<b>12-53029-01</b> 90913-02038 (8x)	<b>71-52571-00</b> <sup>7</sup> 17172-15010 	<b>70-31414-10</b> 	<b>81-53234-00</b> K ← 90311-32017 32x46x6 A SL RD MVQ <b>81-53302-00</b> K → 90311-70004 70x92x8,5 A SL LD MVQ <b>81-53247-00</b> N 90311-35040 35x49x6 A SL RD MVQ	
1,8 1C	41-49 kW (56-67 PS)	COROLLA D LITEACE LITEACE D	10/82-06/93	<b>01-52755-01</b> <sup>12</sup> <sup>13</sup> 04111-64111  <b>02-52755-01</b> <sup>12</sup> 04112-64061	<b>61-52755-00</b> 11115-64110 84 Ø MLS 	<b>14-55028-01</b> 90910-02097 (8x) +90910-02099 (10x) 	<b>15-52204-01</b> 11213-64040 +90210-06007 (6x) 	<b>12-52928-01</b> 90913-02116 (8x) <b>12-52928-02</b> 90913-02117 (8x) <b>70-52928-00</b> 90913-02116 <b>70-52928-10</b> 90913-02117	<b>71-52642-00</b> 17177-64010 8x  8x 	<b>71-53117-00</b> 17173-27010 	<b>70-31414-10</b> 	<b>81-53274-00</b> K ← 90311-42003 42x60x7 A SL RD NBR <b>81-53342-00</b> K → 90x110x9 A SL LD NBR <b>81-53256-00</b> N 90311-38017 38x50x8 A SL RD NBR

TOYOTA													
1.8 1C	43 kW (58 PS)	COROLLA D	01/83-09/83	<b>01-52221-01</b> <sup>12</sup> <sup>13</sup> 04111-64012  <b>02-52221-01</b> <sup>12</sup> 04112-64010	<b>61-52221-00</b> 11115-64010 86 Ø 		<b>15-52204-01</b> 11213-64040 +90210-06007 (6x) 	<b>12-52928-01</b> 90913-02116 (8x) <b>12-52928-02</b> 90913-02117 (8x) <b>70-52928-00</b> 90913-02116 <b>70-52928-10</b> 90913-02117 8x 8x	<b>71-52642-00</b> 17177-64010 		<b>71-53117-00</b> 17173-27010 	<b>70-31414-10</b> 	<b>81-53274-00 K</b> ← 90311-42003 42x60x7 A SL RD NBR <b>81-53341-00 K</b> → 90311-90008 90x110x9,5 A SL LD FPM/ACM <b>81-53256-00 N</b> ← 90311-38017 38x50x8 A SL RD NBR
1.8 1C-L	47 kW (64 PS)	COROLLA D	06/83-06/89	<b>01-52226-01</b> <sup>12</sup> <sup>13</sup> 04111-64061  <b>02-52226-03</b> <sup>12</sup> 04112-64040	<b>61-52226-10</b> 11115-64070 82,6 Ø MLS 	<b>14-55028-01</b> 90910-02097 (8x) +90910-02099 (10x) 	<b>15-52204-01</b> 11213-64040 +90210-06007 (6x) 	<b>12-52928-01</b> 90913-02116 (8x) <b>12-52928-02</b> 90913-02117 (8x) <b>70-52928-00</b> 90913-02116 <b>70-52928-10</b> 90913-02117 8x 8x	<b>71-52642-00</b> 17177-64010 		<b>71-53117-00</b> 17173-27010 	<b>70-31414-10</b> 	<b>81-53274-00 K</b> ← 90311-42003 42x60x7 A SL RD NBR <b>81-53341-00 K</b> → 90311-90008 90x110x9,5 A SL LD FPM/ACM <b>81-53256-00 N</b> 90311-38017 38x50x8 A SL RD NBR
1.8 1C-TL	54 kW (73 PS)	CAMRY TD	11/83-01/88	<b>02-52226-02</b> <sup>12</sup> 04112-64030	<b>61-52226-10</b> 11115-64070 82,6 Ø MLS 	<b>14-55028-01</b> 90910-02097 (8x) +90910-02099 (10x) 	<b>15-52204-01</b> 11213-64040 +90210-06007 (6x) 	<b>12-52928-01</b> 90913-02116 (8x) <b>12-52928-02</b> 90913-02117 (8x) <b>70-52928-00</b> 90913-02116 <b>70-52928-10</b> 90913-02117 8x 8x	<b>71-52642-00</b> 17177-64010 		<b>71-53117-00</b> 17173-27010 	<b>70-31414-10</b> 	<b>81-53274-00 K</b> ← 90311-42003 42x60x7 A SL RD NBR <b>81-53342-00 K</b> → 90x110x9 A SL LD NBR <b>81-53256-00 N</b> 90311-38017 38x50x8 A SL RD NBR
1.8 1S-L	66-74 kW (90-101 PS)	CAMRY CARINA	02/83-08/88	<b>01-52166-01</b> <sup>12</sup> <sup>13</sup> 04111-63020 <b>02-52166-01</b> <sup>12</sup> 04112-63020	<b>61-52166-00</b> 11115-63010 83 Ø 		<b>71-52132-00</b> 11213-63010 	<b>12-52928-01</b> 90913-02116 (8x) <b>12-52928-02</b> 90913-02117 (8x) <b>70-52928-00</b> 90913-02116 <b>70-52928-10</b> 90913-02117 8x 8x	<b>71-52586-00</b> <sup>7</sup> 17172-63010 		<b>70-31414-10</b> 	<b>81-53274-00 K</b> ← 90311-42003 42x60x7 A SL RD NBR <b>81-53332-00 K</b> → 90311-85003 85x105x10 A SL LD FPM <b>81-53256-00 N</b> 90311-38017 38x50x8 A SL RD NBR	
1.8 1ZZ-FE	92-105 kW (125-143 PS)	AVENSIS AVENSIS VVT-i CELICA VT-i COROLLA COROLLA VVTi MR 2 VT-i VITZ VVTi RAV VVTi	08/99→	<b>01-53140-01</b> <sup>12</sup> <sup>13</sup> 04111-22060 <b>02-53140-01</b> <sup>12</sup> 04112-22060	<b>61-53140-00</b> 11115-22040 80 Ø 0,5 mm MLS <b>61-53140-10</b> 80 Ø 0,8 mm MLS 	<b>14-55035-01</b> 90910-02152 (10x) 	<b>15-53108-01</b> 	<b>12-53128-02</b> 90080-31061 (8x) +90080-31062 (8x) <b>70-53993-00 ES</b> 90080-31061 <b>70-53994-00 AS</b> 90080-31062 8x 8x	<b>71-53104-00</b> 17171-22030 		<b>71-53107-00</b> 17173-22010 	<b>70-31414-10</b> 	<b>81-53256-00 K</b> ← 90311-38017 38x50x8 A SL RD NBR <b>81-53318-00 K</b> → 90311-76001 76x94x8,5 A SL LD FPM <b>81-53256-00 N</b> 90311-38017 38x50x8 A SL RD NBR
1.8 13T 3T 3T-C 3T-E	57-63 kW (78-86 PS)	CARINA COROLLA CORONA	01/78-09/83	<b>01-52186-02</b> <sup>12</sup> <sup>13</sup> 04111-28014 <b>02-52186-02</b> <sup>12</sup> 04112-28014	<b>61-52186-00</b> 11115-26024 87 Ø 		<b>71-52167-00</b> 11213-25012 	<b>12-52928-01</b> 90913-02116 (8x) <b>12-52928-02</b> 90913-02117 (8x) <b>70-52928-00</b> 90913-02116 <b>70-52928-10</b> 90913-02117 8x 8x	<b>71-52164-00</b> 17177-25030 		<b>71-52032-00</b> 17173-25012 	<b>71-52034-00</b> 12151-25010 	<b>81-53264-00 K</b> ← 90311-38013 38,5x58x11 A SL RD MVQ <b>81-53312-00 K</b> → 75x100x13 A SL LD MVQ

TOYOTA													
Ltr.													
1,8 2Y 2Y-C	58-61 kW (79-83 PS) F BUS HIACE HILUX	11/82-07/94	<b>01-52181-02</b> ⑫ ⑬ 04111-73010 <b>02-52181-02</b> ⑫ 04112-73010	<b>61-52181-20</b> 11115-73041 88 Ø 	<b>14-32179-01</b> 	<b>71-52177-00</b> 11213-71020 	<b>12-52928-01</b> 90913-02116 (8x) <b>12-52928-02</b> 90913-02117 (8x) <b>70-52928-00</b> 90913-02116 <b>70-52928-10</b> 90913-02117	8x 8x	<b>71-52624-00</b> ⑦ 17172-73010 	<b>70-31414-10</b> 	<b>81-53274-00</b> K ← 90311-42003 42x60x7 A SL RD NBR <b>81-53319-00</b> K → 90311-80007 80x100x8,5 A SL LD FPM		
1,8 2ZR-FAE	98-108 kW (133-147 PS) AURIS VERSO WISH	02/09→	<b>01-54025-03</b> ⑫ ⑬ ⑰ 04111-37201 <b>02-54025-03</b> ⑫ ⑰ 04112-37201	<b>61-54025-00</b> 11115-37060 0,7 mm MLS 	<b>14-32326-01</b> 90910-02166 (10x) 	<b>15-54083-01</b> 11213-0T020 +11193-0T010 (4x) 	<b>12-54024-01</b> 90080-31084 (8x) +90080-31085 (8x) <b>70-54024-00</b> ES 90080-31084 <b>70-54026-00</b> AS 90080-31085	8x 8x	<b>71-54086-00</b> 17177-37030 	<b>71-37166-00</b> 17173-0T020 	<b>70-31414-10</b> 	<b>81-34146-00</b> K ← 90311-W0012 38x50x6 A SL RD FPM <b>81-54087-00</b> K → 90311-W0011 78x110x8,5 A SL LD FPM	
1,8 2ZR-FBE <b>[NEW]</b>	103 kW (140 PS) COROLLA VVTi	08/10→	<b>01-54025-04</b> ⑫ ⑬ ⑰ 04111-37382 <b>02-54025-04</b> ⑫ ⑰ 04112-37322	<b>61-54025-00</b> 11115-37060 0,7 mm MLS 	<b>14-32326-01</b> 90910-02166 (10x) 	<b>15-54083-01</b> 11213-0T020 +11193-0T010 (4x) 	<b>12-54024-01</b> 90080-31084 (8x) +90080-31085 (8x) <b>70-54024-00</b> ES 90080-31084 <b>70-54026-00</b> AS 90080-31085	8x 8x	<b>71-54086-00</b> 17177-37030 	<b>71-37166-00</b> 17173-0T020 	<b>70-31414-10</b> 	<b>81-34146-00</b> K ← 90311-W0012 38x50x6 A SL RD FPM <b>81-54087-00</b> K → 90311-W0011 78x110x8,5 A SL LD FPM	
1,8 2ZR-FE	100-103 kW (136-140 PS) AURIS VVTi COROLLA VVTi COROLLA VVTL-i	10/06→	<b>01-54025-01</b> ⑫ ⑬ 04111-0T081 <b>02-54025-01</b> ⑫ 04112-0T011	<b>61-54025-00</b> 11115-37060 0,7 mm MLS 	<b>14-32326-01</b> 90910-02166 (10x) 	<b>15-54083-01</b> 11213-0T020 +11193-0T010 (4x) 	<b>12-54024-01</b> 90080-31084 (8x) +90080-31085 (8x) <b>70-54024-00</b> ES 90080-31084 <b>70-54026-00</b> AS 90080-31085	8x 8x	<b>71-54086-00</b> 17177-37030 	<b>71-37166-00</b> 17173-0T020 	<b>70-31414-10</b> 	<b>81-34146-00</b> K ← 90311-W0012 38x50x6 A SL RD FPM <b>81-54087-00</b> K ← 90311-W0011 78x110x8,5 A SL LD FPM	
1,8 2ZR-FXE	73 kW (99 PS) AURIS HYBRID PRIUS	04/09→	<b>01-54025-02</b> ⑫ ⑬ ⑰ 04111-37310 <b>02-54025-02</b> ⑫ 04112-37250	<b>61-54025-00</b> 11115-37060 0,7 mm MLS 	<b>14-32326-01</b> 90910-02166 (10x) 	<b>15-54131-01</b> 11213-37040 +11193-37020 (4x) 	<b>12-54024-01</b> 90080-31084 (8x) +90080-31085 (8x) <b>70-54024-00</b> ES 90080-31084 <b>70-54026-00</b> AS 90080-31085	8x 8x	<b>71-54086-00</b> 17177-37030 	<b>71-37166-00</b> 17173-0T020 	<b>70-31414-10</b> 	<b>81-34146-00</b> K ← 90311-W0012 38x50x6 A SL RD FPM <b>81-54087-00</b> K → 90311-W0011 78x110x8,5 A SL LD FPM	
1,8 2ZZ-GE	141 kW (192 PS) CELICA TS COROLLA VVTL-i	08/99-02/07	<b>01-54040-01</b> ⑫ ⑬ 04111-22071 <b>02-54040-01</b> ⑫ 04112-22071	<b>61-54040-00</b> 11115-22060 MLS 	<b>14-32329-01</b> 90910-02140 (10x) 	<b>15-54101-01</b> 11213-88600 (1x) +11193-15010 (4x) 	<b>12-54112-01</b> 90913-02114 (8x) +90913-02115 (8x) <b>70-54112-00</b> ES 90913-02114 <b>70-54113-00</b> AS 90913-02115	8x 8x	<b>71-54103-00</b> 17177-22010 	<b>71-54104-00</b> 17173-88600 →02/03  <b>71-54106-00</b> 17173-88601 03/03→ 	<b>70-31414-10</b> 	<b>81-28236-00</b> K ← 38x50x8 A SL RD FPM <b>81-53332-00</b> K → 90311-85003 85x105x10 A SL LD FPM	
1,8 2ZZ-GE	165 kW (224 PS) COROLLA VVTL-i	02/05-02/07	<b>01-54040-01</b> ⑫ ⑬ 04111-22071 <b>02-54040-01</b> ⑫ 04112-22071	<b>61-54040-00</b> 11115-22060 MLS 	<b>14-32329-01</b> 90910-02140 (10x) 	<b>15-54101-01</b> 11213-88600 (1x) +11193-15010 (4x) 	<b>12-54112-01</b> 90913-02114 (8x) +90913-02115 (8x) <b>70-54112-00</b> ES 90913-02114 <b>70-54113-00</b> AS 90913-02115	8x 8x	<b>71-54103-00</b> 17177-22010 	<b>71-54106-00</b> 17173-88601 	<b>70-31414-10</b> 	<b>81-28236-00</b> K ← 38x50x8 A SL RD FPM <b>81-53332-00</b> K → 90311-85003 85x105x10 A SL LD FPM	

TOYOTA													
Ltr.													
1,8 7A-FE	79-92 kW (107-125 PS) AVENSIS CARINA CELICA COROLLA	04/92-06/02	<b>01-52935-01</b> <sup>12</sup> <sup>13</sup> 04111-16280  <b>02-52935-01</b> <sup>12</sup> 04112-16280	<b>61-52935-00</b> 11115-16120 82 Ø MLS 	<b>14-55002-01</b> 90910-02120 (5x) +90910-02121 (5x) 	<b>15-52809-01</b> 	<b>12-52806-02</b> 90913-02089 (8x) +90913-02090 (8x)	<b>71-52807-00</b> 17171-15030 		<b>71-52808-00</b> 17173-15040 	<b>70-31414-10</b> 	<b>81-53234-00</b> K ← 90311-32017 32x46x6 A SL RD MVQ <b>81-53302-00</b> K → 90311-70004 70x92x8,5 A SL LD MVQ <b>81-53247-00</b> N 90311-35040 35x49x6 A SL RD MVQ	
1,8 7K <b>[NEW]</b>	54-61 kW (73-83 PS)		<b>01-10072-01</b> <sup>12</sup> <sup>13</sup> 04111-06013 <b>02-10072-01</b> <sup>12</sup> 04112-06013	<b>61-10072-00</b> 11115-13060 	<b>14-55002-02</b> 90910-02121 (10x) 	<b>15-52031-01</b> 11213-22010 +90210-09007 (2x) 	<b>12-53204-02</b> 90913-02094 (8x) <b>70-53204-00</b> 90913-02094	8x	<b>71-10633-00</b> <sup>7</sup> 17172-13050 	<b>71-10634-00</b> 12151-13030 	<b>81-10419-00</b> K ← 90311-38086 38,5x58x7,5 A SL RD <b>81-53302-00</b> K → 90311-70004 70x92x8,5 A SL LD MVQ		
1,8 7K-E <b>[NEW]</b>	62 kW (84 PS) TUV	12/96-12/06	<b>01-10072-02</b> <sup>12</sup> <sup>13</sup> 04111-06100 <b>02-10072-02</b> <sup>12</sup> 04112-06060	<b>61-10072-00</b> 11115-13060 	<b>14-55002-02</b> 90910-02121 (10x) 	<b>15-52031-01</b> 11213-22010 +90210-09007 (2x) 	<b>12-53204-02</b> 90913-02094 (8x) <b>70-53204-00</b> 90913-02094	8x	<b>71-10636-00</b> <sup>7</sup> 17172-13060 	<b>71-10634-00</b> 12151-13030 	<b>81-10419-00</b> K ← 90311-38086 38,5x58x7,5 A SL RD <b>81-53302-00</b> K → 90311-70004 70x92x8,5 A SL LD MVQ		
1,9 1WZ	51 kW (69 PS) COROLLA D	02/00-01/02	<b>01-34356-01</b> <sup>12</sup> <sup>13</sup> SU001-00003   <b>02-34356-01</b> <sup>12</sup> SU001-00042 	<b>61-33720-00</b> SU001-00021 84 Ø 1,26 mm 3 MLS <b>61-33720-10</b> SU001-00022 84 Ø 1,3 mm 4 MLS <b>61-33720-20</b> SU001-00023 84 Ø 1,34 mm 5 MLS <b>61-33720-30</b> SU001-00024 84 Ø 1,38 mm 6 MLS <b>61-33720-40</b> SU001-00025 84 Ø 1,42 mm 7 MLS <b>61-33720-50</b> 84 Ø 1,47 mm 4 MLS 	<b>14-32116-01</b> 	<b>15-34356-01</b> <b>71-34353-00</b> U  <b>71-34356-00</b> O 	<b>12-25837-01</b> SU001-00464 (8x)		<b>71-29465-00</b> SU001-00319 	2x <b>71-25918-30</b> 	<b>81-25926-10</b> K ← SU001-00061 42x62x8 A RD FPM <b>81-34456-00</b> K → 90x110x7 A SL LD FPM <b>81-21798-30</b> N SU001-00084 35x50x8 A SL WD ACM		

TOYOTA												
2,0 1AD-FTV	93 kW (126 PS)	AURIS D-4D AVENSIS D AVENSIS D-4D COROLLA D-4D	03/06→	<p><b>01-53930-01</b> <sup>12</sup> <sup>13</sup> 04111-0R180</p> <p><del></del></p> <p><b>02-53930-01</b> <sup>12</sup> 04112-0R180</p> <p><del></del></p>	<p><b>61-53930-00</b> 11115-26052-A0 87 Ø 1 mm 1 </p> <p>MLS</p> <p><b>61-53930-10</b> 11115-26052-B0 87 Ø 1,05 mm 2 </p> <p>MLS</p> <p><b>61-53930-20</b> 11115-26052-C0 87 Ø 1,1 mm 3 </p> <p>MLS</p> <p><b>61-53930-30</b> 11115-26052-D0 87 Ø 1,15 mm 4 </p> <p>MLS</p> <p><b>61-53930-40</b> 11115-26052-E0 87 Ø 1,2 mm 5 </p> <p>MLS</p>	<p><b>14-32327-01</b> 90910-02158 (10x)</p>	<p><b>15-54074-01</b> 11213-26010 +11214-26010</p>	<p><b>12-53854-01</b> 90913-W2001 (16x)</p> <p><b>70-53854-00</b> 90913-W2001</p>	<p><b>71-54073-00</b> 17171-0R010</p> <p>16x </p>	<p><b>71-35180-00</b> 17173-0R010</p>	<p><b>70-31414-10</b></p>	<p><b>81-54078-00 K</b> ← 90311-W0009 48x63x6,5 A SL RD FPM</p> <p><b>81-54079-00 K</b> → 90311-W0010 90x106x8,5 A SL LD FPM</p>
2,0 1AZ-FE	110-114 kW (150-155 PS)	AVENSIS VVT- i AVENSIS VVTi RAV VVTi	06/00→	<p><b>01-53505-02</b> <sup>12</sup> <sup>13</sup> 04111-28074</p> <p><b>02-53505-02</b> <sup>12</sup> 04112-28074</p>	<p><b>61-53505-00</b> 11115-28022 88 Ø 0,5 mm MLS</p>	<p><b>71-53574-00</b> 11213-28021</p>	<p><b>12-54024-01</b> 90080-31084 (8x) +90080-31085 (8x)</p>	<p><b>71-53568-00</b> 17177-28010</p>	<p><b>71-53554-00</b> 17173-28010</p>	<p><b>70-31414-10</b></p>	<p><b>81-53556-00 K</b> → 90311-89013 89x105x10 SL LD FPM</p> <p><b>81-53256-00 N</b> 90311-38017 38x50x8 A SL RD NBR</p>	
2,0 1AZ-FSE	108-110 kW (147-150 PS)	AVENSIS AVENSIS VVT-i	10/00-11/08	<p><b>01-53505-01</b> <sup>12</sup> <sup>13</sup> 04111-0H160</p> <p><b>02-53505-01</b> <sup>12</sup> 04112-0H013</p>	<p><b>61-53505-00</b> 11115-28022 88 Ø 0,5 mm MLS</p>	<p><b>71-53567-00</b> 11213-28041</p>	<p><b>12-54024-01</b> 90080-31084 (8x) +90080-31085 (8x)</p>	<p><b>71-53552-00</b> 17171-28010</p> <p><b>71-53553-00</b> <sup>10</sup> 17177-28020</p>	<p><b>71-53554-00</b> 17173-28010</p>	<p><b>70-31414-10</b></p>	<p><b>81-53556-00 K</b> → 90311-89013 89x105x10 SL LD FPM</p> <p><b>81-53256-00 N</b> 90311-38017 38x50x8 A SL RD NBR</p>	

TOYOTA												
Ltr.												
2,0 1CD-FTV	66-85 kW (90-116 PS)	AVENSIS D-4D COROLLA D-4D PREVIA D-4D	10/99-01/06	<p><b>01-53098-01</b> <sup>12</sup> <sup>13</sup> 04111-0B010 →09/01</p> <p></p> <p><b>01-53098-02</b> <sup>12</sup> <sup>13</sup> 04111-27100 10/01→</p> <p></p> <p><b>02-53098-01</b> <sup>12</sup> 04112-0B010 →09/01</p> <p></p> <p><b>02-53098-02</b> <sup>12</sup> 04112-27090 10/01→</p> <p></p>	<p><b>61-53145-00</b> 11115-27010-A0 83 Ø 1 mm 1 </p> <p>MLS</p> <p><b>61-53145-10</b> 11115-27010-B0 83 Ø 1,05 mm 2 </p> <p>MLS</p> <p><b>61-53145-20</b> 11115-27010-C0 83 Ø 1,1 mm 3 </p> <p>MLS</p> <p><b>61-53145-30</b> 11115-27010-D0 83 Ø 1,15 mm 4 </p> <p>MLS</p> <p><b>61-53145-40</b> 11115-27010-E0 83 Ø 1,2 mm 5 </p> <p>MLS</p> <p></p>	<p><b>14-55034-01</b> 90910-02136 (8x) +90910-02139 (10x)</p> <p></p>	<p><b>71-53098-00</b> 11213-27010</p> <p></p>	<p><b>12-52799-01</b> 90913-02066 (8x) +90913-02090 (8x)</p>	<p><b>71-53099-00</b> 17177-27010</p> <p></p>	<p><b>71-53117-00</b> 17173-27010</p> <p></p>	<p><b>70-31414-10</b></p> <p></p>	<p><b>81-53706-00</b> K ← 45x63x7,5 A SL RD NBR</p> <p><b>81-53342-00</b> K → 90x110x9 A SL LD NBR</p> <p><b>81-53508-00</b> N ← 38x50x6 A SL RD FPM 10/01→</p> <p><b>81-53256-00</b> N 90311-38017 38x50x8 A SL RD NBR →09/01</p>
2,0 1CD-FTV	66-85 kW (90-116 PS)	COROLLA D-4D	01/02-03/09	<p><b>01-53098-02</b> <sup>12</sup> <sup>13</sup> 04111-27100</p> <p></p> <p><b>02-53098-02</b> <sup>12</sup> 04112-27090</p> <p></p>	<p><b>61-53145-00</b> 11115-27010-A0 83 Ø 1 mm 1 </p> <p>MLS</p> <p><b>61-53145-10</b> 11115-27010-B0 83 Ø 1,05 mm 2 </p> <p>MLS</p> <p><b>61-53145-20</b> 11115-27010-C0 83 Ø 1,1 mm 3 </p> <p>MLS</p> <p><b>61-53145-30</b> 11115-27010-D0 83 Ø 1,15 mm 4 </p> <p>MLS</p> <p><b>61-53145-40</b> 11115-27010-E0 83 Ø 1,2 mm 5 </p> <p>MLS</p> <p></p>	<p><b>14-55034-01</b> 90910-02136 (8x) +90910-02139 (10x)</p> <p></p>	<p><b>71-53098-00</b> 11213-27010</p> <p></p>	<p><b>12-52799-01</b> 90913-02066 (8x) +90913-02090 (8x)</p>	<p><b>71-53099-00</b> 17177-27010</p> <p></p>	<p><b>71-53117-00</b> 17173-27010</p> <p></p>	<p><b>70-31414-10</b></p> <p></p>	<p><b>81-53706-00</b> K ← 45x63x7,5 A SL RD NBR</p> <p><b>81-53342-00</b> K → 90x110x9 A SL LD NBR</p> <p><b>81-53508-00</b> N ← 38x50x6 A SL RD FPM</p>

TOYOTA														
Ltr.														
2,0 1CD-FTV	85 kW (116 PS)	AVENSIS D-4D RAV D-4D	08/01-11/08	<b>01-53098-01</b> ⑫ ⑬ 04111-0B010  <b>02-53098-01</b> ⑫ 04112-0B010 	<b>61-53145-00</b> 11115-27010-A0 83 Ø 1 mm 1 MLS <b>61-53145-10</b> 11115-27010-B0 83 Ø 1,05 mm 2 MLS <b>61-53145-20</b> 11115-27010-C0 83 Ø 1,1 mm 3 MLS <b>61-53145-30</b> 11115-27010-D0 83 Ø 1,15 mm 4 MLS <b>61-53145-40</b> 11115-27010-E0 83 Ø 1,2 mm 5 MLS 	<b>14-55034-01</b> 90910-02136 (8x) +90910-02139 (10x) 	<b>71-53098-00</b> 11213-27010 	<b>12-52799-01</b> 90913-02066 (8x) +90913-02090 (8x)	<b>71-53099-00</b> 17177-27010 		<b>71-53117-00</b> 17173-27010 	<b>70-31414-10</b> 	<b>81-53706-00</b> K ← 45x63x7,5 A SL RD NBR <b>81-53342-00</b> K → 90x110x9 A SL LD NBR <b>81-53256-00</b> N 90311-38017 38x50x8 A SL RD NBR	
2,0 1G-EU	80 kW (109 PS)	CRESSIDA	11/82-12/84	<b>01-52595-01</b> ⑫ ⑬ 04111-70013  <b>02-52595-01</b> ⑫ 04112-70013	<b>61-52595-00</b> 11115-70010 77 Ø 		<b>71-52596-00</b> 11213-70010 		<b>71-52598-00</b> 17177-70011 		<b>71-52599-00</b> 17173-70010 	3x <b>70-31414-10</b> 	<b>81-53281-00</b> K ← 90311-45015 45x62x9 A SL RD FPM <b>81-53311-00</b> K → 90311-75009 75x100x8,5 A SL LD MVQ <b>81-53256-00</b> N 90311-38017 38x50x8 A SL RD NBR	
2,0 1RZ 1RZ-E	74-81 kW (101-110 PS)	HIACE HILUX	08/89-07/05	<b>01-54290-01</b> ⑫ ⑬ 04111-75012 <b>02-54290-01</b> ⑫ 04112-75010	<b>61-54290-00</b> 11115-75010 1,4 mm 	<b>14-55030-01</b> 90910-02091 (10x) 	<b>71-53001-00</b> 11213-75020 	<b>12-52928-02</b> 90913-02117 (8x)	<b>71-52997-00</b> 17177-75010 		<b>71-52998-00</b> 17173-75010 	<b>70-31414-10</b> 	<b>81-53649-00</b> K ← 90311-48029 48x68x7 A SL RD MVQ <b>81-53337-00</b> K → 90311-88005 88x106x8,5 A SL LD MVQ	
2,0 1TR-FE	69-100 kW (94-136 PS)			<b>01-53985-01</b> ⑫ ⑬ 04111-0C081 <b>02-53985-01</b> ⑫ 04112-0C051	<b>61-53985-00</b> 11115-0C011 88 Ø 	<b>14-55030-01</b> 90910-02091 (10x) 	<b>15-54021-01</b> 11213-0C010 +11214-0C010 	<b>12-54024-01</b> 90080-31084 (8x) +90080-31085 (8x) <b>70-54024-00</b> ES 90080-31084 <b>70-54026-00</b> AS 90080-31085	8x <b>71-53648-00</b> 17177-0C010 		<b>71-54017-00</b> 17173-0C010 	<b>70-31414-10</b> 	<b>81-54018-00</b> K ← 90311-70025 A SL RD <b>81-53337-00</b> K → 90311-88005 88x106x8,5 A SL LD MVQ	
2,0 1TR-FPE <b>[NEW]</b>	83 kW (113 PS)	COMFORT	01/96→	<b>01-10075-01</b> ⑫ ⑬ ⑰ 04111-7A023 <b>02-10075-01</b> ⑫ ⑰ 04112-75892	<b>61-10075-00</b> 11115-75070 88 Ø 0,6 mm MLS 	<b>14-55030-01</b> 90910-02091 (10x) 	<b>15-54021-01</b> 11213-0C010 +11214-0C010 	<b>12-54024-01</b> 90080-31084 (8x) +90080-31085 (8x) <b>70-54024-00</b> ES 90080-31084 <b>70-54026-00</b> AS 90080-31085	8x <b>71-10627-00</b> 17177-75050 	8x <b>71-10629-00</b> ⑩ 2x 17171-75010 		<b>71-54017-00</b> 17173-0C010 	<b>70-31414-10</b> 	<b>81-53649-00</b> K ← 90311-48029 48x68x7 A SL RD MVQ <b>81-53337-00</b> K → 90311-88005 88x106x8,5 A SL LD MVQ



TOYOTA													
Ltr.													
2,0 2C 2C-L	50-54 kW (68-73 PS) CARINA D	02/84-06/92	01-52620-02 <sup>(12)</sup> <sup>(13)</sup> 04111-64075  02-52620-02 <sup>(12)</sup> 04112-64071	61-52620-10 11115-64100 87,5 Ø MLS 	14-55028-01 90910-02097 (8x) +90910-02099 (10x) 	15-52204-01 11213-64040 +90210-06007 (6x) 	12-52928-01 90913-02116 (8x) 12-52928-02 90913-02117 (8x) 70-52928-00 90913-02116 70-52928-10 90913-02117	71-52642-00 17177-64010 	8x 8x	71-53117-00 17173-27010 	70-31414-10 	81-53274-00 K ← 90311-42003 42x60x7 A SL RD NBR 81-53341-00 K → 90311-90008 90x110x9,5 A SL LD FPM/ACM 81-53256-00 N 90311-38017 38x50x8 A SL RD NBR	
2,0 2C <b>[NEW]</b>	51-54 kW (69-73 PS) COROLLA D LITEACE D	01/92-04/97	01-52929-02 <sup>(12)</sup> <sup>(13)</sup> 04111-64206  02-52929-02 <sup>(12)</sup> 04112-64144 	61-10106-00 11115-64141-01 87 Ø 1,25 mm 1 □ MLS 61-10106-10 11115-64141-02 87 Ø 1,35 mm 2 □ MLS 61-10106-20 11115-64141-03 87 Ø 1,45 mm 3 □ MLS 	14-55028-01 90910-02097 (8x) +90910-02099 (10x) 	71-52929-00 11213-64061 	12-52928-01 90913-02116 (8x) 70-52928-00 90913-02116	71-10895-00 17177-64020 	8x	71-53418-00 17173-64090 71-52924-00 	70-31414-10 	81-53274-00 K ← 90311-42003 42x60x7 A SL RD NBR 81-53341-00 K ← 90311-90008 90x110x9,5 A SL LD FPM/ACM 81-34146-00 N 90311-W0012 38x50x6 A SL RD FPM	
2,0 2C <b>[NEW]</b>	53-54 kW (72-73 PS) CARINA D LITEACE D	03/88-06/92	01-52620-04 <sup>(12)</sup> <sup>(13)</sup> <sup>(19)</sup> 04111-64620 +11115-64170-B0 02-52620-02 <sup>(12)</sup> 04112-64071	61-52620-10 11115-64100 87,5 Ø MLS 	14-55028-01 90910-02097 (8x) +90910-02099 (10x) 	15-52204-01 11213-64040 +90210-06007 (6x) 	12-52928-01 90913-02116 (8x) 70-52928-00 90913-02116	71-52642-00 17177-64010 	8x	71-53117-00 17173-27010 71-52983-00 	70-31414-10 	81-53274-00 K ← 90311-42003 42x60x7 A SL RD NBR 81-53341-00 K → 90311-90008 90x110x9,5 A SL LD FPM/ACM 81-34146-00 N 90311-W0012 38x50x6 A SL RD FPM	
2,0 2C-E 2C-T	53-66 kW (72-90 PS) CAMRY TD CARINA TD COROLLA D	11/86-02/00	01-52980-01 <sup>(12)</sup> <sup>(13)</sup> 04111-64280  02-52980-01 <sup>(12)</sup> 04112-64210	61-52980-00 11115-64122 87 Ø MLS 	14-55028-01 90910-02097 (8x) +90910-02099 (10x) 	71-52929-00 11213-64061 	12-52928-01 90913-02116 (8x) 12-52928-02 90913-02117 (8x) 70-52928-00 90913-02116 70-52928-10 90913-02117	71-52642-00 17177-64010 	8x 8x	71-53418-00 17173-64090 	70-31414-10 	81-53274-00 K ← 90311-42003 42x60x7 A SL RD NBR 81-53341-00 K → 90311-90008 90x110x9,5 A SL LD FPM/ACM 81-53256-00 N 90311-38017 38x50x8 A SL RD NBR	

TOYOTA													
2.0 2C-TE	66 kW (90 PS)	AVENSIS TD	09/97-02/03	<p><b>01-52929-01</b> <sup>12</sup> <sup>13</sup> 04111-64364</p> <p></p> <p><b>02-52929-01</b> <sup>12</sup> 04112-64272</p> <p></p>	<p><b>61-53150-00</b> 11115-64200-01 87 Ø 1,25 mm 1 </p> <p>MLS</p> <p><b>61-53150-10</b> 11115-64200-02 87 Ø 1,35 mm 2 </p> <p>MLS</p> <p><b>61-53150-20</b> 11115-64200-03 87 Ø 1,45 mm 3 </p> <p>MLS</p> <p></p>		<p><b>71-52929-00</b> 11213-64061</p> <p></p>	<p><b>12-52928-01</b> 90913-02116 (8x)</p> <p><b>12-52928-02</b> 90913-02117 (8x)</p> <p><b>70-52928-00</b> 90913-02116</p> <p><b>70-52928-10</b> 90913-02117</p>	<p><b>71-52642-00</b> 17177-64010</p> <p></p>		<p><b>71-53418-00</b> 17173-64090</p> <p></p>	<p><b>70-31414-10</b></p> <p></p>	<p><b>81-53274-00 K</b> ← 90311-42003 42x60x7 A SL RD NBR</p> <p><b>81-53341-00 K</b> → 90311-90008 90x110x9,5 A SL LD FPM/ACM</p> <p><b>81-53256-00 N</b> 90311-38017 38x50x8 A SL RD NBR</p>
2.0 2S-E 2S-EL 2S-ELC	73-79 kW (99-107 PS)	CAMRY	01/83-01/88	<p><b>01-52171-01</b> <sup>12</sup> <sup>13</sup> 04111-74010</p> <p><b>02-52171-01</b> <sup>12</sup> 04112-74010</p>	<p><b>61-52171-00</b> 11115-74010 85,5 Ø</p> <p></p>		<p><b>71-52132-00</b> 11213-63010</p> <p></p>	<p><b>12-52928-01</b> 90913-02116 (8x)</p> <p><b>12-52928-02</b> 90913-02117 (8x)</p> <p><b>70-52928-00</b> 90913-02116</p> <p><b>70-52928-10</b> 90913-02117</p>		<p><b>71-52586-00</b> <sup>7</sup> 17172-63010</p> <p></p>	<p><b>70-31414-10</b></p> <p></p>	<p><b>81-53274-00 K</b> ← 90311-42003 42x60x7 A SL RD NBR</p> <p><b>81-53332-00 K</b> → 90311-85003 85x105x10 A SL LD FPM</p> <p><b>81-53256-00 N</b> 90311-38017 38x50x8 A SL RD NBR</p>	
2.0 2WW <b>[NEW]</b>	105 kW (143 PS)	AVENSIS D-4D	04/15→		<p><b>61-38110-00</b> 11115-WA020-01 84,7 Ø 1,45 mm 1 </p> <p>MLS</p> <p><b>61-38110-10</b> 11115-WA020-02 84,7 Ø 1,55 mm 2 </p> <p>MLS</p> <p><b>61-38110-20</b> 11115-WA020-03 84,7 Ø 1,65 mm 3 </p> <p>MLS</p> <p></p>	<p><b>14-10398-01</b> 90069-31065 (10x)</p> <p></p>	<p><b>15-41286-01</b> 11213-WA010</p> <p></p>	<p><b>12-39398-01</b> 13734-WA010</p> <p><b>70-39398-00</b></p>	<p><b>71-11831-00</b> 4x 17177-WA020</p> <p></p>	<p><b>71-39421-10</b> 2x 17173-WA010</p> <p></p>	<p><b>70-31414-10</b></p> <p></p>	<p><b>81-39382-00 K</b> ← 90069-38023 55x68x8 RD FPM</p> <p><b>81-39379-00 K</b> → 90069-38025 90x104x8,5 LD FPM</p>	
2.0 21R	77 kW (105 PS)	CRESSIDA	02/81-03/85		<p><b>61-52201-00</b> 11115-37020</p> <p></p>		<p><b>15-52187-01</b></p> <p></p>	<p><b>12-52928-03</b> 90913-02072 (10x)</p>		<p><b>71-52589-00</b> 17173-35091</p> <p></p>		<p><b>81-53282-00 K</b> ← 90311-45002 45x68x12 A SL RD ACM</p>	
2.0 21R-C	77 kW (105 PS)	CELICA CRESSIDA	05/81-08/85		<p><b>61-52201-00</b> 11115-37020</p> <p></p>		<p><b>15-52187-01</b></p> <p></p>	<p><b>12-52928-03</b> 90913-02072 (10x)</p>	<p><b>71-53022-00</b> 17177-35022</p> <p></p>	<p><b>71-53024-00</b> 17173-35120</p> <p></p>		<p><b>81-53282-00 K</b> ← 90311-45002 45x68x12 A SL RD ACM</p>	

TOYOTA													
Ltr.													
2,0 3S-FE	88-89 kW (120-121 PS)	CAMRY	11/86-05/91	<b>01-52590-01</b> <sup>12</sup> <sup>13</sup> 04111-74051  <b>02-52590-01</b> <sup>12</sup> 04112-74050	<b>61-52590-00</b> 11115-79015 87,5 Ø 	<b>14-55003-01</b> 90109-10132 (10x) 	<b>15-52803-01</b> 	<b>12-52829-01</b> 90913-02062 (16x) 	<b>71-52801-00</b> 17177-74070 		<b>71-52802-00</b> 17173-74040 	<b>70-31414-10</b> 	<b>81-53274-00 K</b> ← 90311-42003 42x60x7 A SL RD NBR <b>81-53332-00 K</b> → 90311-85003 85x105x10 A SL LD FPM <b>81-53256-00 N</b> 90311-38017 38x50x8 A SL RD NBR
2,0 3S-FE	89-94 kW (121-128 PS)	CARINA	12/87-04/92	<b>01-52860-02</b> <sup>12</sup> <sup>13</sup> 04111-74053 →09/89  <b>01-52860-03</b> <sup>12</sup> <sup>13</sup> 04111-74191 10/89→ <b>02-52860-02</b> <sup>12</sup> 04112-74190	<b>61-52860-00</b> 11115-74040 87,5 Ø 	<b>14-55003-01</b> 90109-10132 (10x) 	<b>15-52803-01</b> 	<b>12-52799-02</b> 90913-02062 (8x) +90913-02066 (8x) 	<b>71-52801-00</b> 17177-74070 		<b>71-52802-00</b> 17173-74040 	<b>70-31414-10</b> 	<b>81-53274-00 K</b> ← 90311-42003 42x60x7 A SL RD NBR <b>81-53332-00 K</b> → 90311-85003 85x105x10 A SL LD FPM <b>81-53256-00 N</b> 90311-38017 38x50x8 A SL RD NBR
2,0 3S-FE	90-94 kW (122-129 PS)	AVENSIS PICNIC RAV	05/96-12/01	<b>01-52865-01</b> <sup>12</sup> <sup>13</sup> 04111-74592  <b>02-52865-01</b> <sup>12</sup> 04112-74592	<b>61-52865-00</b> 11115-74110 87 Ø MLS 	<b>14-55003-01</b> 90109-10132 (10x) 	<b>15-52803-01</b> 	<b>12-52799-01</b> 90913-02066 (8x) +90913-02090 (8x) 	<b>71-52801-00</b> 17177-74070 		<b>71-52802-00</b> 17173-74040 	<b>70-31414-10</b> 	<b>81-53274-00 K</b> ← 90311-42003 42x60x7 A SL RD NBR <b>81-53332-00 K</b> → 90311-85003 85x105x10 A SL LD FPM <b>81-53256-00 N</b> 90311-38017 38x50x8 A SL RD NBR
2,0 3S-FE	93 kW (126 PS)	CARINA	12/92-09/97	<b>01-52860-03</b> <sup>12</sup> <sup>13</sup> 04111-74191 <b>02-52860-02</b> <sup>12</sup> 04112-74190	<b>61-52860-00</b> 11115-74040 87,5 Ø 	<b>14-55003-01</b> 90109-10132 (10x) 	<b>15-52803-01</b> 	<b>12-52799-02</b> 90913-02062 (8x) +90913-02066 (8x) 	<b>71-52801-00</b> 17177-74070 		<b>71-52802-00</b> 17173-74040 	<b>70-31414-10</b> 	<b>81-53274-00 K</b> ← 90311-42003 42x60x7 A SL RD NBR <b>81-53332-00 K</b> → 90311-85003 85x105x10 A SL LD FPM <b>81-53256-00 N</b> 90311-38017 38x50x8 A SL RD NBR
2,0 3S-FE	94 kW (128 PS)	CAMRY	11/86-05/91	<b>01-52860-02</b> <sup>12</sup> <sup>13</sup> 04111-74053  <b>02-52860-02</b> <sup>12</sup> 04112-74190	<b>61-52860-00</b> 11115-74040 87,5 Ø 	<b>14-55003-01</b> 90109-10132 (10x) 	<b>15-52803-01</b> 	<b>12-52799-02</b> 90913-02062 (8x) +90913-02066 (8x) 	<b>71-52801-00</b> 17177-74070 		<b>71-52802-00</b> 17173-74040 	<b>70-31414-10</b> 	<b>81-53274-00 K</b> ← 90311-42003 42x60x7 A SL RD NBR <b>81-53332-00 K</b> → 90311-85003 85x105x10 A SL LD FPM <b>81-53256-00 N</b> 90311-38017 38x50x8 A SL RD NBR

TOYOTA													
Ltr.													
2,0 3S-FE	98 kW (133 PS)	CARINA	04/92-09/97	<b>01-52860-01</b> <sup>12</sup> <sup>13</sup> 04111-74490  <b>02-52860-01</b> <sup>12</sup> 04112-74490	<b>61-52860-00</b> 11115-74040 87,5 Ø 	<b>14-55003-01</b> 90109-10132 (10x) 	<b>15-52803-01</b> 	<b>12-52799-01</b> 90913-02066 (8x) +90913-02090 (8x) 	<b>71-52801-00</b> 17177-74070 		<b>71-52802-00</b> 17173-74040 	<b>70-31414-10</b> 	<b>81-53274-00 K</b> ← 90311-42003 42x60x7 A SL RD NBR <b>81-53332-00 K</b> → 90311-85003 85x105x10 A SL LD FPM <b>81-53256-00 N</b> 90311-38017 38x50x8 A SL RD NBR
2,0 3S-GE	115 kW (156 PS)	MR 2	12/89-05/00	<b>01-52597-04</b> <sup>12</sup> <sup>13</sup> 04111-74220  <b>02-52597-04</b> <sup>12</sup> 04112-74220	<b>61-52597-00</b> 11115-88382 88 Ø 		<b>15-53691-01</b> 11214-88381 +11213-88381 +90210-07001 (10x) 	<b>12-52799-01</b> 90913-02066 (8x) +90913-02090 (8x) 	<b>71-53737-00</b> 17177-74060  <b>71-53738-00</b> <sup>10</sup> 17171-74020 		<b>71-53689-00</b> 17173-88382 	2x <b>70-31414-10</b> 	<b>81-53274-00 K</b> ← 90311-42003 42x60x7 A SL RD NBR <b>81-53556-00 K</b> → 90311-89013 89x105x10 SL LD FPM <b>81-53247-00 N</b> 2x 90311-35040 35x49x6 A SL RD MVQ
2,0 3S-GEL 3S-GELC	103-110 kW (140-150 PS)	CELICA	08/85-08/89	<b>01-52600-01</b> <sup>12</sup> <sup>13</sup> 04111-74042 Mot.→8999999 <b>01-52600-02</b> <sup>12</sup> <sup>13</sup> 04111-74033 Mot.90000000→ <b>02-52600-01</b> <sup>12</sup> 04112-74041 Mot.→8999999 <b>02-52600-02</b> <sup>12</sup> 04112-74031 Mot.90000000→	<b>61-52600-00</b> 11115-88362 88 Ø 		<b>15-52601-01</b> 	<b>12-52829-01</b> 90913-02062 (16x) 	<b>71-52606-00</b> 17177-88360 		<b>71-52607-00</b> 17173-88362 	2x <b>70-31414-10</b> 	<b>81-53274-00 K</b> ← 90311-42003 42x60x7 A SL RD NBR Mot.→8999999 <b>81-53247-00 N</b> 2x 90311-35040 35x49x6 A SL RD MVQ
2,0 3S-GELU	110 kW (150 PS)	CELICA	08/85-08/89	<b>01-52600-02</b> <sup>12</sup> <sup>13</sup> 04111-74033 <b>02-52600-02</b> <sup>12</sup> 04112-74031	<b>61-52600-00</b> 11115-88362 88 Ø 		<b>15-52601-01</b> 	<b>12-52829-01</b> 90913-02062 (16x) 	<b>71-52606-00</b> 17177-88360 		<b>71-52607-00</b> 17173-88362 	2x <b>70-31414-10</b> 	<b>81-53274-00 K</b> ← 90311-42003 42x60x7 A SL RD NBR <b>81-53247-00 N</b> 2x 90311-35040 35x49x6 A SL RD MVQ
2,0 3S-GELU	110 kW (150 PS)	CELICA	01/87-08/89	<b>01-52600-01</b> <sup>12</sup> <sup>13</sup> 04111-74042 <b>02-52600-01</b> <sup>12</sup> 04112-74041	<b>61-52600-00</b> 11115-88362 88 Ø 		<b>15-52601-01</b> 	<b>12-52829-01</b> 90913-02062 (16x) 	<b>71-52606-00</b> 17177-88360 		<b>71-52607-00</b> 17173-88362 	2x <b>70-31414-10</b> 	<b>81-53274-00 K</b> ← 90311-42003 42x60x7 A SL RD NBR <b>81-53247-00 N</b> 90311-35040 35x49x6 A SL RD MVQ
2,0 3S-GTE	136 kW (185 PS)	CELICA	03/88-08/89	<b>01-52597-01</b> <sup>12</sup> <sup>13</sup> 04111-74062  <b>02-52597-01</b> <sup>12</sup> 04112-74062	<b>61-52597-00</b> 11115-88382 88 Ø 		<b>15-52601-01</b> 	<b>12-52829-01</b> 90913-02062 (16x) 	<b>71-52606-00</b> 17177-88360 		<b>71-52603-00</b> 17173-88380 	2x <b>70-31414-10</b> 	<b>81-53274-00 K</b> ← 90311-42003 42x60x7 A SL RD NBR <b>81-53332-00 K</b> → 90311-85003 85x105x10 A SL LD FPM <b>81-53247-00 N</b> 90311-35040 35x49x6 A SL RD MVQ

TOYOTA													
2,0 3Y	65-79 kW (88-107 PS)	DYNA F BUS SUPER HILUX	01/84-08/88	01-52181-02 <sup>(12)</sup> <sup>(13)</sup> 04111-73010 02-52181-02 <sup>(12)</sup> 04112-73010	61-52181-20 11115-73041 88 Ø 	14-32179-01 	71-52177-00 11213-71020 	12-52928-01 90913-02116 (8x) 12-52928-02 90913-02117 (8x) 70-52928-00 90913-02116 70-52928-10 90913-02117	8x 8x	71-52624-00 <sup>(7)</sup> 17172-73010 08/85→ 	70-31414-10 	81-53274-00 K ← 90311-42003 42x60x7 A SL RD NBR 81-53319-00 K → 90311-80007 80x100x8,5 A SL LD FPM	
2,0 3Y	79 kW (107 PS)	DYNA	08/85-08/88	01-52181-02 <sup>(12)</sup> <sup>(13)</sup> 04111-73010 02-52181-02 <sup>(12)</sup> 04112-73010	61-52181-20 11115-73041 88 Ø 	14-32179-01 	71-52177-00 11213-71020 	12-52928-01 90913-02116 (8x) 12-52928-02 90913-02117 (8x) 70-52928-00 90913-02116 70-52928-10 90913-02117	8x 8x	71-52624-00 <sup>(7)</sup> 17172-73010 	70-31414-10 	81-53274-00 K ← 90311-42003 42x60x7 A SL RD NBR 81-53319-00 K → 90311-80007 80x100x8,5 A SL LD FPM	
2,0 3ZR-FAE	112-116 kW (152-158 PS)	AVENSIS WISH	11/08→	01-54025-03 <sup>(12)</sup> <sup>(13)</sup> <sup>(19)</sup> 04111-37201 02-54025-03 <sup>(12)</sup> <sup>(19)</sup> 04112-37201	61-54025-00 11115-37060 0,7 mm MLS 	14-32326-01 90910-02166 (10x) 	15-54083-01 11213-0T020 +11193-0T010 (4x) 	12-54024-01 90080-31084 (8x) +90080-31085 (8x) 70-54024-00 ES 90080-31084 70-54026-00 AS 90080-31085	8x 8x	71-54086-00 17177-37030 	71-37166-00 17173-0T020 	70-31414-10 	81-34146-00 K ← 90311-W0012 38x50x6 A SL RD FPM 81-54087-00 K → 90311-W0011 78x110x8,5 A SL LD FPM
2,0 3ZR-FAE	114-116 kW (155-158 PS)	NOAH RAV 4	06/07→	01-54065-01 <sup>(12)</sup> <sup>(13)</sup> <sup>(19)</sup> 04111-37200 →02/09 01-54025-03 <sup>(12)</sup> <sup>(13)</sup> <sup>(19)</sup> 04111-37201 03/09→ 02-54065-01 <sup>(12)</sup> <sup>(19)</sup> 04112-37200 →02/09 02-54025-03 <sup>(12)</sup> <sup>(19)</sup> 04112-37201 03/09→	61-54065-00 11115-37040 0,7 mm MLS →02/09  61-54025-00 11115-37060 0,7 mm MLS 03/09→ 	14-32326-01 90910-02166 (10x) 	15-54083-01 11213-0T020 +11193-0T010 (4x) 	12-54024-01 90080-31084 (8x) +90080-31085 (8x) 70-54024-00 ES 90080-31084 70-54026-00 AS 90080-31085	8x 8x	71-54086-00 17177-37030 	71-37166-00 17173-0T020 	70-31414-10 	81-34146-00 K ← 90311-W0012 38x50x6 A SL RD FPM 81-54087-00 K → 90311-W0011 78x110x8,5 A SL LD FPM
2,0 3ZR-FE <b>[NEW]</b>	107-116 kW (146-158 PS)	AVENSIS COROLLA WISH	11/08→	01-54025-01 <sup>(12)</sup> <sup>(13)</sup> 04111-0T081 02-54025-01 <sup>(12)</sup> 04112-0T011	61-54025-00 11115-37060 0,7 mm MLS 	14-32326-01 90910-02166 (10x) 	15-54083-01 11213-0T020 +11193-0T010 (4x) 	12-54024-01 90080-31084 (8x) +90080-31085 (8x) 70-54024-00 ES 90080-31084 70-54026-00 AS 90080-31085	8x 8x	71-54086-00 17177-37030 	71-37166-00 17173-0T020 	70-31414-10 	81-34146-00 K ← 90311-W0012 38x50x6 A SL RD FPM 81-54087-00 K → 90311-W0011 78x110x8,5 A SL LD FPM
2,2 L	46-53 kW (63-72 PS)	CRESSIDA D CROWN D HIACE D	01/79-11/89	01-52133-03 <sup>(12)</sup> <sup>(13)</sup> 04111-54035 02-52133-03 <sup>(12)</sup> 04112-54035	61-52133-00 11115-54012 95 Ø 		15-52209-01 11213-54030 +90210-13001 (3x) 	12-53647-01 90913-02060 (8x) 70-53647-00 90913-02060	8x	71-52609-00 17177-54012 	71-52611-00 17173-54011 	71-52208-00 12151-54020 	81-53274-00 K ← 90311-42003 42x60x7 A SL RD NBR 81-53274-00 N 90311-42003 42x60x7 A SL RD NBR

TOYOTA													
2,2 Ltr.	2AD-FHV 2AD-FTV	100-130 kW (136-177 PS)	AURIS D AVENSIS D AVENSIS D- CAT AVENSIS D-4D COROLLA D COROLLA D-4D COROLLA D4d RAV D-CAT RAV D-4D RAV 4 D-4D RAV 4	07/05→ 	 <b>01-53930-01</b> <sup>12</sup> <sup>13</sup> 04111-0R180  <b>02-53930-01</b> <sup>12</sup> 04112-0R180 	 <b>61-53930-00</b> 11115-26052-A0 87 Ø 1 mm 1 MLS <b>61-53930-10</b> 11115-26052-B0 87 Ø 1,05 mm 2 MLS <b>61-53930-20</b> 11115-26052-C0 87 Ø 1,1 mm 3 MLS <b>61-53930-30</b> 11115-26052-D0 87 Ø 1,15 mm 4 MLS <b>61-53930-40</b> 11115-26052-E0 87 Ø 1,2 mm 5 MLS 	 <b>14-32327-01</b> 90910-02158 (10x) 	 <b>15-54074-01</b> 11213-26010 +11214-26010 	 <b>12-53854-01</b> 90913-W2001 (16x) <b>70-53854-00</b> 90913-W2001	 <b>71-54073-00</b> 17171-0R010 16x 	 <b>71-35180-00</b> 17173-0R010 	 <b>70-31414-10</b> 	 <b>81-54078-00 K</b> ← 90311-W0009 48x63x6,5 A SL RD FPM <b>81-54079-00 K</b> → 90311-W0010 90x106x8,5 A SL LD FPM
2,2 3C-TE	66 kW (90 PS)	PICNIC D	08/97-12/01	 <b>01-52929-01</b> <sup>12</sup> <sup>13</sup> 04111-64364   <b>02-52929-01</b> <sup>12</sup> 04112-64272 	 <b>61-53150-00</b> 11115-64200-01 87 Ø 1,25 mm 1 MLS <b>61-53150-10</b> 11115-64200-02 87 Ø 1,35 mm 2 MLS <b>61-53150-20</b> 11115-64200-03 87 Ø 1,45 mm 3 MLS 		 <b>71-52929-00</b> 11213-64061 	 <b>12-52928-01</b> 90913-02116 (8x) <b>12-52928-02</b> 90913-02117 (8x) <b>70-52928-00</b> 90913-02116 <b>70-52928-10</b> 90913-02117	 <b>71-52642-00</b> 17177-64010 8x 	 <b>71-53418-00</b> 17173-64090 8x 	 <b>70-31414-10</b> 	 <b>81-53274-00 K</b> ← 90311-42003 42x60x7 A SL RD NBR <b>81-53341-00 K</b> → 90311-90008 90x110x9,5 A SL LD FPM/ACM <b>81-53256-00 N</b> 90311-38017 38x50x8 A SL RD NBR	
2,2 4Y 4Y-EC	69-72 kW (94-98 PS)	F BUS HILUX LITEACE	01/87-01/95	 <b>01-53110-01</b> <sup>12</sup> <sup>13</sup> 04111-73045 <b>02-53110-01</b> <sup>12</sup> 04111-73043 	 <b>61-53110-00</b> 11115-73030 93 Ø 1,6 mm <b>61-53110-10</b> 93 Ø 2 mm 	 <b>14-32179-01</b> 	 <b>71-52177-00</b> 11213-71020 	 <b>12-52928-01</b> 90913-02116 (8x) <b>12-52928-02</b> 90913-02117 (8x) <b>70-52928-00</b> 90913-02116 <b>70-52928-10</b> 90913-02117	 <b>71-52624-00</b> <sup>7</sup> 17172-73010 8x 	 <b>70-31414-10</b> 	 <b>81-53274-00 K</b> ← 90311-42003 42x60x7 A SL RD NBR <b>81-53319-00 K</b> → 90311-80007 80x100x8,5 A SL LD FPM		
2,2 5S-FE 5S-FNE	96 kW (131 PS)	CAMRY	08/96-11/01	 <b>01-53160-01</b> <sup>12</sup> <sup>13</sup> 04111-74641 <b>02-53160-01</b> <sup>12</sup> 04112-74581 	 <b>61-53160-00</b> 11115-74120 88 Ø MLS 	 <b>14-55003-01</b> 90109-10132 (10x) 	 <b>15-52803-01</b> 	 <b>12-52799-01</b> 90913-02066 (8x) +90913-02090 (8x)	 <b>71-52801-00</b> 17177-74070 8x 	 <b>71-52802-00</b> 17173-74040 8x 	 <b>70-31414-10</b> 	 <b>81-53274-00 K</b> ← 90311-42003 42x60x7 A SL RD NBR <b>81-53332-00 K</b> → 90311-85003 85x105x10 A SL LD FPM <b>81-53256-00 N</b> 90311-38017 38x50x8 A SL RD NBR	

TOYOTA													
Ltr.													
2,2 5S-FE	100 kW (136 PS) CAMRY	06/91-08/96	<b>01-52855-01</b> <sup>12</sup> <sup>13</sup> 04111-64421 →08/95  <b>01-52855-02</b> <sup>12</sup> <sup>13</sup> 04111-64178 09/95→  <b>02-52855-01</b> <sup>12</sup> 04112-74292	<b>61-52855-00</b> 11115-74081 88 Ø 	<b>14-55003-01</b> 90109-10132 (10x) 	<b>15-52803-01</b> 	<b>12-52799-01</b> 90913-02066 (8x) +90913-02090 (8x)	<b>71-52801-00</b> 17177-74070 		<b>71-52802-00</b> 17173-74040  <b>71-52919-00</b> <sup>10</sup> 90917-06039 →08/95 	<b>70-31414-10</b> 	<b>81-53274-00</b> K ← 90311-42003 42x60x7 A SL RD NBR <b>81-53332-00</b> K → 90311-85003 85x105x10 A SL LD FPM <b>81-53256-00</b> N 90311-38017 38x50x8 A SL RD NBR	
2,4 2AZ-FE	112-125 kW (152-170 PS) CAMRY CAMRY VVT-i CAMRY VVTi PREVIA TARAGO	08/00→	<b>01-53515-01</b> <sup>12</sup> <sup>13</sup> 04111-28056 <b>02-53515-01</b> <sup>12</sup> 04112-28056	<b>61-53515-00</b> 11115-28012 90 Ø 0,5 mm MLS 		<b>71-53574-00</b> 11213-28021 	<b>12-54024-01</b> 90080-31084 (8x) +90080-31085 (8x)	<b>71-53568-00</b> 17177-28010 		<b>71-53554-00</b> 17173-28010 	<b>70-31414-10</b> 	<b>81-53556-00</b> K → 90311-89013 89x105x10 SL LD FPM <b>81-53256-00</b> N 90311-38017 38x50x8 A SL RD NBR	
2,4 2AZ-FSE	120-125 kW (163-170 PS) AVENSIS	09/03-11/08	<b>01-54260-01</b> <sup>12</sup> <sup>13</sup> <sup>19</sup> 04111-28810 <b>02-54260-01</b> <sup>12</sup> <sup>19</sup> 04112-28670	<b>61-54260-00</b> 11115-28040 90 Ø 0,5 mm MLS 	<b>14-32386-01</b> 90910-02141 (10x) 	<b>71-53567-00</b> 11213-28041 	<b>12-54024-01</b> 90080-31084 (8x) +90080-31085 (8x) <b>70-54024-00</b> ES 90080-31084 <b>70-54026-00</b> AS 90080-31085	<b>71-53552-00</b> 17171-28010  <b>71-53553-00</b> <sup>10</sup> 17177-28020 		<b>71-53554-00</b> 17173-28010 	<b>70-31414-10</b> 	<b>81-34146-00</b> K ← 90311-W0012 38x50x6 A SL RD FPM <b>81-53556-00</b> K → 90311-89013 89x105x10 SL LD FPM	
2,4 2AZ-FXE	105-110 kW (143-150 PS) ALPHARD CAMRY VVTi PREVIA	01/06→		<b>61-54260-00</b> 11115-28040 90 Ø 0,5 mm MLS 	<b>14-32333-03</b> 90910-02162 (10x) 	<b>71-53574-00</b> 11213-28021 	<b>12-54024-01</b> 90080-31084 (8x) +90080-31085 (8x) <b>70-54024-00</b> ES 90080-31084 <b>70-54026-00</b> AS 90080-31085	<b>71-53568-00</b> 17177-28010  8x <b>71-53553-00</b> <sup>10</sup> 17177-28020  8x		<b>71-53554-00</b> 17173-28010 	<b>70-31414-10</b> 	<b>81-34146-00</b> K ← 90311-W0012 38x50x6 A SL RD FPM <b>81-53556-00</b> K → 90311-89013 89x105x10 SL LD FPM	
2,4 2L	53-55 kW (72-75 PS) HIACE D HILUX D LAND CRUISER D	01/84-11/89	<b>02-52134-01</b> <sup>12</sup> 04112-54043	<b>61-52134-00</b> 11115-54021 94,8 Ø 	<b>14-55064-01</b> 90910-02090 (18x) 	<b>15-52209-01</b> 11213-54030 +90210-13001 (3x) 	<b>12-53647-01</b> 90913-02060 (8x) <b>70-53647-00</b> 90913-02060	<b>71-52609-00</b> 17177-54012  8x		<b>71-52611-00</b> 17173-54011  <b>71-52983-00</b> <sup>10</sup> 	<b>71-52208-00</b> 12151-54020 	<b>81-53274-00</b> K ← 90311-42003 42x60x7 A SL RD NBR <b>81-53332-00</b> K → 90311-85003 85x105x10 A SL LD FPM <b>81-53274-00</b> N 90311-42003 42x60x7 A SL RD NBR	

TOYOTA												
Ltr.												
2,4 2L	55-59 kW (75-80 PS)	HIACE D HILUX D	10/88-08/06	<b>01-52750-03</b> <sup>12</sup> <sup>13</sup> 04111-54084  <b>02-52750-03</b> <sup>12</sup> 04112-54073 	<b>61-52750-10</b> 11115-54084-B0 93,5 Ø 1,45 mm MLS <b>61-52750-20</b> 11115-54084-D0 93,5 Ø 1,55 mm MLS <b>61-52750-30</b> 11115-54084-F0 93,5 Ø 1,65 mm MLS 	<b>14-55000-01</b> 90910-02080 (14x) +90910-02081 (4x) 	<b>71-52644-00</b> 11213-54050 	<b>12-52928-01</b> 90913-02116 (8x) <b>70-52928-00</b> 90913-02116 8x 	<b>71-52981-00</b> 17177-54020 8x 	<b>71-52982-00</b> 17173-54030  <b>71-52983-00</b> <sup>A</sup> 	<b>70-31414-10</b> 	<b>81-53274-00</b> K ← 90311-42003 42x60x7 A SL RD NBR <b>81-53332-00</b> K → 90311-85003 85x105x10 A SL LD FPM <b>81-53234-00</b> N 90311-32017 32x46x6 A SL RD MVQ
2,4 2L-T	63-66 kW (86-90 PS)	CRESSIDA TD LAND CRUISER TD	05/85-05/90	<b>01-52134-03</b> <sup>12</sup> <sup>13</sup> 04111-54041 <b>02-52134-03</b> <sup>12</sup> 04112-54032	<b>61-52134-00</b> 11115-54021 94,8 Ø 	<b>14-55064-01</b> 90910-02090 (18x) 	<b>15-52209-01</b> 11213-54030 +90210-13001 (3x) 	<b>12-53647-01</b> 90913-02060 (8x) <b>70-53647-00</b> 90913-02060 8x 	<b>71-52609-00</b> 17177-54012 8x 	<b>71-52632-00</b> 17173-54020  <b>71-52983-00</b> <sup>A</sup> 	<b>71-52208-00</b> 12151-54020 	<b>81-53274-00</b> K ← 90311-42003 42x60x7 A SL RD NBR <b>81-53332-00</b> K → 90311-85003 85x105x10 A SL LD FPM <b>81-53274-00</b> N 90311-42003 42x60x7 A SL RD NBR
2,4 2L-T	66 kW (90 PS)	HIACE TD HILUX TD LAND CRUISER TD	08/89-08/06	<b>01-52750-02</b> <sup>12</sup> <sup>13</sup> 04111-54103   <b>02-52750-02</b> <sup>12</sup> 04112-54101 	<b>61-52750-10</b> 11115-54084-B0 93,5 Ø 1,45 mm MLS <b>61-52750-20</b> 11115-54084-D0 93,5 Ø 1,55 mm MLS <b>61-52750-30</b> 11115-54084-F0 93,5 Ø 1,65 mm MLS 	<b>14-55000-01</b> 90910-02080 (14x) +90910-02081 (4x) 	<b>71-52644-00</b> 11213-54050 	<b>12-52928-02</b> 90913-02117 (8x) <b>70-52928-10</b> 90913-02117 8x 	<b>71-52981-00</b> 17177-54020 8x 	<b>71-53729-00</b> 17173-54050  <b>71-52983-00</b> <sup>A</sup> 	<b>70-31414-10</b> 	<b>81-53274-00</b> K ← 90311-42003 42x60x7 A SL RD NBR <b>81-53332-00</b> K → 90311-85003 85x105x10 A SL LD FPM <b>81-53234-00</b> N 90311-32017 32x46x6 A SL RD MVQ
2,4 2L-TE			08/82-08/84	<b>01-52134-03</b> <sup>12</sup> <sup>13</sup> 04111-54041 <b>02-52134-03</b> <sup>12</sup> 04112-54032	<b>61-52134-00</b> 11115-54021 94,8 Ø 	<b>14-55064-01</b> 90910-02090 (18x) 	<b>15-52209-01</b> 11213-54030 +90210-13001 (3x) 	<b>12-53647-01</b> 90913-02060 (8x) <b>70-53647-00</b> 90913-02060 8x 	<b>71-52609-00</b> 17177-54012 8x 	<b>71-52632-00</b> 17173-54020 	<b>71-52208-00</b> 12151-54020 	<b>81-53274-00</b> K ← 90311-42003 42x60x7 A SL RD NBR <b>81-53332-00</b> K → 90311-85003 85x105x10 A SL LD FPM <b>81-53274-00</b> N 90311-42003 42x60x7 A SL RD NBR
2,4 2RZ-E	85-88 kW (115-120 PS)	HIACE	08/89-02/05	<b>01-53080-01</b> <sup>12</sup> <sup>13</sup> 04111-75041 <b>02-53080-01</b> <sup>12</sup> 04112-75040	<b>61-53080-00</b> 11115-75020 96,5 Ø 	<b>14-55030-01</b> 90910-02091 (10x) 	<b>71-53001-00</b> 11213-75020 	<b>12-52928-01</b> 90913-02116 (8x) <b>12-52928-02</b> 90913-02117 (8x) <b>70-52928-00</b> 90913-02116 8x <b>70-52928-10</b> 90913-02117 8x 	<b>71-52997-00</b> 17177-75010 8x 	<b>71-52998-00</b> 17173-75010  <b>71-52999-00</b> <sup>A</sup> 	<b>70-31414-10</b> 	<b>81-53649-00</b> K ← 90311-48029 48x68x7 A SL RD MVQ <b>81-53337-00</b> K → 90311-88005 88x106x8,5 A SL LD MVQ



TOYOTA													
Ltr.			<b>1</b>										
2,4 2RZ-FE	103 kW (140 PS) HILUX	08/97-07/05	<b>01-53095-01</b> ⑫ ⑬ 04111-75092 <b>02-53095-01</b> ⑫ 04112-75091	<b>61-53095-00</b> 11115-75031 97 Ø 	<b>14-55030-01</b> 90910-02091 (10x) 	<b>15-53016-01</b> 11213-75030 +11193-15010 (4x) +90210-07001 (10x) 	<b>12-53057-01</b> 90913-02071 (16x) 	<b>71-53011-00</b> 17173-75020 	<b>71-53013-00</b> 17173-75020 	<b>70-31414-10</b> 	<b>81-53649-00</b> K ← 90311-48029 48x68x7 A SL RD MVQ <b>81-53337-00</b> K → 90311-88005 88x106x8,5 A SL LD MVQ		
2,4 2TZ-FE	97 kW (132 PS) PREVIA	05/90-08/00	<b>01-52850-01</b> ⑫ ⑬ 04111-76071 	<b>61-52850-00</b> 11115-76030 97 Ø 	<b>14-55030-01</b> 90910-02091 (10x) 	<b>15-52796-01</b> 	<b>12-52806-03</b> 90913-02085 (8x) +90913-02090 (8x) 	<b>71-52793-00</b> 17177-76020 	<b>71-52794-00</b> 17173-76010 	<b>70-31414-10</b> 	<b>81-53649-00</b> K ← 90311-48029 48x68x7 A SL RD MVQ <b>81-53337-00</b> K → 90311-88005 88x106x8,5 A SL LD MVQ		
2,4 22R 22RE	77-84 kW (105-114 PS) LAND CRUISER	11/84-12/96	<b>01-52605-01</b> ⑫ ⑬ 04111-35070 <b>02-52605-01</b> ⑫ 04112-35060	<b>61-52605-00</b> 11115-35030 94,5 Ø 	<b>14-32180-01</b> 90910-02058 (10x) 	<b>15-52187-01</b> 	<b>12-52928-01</b> 90913-02116 (8x) →11/92 <b>12-52928-02</b> 90913-02117 (8x) →11/92 <b>70-52928-00</b> 90913-02116 →11/92 <b>70-52928-10</b> 90913-02117 →11/92	<b>71-53022-00</b> 17177-35022 	<b>71-53023-00</b> ⑩ 17176-35020 	<b>71-53024-00</b> 17173-35120 	<b>71-53026-00</b> 12151-38010 	<b>81-53282-00</b> K ← 90311-45002 45x68x12 A SL RD ACM <b>81-53353-00</b> K → 80x100x12 A SL LD MVQ <b>81-53247-00</b> N 90311-35040 35x49x6 A SL RD MVQ	
2,4 22REC	82 kW (112 PS) 4 RUNNER	08/87-07/89	<b>01-52605-01</b> ⑫ ⑬ 04111-35070 <b>02-52605-01</b> ⑫ 04112-35060	<b>61-52605-00</b> 11115-35030 94,5 Ø 	<b>14-32180-01</b> 90910-02058 (10x) 	<b>15-52187-01</b> 	<b>12-52928-01</b> 90913-02116 (8x) <b>12-52928-02</b> 90913-02117 (8x) <b>70-52928-00</b> 90913-02116 <b>70-52928-10</b> 90913-02117	<b>71-53022-00</b> 17177-35022 	<b>71-53023-00</b> ⑩ 17176-35020 	<b>71-53024-00</b> 17173-35120 	<b>71-53026-00</b> 12151-38010 	<b>81-53282-00</b> K ← 90311-45002 45x68x12 A SL RD ACM <b>81-53353-00</b> K → 80x100x12 A SL LD MVQ <b>81-53247-00</b> N 90311-35040 35x49x6 A SL RD MVQ	
2,5 2AR-FE <b>[NEW]</b>	129-133 kW (175-181 PS) CAMRY ZELAS	01/10→	<b>01-10065-01</b> ⑫ ⑬ ⑰ 04111-36114 <b>02-10065-01</b> ⑫ ⑰ 04112-36092	<b>61-10152-00</b> 11115-36030 91 Ø 0,7 mm MLS 	<b>14-32333-03</b> 90910-02162 (10x) 	<b>15-10582-01</b> 11213-36020 +11193-36010 (4x) 	<b>12-54024-01</b> 90080-31084 (8x) +90080-31085 (8x) <b>70-54024-00</b> ES 90080-31084 <b>70-54026-00</b> AS 90080-31085	<b>71-10584-00</b> 17171-36020 	<b>71-10585-00</b> 17173-36020 	<b>70-31414-10</b> 	<b>81-10416-00</b> K ← 90311-42051 42x54x6 A SL RD <b>81-53556-00</b> K → 90311-89013 89x105x10 SL LD FPM		
2,5 2AR-FXE <b>[NEW]</b>	118 kW (160 PS) CAMRY	09/11→	<b>01-10065-01</b> ⑫ ⑬ ⑰ 04111-36114 <b>02-10065-01</b> ⑫ ⑰ 04112-36092	<b>61-10065-00</b> 11115-36040 91 Ø 0,7 mm MLS 	<b>14-32333-03</b> 90910-02162 (10x) 	<b>15-10582-01</b> 11213-36020 +11193-36010 (4x) 	<b>12-54024-01</b> 90080-31084 (8x) +90080-31085 (8x) <b>70-54024-00</b> ES 90080-31084 <b>70-54026-00</b> AS 90080-31085	<b>71-10584-00</b> 17171-36020 	<b>71-10585-00</b> 17173-36020 	<b>70-31414-10</b> 	<b>81-10416-00</b> K ← 90311-42051 42x54x6 A SL RD <b>81-53556-00</b> K → 90311-89013 89x105x10 SL LD FPM		

TOYOTA												
Ltr.												
2,5 2KD-FTV	65-88 kW (88-120 PS)	HIACE D HIACE D-4D HIACE D4d HILUX D HILUX D-4D HILUX D4d	08/01→	<b>01-53559-01</b> <sup>12</sup> <sup>13</sup> 04111-30420 <b>02-53559-01</b> <sup>12</sup> 04112-30070	<b>61-53510-00</b> 11115-30040-A0 93,5 Ø 0,7 mm 1 MLS <b>61-53510-10</b> 11115-30040-B0 93,5 Ø 0,75 mm 2 MLS <b>61-53510-20</b> 11115-30040-C0 93,5 Ø 0,8 mm 3 MLS <b>61-53510-30</b> 11115-30040-D0 93,5 Ø 0,85 mm 4 MLS <b>61-53510-40</b> 11115-30040-E0 93,5 Ø 0,9 mm 5 MLS 	<b>14-32388-01</b> 90910-02145 (10x) +90910-02146 (8x) 	<b>71-54011-00</b> 11213-0L010 ACM 	<b>12-53457-02</b> 90913-02121 (16x) 	<b>71-54012-00</b> 17177-0L011 	<b>71-53168-00</b> 17173-30020 	<b>70-31414-10</b> 	<b>81-53287-00</b> K ← 90311-50017 50x68x14 A SL RD FPM <b>81-53561-00</b> K ← 90080-31098 65x79x7 A SL RD FPM <b>81-53348-00</b> K → 90311-95008 95x115x12 A SL LD MVQ <b>81-53234-00</b> N 90311-32017 32x46x6 A SL RD MVQ
2,5 2MZ-FE <b>[NEW]</b>	147 kW (200 PS)	WINDOM	10/96-07/01	<b>01-54300-01</b> <sup>12</sup> <sup>13</sup> 04111-20041 →12/99 <b>01-54310-01</b> <sup>12</sup> <sup>13</sup> <sup>19</sup> 04111-20043 01/00→ <b>02-54300-01</b> <sup>12</sup> 04112-20031 →12/99 <b>02-54310-01</b> <sup>12</sup> <sup>19</sup> 04112-20033 01/00→	<b>61-54300-00</b> R 11115-20010 →12/99  <b>61-54305-00</b> L 11116-20010 →12/99  <b>61-54310-00</b> R 11115-20042 88,9 Ø 1,3 mm MLS 01/00→  <b>61-54315-00</b> L 11116-20042 88,9 Ø 1,3 mm MLS 01/00→ 	<b>14-32392-01</b> 90910-02117 (8x) 	2x <b>15-43042-01</b> R 11213-20020 +11193-70010 (3x)  <b>15-43043-01</b> L 11214-20010 +11193-70010 (3x) 	<b>12-54024-03</b> 90913-02101 (6x) +90913-02112 (6x) <b>70-54024-00</b> ES 90080-31084 <b>70-54026-00</b> AS 90080-31085	2x <b>71-43044-00</b> R 17177-20020  12x <b>71-43046-00</b> L 17178-20020  12x <b>71-43047-00</b> <sup>19</sup> 17176-62030 	<b>71-43048-00</b> 17173-20030 	2x <b>70-31414-10</b> 	<b>81-53576-00</b> K ← 90311-40013 40x55x6 A SL RD <b>81-53344-10</b> K → 90311-92010 92x110x8,5 A SL LD FPM <b>81-53572-00</b> N 2x 90311-38034 38x50x10,5 A SL RD FPM

TOYOTA												
Ltr.												
2,5 2VZ-FE	118 kW (160 PS)	CAMRY V6	02/88-05/91	<b>02-52940-01</b> ⑫ 04112-62020	<b>61-52940-00 R</b> 11115-62060 89,5 Ø  <b>61-53120-00 L</b> 11116-62060 89,5 Ø 	<b>15-52884-01</b> 2x 	<b>12-53057-02</b> 90913-02071 (24x)	<b>71-52893-00</b> 2x 17177-62030 	<b>71-52894-00</b> 2x 17173-62020 	<b>70-31414-10</b> 	<b>81-53409-00 K</b> ← 35x48x7 A SL RD MVQ <b>81-53344-00 K</b> → 90311-92006 92x110x8,5 A SL LD MVQ <b>81-53256-00 N</b> 90311-38017 38x50x8 A SL RD NBR	
2,5 4GR-FSE	149 kW (203 PS)	MARK X	10/09→	<b>01-54280-01</b> ⑫ ⑬ ⑰ <b>02-54280-01</b> ⑫ ⑰ 04112-31330	<b>61-54280-00 R</b> 11115-31051 84,5 Ø 0,5 mm MLS  <b>61-54285-00 L</b> 11116-31031 84,5 Ø 0,5 mm MLS 	<b>14-32333-01</b> 2x 90910-02162 (8x) +90105-10521 (2x) 	<b>15-42847-01 R</b> 11213-31040 +11193-70010 (3x)  <b>15-42848-01 L</b> 11214-31020 +11193-70010 (3x) 	<b>12-54024-03</b> 2x 90913-02101 (6x) +90913-02112 (6x) <b>70-54024-00 ES</b> 12x 90080-31084 <b>70-54026-00 AS</b> 12x 90080-31085	<b>71-42893-00</b> 2x 17177-31021  <b>71-42979-00</b> ⑩ 3x 	<b>71-42846-00</b> 2x 17173-31020 	<b>70-31414-10</b> 	<b>81-53274-00 K</b> ← 90311-42003 42x60x7 A SL RD NBR <b>81-53344-10 K</b> → 90311-92010 92x110x8,5 A SL LD FPM
2,5 5GR-FE	145 kW (194 PS)				<b>61-54270-00 R</b> 11115-31041 89,5 Ø 0,5 mm MLS  <b>61-54275-00 L</b> 11116-31021 89,5 Ø 0,5 mm MLS 	<b>14-32333-01</b> 2x 90910-02162 (8x) +90105-10521 (2x) 	<b>15-42848-01 L</b> 11214-31020 +11193-70010 (3x)  <b>15-54132-01 R</b> 11213-31050 +11193-70010 (3x) 	<b>12-54024-03</b> 2x 90913-02101 (6x) +90913-02112 (6x) <b>70-54024-00 ES</b> 12x 90080-31084 <b>70-54026-00 AS</b> 12x 90080-31085	<b>71-42846-00</b> 2x 17173-31020 	<b>70-31414-10</b> 	<b>81-53274-00 K</b> ← 90311-42003 42x60x7 A SL RD NBR <b>81-53344-10 K</b> → 90311-92010 92x110x8,5 A SL LD FPM	
2,7 1AR-FE <b>[NEW]</b>	136-140 kW (185-190 PS)	KLUGER VENZA	05/07→	<b>01-10152-01</b> ⑫ ⑬ ⑰ 04111-36052 →06/12 <b>01-10152-02</b> ⑫ ⑬ ⑰ 04111-0V031 07/12→ <b>02-10152-01</b> ⑫ ⑰ 04112-36044 →06/12 <b>02-10152-02</b> ⑫ ⑰ 04112-0V031 07/12→	<b>61-10152-00</b> 11115-36030 91 Ø 0,7 mm MLS 	<b>14-32333-03</b> 90910-02162 (10x) 	<b>15-10582-01</b> 11213-36020 +11193-36010 (4x)  <b>71-10582-00</b> 11213-36020 	<b>12-54024-01</b> 90080-31084 (8x) +90080-31085 (8x) <b>70-54024-00 ES</b> 8x 90080-31084 <b>70-54026-00 AS</b> 8x 90080-31085	<b>71-11849-00</b> 17171-36010 	<b>71-10585-00</b> 17173-36020 →06/12  <b>71-11853-00</b> 17173-0V010 07/12→  <b>71-11858-00</b> ⚠ 17451-0V020 	<b>70-31414-10</b> 	<b>81-10416-00 K</b> ← 90311-42051 42x54x6 A SL RD <b>81-53556-00 K</b> → 90311-89013 89x105x10 SL LD FPM

TOYOTA													
2,7 2TR-FE	106-120 kW (144-163 PS)	COASTER LAND CRUISER	11/03→	<b>01-53590-02</b> ⑫ ⑬ ⑰ 04111-75864 <b>02-53590-02</b> ⑫ ⑰ 04112-75783	<b>61-53590-00</b> 11115-75051 97 Ø 0,6 mm MLS <b>61-53590-10</b> 0,9 mm 1 MLS 	<b>14-55030-01</b> 90910-02091 (10x) 	<b>15-54021-01</b> 11213-0C010 +11214-0C010 	<b>12-54024-01</b> 90080-31084 (8x) +90080-31085 (8x) <b>70-54024-00</b> ES 90080-31084 <b>70-54026-00</b> AS 90080-31085 8x 8x	<b>71-53648-00</b> 17177-0C010 	<b>71-54017-00</b> 17173-0C010 	<b>70-31414-10</b> 	<b>81-53649-00</b> K ← 90311-48029 48x68x7 A SL RD MVQ <b>81-53337-00</b> K → 90311-88005 88x106x8,5 A SL LD MVQ	
2,7 2TR-FZE	111 kW (151 PS)	QUANTUM	01/05→	<b>01-53590-01</b> ⑫ ⑬ 04111-75092 <b>02-53590-01</b> ⑫ 04112-75710	<b>61-53590-00</b> 11115-75051 97 Ø 0,6 mm MLS <b>61-53590-10</b> 0,9 mm 1 MLS 	<b>14-55030-01</b> 90910-02091 (10x) 	<b>15-54021-01</b> 11213-0C010 +11214-0C010 	<b>12-53128-02</b> 90080-31061 (8x) +90080-31062 (8x) <b>70-53993-00</b> ES 90080-31061 <b>70-53994-00</b> AS 90080-31062 8x 8x	<b>71-53648-00</b> 17177-0C010 	<b>71-53644-00</b> 17173-75040 	<b>70-31414-10</b> 	<b>81-53649-00</b> K ← 90311-48029 48x68x7 A SL RD MVQ <b>81-53337-00</b> K → 90311-88005 88x106x8,5 A SL LD MVQ	
2,7 3RZ-FE	105-106 kW (143-144 PS)	HIACE	04/98→	<b>01-53095-01</b> ⑫ ⑬ 04111-75092 <b>02-53095-01</b> ⑫ 04112-75091	<b>61-53095-00</b> 11115-75031 97 Ø 	<b>14-55030-01</b> 90910-02091 (10x) 	<b>15-53016-01</b> 11213-75030 +11193-15010 (4x) +90210-07001 (10x) 	<b>12-53057-01</b> 90913-02071 (16x) 	<b>71-53011-00</b> 17177-75020 	<b>71-53013-00</b> 17173-75020 	<b>71-53014-00</b> 	<b>70-31414-10</b> 	<b>81-53649-00</b> K ← 90311-48029 48x68x7 A SL RD MVQ <b>81-53337-00</b> K → 90311-88005 88x106x8,5 A SL LD MVQ
2,8 3L	60 kW (82 PS)	HILUX D	10/88-12/97	<b>01-52750-01</b> ⑫ ⑬ 04111-54083   <b>02-52750-01</b> ⑫ 04112-54071 	<b>61-53035-00</b> 11115-54071-B0 97,5 Ø 1,45 mm MLS <b>61-53035-10</b> 11115-54071-D0 97,5 Ø 1,55 mm MLS <b>61-53035-20</b> 11115-54071-F0 97,5 Ø 1,65 mm MLS 	<b>14-55000-01</b> 90910-02080 (14x) +90910-02081 (4x) 	<b>71-52644-00</b> 11213-54050 	<b>12-52928-01</b> 90913-02116 (8x) <b>12-52928-02</b> 90913-02117 (8x) <b>70-52928-00</b> 90913-02116 <b>70-52928-10</b> 90913-02117 8x 8x	<b>71-52981-00</b> 17177-54020 	<b>71-52982-00</b> 17173-54030 	<b>71-52983-00</b> 2x	<b>70-31414-10</b> 	<b>81-53274-00</b> K ← 90311-42003 42x60x7 A SL RD NBR <b>81-53332-00</b> K → 90311-85003 85x105x10 A SL LD FPM <b>81-53234-00</b> N 90311-32017 32x46x6 A SL RD MVQ
2,8 5M-GE	125 kW (170 PS)	CELICA CROWN	08/81-12/85	<b>01-52216-02</b> ⑫ ⑬ 04111-43040 <b>02-52216-02</b> ⑫ 04112-43040	<b>61-52216-00</b> 11115-43030 85 Ø 		<b>71-52194-10</b> 2x 11213-43020 	<b>12-52928-05</b> 90913-02116 (12x) <b>70-52928-10</b> 90913-02117 12x	<b>71-52612-00</b> 17177-43010 	<b>71-52613-00</b> 17173-43020 	<b>71-52193-00</b> 12151-41010 	<b>81-53274-00</b> K ← 90311-42003 42x60x7 A SL RD NBR <b>81-53353-00</b> K → 80x100x12 A SL LD MVQ <b>81-53264-00</b> N 90311-38013 38,5x58x11 A SL RD MVQ	

TOYOTA													
3,0 B	59 kW (80 PS)	LAND CRUISER D	02/74-10/84	<b>01-52630-01</b> <sup>12</sup> <sup>13</sup> 04111-56040 <b>02-52630-01</b> <sup>12</sup> 04112-56030	<b>61-52630-00</b> 11115-56120 102,5 Ø 		<b>71-52616-00</b> 11213-56012 	<b>12-53027-01</b> 90913-02051 (8x)	<b>71-53651-00</b> 17171-56010 		<b>71-52614-00</b> 17173-58010 	<b>70-31414-10</b> 	<b>81-53642-00 K</b> ← 90311-50013 50x72 A SL RD FPM <b>81-53349-00 K</b> → 95x115x12 A SL LD MVQ
3,0 1KD-FTV	80-140 kW (109-190 PS)	DYNA D4d FORTUNER D HIACE D HILUX HILUX D HILUX D LAND CRUISER D-4D	10/00→	<b>01-54011-01</b> <sup>12</sup> <sup>13</sup> 04111-30711   <b>02-54011-01</b> <sup>12</sup> 04112-30331 	<b>61-53980-00</b> 11115-0L020-A0 0,7 mm MLS <b>61-53980-10</b> 11115-0L020-B0 0,75 mm MLS <b>61-53980-20</b> 11115-0L020-C0 0,8 mm MLS <b>61-53980-30</b> 11115-0L020-D0 0,85 mm MLS <b>61-53980-40</b> 11115-0L020-E0 0,9 mm MLS 	<b>14-32388-01</b> 90910-02145 (10x) +90910-02146 (8x) 	<b>71-54011-00</b> 11213-0L010 ACM 	<b>12-53457-02</b> 90913-02121 (16x)	<b>71-54012-00</b> 17177-0L011 		<b>71-54013-00</b> 17173-0L020 	<b>70-31414-10</b> 	<b>81-53287-00 K</b> ← 90311-50017 50x68x14 A SL RD FPM <b>81-53561-00 K</b> ← 90080-31098 65x79x7 A SL RD FPM <b>81-54016-00 K</b> → 90080-31100 95x115x9,5 A SL LD FPM <b>81-54014-00 N</b> 90311-32019 32x46x6 FPM
3,0 1KZ-T	92 kW (125 PS)	LAND CRUISER TD 4 RUNNER D	05/93-05/96	<b>01-53147-01</b> <sup>12</sup> 04111-67021  <b>02-53147-01</b> <sup>12</sup> 04112-67020 	<b>61-53240-00</b> 11115-67040-01 97 Ø 0,75 mm 1 □ MLS <b>61-53240-10</b> 11115-67050-03 97 Ø 0,85 mm 3 □ MLS <b>61-53240-20</b> 11115-67040-05 97 Ø 0,95 mm 5 □ MLS 	<b>14-55037-01</b> 90910-02112 (18x) 	<b>15-53147-01</b> 	<b>12-52928-01</b> 90913-02116 (8x) <b>12-52928-02</b> 90913-02117 (8x) <b>70-52928-00</b> 90913-02116 <b>70-52928-10</b> 90913-02117	<b>71-53167-00</b> 17177-67011 4x  8x  8x 		<b>71-53169-00</b> 17173-67030 	<b>70-31414-10</b> 	<b>81-53287-00 K</b> ← 90311-50017 50x68x14 A SL RD FPM <b>81-53348-00 K</b> → 90311-95008 95x115x12 A SL LD MVQ <b>81-53234-00 N</b> 90311-32017 32x46x6 A SL RD MVQ
3,0 1KZ-TE	92-103 kW (125-140 PS)	LAND CRUISER TD	04/95→	<b>01-53147-02</b> <sup>12</sup> <sup>13</sup> 04111-67025  <b>02-53147-02</b> <sup>12</sup> 04112-67022 	<b>61-53240-00</b> 11115-67040-01 97 Ø 0,75 mm 1 □ MLS <b>61-53240-10</b> 11115-67050-03 97 Ø 0,85 mm 3 □ MLS <b>61-53240-20</b> 11115-67040-05 97 Ø 0,95 mm 5 □ MLS 	<b>14-55037-01</b> 90910-02112 (18x) 	<b>15-53147-01</b> 	<b>12-52928-01</b> 90913-02116 (8x) <b>12-52928-02</b> 90913-02117 (8x) <b>70-52928-00</b> 90913-02116 <b>70-52928-10</b> 90913-02117	<b>71-53167-00</b> 17177-67011 4x  8x  8x 		<b>71-53168-00</b> 17173-30020 	<b>70-31414-10</b> 	<b>81-53287-00 K</b> ← 90311-50017 50x68x14 A SL RD FPM <b>81-53348-00 K</b> → 90311-95008 95x115x12 A SL LD MVQ <b>81-53234-00 N</b> 90311-32017 32x46x6 A SL RD MVQ

TOYOTA														
Ltr.														
3,0 1MZ-FE	135-140 kW (183-190 PS) CAMRY CAMRY V6	09/93-11/01	<b>01-54300-01</b> <sup>12</sup> <sup>13</sup> 04111-20041 <b>02-54300-01</b> <sup>12</sup> 04112-20031	<b>61-54300-00 R</b> 11115-20010  <b>61-54305-00 L</b> 11116-20010 	<b>14-32392-01</b> 90910-02117 (8x) 	2x	<b>15-43042-01 R</b> 11213-20020 +11193-70010 (3x)  <b>15-43043-01 L</b> 11214-20010 +11193-70010 (3x) 	<b>12-54024-03</b> 90913-02101 (6x) +90913-02112 (6x) <b>70-54024-00 ES</b> 90080-31084 <b>70-54026-00 AS</b> 90080-31085	2x	<b>71-43044-00 R</b> 17177-20020  <b>71-43046-00 L</b> 17178-20020  <b>71-43047-00</b> <sup>10</sup> 17176-62030 	<b>71-43048-00</b> 17173-20030 	2x	<b>70-31414-10</b> 	<b>81-53576-00 K</b> ← 90311-40013 40x55x6 A SL RD <b>81-53344-10 K</b> → 90311-92010 92x110x8,5 A SL LD FPM <b>81-53572-00 N</b> 2x 90311-38034 38x50x10,5 A SL RD FPM
3,0 1MZ-FE	137-145 kW (186-197 PS) AVALON CAMRY CAMRY V6	04/00-11/06	<b>01-54310-01</b> <sup>12</sup> <sup>13</sup> <sup>19</sup> 04111-20043 →12/02 <b>01-54320-01</b> <sup>12</sup> <sup>13</sup> <sup>19</sup> 04111-0A073 01/03→ <b>02-54310-01</b> <sup>12</sup> <sup>19</sup> 04112-20033 →12/02 <b>02-54320-01</b> <sup>12</sup> <sup>19</sup> 04112-0A073 01/03→	<b>61-54310-00 R</b> 11115-20042 88,9 Ø 1,3 mm MLS →12/02  <b>61-54315-00 L</b> 11116-20042 88,9 Ø 1,3 mm MLS →12/02  <b>61-54320-00 R</b> 11115-20032 88,9 Ø 1,3 mm MLS 01/03→  <b>61-54325-00 L</b> 11116-20032 88,9 Ø 1,3 mm MLS 01/03→ 	<b>14-32392-01</b> 90910-02117 (8x) 	2x	<b>15-43042-01 R</b> 11213-20020 +11193-70010 (3x) →12/02  <b>15-43043-01 L</b> 11214-20010 +11193-70010 (3x) →12/02  <b>15-43049-01 R</b> 11213-20030 +11193-70010 (3x) 01/03→  <b>15-43051-01 L</b> 11214-20030 +11193-70010 (3x) 01/03→ 	<b>12-54024-03</b> 90913-02101 (6x) +90913-02112 (6x) <b>70-54024-00 ES</b> 90080-31084 <b>70-54026-00 AS</b> 90080-31085	2x	<b>71-43044-00 R</b> 17177-20020  <b>71-43046-00 L</b> 17178-20020  <b>71-43047-00</b> <sup>10</sup> 17176-62030 →12/02  <b>71-43052-00</b> <sup>10</sup> 17176-20010 01/03→ 	<b>71-43048-00</b> 17173-20030 	2x	<b>70-31414-10</b> 	<b>81-53576-00 K</b> ← 90311-40013 40x55x6 A SL RD <b>81-53344-10 K</b> → 90311-92010 92x110x8,5 A SL LD FPM <b>81-53572-00 N</b> 2x 90311-38034 38x50x10,5 A SL RD FPM
3,0 1MZ-FE	137-162 kW (186-220 PS) ALPHARD CAMRY	04/03-11/08	<b>01-54320-01</b> <sup>12</sup> <sup>13</sup> <sup>19</sup> 04111-0A073 <b>02-54320-01</b> <sup>12</sup> <sup>19</sup> 04112-0A073	<b>61-54320-00 R</b> 11115-20032 88,9 Ø 1,3 mm MLS  <b>61-54325-00 L</b> 11116-20032 88,9 Ø 1,3 mm MLS 	<b>14-32392-01</b> 90910-02117 (8x) 	2x	<b>15-43049-01 R</b> 11213-20030 +11193-70010 (3x)  <b>15-43051-01 L</b> 11214-20030 +11193-70010 (3x) 	<b>12-54024-03</b> 90913-02101 (6x) +90913-02112 (6x) <b>70-54024-00 ES</b> 90080-31084 <b>70-54026-00 AS</b> 90080-31085	2x	<b>71-43044-00 R</b> 17177-20020  <b>71-43046-00 L</b> 17178-20020  <b>71-43052-00</b> <sup>10</sup> 17176-20010 	<b>71-43048-00</b> 17173-20030 	2x	<b>70-31414-10</b> 	<b>81-53576-00 K</b> ← 90311-40013 40x55x6 A SL RD <b>81-53344-10 K</b> → 90311-92010 92x110x8,5 A SL LD FPM <b>81-53572-00 N</b> 2x 90311-38034 38x50x10,5 A SL RD FPM

TOYOTA												
3,0 1MZ-FE	140-154 kW (190-209 PS)	AVALON SIENNA	03/95-05/05	<b>01-54300-01</b> <sup>12</sup> <sup>13</sup> 04111-20041 →12/99 <b>01-54310-01</b> <sup>12</sup> <sup>13</sup> <sup>19</sup> 04111-20043 01/00→ <b>02-54300-01</b> <sup>12</sup> 04112-20031 →12/99 <b>02-54310-01</b> <sup>12</sup> <sup>19</sup> 04112-20033 01/00→	<b>61-54300-00 R</b> 11115-20010 →12/99  <b>61-54305-00 L</b> 11116-20010 →12/99  <b>61-54310-00 R</b> 11115-20042 88,9 Ø 1,3 mm MLS 01/00→  <b>61-54315-00 L</b> 11116-20042 88,9 Ø 1,3 mm MLS 01/00→ 	<b>14-32392-01</b> 90910-02117 (8x) 	2x <b>15-43042-01 R</b> 11213-20020 +11193-70010 (3x)  <b>15-43043-01 L</b> 11214-20010 +11193-70010 (3x) 	<b>12-54024-03</b> 90913-02101 (6x) +90913-02112 (6x) <b>70-54024-00 ES</b> 90080-31084 <b>70-54026-00 AS</b> 90080-31085 	2x <b>71-43044-00 R</b> 17177-20020  12x <b>71-43046-00 L</b> 17178-20020  12x <b>71-43047-00 10</b> 17176-62030 	<b>71-43048-00</b> 2x 17173-20030 	<b>70-31414-10</b> 	<b>81-53576-00 K</b> ← 90311-40013 40x55x6 A SL RD <b>81-53344-10 K</b> → 90311-92010 92x110x8,5 A SL LD FPM <b>81-53572-00 N</b> 2x 90311-38034 38x50x10,5 A SL RD FPM
3,0 11B	61 kW (88 PS)	DYNA 200	08/88→	<b>01-52988-01</b> <sup>12</sup> <sup>13</sup> 04111-56060  <b>02-52988-01</b> <sup>12</sup> 	<b>61-53040-10</b> 11115-56100 96 Ø 1,6 mm 3 MLS 			<b>12-52984-01</b> 90913-02076 (8x) 	<b>71-53651-00</b> 17171-56010 	<b>71-52614-00</b> 17173-58010  <b>71-52144-00 10</b> 90917-06012 	<b>70-31414-10</b> 	<b>81-53642-00 K</b> ← 90311-50013 50x72 A SL RD FPM <b>81-53348-00 K</b> → 90311-95008 95x115x12 A SL LD MVQ
3,0 11B	75 kW (102 PS)	DYNA D	08/88-05/95	<b>01-52988-01</b> <sup>12</sup> <sup>13</sup> 04111-56060  <b>02-52988-01</b> <sup>12</sup> 	<b>61-53040-10</b> 11115-56100 96 Ø 1,6 mm 3 MLS 		<b>71-52988-00</b> 11213-56030 	<b>12-52984-01</b> 90913-02076 (8x) 	<b>71-53651-00</b> 17171-56010 	<b>71-52614-00</b> 17173-58010  <b>71-52144-00 10</b> 90917-06012 	<b>70-31414-10</b> 	<b>81-53642-00 K</b> ← 90311-50013 50x72 A SL RD FPM <b>81-53348-00 K</b> → 90311-95008 95x115x12 A SL LD MVQ
3,0 2JZ-GE	162 kW (220 PS)	CROWN	08/91-08/99	<b>01-10013-01</b> <sup>12</sup> <sup>13</sup> <sup>19</sup> 04111-46065 <b>02-10013-01</b> <sup>12</sup> <sup>19</sup> 04112-46065	<b>61-10013-00</b> 11115-46045 87,5 Ø 0,3 mm MLS 	<b>14-10112-01</b> 90910-02102 (14x) 	<b>71-10113-00 ES</b> 11213-46020  <b>71-10114-00 AS</b> 11214-46011 	<b>12-52806-04</b> 90913-02090 (12x) +90913-02089 (12x) <b>70-52806-00 ES</b> 90913-02090 <b>70-54261-00 AS</b> 90913-02089 	12x <b>71-10115-00</b> 17177-46040  12x <b>71-10438-00 10</b> 17176-46020 	<b>71-10117-00</b> 2x 17173-46020 	<b>70-31414-10</b> 	<b>81-10375-00 K</b> ← 90311-46001 45,5x63x6,5 A SL RD <b>81-10376-00 K</b> → 90311-90006 90x110x9,5 A SL LD <b>81-10377-00 N</b> 2x 90311-40020 40,5x52,5x6,5 A SL RD

TOYOTA												
Ltr.			<b>1</b>									
3,0 2JZ-GE	168 kW (228 PS)	SUPRA	05/93-08/02	<b>01-10013-01</b> ⑫ ⑬ ⑰ 04111-46065 →09/97 <b>01-10013-02</b> ⑫ ⑬ ⑰ 04111-46102 10/97→ <b>02-10013-01</b> ⑫ ⑰ 04112-46065 →09/97 <b>02-10013-02</b> ⑫ ⑰ 04112-46102 10/97→	<b>61-10013-00</b> 11115-46045 87,5 Ø 0,3 mm MLS 	<b>14-10112-01</b> 90910-02102 (14x) 	<b>71-10113-00 ES</b> 11213-46020 →09/97 <b>71-10119-00 ES</b> 11213-46030 10/97→ <b>71-10114-00 AS</b> 11214-46011 	<b>12-52806-04</b> 90913-02090 (12x) +90913-02089 (12x) <b>70-52806-00 ES</b> 90913-02090 12x <b>70-54261-00 AS</b> 90913-02089 12x 	<b>71-10115-00</b> 17177-46040 →09/97 <b>71-10120-00</b> 17177-46060 10/97→ <b>71-10438-00 ⑩</b> 17176-46020 	<b>71-10117-00</b> 2x 17173-46020 →09/97 <b>71-10121-00</b> 2x 17173-46051 10/97→ 	<b>70-31414-10</b> 	<b>81-10375-00 K</b> ← 90311-46001 45,5x63x6,5 A SL RD <b>81-10376-00 K</b> → 90311-90006 90x110x9,5 A SL LD <b>81-10377-00 N</b> 2x 90311-40020 40,5x52,5x6,5 A SL RD
3,0 2JZ-GTE	243 kW (330 PS)	SUPRA V6 TURBO	05/93-08/02	<b>01-10030-01</b> ⑫ ⑬ ⑰ 04111-46094 <b>02-10030-01</b> ⑫ ⑰ 04112-46094	<b>61-10030-00</b> 11115-46052 87,5 Ø 1,25 mm MLS 	<b>14-10112-01</b> 90910-02102 (14x) 	<b>71-10113-00 ES</b> 11213-46020 <b>71-10114-00 AS</b> 11214-46011 	<b>12-52806-04</b> 90913-02090 (12x) +90913-02089 (12x) <b>70-52806-00 ES</b> 90913-02090 12x <b>70-54261-00 AS</b> 90913-02089 12x 	<b>71-10200-00</b> 17177-46031 <b>71-10201-00 ⑩</b> 17176-46030 	<b>71-10202-00</b> 17173-46040 Zyl. 1-3 <b>71-10203-00</b> 17198-46010 Zyl. 4-6 	<b>70-31414-10</b> 	<b>81-10375-00 K</b> ← 90311-46001 45,5x63x6,5 A SL RD <b>81-10376-00 K</b> → 90311-90006 90x110x9,5 A SL LD <b>81-10377-00 N</b> 2x 90311-40020 40,5x52,5x6,5 A SL RD
3,0 3GR-FE	167-170 kW (227-231 PS)	CROWN	09/04-11/12		<b>61-54270-00 R</b> 11115-31041 89,5 Ø 0,5 mm MLS  <b>61-54275-00 L</b> 11116-31021 89,5 Ø 0,5 mm MLS 	<b>14-32333-01</b> 2x 90910-02162 (8x) +90105-10521 (2x) 	<b>15-42848-01 L</b> 11214-31020 +11193-70010 (3x)  <b>15-54132-01 R</b> 11213-31050 +11193-70010 (3x) 	<b>12-54024-03</b> 2x 90913-02101 (6x) +90913-02112 (6x) <b>70-54024-00 ES</b> 90080-31084 12x <b>70-54026-00 AS</b> 90080-31085 12x 		<b>71-42846-00</b> 2x 17173-31020 	<b>70-31414-10</b> 	<b>81-53274-00 K</b> ← 90311-42003 42x60x7 A SL RD NBR <b>81-53344-10 K</b> → 90311-92010 92x110x8,5 A SL LD FPM
3,0 3GR-FSE	183-188 kW (249-256 PS)			<b>01-54270-01</b> ⑫ ⑬ ⑰ 04111-31290 <b>02-54270-01</b> ⑫ ⑰ 04112-31160	<b>61-54270-00 R</b> 11115-31041 89,5 Ø 0,5 mm MLS  <b>61-54275-00 L</b> 11116-31021 89,5 Ø 0,5 mm MLS 	<b>14-32333-01</b> 2x 90910-02162 (8x) +90105-10521 (2x) 	<b>15-42847-01 R</b> 11213-31040 +11193-70010 (3x)  <b>15-42848-01 L</b> 11214-31020 +11193-70010 (3x) 	<b>12-54024-03</b> 2x 90913-02101 (6x) +90913-02112 (6x) <b>70-54024-00 ES</b> 90080-31084 12x <b>70-54026-00 AS</b> 90080-31085 12x 	<b>71-42893-00</b> 2x 17177-31021 <b>71-42894-00 ⑩</b> 17176-31020 	<b>71-42846-00</b> 2x 17173-31020 	<b>70-31414-10</b> 	<b>81-53274-00 K</b> ← 90311-42003 42x60x7 A SL RD NBR <b>81-53344-10 K</b> → 90311-92010 92x110x8,5 A SL LD FPM



TOYOTA												
3,0 3VZ-E	105 kW (143 PS)	4 RUNNER V6	07/90-11/95	<b>01-53520-01</b> <sup>12</sup> <sup>13</sup> 04111-65018 <b>02-53520-01</b> <sup>12</sup> 04112-65015	<b>61-53520-00 L</b> 11116-65031 89 Ø 1,45 mm  <b>61-53525-00 R</b> 11116-65031 89 Ø 1,45 mm 		<b>71-53579-00</b> 2x 11213-65010 	<b>71-53578-00</b> 2x 17177-65010  <b>71-53563-00</b> <sup>10</sup> 17176-65020 		<b>71-53581-00 L</b> 17198-65031  <b>71-53582-00 R</b> 17173-65031 	<b>70-31414-10</b> 	<b>81-53576-00 K</b> ← 90311-40013 40x55x6 A SL RD <b>81-53344-00 K</b> → 90311-92006 92x110x8,5 A SL LD MVQ <b>81-53582-00 N</b> ← 90311-42027 42x55x8 A SL RD FPM
3,0 3VZ-FE	136-140 kW (185-190 PS)	CAMRY CAMRY V6	06/91-07/01	<b>01-52940-02</b> <sup>12</sup> <sup>13</sup> 04111-62050 <b>02-52940-02</b> <sup>12</sup> 04112-62040	<b>61-52940-00 R</b> 11115-62060 89,5 Ø  <b>61-53120-00 L</b> 11116-62060 89,5 Ø 		<b>15-53577-01</b> 2x 11213-62020 	<b>12-53573-01</b> 90913-02103 (12x) E +90913-02095 (12x) A	<b>71-53569-00</b> 2x 17177-62050 	<b>71-53571-00</b> 2x 17173-62040 	<b>70-31414-10</b> 	<b>81-53409-00 K</b> ← 35x48x7 A SL RD MVQ <b>81-53344-00 K</b> → 90311-92006 92x110x8,5 A SL LD MVQ <b>81-53572-00 N</b> ← 2x 90311-38034 38x50x10,5 A SL RD FPM
3,0 5L	65 kW (88 PS)	HILUX LN	08/97→	<b>01-52750-01</b> <sup>12</sup> <sup>13</sup> 04111-54083   <b>02-52750-01</b> <sup>12</sup> 04112-54071 	<b>61-53190-00</b> 11115-54130-B0 100,5 Ø 1,45 mm MLS <b>61-53190-10</b> 11115-54130-D0 100,5 Ø 1,55 mm MLS <b>61-53190-20</b> 11115-54130-F0 100,5 Ø 1,65 mm MLS 	<b>14-55000-01</b> 90910-02080 (14x) +90910-02081 (4x) 	<b>71-52644-00</b> 11213-54050 	<b>12-52928-01</b> 90913-02116 (8x) <b>12-52928-02</b> 90913-02117 (8x) <b>70-52928-00</b> 90913-02116 <b>70-52928-10</b> 90913-02117 8x 8x	<b>71-52981-00</b> 17177-54020 	<b>71-52982-00</b> 17173-54030  <b>71-52983-00</b> <sup>10</sup> 2x 	<b>70-31414-10</b> 	<b>81-53274-00 K</b> ← 90311-42003 42x60x7 A SL RD NBR <b>81-53332-00 K</b> → 90311-85003 85x105x10 A SL LD FPM <b>81-53234-00 N</b> 90311-32017 32x46x6 A SL RD MVQ
3,0 5L-E <b>[NEW]</b>	67-71 kW (91-97 PS)	HILUX D LAND CRUISER D	08/97-07/09	<b>01-52644-01</b> <sup>12</sup> <sup>13</sup> 04111-05020  <b>02-52644-01</b> <sup>12</sup> 04112-05020 	<b>61-53190-00</b> 11115-54130-B0 100,5 Ø 1,45 mm MLS <b>61-53190-10</b> 11115-54130-D0 100,5 Ø 1,55 mm MLS <b>61-53190-20</b> 11115-54130-F0 100,5 Ø 1,65 mm MLS 	<b>14-55000-01</b> 90910-02080 (14x) +90910-02081 (4x) 	<b>71-52644-00</b> 11213-54050 	<b>12-52928-02</b> 90913-02117 (8x) <b>70-52928-10</b> 90913-02117 8x	<b>71-52981-00</b> 17177-54020 	<b>71-52982-00</b> 17173-54030 	<b>70-31414-10</b> 	<b>81-53274-00 K</b> ← 90311-42003 42x60x7 A SL RD NBR <b>81-53332-00 K</b> → 90311-85003 85x105x10 A SL LD FPM <b>81-54014-00</b> 90311-32019 32x46x6 FPM

TOYOTA												
Ltr.												
3,0 7M-GEU 7M-GTE	149-175 kW (203-238 PS) CELICA SUPRA SUPRA V6 TURBO	09/87→	01-52615-01 <sup>12</sup> <sup>13</sup> 04111-42030 02-52615-01 <sup>12</sup> 04112-42030	61-52615-00 11115-42020 84,5 Ø 	14-55065-01 90110-12002 (14x) 	71-52619-00 2x 11213-42020 	12-52829-03 90913-02062 (24x)	71-52621-00 17177-42010 		71-52613-00 17173-43020 	70-31414-10 	81-53274-00 K ← 90311-42003 42x60x7 A SL RD NBR 81-53353-00 K → 80x100x12 A SL LD MVQ 81-53247-00 N 90311-35040 35x49x6 A SL RD MVQ
3,3 3MZ-FE	165-171 kW (224-233 PS) CAMRY CAMRY VVTI KLUGER SIENNA	08/02-11/09	01-38320-01 <sup>12</sup> <sup>13</sup> <sup>19</sup> 04111-20630 02-38320-01 <sup>12</sup> <sup>19</sup> 04112-20270	61-38320-00 R 11115-20051 93,4 Ø 1,3 mm MLS  61-38325-00 L 11116-20051 93,4 Ø 1,3 mm MLS 	14-32392-01 2x 90910-02117 (8x) 	15-43049-01 R 11213-20030 +11193-70010 (3x)  15-43051-01 L 11214-20030 +11193-70010 (3x) 	12-54024-03 2x 90913-02101 (6x) +90913-02112 (6x) 70-54024-00 ES 12x 90080-31084 70-54026-00 AS 12x 90080-31085	71-43044-00 R 17177-20020  71-43046-00 L 12x 17178-20020  71-43057-00 <sup>10</sup> 17176-20020 		71-43048-00 2x 17173-20030 	70-31414-10 	81-53576-00 K ← 90311-40013 40x55x6 A SL RD 81-53344-10 K → 90311-92010 92x110x8,5 A SL LD FPM 81-53572-00 N 2x 90311-38034 38x50x10,5 A SL RD FPM
3,4 13B	66 kW (90 PS) DYNA D	08/77-08/87	01-52148-01 <sup>12</sup> <sup>13</sup> 04111-58013 01-52148-02 <sup>12</sup> <sup>13</sup> 04111-58050  02-52148-01 <sup>12</sup> 04112-58011 02-52148-02 <sup>12</sup> 04112-58042	61-52148-00 11115-58013 106,8 Ø 		71-52616-00 11213-56012 	12-53027-01 90913-02051 (8x)	71-52164-00 17177-25030 		71-52614-00 17173-58010  71-52144-00 <sup>10</sup> 90917-06012 	70-31414-10 	81-53642-00 K ← 90311-50013 50x72 A SL RD FPM 81-53349-00 K → 95x115x12 A SL LD MVQ
3,4 3B	66 kW (90 PS) DYNA D	08/77-08/87	01-52148-01 <sup>12</sup> <sup>13</sup> 04111-58013 →08/84 01-52148-02 <sup>12</sup> <sup>13</sup> 04111-58050 11/84→  02-52148-01 <sup>12</sup> 04112-58011 →08/84 02-52148-02 <sup>12</sup> 04112-58042 11/84→	61-52148-00 11115-58013 106,8 Ø 		71-52616-00 11213-56012 	12-53027-01 90913-02051 (8x)	71-52164-00 17177-25030 		71-52614-00 17173-58010  71-52144-00 <sup>10</sup> 90917-06012 	70-31414-10 	81-53642-00 K ← 90311-50013 50x72 A SL RD FPM 81-53349-00 K → 95x115x12 A SL LD MVQ
3,4 3B	70 kW (95 PS) LAND CRUISER D	11/84-12/96	01-52148-02 <sup>12</sup> <sup>13</sup> 04111-58050 →08/88  01-53050-01 <sup>12</sup> <sup>13</sup> 04111-58060 09/88→ 02-52148-02 <sup>12</sup> 04112-58042 →08/88 02-53050-01 <sup>12</sup> 04112-58050 09/88→	61-52148-00 11115-58013 106,8 Ø  61-53050-00 11115-58081 103,5 Ø MLS 	14-55005-01 90910-02084 (18x) 09/88→ 	71-52616-00 11213-56012 →08/88  71-52988-00 11213-56030 09/88→ 	12-53027-01 90913-02051 (8x) →08/88 12-52984-01 90913-02076 (8x) 09/88→	71-53651-00 17171-56010 09/88→ 		71-52614-00 17173-58010 →08/88  71-53134-00 09/88→  71-52144-00 <sup>10</sup> 90917-06012 	70-31414-10 	81-53642-00 K ← 90311-50013 50x72 A SL RD FPM 81-53349-00 K → 95x115x12 A SL LD MVQ

TOYOTA												
3,4 5VZ-FE	131-136 kW (178-185 PS)	HILUX LAND CRUISER V6	11/95→	<b>01-54215-01</b> <sup>12</sup> <sup>13</sup> 04111-62081 →12/98 <b>01-54235-01</b> <sup>12</sup> <sup>13</sup> <sup>19</sup> 04111-62130 01/99→ <b>02-54215-01</b> <sup>12</sup> 04112-62071 →12/98 <b>02-54235-01</b> <sup>12</sup> <sup>19</sup> 04112-62110 01/99→	<b>61-54215-00 R</b> 11115-62071 95,5 Ø 1,3 mm →12/98  <b>61-54220-00 L</b> 11116-62071 95,5 Ø 1,3 mm →12/98  <b>61-54235-00 R</b> 11115-62081 1,3 mm MLS 01/99→  <b>61-54240-00 L</b> 11116-62081 1,3 mm MLS 01/99→ 	<b>14-55099-01</b> 90910-02077 (8x) 	2x <b>15-53577-02</b> 2x 11213-62020 +11193-70010 (3x) +90210-05007 (8x) 	<b>12-53573-01</b> 90913-02103 (12x) E +90913-02095 (12x) A 	<b>71-42751-00</b> 2x 17177-62060  <b>71-42752-00</b> <sup>10</sup> 2x 17176-62040 	 <b>71-42753-00</b> 2x 17173-62050 	<b>70-31414-10</b> 	<b>81-53576-00 K</b> ← 90311-40013 40x55x6 A SL RD <b>81-53344-10 K</b> → 90311-92010 92x110x8,5 A SL LD FPM <b>81-54322-00 N</b> 2x 90311-38051 38x50x10 A SL RD
3,4 5VZ-FE	131-140 kW (178-190 PS)	HILUX LAND CRUISER TUNDRA	04/99-07/05	<b>01-54235-01</b> <sup>12</sup> <sup>13</sup> <sup>19</sup> 04111-62130 <b>02-54235-01</b> <sup>12</sup> <sup>19</sup> 04112-62110	<b>61-54235-00 R</b> 11115-62081 1,3 mm MLS  <b>61-54240-00 L</b> 11116-62081 1,3 mm MLS 	<b>14-55099-01</b> 90910-02077 (8x) 	2x <b>15-53577-02</b> 2x 11213-62020 +11193-70010 (3x) +90210-05007 (8x) 	<b>12-53573-01</b> 90913-02103 (12x) E +90913-02095 (12x) A 	<b>71-42751-00</b> 2x 17177-62060  <b>71-42752-00</b> <sup>10</sup> 2x 17176-62040 	 <b>71-42753-00</b> 2x 17173-62050 	<b>70-31414-10</b> 	<b>81-53576-00 K</b> ← 90311-40013 40x55x6 A SL RD <b>81-53344-10 K</b> → 90311-92010 92x110x8,5 A SL LD FPM <b>81-54322-00 N</b> 2x 90311-38051 38x50x10 A SL RD
3,5 1PZ	85 kW (116 PS)	LAND CRUISER	01/90-08/92	<b>02-53009-01</b> <sup>12</sup> 04112-17030 	<b>61-53090-20</b> 11115-18010-05 95,5 Ø 5 MLS 	<b>14-55031-01</b> 90910-02096 (22x) 	<b>71-53009-00</b> 11213-18010 	<b>12-52928-03</b> 90913-02072 (10x) 	<b>71-53006-00</b> 4x 17179-17010  <b>71-53007-00</b> 1x 17171-17010 	<b>71-53008-00 L</b> 17173-17010  <b>71-53012-00 R</b> 17179-18010  <b>71-53118-00</b> <sup>10</sup> 	<b>70-31414-10</b> 	<b>81-53291-00 K</b> ← 90311-58006 58x72x7 A SL RD MVQ <b>81-53348-00 K</b> → 90311-95008 95x115x12 A SL LD MVQ <b>81-53234-00 N</b> 90311-32017 32x46x6 A SL RD MVQ

TOYOTA												
3,5 2GR-FE	197-206 kW (268-280 PS)	ALPHARD AVALON VVTi CAMRY CAMRY VVTi	01/05→	<b>01-54250-01</b> <sup>12</sup> <sup>13</sup> <sup>19</sup> 04111-31444 <b>02-54250-01</b> <sup>12</sup> <sup>19</sup> 04112-31272	<b>61-54250-00 R</b> 11115-31080 96 Ø 0,5 mm MLS  <b>61-54255-00 L</b> 11116-31060 96 Ø 0,5 mm MLS 	<b>14-32333-01</b> 90910-02162 (8x) +90105-10521 (2x) 	2x <b>15-42848-01 L</b> 11214-31020 +11193-70010 (3x)  <b>15-54132-01 R</b> 11213-31050 +11193-70010 (3x) 	<b>12-54024-03</b> 90913-02101 (6x) +90913-02112 (6x) <b>70-54024-00 ES</b> 90080-31084 <b>70-54026-00 AS</b> 90080-31085	2x <b>71-42842-00 R</b> 17177-31040  12x <b>71-42843-00 L</b> 17178-31030  12x <b>71-42844-00</b> <sup>10</sup> 17176-31090 3x	<b>71-42846-00</b> 17173-31020 2x	<b>70-31414-10</b> 	<b>81-53274-00 K</b> ← 90311-42003 42x60x7 A SL RD NBR <b>81-53344-10 K</b> → 90311-92010 92x110x8,5 A SL LD FPM
3,5 2GR-FSE	218-235 kW (296-320 PS)			<b>01-54250-02</b> <sup>12</sup> <sup>13</sup> <sup>19</sup> 04111-31602 <b>02-54250-02</b> <sup>12</sup> <sup>19</sup>	<b>61-54250-00 R</b> 11115-31080 96 Ø 0,5 mm MLS  <b>61-54255-00 L</b> 11116-31060 96 Ø 0,5 mm MLS 	<b>14-32333-01</b> 90910-02162 (8x) +90105-10521 (2x) 	2x <b>15-42847-01 R</b> 11213-31040 +11193-70010 (3x)  <b>15-42848-01 L</b> 11214-31020 +11193-70010 (3x) 	<b>12-54024-03</b> 90913-02101 (6x) +90913-02112 (6x) <b>70-54024-00 ES</b> 90080-31084 <b>70-54026-00 AS</b> 90080-31085	2x <b>71-42861-00</b> 17177-31060 12x	<b>71-42846-00</b> 17173-31020 2x	<b>70-31414-10</b> 	<b>81-53274-00 K</b> ← 90311-42003 42x60x7 A SL RD NBR <b>81-53344-10 K</b> → 90311-92010 92x110x8,5 A SL LD FPM
3,5 2GR-FXE	183 kW (249 PS)			<b>01-54250-03</b> <sup>12</sup> <sup>13</sup> <sup>19</sup> 04111-31891 <b>02-54250-03</b> <sup>12</sup> <sup>19</sup> 04112-31561	<b>61-54250-00 R</b> 11115-31080 96 Ø 0,5 mm MLS  <b>61-54255-00 L</b> 11116-31060 96 Ø 0,5 mm MLS 	<b>14-32333-01</b> 90910-02162 (8x) +90105-10521 (2x) 	2x <b>15-42848-01 L</b> 11214-31020 +11193-70010 (3x)  <b>15-54132-01 R</b> 11213-31050 +11193-70010 (3x) 	<b>12-54024-03</b> 90913-02101 (6x) +90913-02112 (6x) <b>70-54024-00 ES</b> 90080-31084 <b>70-54026-00 AS</b> 90080-31085	2x <b>71-42842-00 R</b> 17177-31040  12x <b>71-42843-00 L</b> 17178-31030  12x <b>71-42844-00</b> <sup>10</sup> 17176-31090 3x	<b>71-42846-00</b> 17173-31020 2x	<b>70-31414-10</b> 	<b>81-53274-00 K</b> ← 90311-42003 42x60x7 A SL RD NBR <b>81-53344-10 K</b> → 90311-92010 92x110x8,5 A SL LD FPM

TOYOTA													
Ltr.													
3,7 14B	71 kW (97 PS) DYNA D	08/88-07/01	<b>01-52148-02</b> <sup>12</sup> <sup>13</sup> 04111-58050  <b>01-52988-01</b> <sup>12</sup> <sup>13</sup> 04111-56060  <b>02-52988-01</b> <sup>12</sup> 	<b>61-53045-00</b> 11115-58070 1,5 mm <b>61-53045-10</b> 11115-58090 1,6 mm <b>61-53045-20</b> 11115-58100 1,7 mm 	<b>14-55005-01</b> 90910-02084 (18x) 	<b>71-52988-00</b> 11213-56030 	<b>12-52984-01</b> 90913-02076 (8x) 	<b>71-52621-00</b> 17177-42010 		<b>71-52144-00</b> <sup>A</sup> 90917-06012 	<b>70-31414-10</b> 	<b>81-53642-00 K</b> ← 90311-50013 50x72 A SL RD FPM <b>81-53348-00 K</b> → 90311-95008 95x115x12 A SL LD MVQ	
4,0 N04C-UH N04C-UL N04C-UP N04C-UQ <b>[NEW]</b>	110-132 kW (150-180 PS) DYNA DYNA D	05/11→	<b>01-10120-01</b> <sup>12</sup> <sup>13</sup> 04111-E0D93 <b>02-10120-01</b> <sup>12</sup> 04112-78082	<b>61-10120-00</b> 11115-E0030 107,5 Ø 1,3 mm MLS 	<b>14-11126-01</b> 90910-02155 (18x) 	<b>15-11118-01</b> 11213-78070 +S1121-32092 (4x) 	<b>12-11129-01</b> 90038-12004 (16x) <b>70-11129-00</b> 90038-12005 16x 		<b>71-11121-00</b> S1710-41880 	4x <b>70-31414-10</b> 	<b>81-53292-00 K</b> ← 90311-58007 58x75x14 A SL RD MVQ <b>81-10437-00 K</b> → 90311-99002 100x120x13 A SL LD		
4,0 W04D-TP <b>[NEW]</b>	81 kW (110 PS) DYNA D4d	08/01→	<b>01-10128-01</b> <sup>12</sup> <sup>13</sup> 04111-80531 →12/04 <b>01-10120-02</b> <sup>12</sup> <sup>13</sup> 04111-E0D72 01/05→ <b>02-10128-01</b> <sup>12</sup> 04112-78041 +S1717-12220 →12/04 <b>02-10120-02</b> <sup>12</sup> 04112-78320 01/05→	<b>61-10128-00</b> 11115-78012 107,5 Ø 1,4 mm →12/04  <b>61-10120-00</b> 11115-E0030 107,5 Ø 1,3 mm MLS 01/05→ 	<b>14-11290-01</b> 90031-01199 (13x) +90031-01200 (5x) 	<b>71-11280-00</b> S1121-31550 	<b>12-11292-01</b> 90038-12006 (8x) <b>70-11292-00</b> 90038-12006 8x 	<b>71-11283-00</b> S1717-12220 	<b>71-11121-00</b> S1710-41880 	4x <b>70-31414-10</b> 	<b>81-53292-00 K</b> ← 90311-58007 58x75x14 A SL RD MVQ <b>81-10437-00 K</b> → 90311-99002 100x120x13 A SL LD		
4,0 W04D-TP W04D-TR <b>[NEW]</b>	81-96 kW (110-130 PS) DYNA D4d	10/06→	<b>01-10120-02</b> <sup>12</sup> <sup>13</sup> 04111-E0D72 <b>02-10120-02</b> <sup>12</sup> 04112-78320	<b>61-10120-00</b> 11115-E0030 107,5 Ø 1,3 mm MLS 	<b>14-11290-01</b> 90031-01199 (13x) +90031-01200 (5x) 	<b>71-11280-00</b> S1121-31550 	<b>12-11292-01</b> 90038-12006 (8x) <b>70-11292-00</b> 90038-12006 8x 	<b>71-11283-00</b> S1717-12220 	<b>71-11121-00</b> S1710-41880 	4x <b>70-31414-10</b> 	<b>81-53292-00 K</b> ← 90311-58007 58x75x14 A SL RD MVQ <b>81-10437-00 K</b> → 90311-99002 100x120x13 A SL LD		
4,0 1GR-FE	175-183 kW (238-249 PS) HILUX LAND CRUISER 4 RUNNER VVTi	08/02→	<b>01-54050-01</b> <sup>12</sup> <sup>13</sup> <sup>19</sup> 04111-31343 <b>02-54050-01</b> <sup>12</sup> 04112-31123	<b>61-54050-00 R</b> 11115-31031 MLS  <b>61-54055-00 L</b> 11116-31011 MLS 	<b>14-32333-01</b> 90910-02162 (8x) +90105-10521 (2x) 	2x <b>71-54121-00 R</b> 11213-31030 ACM  <b>71-54122-00 L</b> 11214-31010 ACM 	<b>12-54024-02</b> 90080-31084 (12x) +90080-31085 (12x) <b>70-54024-00 ES</b> 90080-31084 <b>70-54026-00 AS</b> 90080-31085 12x 	<b>71-54123-00 R</b> 17177-31010  12x <b>71-54124-00 L</b> 17178-31010  12x <b>71-54127-00</b> <sup>19</sup> 17176-31010 	<b>71-54126-00</b> 17173-31010 	2x <b>70-31414-10</b> 	<b>81-53274-00 K</b> ← 90311-42003 42x60x7 A SL RD NBR <b>81-54129-00 K</b> → 90311-99010 100x118x8,6 A SL LD FPM		

TOYOTA														
4,0 1GR-FE	175-207 kW (238-282 PS)	FJ CRUISER FORTUNER LAND CRUISER V6 LAND CRUISER V6 VVTi	01/10→	<b>01-54070-01</b> <sup>12</sup> <sup>13</sup> <sup>19</sup> 04111-31A23 <b>02-54070-01</b> <sup>12</sup> <sup>19</sup> 04112-31700	<b>61-54070-00 R</b> 11115-31090 MLS 	<b>14-32333-01</b> 90910-02162 (8x) +90105-10521 (2x) 	2x <b>15-54132-01 R</b> 11213-31050 +11193-70010 (3x) 	<b>12-54024-02</b> 90080-31084 (12x) +90080-31085 (12x) <b>70-54024-00 ES</b> 90080-31084 <b>70-54026-00 AS</b> 90080-31085 12x 	<b>71-54136-00 R</b> 17177-31050 	<b>71-54137-00 L</b> 17178-31040 	<b>71-54139-00</b> <sup>10</sup> 17176-31100 	<b>71-54138-00</b> 2x 17173-31050 	<b>70-31414-10</b> 	<b>81-53274-00 K</b> ← 90311-42003 42x60x7 A SL RD NBR <b>81-54129-00 K</b> → 90311-99010 100x118x8,6 A SL LD FPM
4,0 1UZ-FE <b>[NEW]</b>	173-216 kW (235-294 PS)			<b>61-10168-00 R</b> 11115-50021 89,5 Ø 1,4 mm →07/97 	<b>14-12043-01</b> 90910-02180 (10x) 	2x <b>15-12044-01</b> 2x 11213-50021 +11193-15010 (4x) →07/97 	<b>12-52806-05</b> 90913-02123 (16x) →07/97 <b>12-54024-01</b> 90080-31084 (8x) +90080-31085 (8x) 08/97→ <b>70-52806-00</b> 90913-02090 →07/97 <b>70-54024-00 ES</b> 90080-31084 08/97→ <b>70-54026-00 AS</b> 90080-31085 08/97→ 32x 16x 16x	2x <b>71-12045-00</b> 2x 17171-50011 →07/97 	<b>71-11947-00</b> 2x 17171-50020 08/97→ 	<b>71-12046-00</b> 2x 17173-50011 →07/97 	<b>71-11948-00</b> 2x 17173-50021 08/97→ 	<b>70-31414-10</b> 	<b>81-10469-00 K</b> ← 90311-43006 43x60x7 A SL RD <b>81-10470-00 K</b> → 90311-95012 95x113x8,5 A SL LD <b>81-53256-00 N</b> 2x 90311-38017 38x50x8 A SL RD NBR →07/97 <b>81-10452-00 N</b> 2x 90311-71002 71x85x10 A SL RD 08/97→	
4,0 1W <b>[NEW]</b>	85 kW (116 PS)			<b>01-10128-02</b> <sup>12</sup> <sup>13</sup> 04111-78013 <b>02-10128-02</b> <sup>12</sup> 04112-78013	<b>61-10128-00</b> 11115-78012 107,5 Ø 1,4 mm 	<b>14-11290-01</b> 90031-01199 (13x) +90031-01200 (5x) 	<b>71-11280-00</b> S1121-31550 	<b>12-11292-01</b> 90038-12006 (8x) <b>70-11292-00</b> 90038-12006 8x	<b>71-11283-00</b> S1717-12220 	<b>71-11830-00</b> 4x S1710-41220 	<b>70-31414-10</b> 	<b>81-53292-00 K</b> ← 90311-58007 58x75x14 A SL RD MVQ <b>81-10437-00 K</b> → 90311-99002 100x120x13 A SL LD		

TOYOTA													
4,0 12HT	100 kW (136 PS)	LAND CRUISER TD	10/85-12/89	<b>01-52640-01</b> <sup>12</sup> <sup>13</sup> 04111-68030 <b>02-52640-01</b> <sup>12</sup> 04112-68030	<b>61-52640-00</b> 11115-68030 92 Ø 		<b>71-52634-00</b> 11213-68020 	<b>12-53033-01</b> 90913-02050 (12x)	<b>71-53049-00</b> 17171-68020 		<b>71-52637-00</b> 17173-68010 6x 	<b>70-31414-10</b> 	<b>81-53287-00 K</b> ← 90311-50017 50x68x14 A SL RD FPM <b>81-53349-00 K</b> → 95x115x12 A SL LD MVQ
4,0 2H	74-77 kW (101-105 PS)	LAND CRUISER D	08/80-01/88	<b>01-52635-01</b> <sup>12</sup> <sup>13</sup> 04111-68020 <b>02-52635-01</b> <sup>12</sup> 04112-68020	<b>61-52635-00</b> 11115-68020 92,5 Ø 		<b>71-52633-00</b> 11213-68010 	<b>12-53033-01</b> 90913-02050 (12x)			<b>71-52637-00</b> 17173-68010 6x 	<b>71-52636-00</b> 12151-68010 	<b>81-53642-00 K</b> ← 90311-50013 50x72 A SL RD FPM <b>81-53349-00 K</b> → 95x115x12 A SL LD MVQ
4,0 3F	101 kW (137 PS)	LAND CRUISER	11/84-08/87	<b>01-52065-05</b> <sup>12</sup> <sup>13</sup> 04111-61070 <b>02-52065-05</b> <sup>12</sup> 04112-61060	<b>61-52065-00</b> 11115-61010 97 Ø 		<b>71-52626-00</b> 11213-61020 	<b>12-53037-01</b> 90913-02048 (12x)		<b>71-52629-00</b> <sup>7</sup> 17172-61060 		<b>71-52202-10</b> 12151-60021 	<b>81-53352-00 K</b> → 90311-99005 105x120x11 A SL LD MVQ
4,1 1BZ-FPE <b>[NEW]</b>	85 kW (116 PS)	COASTER	11/03→	<b>01-10093-01</b> <sup>12</sup> <sup>13</sup> <sup>19</sup> 04111-58320 <b>02-10093-01</b> <sup>12</sup> <sup>19</sup> 04112-58270	<b>61-10093-00</b> 11115-58131 109,5 Ø 1,2 mm MLS 	<b>14-55005-01</b> 90910-02084 (18x) 	<b>15-10856-01</b> 11213-58021 +11193-15010 (4x) <b>71-10856-00</b> 11213-58021 	<b>12-54196-04</b> 90913-02096 (16x) <b>70-54196-00</b> 90913-02096 16x	<b>71-10858-00</b> 17171-58010 		<b>71-10859-00</b> 17173-5803 	<b>70-31414-10</b> 	<b>81-53642-00 K</b> ← 90311-50013 50x72 A SL RD FPM <b>81-53348-00 K</b> → 90311-95008 95x115x12 A SL LD MVQ
4,1 15B-F <b>[NEW]</b>	92 kW (125 PS)	DYNA D DYNA Di	06/95-06/99	<b>01-10856-01</b> <sup>12</sup> <sup>13</sup> 04111-58102  <b>02-10856-01</b> <sup>12</sup> 04112-58092 	<b>61-10093-00</b> 11115-58131 109,5 Ø 1,2 mm MLS <b>61-10093-10</b> 11115-58141 109,5 Ø 1,3 mm MLS <b>61-10093-20</b> 11115-58151 109,5 Ø 1,4 mm MLS 	<b>14-55005-01</b> 90910-02084 (18x) 	<b>71-10856-00</b> 11213-58021 	<b>12-54196-04</b> 90913-02096 (16x) <b>70-54196-00</b> 90913-02096 16x	<b>71-10858-00</b> 17171-58010 		<b>71-10859-00</b> 17173-5803 	<b>70-31414-10</b> 	<b>81-53642-00 K</b> ← 90311-50013 50x72 A SL RD FPM <b>81-53348-00 K</b> → 90311-95008 95x115x12 A SL LD MVQ
4,1 15B-FT <b>[NEW]</b>	92 kW (125 PS)	DYNA Di	06/95-05/99	<b>01-10856-02</b> <sup>12</sup> <sup>13</sup> 04111-58112  <b>02-10856-02</b> <sup>12</sup> 04112-58102 	<b>61-10093-00</b> 11115-58131 109,5 Ø 1,2 mm MLS <b>61-10093-10</b> 11115-58141 109,5 Ø 1,3 mm MLS <b>61-10093-20</b> 11115-58151 109,5 Ø 1,4 mm MLS 	<b>14-55005-01</b> 90910-02084 (18x) 	<b>71-10856-00</b> 11213-58021 	<b>12-54196-04</b> 90913-02096 (16x) <b>70-54196-00</b> 90913-02096 16x	<b>71-10858-00</b> 17171-58010 		<b>71-10860-00</b> 17173-58040 	<b>70-31414-10</b> 	<b>81-53642-00 K</b> ← 90311-50013 50x72 A SL RD FPM <b>81-53348-00 K</b> → 90311-95008 95x115x12 A SL LD MVQ

TOYOTA												
Ltr.												
4,1 15B-FTE <b>[NEW]</b>	92-125 kW (125-170 PS) DYNA D DYNA TDi	06/95-12/02	<b>01-10856-03</b> ⑫ ⑬ 04111-58200  <b>02-10856-03</b> ⑫ 04112-58150 	<b>61-10093-00</b> 11115-58131 109,5 Ø 1,2 mm MLS <b>61-10093-10</b> 11115-58141 109,5 Ø 1,3 mm MLS <b>61-10093-20</b> 11115-58151 109,5 Ø 1,4 mm MLS 	<b>14-55005-01</b> 90910-02084 (18x) 	<b>71-10856-00</b> 11213-58021 	<b>12-54196-04</b> 90913-02096 (16x) <b>70-54196-00</b> 90913-02096	16x <b>71-10858-00</b> 17171-58010 	<b>71-10862-00</b> 17173-58050 	<b>70-31414-10</b> 	<b>81-53642-00 K</b> ← 90311-50013 50x72 A SL RD FPM <b>81-53348-00 K</b> → 90311-95008 95x115x12 A SL LD MVQ	
4,1 15B-FTE <b>[NEW]</b>	125 kW (170 PS) DYNA TDi	10/04→	<b>01-10856-04</b> ⑫ ⑬ 04111-58431  <b>02-10856-04</b> ⑫ 04112-58350 	<b>61-10105-00</b> 11115-58160 109,5 Ø 1,2 mm MLS <b>61-10105-10</b> 11115-58170 109,5 Ø 1,3 mm MLS <b>61-10105-20</b> 11115-58210 109,5 Ø 1,4 mm MLS 	<b>14-55005-01</b> 90910-02084 (18x) 	<b>71-10856-00</b> 11213-58021 	<b>12-54196-04</b> 90913-02096 (16x) <b>70-54196-00</b> 90913-02096	16x <b>71-10861-00</b> 17171-58030 	<b>71-10862-00</b> 17173-58050 	<b>70-31414-10</b> 	<b>81-53642-00 K</b> ← 90311-50013 50x72 A SL RD FPM <b>81-53348-00 K</b> → 90311-95008 95x115x12 A SL LD MVQ	
4,2 1HD-FT	125 kW (170 PS) LAND CRUISER TD	03/95-12/97		<b>61-54200-00</b> 11115-17031-01 1 mm 1 MLS <b>61-54200-10</b> 11115-17031-03 1,1 mm 3 MLS <b>61-54200-20</b> 11115-17031-05 1,2 mm 5 MLS 		<b>71-54316-00</b> 11213-17020 	<b>12-54196-02</b> 90913-02096 (24x) <b>70-54196-00</b> 90913-02096	24x <b>71-54317-00</b> 17171-17020 	2x <b>71-54314-00</b> 17173-17020 	<b>70-31414-10</b> 	<b>81-53291-00 K</b> ← 90311-58006 58x72x7 A SL RD MVQ <b>81-53292-00 K</b> ← 90311-58007 58x75x14 A SL RD MVQ <b>81-53348-00 K</b> → 90311-95008 95x115x12 A SL LD MVQ <b>81-53234-00 N</b> 90311-32017 32x46x6 A SL RD MVQ	
4,2 1HD-FTE	150 kW (204 PS) LAND CRUISER TD	01/98-08/07		<b>61-54200-00</b> 11115-17031-01 1 mm 1 MLS <b>61-54200-10</b> 11115-17031-03 1,1 mm 3 MLS <b>61-54200-20</b> 11115-17031-05 1,2 mm 5 MLS 		<b>71-54311-00</b> 11213-17030 	<b>12-54196-02</b> 90913-02096 (24x) <b>70-54196-00</b> 90913-02096	24x <b>71-54312-00</b> 17171-17030  <b>71-54313-00</b> ⑩ 17116-17020 	2x <b>71-54314-00</b> 17173-17020 	<b>70-31414-10</b> 	<b>81-53292-00 K</b> ← 90311-58007 58x75x14 A SL RD MVQ <b>81-53561-00 K</b> ← 90080-31098 65x79x7 A SL RD FPM <b>81-53348-00 K</b> → 90311-95008 95x115x12 A SL LD MVQ <b>81-53234-00 N</b> 90311-32017 32x46x6 A SL RD MVQ	



TOYOTA													
Ltr.													
4,2 1HD-T 1H-Z	59-123 kW (80-167 PS)	COASTER D COASTER TD LAND CRUISER D LAND CRUISER TD	10/87→	<b>01-53199-01</b> <sup>12</sup> <sup>13</sup> 04111-17011  <b>02-53199-01</b> <sup>12</sup> 04112-17011 	<b>61-53340-00</b> 11115-17010-01 95 Ø 1,2 mm 1 <b>61-53340-10</b> 11115-17010-03 95 Ø 1,3 mm 3 <b>61-53340-20</b> 11115-17010-05 95 Ø 1,4 mm 5 	<b>14-55031-03</b> 90910-02096 (26x) 	<b>71-53199-00</b> 11213-17010 	<b>12-53204-01</b> 90913-02094 (12x) <b>70-53204-00</b> 90913-02094 12x 	<b>71-53006-00</b> 17179-17010 5x  <b>71-53007-00</b> 17171-17010 1x 	<b>71-53008-00</b> 17173-17010 2x 	<b>70-31414-10</b> 	<b>81-53291-00</b> K ← 90311-58006 58x72x7 A SL RD MVQ <b>81-53292-00</b> K ← 90311-58007 58x75x14 A SL RD MVQ <b>81-53348-00</b> K → 90311-95008 95x115x12 A SL LD MVQ <b>81-53234-00</b> N 90311-32017 32x46x6 A SL RD MVQ	
4,2 2F	88-89 kW (120-121 PS)	LAND CRUISER	01/75-01/88	<b>01-52065-03</b> <sup>12</sup> <sup>13</sup> 04111-61044 <b>02-52065-03</b> <sup>12</sup> 04112-61041	<b>61-52065-00</b> 11115-61010 97 Ø 		<b>71-52203-00</b> 11213-61011 	<b>12-53033-01</b> 90913-02050 (12x)		<b>71-52631-00</b> <sup>7</sup> 17172-61040 	<b>71-52202-10</b> 12151-60021 	<b>81-53282-00</b> K ← 90311-45002 45x68x12 A SL RD ACM	
4,3 3UZ-FE <b>[NEW]</b>	208 kW (283 PS)	CELSIOR VVTi	09/00-08/06		<b>61-10160-00</b> R 11115-50070 92,4 Ø 1,1 mm MLS  <b>61-10161-00</b> L 11116-50060 92,4 Ø 1,1 mm MLS 	<b>14-12043-01</b> 2x 90910-02180 (10x) 	<b>15-11945-01</b> R 11213-50031 +11193-50010 (4x)  <b>15-11946-01</b> L 11214-50011 +11193-50010 (4x)  <b>71-11945-00</b> R 11213-50031  <b>71-11946-00</b> L 11214-50011 	<b>12-54024-01</b> 2x 90080-31084 (8x) +90080-31085 (8x) <b>70-54024-00</b> ES 16x 90080-31084 <b>70-54026-00</b> AS 16x 90080-31085	<b>71-11947-00</b> 2x 17171-50020  <b>71-11949-00</b> <sup>10</sup> 17116-50010 	<b>71-11948-00</b> 2x 17173-50021  <b>71-11960-00</b> <sup>8</sup> 90917-06059 	<b>70-31414-10</b> 	<b>81-10469-00</b> K ← 90311-43006 43x60x7 A SL RD <b>81-10470-00</b> K → 90311-95012 95x113x8,5 A SL LD <b>81-10452-00</b> N 2x 90311-71002 71x85x10 A SL RD	
4,5 1FZ-FE	151-215 kW (205-292 PS)	LAND CRUISER	08/92-01/98	<b>01-54125-01</b> <sup>12</sup> <sup>13</sup> 04111-66035 <b>02-54125-01</b> <sup>12</sup> 04112-66035	<b>61-54125-00</b> 11115-66031 1,4 mm 	<b>14-32354-01</b> 90910-02111 (14x) 	<b>15-54186-01</b> 11213-66021 +11193-15010 (6x) 	<b>12-54196-01</b> 90913-02096 (12x) +90913-02105 (12x) <b>70-54196-00</b> ES 12x 90913-02096 <b>70-54197-00</b> AS 12x 90913-02105	<b>71-54187-00</b> 17177-66040  <b>71-54191-00</b> <sup>10</sup> R 12x 17171-66010  <b>71-54192-00</b> <sup>10</sup> L 12x 17179-66010 	<b>71-54188-00</b> R 17173-66020  <b>71-54189-00</b> L 17198-66010 	<b>70-31414-10</b> 	<b>81-54193-00</b> K ← 90311-52022 52x70 A SL RD <b>81-54194-00</b> K → 90311-99009 99x119x9,5 A SL LD	

TOYOTA













Ltr. 






**1**

4,5 1VD-FTV **[NEW]** 151-210 kW (205-286 PS) LAND CRUISER D4-D LAND CRUISER TD LAND CRUISER V8 D LAND CRUISER V8 D-4D 03/07→






**61-10145-00 R**  
11115-51030-A0  
87,5 Ø  
1,25 mm 1   
MLS  
**61-10145-10 R**  
11115-51030-B0  
87,5 Ø  
1,3 mm 2   
MLS  
**61-10145-20 R**  
11115-51030-C0  
87,5 Ø  
1,35 mm 3   
MLS  
**61-10145-30 R**  
11115-51030-D0  
87,5 Ø  
1,4 mm 4   
MLS  
**61-10145-40 R**  
11115-51030-E0  
87,5 Ø  
1,45 mm 5   
MLS  
  
**61-10146-00 L**  
11116-51030-A0  
87,5 Ø  
1,25 mm 1   
MLS  
**61-10146-10 L**  
11116-51030-B0  
87,5 Ø  
1,3 mm 2   
MLS  
**61-10146-20 L**  
11116-51030-C0  
87,5 Ø  
1,35 mm 3   
MLS  
**61-10146-30 L**  
11116-51030-D0  
87,5 Ø  
1,4 mm 4   
MLS  
**61-10146-40 L**  
11116-51030-E0  
87,5 Ø  
1,45 mm 5   
MLS  


**14-11664-01**  
90910-02169 (10x)  


2x **15-11655-01 R**  
11213-51020  
+23682-51010 (4x)  
  
**15-11656-01 L**  
11214-51010  
+23682-51010 (4x)  


**12-53854-01**  
90913-W2001 (16x)  
**70-53854-00**  
90913-W2001

2x **71-11658-00**  
17177-51011  
32x **71-11659-00 R**  
17171-51010  
**71-11660-00 L**  
17179-51010  
**71-11663-00** <sup>10</sup>  
17116-51010  


**71-11661-00 R**  
17173-51020  
  
**71-11662-00 L**  
17198-51010  


**70-31414-10**  


**81-54193-00 K** ←  
90311-52022  
52x70  
A SL RD  
**81-54129-00 K** →  
90311-99010  
100x118x8,6  
A SL LD FPM