

LANCIA														
0,9 312 A2.000	63 kW (86 PS)	YPSILON	05/11→	02-38860-01 <sup>12</sup> 08-42098-01 <sup>13</sup>	61-38860-00 55239522 82,7 Ø MLS 	14-32376-01 55225419 (6X)	15-42102-01 55228597 +55225422 	12-42094-01 55225416 (8x) 70-42094-00 55225416	11-42116-01 77365787 8x 		71-42103-00 55230477 	70-31414-10 	81-35882-00 K ← 7628850 31x41x7 AB SL RD FPM 81-42108-00 K → 55229956 85x105x9 AB RD FPM	
1,0 156 A1.000	62 kW (84 PS)	Y10 Turbo	03/85-02/89	01-35570-03 <sup>12</sup> <sup>13</sup> 5882346 02-35570-03 <sup>12</sup> 5882347	61-35570-00 5921087 77 Ø 	14-35729-01 4467206 (5x) +7581743 (5x)	71-35611-00 7541092 	12-25837-01 7553637 (8x) 70-25837-00 5930415	8x 	71-35608-00 <sup>7</sup> 7741847 	2x	71-31743-00 4249510 	81-35878-00 K → 40004373 70x85x8 A LD MVQ 81-35883-00 N 40004940 30x52x7 AB SL RD FPM	
1,0 156 A2.000 156 A2.048 156 A2.100 156 A2.246	32-37 kW (44-50 PS)	Y10	03/85→	01-31790-01 <sup>12</sup> <sup>13</sup> 5892376 02-31790-02 <sup>12</sup> 5892375 08-35743-01 <sup>13</sup>	61-31790-10 7640784 1,65 mm 61-31790-20 X 1,9 mm 	14-32093-01 7696197 (10x) 	71-31734-00 7688450 	12-26058-02 4357028 (8x) 70-26058-00 7581344	8x 	71-35639-00 46426046 	2x	71-35617-00 7749711 	70-31414-10 	81-35719-00 K ← 40004200 23x35x7 AB SL RD FPM 81-35721-00 K → 40004190 70x88x8 AB SL LD FPM 81-17539-50 N 40004400 30x42x7 A SL RD FPM
1,1 156 C.000 156 C.046 176 B2.000	37-42 kW (50-57 PS)	Y Y10	07/89-09/03	01-31790-04 <sup>12</sup> <sup>13</sup> 5892382 02-31790-07 <sup>12</sup> 5892383	61-31790-10 7640784 1,65 mm 61-31790-20 X 1,9 mm 	14-32093-01 7696197 (10x) 	71-31734-00 7688450 	12-26058-02 4357028 (8x) 70-26058-00 7581344	8x 	71-35639-00 46426046 	2x	71-35617-00 7749711 	70-31414-10 	81-35721-00 K → 40004190 70x88x8 AB SL LD FPM Mot.→6315750 71754491 81-36644-00 K → 71754491 74x88x8 AB SL LD FPM Mot.6315751→ 81-17539-50 N 40004400 30x42x7 A SL RD FPM
1,2 169 A4.000	49-51 kW (67-69 PS)	YPSILON	08/10→	02-36900-01 <sup>12</sup> 71740655 08-37464-01 <sup>13</sup> 71728839	61-36900-00 55183371 MLS 	14-32093-01 7696197 (10x) 	15-37544-01 71740678 +71740677 (4x) 	70-33512-00 46470334	8x 	11-37546-01 77363787 		71-35617-00 7749711 	70-31414-10 	81-37461-00 K ← 71740681 27x37x7 AB RD FPM 81-36644-00 K → 71754491 74x88x8 AB SL LD FPM 81-35623-00 N 55195339 40x55x7 AB SL RD FPM/ACM
1,2 176 B9.000	63 kW (86 PS)	Y 16V	04/97-09/03	02-35575-01 <sup>12</sup> 71711936 08-37464-01 <sup>13</sup> 71728839	61-35575-10 46434596 72 Ø 	14-35731-01 7795992 (10x) 	71-35621-10 55194045 	12-33512-02 46470334 (16x) 70-33512-00 46470334	16x 	71-35618-00 46425904 		71-35619-00 46425908 	70-31414-10 	81-37461-00 K ← 71740681 27x37x7 AB RD FPM 81-36644-00 K → 71754491 74x88x8 AB SL LD FPM 81-35623-00 N 55195339 40x55x7 AB SL RD FPM/ACM



LANCIA													
Ltr.													
1,3 146 A 5.046 156 B.000	53-56 kW (72-76 PS) Y10	11/87-12/95	<b>02-35570-04</b> <sup>12</sup> 5891839	<b>61-35570-00</b> 5921087 77 Ø 	<b>14-35729-01</b> 4467206 (5x) +7581743 (5x) 	<b>71-35611-00</b> 7541092 	<b>12-25837-01</b> 7553637 (8x) <b>70-25837-00</b> 5930415	8x	<b>71-35608-00</b> <sup>7</sup> 7741847 	2x	<b>71-31743-00</b> 4249510 	<b>81-35878-00</b> K → 40004373 70x85x8 A LD MVQ <b>81-35883-00</b> N 40004940 30x52x7 AB SL RD FPM	
1,3 149 A7.000	50 kW (68 PS)	01/85→	<b>02-26250-02</b> <sup>12</sup>	<b>61-26250-10</b> 7679380 87 Ø 1,8 mm 	<b>14-35733-01</b> 46430687 (5x) +46430688 (5x) 	<b>71-13027-00</b> 7554851 	<b>12-25837-01</b> 7553637 (8x) <b>70-25837-00</b> 5930415	8x	<b>71-35713-00</b> <sup>7</sup> 7665722 	2x	<b>71-12929-00</b> 4179038 		
1,3 188 A9.000	51 kW (70 PS) MUSA YPSILON JTD	10/03-09/12	<b>02-36259-01</b> <sup>12</sup> 71729499  <b>08-36261-01</b> <sup>13</sup> 71736913 	<b>61-36210-00</b> 55209070 70,5 Ø 0,72 mm MLS <b>61-36210-10</b> 55209071 70,5 Ø 0,82 mm 1 MLS <b>61-36210-20</b> 55209072 70,5 Ø 0,92 mm 2 MLS 	<b>14-32191-01</b> 55192265 (10x)  RIBE	<b>71-36259-00</b> 73500063 Metall 	<b>12-31306-12</b> 46556651 (16x) <b>70-31306-00</b> 46556651	16x	<b>71-36209-00</b> 73501362 	<b>71-36322-00</b> 73500058 	<b>70-31414-10</b> 	<b>81-36233-00</b> K ← 55186757 40x52x7 AB SL RD ACM FPM <b>81-36232-00</b> K → 55180937 78x100x9 A SL LD PTFE	
1,3 199 A2.000	55 kW (75 PS) YPSILON	09/06-12/11	<b>02-36259-01</b> <sup>12</sup> 71729499  <b>08-36261-01</b> <sup>13</sup> 71736913 	<b>61-36210-00</b> 55209070 70,5 Ø 0,72 mm MLS <b>61-36210-10</b> 55209071 70,5 Ø 0,82 mm 1 MLS <b>61-36210-20</b> 55209072 70,5 Ø 0,92 mm 2 MLS 	<b>14-32191-01</b> 55192265 (10x)  RIBE	<b>71-36259-00</b> 73500063 Metall 	<b>12-31306-12</b> 46556651 (16x) <b>70-31306-00</b> 46556651	16x	<b>71-38228-00</b> 71748757 	<b>71-36322-00</b> 73500058 	<b>70-31414-10</b> 	<b>81-36233-00</b> K ← 55186757 40x52x7 AB SL RD ACM FPM <b>81-36232-00</b> K → 55180937 78x100x9 A SL LD PTFE	

LANCIA												
Ltr.												
1,3 199 A3.000	66-77 kW (90-105 PS)	MUSA YPSILON	09/06-09/12	<b>02-36259-02</b> <sup>12</sup> 71744288  <b>08-36261-02</b> <sup>13</sup> 71744287 	<b>61-36210-00</b> 55209070 70,5 Ø 0,72 mm MLS <b>61-36210-10</b> 55209071 70,5 Ø 0,82 mm 1 MLS <b>61-36210-20</b> 55209072 70,5 Ø 0,92 mm 2 MLS 	<b>14-32191-01</b> 55192265 (10x)  RIBE	<b>71-36259-00</b> 73500063 Metall 	<b>12-31306-12</b> 46556651 (16x) <b>70-31306-00</b> 46556651	<b>71-38228-00</b> 71748757 16x 	<b>71-36322-00</b> 73500058 	<b>70-31414-10</b> 	<b>81-36233-00</b> K ← 55186757 40x52x7 AB SL RD ACM FPM <b>81-36232-00</b> K → 55180937 78x100x9 A SL LD PTFE
1,3 199 B1.000	70 kW (95 PS)	MUSA YPSILON	03/09→	<b>02-36259-04</b> <sup>12</sup> 71753908  <b>08-36261-05</b> <sup>13</sup> 71753767 	<b>61-36210-00</b> 55209070 70,5 Ø 0,72 mm MLS <b>61-36210-10</b> 55209071 70,5 Ø 0,82 mm 1 MLS <b>61-36210-20</b> 55209072 70,5 Ø 0,92 mm 2 MLS 	<b>14-32191-01</b> 55192265 (10x)  RIBE	<b>71-36259-00</b> 73500063 Metall 	<b>12-31306-12</b> 46556651 (16x) <b>70-31306-00</b> 46556651	<b>71-39538-00</b> 71749369 4x 	<b>71-36322-00</b> 73500058 	<b>70-31414-10</b> 	<b>81-36233-00</b> K ← 55186757 40x52x7 AB SL RD ACM FPM <b>81-36232-00</b> K → 55180937 78x100x9 A SL LD PTFE
1,3 831 B.000	55 kW (75 PS)	DELTA	09/79-08/92	<b>01-31775-01</b> <sup>12</sup> <sup>13</sup> 5892412 <b>02-31775-01</b> <sup>12</sup> 5892374	<b>61-31775-00</b> 7588550 87,5 Ø <b>61-31775-10</b> 4479025 77,5 Ø 1,8 mm 	<b>14-35733-01</b> 46430687 (5x) +46430688 (5x) 	<b>71-31731-00</b> 4448677 	<b>12-25837-01</b> 7553637 (8x) <b>70-25837-00</b> 5930415	<b>71-35716-00</b> <sup>7</sup> 7772495 	<b>71-12929-00</b> 4179038 	<b>81-35877-00</b> K → 40004280 64x80x8 A SL LD MVQ <b>81-35883-00</b> N 40004940 30x52x7 AB SL RD FPM	
1,4 160 A1.046 836 A4.000	51 kW (69 PS)	DELTA	10/94-08/99	<b>01-31760-01</b> <sup>12</sup> <sup>13</sup> 5893279 <b>02-31760-02</b> <sup>12</sup>	<b>61-31760-00</b> 7666858 81 Ø 	<b>14-35733-01</b> 46430687 (5x) +46430688 (5x) 	<b>71-31732-00</b> 7784728 	<b>12-25837-01</b> 7553637 (8x) <b>70-25837-00</b> 5930415	<b>71-35716-00</b> <sup>7</sup> 7772495 	<b>71-31742-00</b> 7554364 	<b>81-35877-00</b> K → 40004280 64x80x8 A SL LD MVQ <b>81-35883-00</b> N 2x 40004940 30x52x7 AB SL RD FPM	
1,4 192 B2.000	66 kW (90 PS)	MUSA	10/07-09/12	<b>02-37110-02</b> <sup>12</sup> 71747638 <b>08-90041-01</b> <sup>13</sup> <sup>35</sup>	<b>61-37110-00</b> 55202800 73 Ø MLS 	<b>14-35731-01</b> 7795992 (10x)  RIBE	<b>71-35621-10</b> 55194045 	<b>70-26058-00</b> 7581344 16x	<b>11-37648-01</b> 71739944 	<b>71-35702-00</b> 46526271 	<b>70-31414-10</b> 	<b>81-37461-00</b> K ← 71740681 27x37x7 AB RD FPM <b>81-90041-00</b> K → 46539824 FPM/ACM <b>81-35623-00</b> N 55195339 40x55x7 AB SL RD FPM/ACM

LANCIA													
Ltr.													
1,4 198 A1.000 198 A4.000	88-110 kW (120-150 PS)	DELTA	09/08-08/14	02-38835-01 <sup>12</sup> 71749165 08-90041-01 <sup>13</sup> <sup>35</sup>	61-38835-00 55206232 73 Ø MLS 	14-35731-01 7795992 (10x) 	71-35621-10 55194045 	12-33512-02 46470334 (16x) 70-33512-00 46470334	16x 	11-38834-01 77364551 	71-38831-00 55210321 	70-31414-10 	81-37461-00 K ← 71740681 27x37x7 AB RD FPM 81-90041-00 K → 46539824 FPM/ACM 81-35623-00 N 55195339 40x55x7 AB SL RD FPM/ACM
1,4 198 A7.000	103 kW (140 PS)	DELTA III	07/10-08/14	02-38835-02 <sup>12</sup> 08-90041-03 <sup>13</sup>	61-38835-00 55206232 73 Ø MLS 	14-35731-01 7795992 (10x) 	15-42128-01 55233643 +55233644 (4x) 	12-33512-02 46470334 (16x) 70-33512-00 46470334	16x 	11-38834-01 77364551 	71-42124-00 55233663 	70-31414-10 	81-37461-00 K ← 71740681 27x37x7 AB RD FPM 81-90041-00 K → 46539824 FPM/ACM 81-37459-00 N 55189997 31x55x7 AB SL RD FPM
1,4 350 A1.000	57 kW (78 PS)	MUSA YPSILON	09/05-09/12	02-36900-01 <sup>12</sup> 71740655 08-37464-01 <sup>13</sup> 71728839	61-36900-00 55183371 MLS 	14-32093-01 7696197 (10x) 	15-37544-01 71740678 +71740677 (4x) 	12-34223-03 55190344 (8x) 70-34223-00 55190344	8x 	11-37546-01 77363787 	71-35617-00 7749711 	2x 70-31414-10 	81-37461-00 K ← 71740681 27x37x7 AB RD FPM 81-36644-00 K → 71754491 74x88x8 AB SL LD FPM 81-35623-00 N 55195339 40x55x7 AB SL RD FPM/ACM
1,4 840 A2.000 840 A4.000	55-59 kW (75-80 PS)	Y	03/96-09/03	01-35585-01 <sup>12</sup> <sup>13</sup> 5895645 02-35585-01 <sup>12</sup> 5895644 08-35749-01 <sup>13</sup>	61-35585-00 7744000 83 Ø 	14-35732-01 46420638 (10x) 	71-35644-00 7768026 	12-26058-01 4357028 (12x) 70-26058-00 7581344	12x 	71-35642-00 46410891 	71-35643-00 46414438 	70-31414-10 	81-35882-00 K ← 7628850 31x41x7 AB SL RD FPM 81-90027-00 K → 71718365 81-17539-50 N 2x 40004400 30x42x7 A SL RD FPM
1,4 843 A1.000	70 kW (95 PS)	MUSA YPSILON	10/03-09/12	02-34940-01 <sup>12</sup> 71739945 →04/06 02-37110-02 <sup>12</sup> 71747638 05/06→ 08-90041-01 <sup>13</sup> <sup>35</sup>	61-34940-00 55197283 MLS →04/06  61-37110-00 55202800 73 Ø MLS 05/06→ 	14-35731-01 7795992 (10x) 	71-35621-10 55194045 	70-33512-00 46470334 →04/06 70-26058-00 7581344 05/06→	16x 	11-37648-01 71739944 	71-35702-00 46526271 	70-31414-10 	81-37461-00 K ← 71740681 27x37x7 AB RD FPM 81-90041-00 K → 46539824 FPM/ACM 81-35623-00 N 55195339 40x55x7 AB SL RD FPM/ACM
1,5 138 C2.048	55 kW (75 PS)	PRISMA	09/85-02/92		61-35725-00 87 Ø 	14-35733-01 46430687 (5x) +46430688 (5x) 	71-31731-00 4448677 	12-25837-01 7553637 (8x) 70-25837-00 5930415	8x 		71-35713-00 <sup>7</sup> 7665722 	2x 71-12929-00 4179038 	81-35877-00 K → 40004280 64x80x8 A SL LD MVQ 81-35883-00 N 40004940 30x52x7 AB SL RD FPM

LANCIA													
Ltr.													
1,5 831 A1.000 831 B1.048	55-63 kW (75-86 PS) DELTA PRISMA	09/79-12/92	<b>02-31825-02</b> ⑫ 5892381	<b>61-31825-10</b> 7580221 87 Ø	<b>14-35733-01</b> 46430687 (5x) +46430688 (5x)	<b>71-31731-00</b> 4448677	<b>12-26058-02</b> 4357028 (8x) <b>70-26058-00</b> 7581344	8x	<b>71-35716-00</b> ⑦ 7772495	2x	<b>71-12929-00</b> 4179038	<b>81-35877-00</b> K → 40004280 64x80x8 <b>81-35883-00</b> N 40004940 30x52x7 AB SL RD FPM	2x
1,6 159 B9.000 835 C1.000	55-66 kW (75-90 PS) DEDRA DELTA	04/93-08/99	<b>01-31755-04</b> ⑫ ⑬ 5894257 <b>02-31755-03</b> ⑫ 5894256 <b>08-31742-06</b> ⑬	<b>61-31755-00</b> 46414567 87,3 Ø	<b>14-35733-01</b> 46430687 (5x) +46430688 (5x)	<b>71-31729-00</b> 7797034	<b>12-25837-01</b> 7553637 (8x) <b>70-25837-00</b> 5930415	8x	<b>71-35716-00</b> ⑦ 7772495		<b>71-31742-00</b> 7554364	<b>81-35877-00</b> K → 40004280 64x80x8 A SL LD MVQ <b>81-35883-00</b> N 40004940 30x52x7 AB SL RD FPM	2x
1,6 182 A4.000 182 A6.000	66-76 kW (90-103 PS) DEDRA 16V DELTA 16V LYBRA 16V	01/96-10/05	<b>01-35595-01</b> ⑫ ⑬ 71713032 Mot.→010784 <b>02-35595-01</b> ⑫ 5895663 <b>08-31742-03</b> ⑬ Mot.→010784	<b>61-35595-00</b> 46410960 87 Ø	<b>14-35734-03</b> 7758731 (10x)  RIBE	<b>71-35648-00</b> 2x 7773831	<b>12-26058-03</b> 4357028 (16x) <b>70-26058-00</b> 7581344	16x	<b>71-35649-00</b> 46410505 <b>71-35651-00</b> 4x 46402220	<b>71-35652-00</b> 46412116	<b>71-31742-00</b> 7554364 Mot.→010784	<b>81-35877-00</b> K → 40004280 64x80x8 A SL LD MVQ Mot.→010784 <b>81-35883-00</b> N 40004940 30x52x7 AB SL RD FPM Mot.→010784	2x
1,6 182 B6.000	76 kW (103 PS) LYBRA	10/00-10/05	<b>01-35595-01</b> ⑫ ⑬ 71713032 Mot.→9508753 <b>02-35595-01</b> ⑫ 5895663 <b>08-31742-03</b> ⑬ Mot.→9508753	<b>61-35595-00</b> 46410960 87 Ø	<b>14-35734-03</b> 7758731 (10x) Mot.→9508753  RIBE <b>14-35733-01</b> 46430687 (5x) +46430688 (5x) Mot.9508754→ 	<b>71-35648-00</b> 2x 7773831	<b>12-26058-03</b> 4357028 (16x) <b>70-26058-00</b> 7581344	16x	<b>71-35649-00</b> 46410505 <b>71-35651-00</b> 4x 46402220	<b>71-35652-00</b> 46412116	<b>71-31742-00</b> 7554364 Mot.→9508753	<b>81-21087-10</b> K ← 40x56x7 B RD ACM <b>81-35876-00</b> K → 42x56/63x7 AB SL RD MVQ Mot.→9508753 <b>81-34805-00</b> K → 32x45x6 A SL RD ACM Mot.9508754→ <b>81-35883-00</b> N 40004940 30x52x7 AB SL RD FPM	2x
1,6 198 A2.000 944 A 3.000	77-88 kW (105-120 PS) DELTA	09/08-08/14	<b>02-42061-02</b> ⑫ 71754668  <b>08-36278-03</b> ⑬ ⑳ 71749743 	<b>61-38200-00</b> 55221093 80,5 Ø 0,82 mm 0 MLS <b>61-38200-10</b> 55221094 80,5 Ø 0,92 mm 1 □ MLS <b>61-38200-20</b> 55221095 80,5 Ø 1,02 mm 2 □ MLS	<b>14-32363-01</b> 55214378 (10x)  RIBE	<b>71-42061-00</b> 55205111	<b>12-38209-02</b> 55183812 (16x) <b>70-38209-00</b> 55183812	16x	<b>11-40692-01</b> 71754211 	<b>71-42064-00</b> 55210879  <b>71-42073-00</b> ① 55206838 	<b>70-31414-10</b> 	<b>81-35882-00</b> K ← 7828850 31x41x7 AB SL RD FPM <b>81-90027-00</b> K → 71718365 <b>81-36229-00</b> N 46802577 30x45x7 AB SL RD FPM	

LANCIA												
Ltr.												
1,6 350 A2.000 350 A3.000	85-88 kW (116-120 PS)	MUSA	07/08-09/12	<b>02-42061-02</b> ⑫ 71754668  <b>08-36278-03</b> ⑬ ⑮ 71749743 	<b>61-38200-00</b> 55221093 80,5 Ø 0,82 mm 0 MLS <b>61-38200-10</b> 55221094 80,5 Ø 0,92 mm 1 □ MLS <b>61-38200-20</b> 55221095 80,5 Ø 1,02 mm 2 □ MLS 	<b>14-32363-01</b> 55214378 (10x)  RIBE	<b>71-42061-00</b> 55205111 	<b>12-38209-02</b> 55183812 (16x) <b>70-38209-00</b> 55183812 	<b>11-40692-01</b> 71754211 16x 	<b>71-42064-00</b> 55210879 	<b>70-31414-10</b> 	<b>81-35882-00 K</b> ← 7628850 31x41x7 AB SL RD FPM <b>81-90027-00 K</b> → 71718365 <b>81-36229-00 N</b> 46802577 30x45x7 AB SL RD FPM
1,6 828 B.000	74 kW (100-101 PS)	BETA TREVI	08/73-01/87	<b>01-31800-01</b> ⑫ ⑬ 5880452 <b>02-31800-01</b> 5880451 <b>08-12961-04</b> ⑬ 	<b>61-31800-00</b> 4387624 85 Ø 1,35 mm <b>61-31800-10</b> 5951675 85 Ø 1,8 mm 		<b>71-31738-00</b> 2x 4158646 	<b>12-25837-01</b> 7553637 (8x) <b>70-25837-00</b> 5930415 	<b>71-35722-00</b> 4194060 8x 	<b>71-21584-00</b> 4177112  <b>71-21608-10</b> 4166914 	<b>71-12961-00</b> 4331606 	<b>81-15287-10 K</b> → 70x90x10 A LD MVQ <b>81-35883-00 N</b> 2x 40004940 30x52x7 AB SL RD FPM
1,6 831 A4.000	77 kW (105 PS)	DELTA PRISMA	11/82-04/86	<b>01-31740-01</b> ⑫ ⑬ 5881903 <b>02-31740-01</b> ⑫ 5881904 	<b>61-31740-00</b> 5951675 85 Ø 		<b>71-31738-00</b> 2x 4158646 	<b>12-25837-01</b> 7553637 (8x) <b>70-25837-00</b> 5930415 	<b>71-35722-00</b> 4194060 8x 	<b>71-21584-00</b> 4177112 	<b>71-12961-00</b> 4331606 	<b>81-35881-00 K</b> → 40004300 74x90x10 AB SL LD MVQ <b>81-35883-00 N</b> 2x 40004940 30x52x7 AB SL RD FPM
1,6 831 A7.000	96 kW (131 PS)	DELTA Turbo	10/83-12/86	<b>02-31735-04</b> ⑫ 5882240 	<b>61-31735-00</b> 4314165 85 Ø 	<b>14-35742-01</b> 60807357 (10x)  RIBE	<b>71-31726-00</b> 2x 4158656 	<b>12-25837-01</b> 7553637 (8x) <b>70-25837-00</b> 5930415 	<b>71-35666-00</b> 2x 7700197 8x 	<b>71-21584-00</b> 4177112 	<b>71-31744-00</b> 5959226 Gummi Kork 	<b>81-35624-00 K</b> ← 40004260 30x43x8 AB SL RD FPM <b>81-15287-10 K</b> → 70x90x10 A LD MVQ <b>81-35883-00 N</b> 2x 40004940 30x52x7 AB SL RD FPM
1,6 831 B6.000	73 kW (99 PS)	PRISMA	08/86-02/92	<b>01-31735-04</b> ⑫ ⑬ 	<b>61-31735-00</b> 4314165 85 Ø 		<b>71-31738-00</b> 2x 4158646 	<b>12-25837-01</b> 7553637 (8x) <b>70-25837-00</b> 5930415 	<b>71-35724-00</b> 7625504 8x 	<b>71-21584-00</b> 4177112 	<b>71-31744-00</b> 5959226 Gummi Kork 	<b>81-15287-10 K</b> → 70x90x10 A LD MVQ <b>81-35883-00 N</b> 2x 40004940 30x52x7 AB SL RD FPM
1,6 831 B7.000	80 kW (108-109 PS)	DELTA PRISMA	05/86-12/89	<b>01-31735-02</b> ⑫ ⑬ 5882699 <b>08-31744-03</b> ⑬ 	<b>61-31735-00</b> 4314165 85 Ø 	<b>14-35742-01</b> 60807357 (10x)  RIBE	<b>71-31726-00</b> 4158656 	<b>12-25837-01</b> 7553637 (8x) <b>70-25837-00</b> 5930415 	<b>71-35666-00</b> 2x 7700197 8x 	<b>71-21584-00</b> 4177112 	<b>71-31744-00</b> 5959226 Gummi Kork 	<b>81-35624-00 K</b> ← 40004260 30x43x8 AB SL RD FPM <b>81-15287-10 K</b> → 70x90x10 A LD MVQ <b>81-35883-00 N</b> 2x 40004940 30x52x7 AB SL RD FPM

LANCIA												
Ltr.												
1,6 831 B7.046	97 kW (132 PS)	DELTA Turbo	04/87-03/89	<b>01-35680-01</b> ⑫ ⑬ 5882032 <b>02-35680-01</b> ⑫ 5882033 <b>08-12961-05</b> ⑬	<b>61-35680-00</b> 5953040 85 Ø 	<b>14-35742-01</b> 60807357 (10x) 	<b>71-31738-00</b> 2x 4158646 	<b>12-25837-01</b> 7553637 (8x) <b>70-25837-00</b> 5930415 	<b>71-35722-00</b> 4194060 8x 	<b>71-21584-00</b> 4177112 	<b>71-12961-00</b> 4331606 	<b>81-35624-00</b> K ← 40004260 30x43x8 AB SL RD FPM <b>81-15287-10</b> K → 70x90x10 A LD MVQ <b>81-35883-00</b> N 2x 40004940 30x52x7 AB SL RD FPM
1,6 835 A1.000 835 A1.046	57-66 kW (78-90 PS)	DEDRA	08/89-06/94	<b>01-31755-02</b> ⑫ ⑬ 5892378 <b>02-31755-01</b> ⑫ 5892379 <b>08-31742-01</b> ⑬	<b>61-31755-00</b> 46414567 87,3 Ø 	<b>14-35733-01</b> 46430687 (5x) +46430688 (5x) 	<b>71-31729-00</b> 0 7797034 <b>71-31732-00</b> U 7784728 	<b>12-25837-01</b> 7553637 (8x) <b>70-25837-00</b> 5930415 8x 	<b>71-35716-00</b> ⑦ 7772495 	<b>71-31742-00</b> 7554364 	<b>81-35883-00</b> N 2x 40004940 30x52x7 AB SL RD FPM	
1,6 955 A4.000 <b>[NEW]</b>	85 kW (116 PS)	DELTA III (844)	08/08-08/14	<b>02-42061-02</b> ⑫ 71754668  <b>08-36278-03</b> ⑬ ⑮ 71749743 	<b>61-38200-00</b> 55221093 80,5 Ø 0,82 mm 0 MLS <b>61-38200-10</b> 55221094 80,5 Ø 0,92 mm 1 □ MLS <b>61-38200-20</b> 55221095 80,5 Ø 1,02 mm 2 □ MLS 	<b>14-32363-01</b> 55214378 (10x) 	<b>71-42061-00</b> 55205111 	<b>12-38209-02</b> 55183812 (16x) <b>70-38209-00</b> 55183812 16x 	<b>11-40692-01</b> 71754211 	<b>71-42064-00</b> 55210879 	<b>70-31414-10</b> 	<b>81-90027-00</b> K → 71718365 <b>81-36229-00</b> N 46802577 30x45x7 AB SL RD FPM
1,8 182 A2.000 183 A1.000 839 A4.000	83-96 kW (113-131 PS)	DEDRA GT 16V DEDRA 16V DELTA 16V LYBRA 16V	03/96-10/05	<b>01-35600-01</b> ⑫ ⑬ ⑮ 5895244 <b>02-35600-01</b> ⑫ 5895243	<b>61-35600-00</b> 60608894 83 Ø 	<b>14-32220-01</b> 7710582 (10x) 	<b>71-35659-00</b> 4x 7715492 	<b>12-26058-03</b> 4357028 (16x) <b>70-26058-00</b> 7581344 16x 	<b>71-35657-00</b> 60659747 	<b>71-35658-00</b> 60611531 	<b>70-31414-10</b> 	<b>81-35882-00</b> K ← 7628850 31x41x7 AB SL RD FPM <b>81-90027-00</b> K → 71718365 <b>81-17539-50</b> N 2x 40004400 30x42x7 A SL RD FPM <b>81-35723-00</b> N 60811144 55x68x8 AB SL RD FPM
1,8 835 A2.000	80 kW (109 PS)	DEDRA	09/89-06/94	<b>01-31830-08</b> ⑫ ⑬ 5892008 <b>02-31830-10</b> ⑫ 5892007 <b>08-31751-04</b> ⑬	<b>61-31830-00</b> 5891307 85 Ø 	<b>14-35742-01</b> 60807357 (10x) 	<b>71-35677-00</b> 2x 7715789 	<b>12-25837-01</b> 7553637 (8x) <b>70-25837-00</b> 5930415 	<b>71-35666-00</b> 2x 7700197 8x 	<b>71-21584-00</b> 4177112 	<b>71-31751-00</b> 7646248 	<b>81-35624-00</b> K ← 40004260 30x43x8 AB SL RD FPM <b>81-35627-00</b> K → 40005000 30x44x8 AB SL LD FPM <b>81-35881-00</b> N 40004300 74x90x10 AB SL LD FPM <b>81-35883-00</b> N 2x 40004940 30x52x7 AB SL RD FPM



LANCIA													
1.8 835 C4.000 836 A6.000 836 C4.000	66 kW (90 PS)	DELTA	07/94-08/99	01-31830-07 <sup>12</sup> <sup>13</sup> 5893003	61-31830-00 5891307 85 Ø 		71-35677-00 2x 7715789 	12-25837-01 7553637 (8x) 70-25837-00 5930415	71-35666-00 2x 7700197 8x 		71-21584-00 4177112 	71-31751-00 7646248 	81-35624-00 K ← 40004260 30x43x8 AB SL RD FPM 81-35881-00 K → 40004300 74x90x10 AB SL LD MVQ
1.8 835 C5.000	66 kW (90 PS)	DEDRA	08/93-07/99	01-31830-09 <sup>12</sup> <sup>13</sup> 02-31830-11 <sup>12</sup> 5893002	61-31830-00 5891307 85 Ø 		71-31726-00 2x 4158656 	12-26058-02 4357028 (8x) 70-26058-00 7581344	71-35666-00 2x 7700197 8x 		71-21584-00 4177112 	71-12961-00 4331606 	81-35624-00 K ← 40004260 30x43x8 AB SL RD FPM 81-35881-00 K → 40004300 74x90x10 AB SL LD MVQ 81-34368-00 N 2x 32x47x10 A SL LD PTFE ACM
1.8 836 A2.046 836 A5.000	74 kW (101 PS)	DEDRA	07/94 →	02-31830-09 <sup>12</sup> 5893329	61-31830-00 5891307 85 Ø 		71-35677-00 2x 7715789 	12-25837-01 7553637 (8x) 70-25837-00 5930415	71-35666-00 2x 7700197 8x 		71-21584-00 4177112 	71-31751-00 7646248 	
1.8 839 A7.000 839 A9.000	96 kW (131 PS)	LYBRA 16V	07/99-10/05	02-36140-01 71717900 08-38299-01 <sup>13</sup> <sup>35</sup> 71730148 +71718365 	61-36140-00 60664642 MLS 	14-32220-01 7710582 (10x)  RIBE	71-35659-00 4x 7715492  71-35661-00 60586217 	12-26058-03 4357028 (16x) 70-26058-00 7581344	71-35657-00 60659747 16x 		71-35658-00 60611531 	70-31414-10 	81-35882-00 K ← 7628850 31x41x7 AB SL RD FPM 81-90027-00 K → 71718365 81-17539-50 N ← 40004400 30x42x7 A SL RD FPM 81-35723-00 N → 60811144 55x68x8 AB SL RD FPM
1.8 939 B1.000	147 kW (200 PS)	DELTA	01/09-08/14		61-38230-00 55215398 MLS 	14-32375-01 55214072 (10x) 	70-31414-10 		11-42136-01 77365293 		71-42131-00 55214576 	70-31414-10 	81-35882-00 K ← 7628850 31x41x7 AB SL RD FPM 81-90027-00 K → 71718365 81-35623-00 N 2x 55195339 40x55x7 AB SL RD FPM/ACM
1.9 AR 32302	77 kW (105 PS)	LYBRA JTD	07/99-09/00	01-35679-02 <sup>12</sup> <sup>13</sup> 71712830  02-35679-02 <sup>12</sup> 71712831  08-35748-01 <sup>13</sup>	61-33755-00 60814599 83 Ø 1,6 mm MLS 61-33755-10 60814600 83 Ø 1,7 mm 1 MLS 61-33755-20 60814601 83 Ø 1,8 mm 2 MLS 	14-35738-01 7775920 (10x)  RIBE	71-35679-00 7737607 	12-25837-01 7553637 (8x) 70-25837-00 5930415	71-36306-00 71738458 8x 		71-35637-00 46467747 	70-31414-10 	81-35882-00 K ← 7628850 31x41x7 AB SL RD FPM 81-90027-00 K → 71718365 81-17539-50 N 2x 40004400 30x42x7 A SL RD FPM

LANCIA													
Ltr.			<b>1</b>										
1,9 160 D1.000 835 A4.000 835 A4.046	66 kW (90 PS) DEDRA TDS DELTA TD	04/89-08/99		<b>01-31737-05</b> <sup>(12)</sup> <sup>(13)</sup> 5892422 	<b>61-31750-00</b> 7630180 83,2 Ø 1,65 mm <b>61-31750-10</b> 46431640 83,2 Ø 1,8 mm 1	<b>14-32094-01</b> 7653650 (10x) 	<b>71-31737-00</b> 4394109 	<b>12-25837-01</b> 7553637 (8x) <b>70-25837-00</b> 5930415	8x	<b>71-35727-00</b> <sup>(7)</sup> 46462772 	<b>71-31744-00</b> 5959226 Gummi Kork 	<b>81-35624-00</b> K ← 40004260 30x43x8 AB SL RD FPM <b>81-35881-00</b> K → 40004300 74x90x10 AB SL LD MVQ <b>81-35883-00</b> N 2x 40004940 30x52x7 AB SL RD FPM	
1,9 188 B2.000	74 kW (101 PS) MUSA	10/04-09/12		<b>02-35638-04</b> <sup>(12)</sup> 71718658 Mot.→4081110 	<b>61-35580-00</b> 46749904 83 Ø 0,82 mm <b>61-35580-10</b> 46749905 83 Ø 0,92 mm 1	<b>14-35738-01</b> 7775920 (10x) Mot.→5693776 	<b>71-35638-10</b> 46552748 Mot.→4081110 	<b>12-22737-01</b> 5930415 (8x) <b>70-22737-00</b> 5930415	8x	<b>71-36306-00</b> 71738458 	<b>71-35637-00</b> 46467747 	<b>70-31414-10</b> 	<b>81-35882-00</b> K ← 7628850 31x41x7 AB SL RD FPM <b>81-90027-00</b> K → 71718365 <b>81-17539-50</b> N 40004400 30x42x7 A SL RD FPM
1,9 831 D.000	48 kW (65 PS) PRISMA D	01/83-02/92		<b>01-31737-04</b> <sup>(12)</sup> <sup>(13)</sup> 5882358 	<b>61-31795-00</b> 5962711 83 Ø 1,65 mm <b>61-31795-10</b> 5962712 83 Ø 1,8 mm 1	<b>14-32094-01</b> 7653650 (10x) 	<b>71-31737-00</b> 4394109 	<b>12-25837-01</b> 7553637 (8x) <b>70-25837-00</b> 5930415	8x	<b>71-35662-00</b> <sup>(7)</sup> 46462772 	<b>71-31744-00</b> 5959226 Gummi Kork 	<b>81-35624-00</b> K ← 40004260 30x43x8 AB SL RD FPM <b>81-35881-00</b> K → 40004300 74x90x10 AB SL LD MVQ <b>81-35883-00</b> N 2x 40004940 30x52x7 AB SL RD FPM	
1,9 831 D1.000	59 kW (80 PS) DELTA TD PRISMA TD	05/85-12/89		<b>01-31728-01</b> <sup>(12)</sup> <sup>(13)</sup> 5892426 	<b>61-31795-00</b> 5962711 83 Ø 1,65 mm <b>61-31795-10</b> 5962712 83 Ø 1,8 mm 1	<b>14-32094-01</b> 7653650 (10x) 	<b>71-31728-00</b> 5980056 	<b>12-25837-01</b> 7553637 (8x) <b>70-25837-00</b> 5930415	8x	<b>71-35662-00</b> <sup>(7)</sup> 46462772 	<b>71-31744-00</b> 5959226 Gummi Kork 	<b>81-35624-00</b> K ← 40004260 30x43x8 AB SL RD FPM <b>81-35881-00</b> K → 40004300 74x90x10 AB SL LD MVQ <b>81-35883-00</b> N 2x 40004940 30x52x7 AB SL RD FPM	

LANCIA													
Ltr.													
1,9 844 A1.000	140 kW (190 PS)	DELTA	01/09-08/14	<b>02-42061-01</b> ⑫ 71752999  <b>08-36278-04</b> ⑬ ⑮ 71752104 +71718365 	<b>61-38225-00</b> 55206445 0,95 mm 0 MLS <b>61-38225-10</b> 55206455 1,05 mm 1 □ MLS <b>61-38225-20</b> 55206456 1,15 mm 2 □ MLS 	<b>14-32321-01</b> 55214216 (10x)  RIBE	<b>71-42061-00</b> 55205111 	<b>12-38209-02</b> 55183812 (16x) <b>70-38209-00</b> 55183812 16x 	<b>11-40692-01</b> 71754211 	<b>71-42064-00</b> 55210879 	<b>70-31414-10</b> 	<b>81-35882-00 K</b> ← 7628850 31x41x7 AB SL RD FPM <b>81-90027-00 K</b> → 71718365 <b>81-36229-00 N</b> 46802577 30x45x7 AB SL RD FPM	
1,9 937 A2.000	85 kW (116 PS)	LYBRA JTD	05/01-10/05	<b>02-35638-04</b> ⑫ 71718658 Mot.→4081110  <b>02-38204-01</b> ⑫ 71739971 Mot.4081111→ 	<b>61-35580-00</b> 46749904 83 Ø 0,82 mm <b>61-35580-10</b> 46749905 83 Ø 0,92 mm 1 □ <b>61-35580-20</b> 46749906 83 Ø 1,02 mm 2 □ 	<b>14-35738-01</b> 7775920 (10x)  RIBE	<b>71-35638-10</b> 46552748 Mot.→4081110  <b>71-38204-00</b> 55197598 Mot.4081111→ 	<b>12-25837-01</b> 7553637 (8x) <b>70-25837-00</b> 5930415 8x 	<b>71-36306-00</b> 71738458 	<b>71-35637-00</b> 46467747 	<b>70-31414-10</b> 	<b>81-35882-00 K</b> ← 7628850 31x41x7 AB SL RD FPM <b>81-90027-00 K</b> → 71718365 <b>81-17539-50 N</b> 40004400 30x42x7 A SL RD FPM	
2,0 RFN RFN (EW10J4)(136 PS)	100 kW (136 PS)	PHEDRA ZETA 16V	07/00-11/10	<b>01-35045-01</b> ⑫ ⑬ ⑰ <b>02-35045-01</b> ⑫ ⑰ 	<b>61-35045-00</b> 9636017380 85 Ø MLS 	<b>14-32234-01</b> 9647888280 (10x)  RIBE	<b>71-34452-00 R</b> 9463377580  <b>71-34453-00 L</b> 9463377480 	<b>12-34439-01</b> <b>70-34439-00</b> 16x 	<b>71-35903-00</b> 9463260280 4x 	<b>71-33853-00</b> 9464038380 	<b>70-31414-10</b> 	<b>81-34454-10 K</b> ← 40x55x6 A SL RD PTFE <b>81-34456-00 K</b> → 9614379380 90x110x7 A SL LD FPM <b>81-34403-00 N</b> 2x 36x50x7 A SL RD FPM	
2,0 RFV (XU10J4R)	97 kW (132 PS)	ZETA 16V	05/98-07/00	<b>01-33650-05</b> ⑫ ⑬ →09/98 <b>01-33650-06</b> ⑫ ⑬ 10/98→ <b>02-33650-05</b> ⑫ →09/98 <b>02-33650-06</b> ⑫ 10/98→	<b>61-33650-00</b> 9616818580 87 Ø 1,35 mm 	<b>14-32148-01</b> 9605999480 (10x)  RIBE	<b>71-34446-00 R</b> 9463330180  <b>71-34447-00 L</b> 9463330280 	<b>12-34438-01</b> →09/98 <b>12-34439-01</b> 10/98→ <b>70-34438-00</b> →09/98 <b>70-34439-00</b> 10/98→ 16x 	<b>71-33666-00</b>  <b>71-35728-00</b> 4x 9569108380 	<b>71-34443-00</b> Mot.→07664  <b>71-35768-00</b> 9569136880 Mot.07665→ 	<b>70-31414-10</b> 	<b>81-25926-10 K</b> ← 9614194980 42x62x8 ARD FPM <b>81-34456-00 K</b> → 9614379380 90x110x7 A SL LD FPM <b>81-34403-00 N</b> 2x 36x50x7 A SL RD FPM	
2,0 RGX (XU10J2TE)	108 kW (147 PS)	ZETA Turbo	05/95-09/02	<b>02-33650-04</b> ⑫ 5894989	<b>61-33650-00</b> 9616818580 87 Ø 1,35 mm 	<b>14-32077-01</b> 9607384680 (10x)  RIBE	<b>71-26237-00</b> 9400249489 	<b>12-25837-01</b> 7553637 (8x) <b>70-25837-00</b> 5930415 8x 	<b>71-33676-00</b> 9612595180 Mot.→7664  <b>71-34361-00</b> 9569138780 	<b>70-31414-10</b> 	<b>81-25926-10 K</b> ← 9614194980 42x62x8 ARD FPM <b>81-34456-00 K</b> → 9614379380 90x110x7 A SL LD FPM <b>81-22660-00 N</b> 9153892580 32x45x7 A LD FPM <b>81-26244-10 N</b> 97510802 36x50x8 A RD ACM		

LANCIA												
Ltr.												
2,0 RHK (DW10UTED4) (120-136 PS) RHR (DW10BTED4)	88-100 kW PHEDRA PHEDRA JTD	06/06-11/10	01-36571-01 <sup>12</sup> <sup>13</sup> 	61-34370-00 9644450580 86 Ø 1,25 mm 2 MLS 61-34370-10 9644450680 86 Ø 1,3 mm 3 MLS 61-34370-20 9644450780 86 Ø 1,35 mm 4 MLS 61-34370-30 9644450880 86 Ø 1,4 mm 5 MLS 	14-35774-01 9802033280 (10x) 	15-36571-01 	12-34399-02 9400956489 (16x) 70-34399-00 9400956489 16x		71-33223-00 9400349129 	70-31414-10 	81-36557-00 K ← 9614194980 42x62x7 A SL RD PTFE 81-36556-00 K → 9400127459 90x110x7 A SL LD PTFE 81-34144-00 N 9400807289 27x47x7 A SL RD FPM	
2,0 RHM (DW10ATED4) (107-109 PS) RHW (DW10ATED4)	79-80 kW PHEDRA JTD ZETA JTD	09/99-11/10	01-34404-01 <sup>12</sup> <sup>13</sup> 9463378980   02-34404-01 <sup>12</sup> 9463380080 	61-34370-00 9644450580 86 Ø 1,25 mm 2 MLS 61-34370-10 9644450680 86 Ø 1,3 mm 3 MLS 61-34370-20 9644450780 86 Ø 1,35 mm 4 MLS 61-34370-30 9644450880 86 Ø 1,4 mm 5 MLS 	14-32233-01 9646397880 	71-34404-00 9463380380 	12-34399-02 9400956489 (16x) 70-34399-00 9400956489 16x		71-33223-00 9400349129 	70-31414-10 	81-25926-10 K ← 9614194980 42x62x8 A RD FPM 81-34456-00 K → 9614379380 90x110x7 A SL LD FPM 81-34144-00 N 9400807289 27x47x7 A SL RD FPM	



LANCIA												
Ltr.												
2,0 198 A5.000 198 A8.000	121 kW (165 PS)	DELTA	09/08-08/14	02-42061-02 <sup>12</sup> 71754668  08-36278-03 <sup>13 35</sup> 71749743 	61-36595-00 55211409 84 Ø 0,95 mm 0 MLS 61-36595-10 55211410 84 Ø 1,05 mm 1 <input type="checkbox"/> MLS 61-36595-20 55211411 84 Ø 1,15 mm 2 <input type="checkbox"/> MLS 	14-32321-01 55214216 (10x) 	71-42061-00 55205111 	12-38209-02 55183812 (16x) 70-38209-00 55183812	11-40692-01 71754211 16x 	71-42064-00 55210879  71-42072-00 <sup>13</sup> 55212785 	70-31414-10 	81-35882-00 K ← 7628850 31x41x7 AB SL RD FPM 81-90027-00 K → <sup>13</sup> 71718365 81-36229-00 N 46802577 30x45x7 AB SL RD FPM
2,0 828 B1.000	85-88 kW (115-120 PS)	BETA	04/76-10/86	01-31800-01 <sup>12 13</sup> 5880452 02-31800-01 5880451 08-12961-04 <sup>13</sup>	61-31800-00 4387624 85 Ø 1,35 mm 61-31800-10 5951675 85 Ø 1,8 mm 		71-31738-00 2x 4158646 	12-25837-01 7553637 (8x) 70-25837-00 5930415	71-35722-00 4194060 8x 	71-21584-00 4177112  71-21608-10 <sup>13</sup> 4166914 	71-12961-00 4331606 	81-15287-10 K → 70x90x10 A LD MVQ 81-35883-00 N 2x 40004940 30x52x7 AB SL RD FPM
2,0 828 B4.000	90 kW (122 PS)	BETA TREVI	05/80-01/87	02-31740-03 <sup>12</sup> 5881916	61-31740-00 5951675 85 Ø 	14-35742-01 60807357 (10x) 	71-31738-00 2x 4158646 	12-25837-01 7553637 (8x) 70-25837-00 5930415	71-35764-00 8x 	71-21584-00 4177112 	71-12961-00 4331606 	81-35881-00 K → 40004300 74x90x10 AB SL LD MVQ 81-35883-00 N 2x 40004940 30x52x7 AB SL RD FPM
2,0 831 AB.026 831 D5.000	144 kW (196 PS)	DELTA 16V	01/89-12/91	01-31735-11 <sup>12 13</sup> 5893560 02-31735-11 <sup>12</sup> 5891891 08-31744-10 <sup>13</sup>	61-31735-00 4314165 85 Ø 	14-35742-01 60807357 (10x) 	15-31741-01 	12-26058-03 4357028 (16x) 70-26058-00 7581344	71-35688-00 7646020 16x 	71-35689-00 7575386 	71-31744-00 5959226 Gummi Kork 	81-35624-00 K ← 40004260 30x43x8 AB SL RD FPM 81-35881-00 K → 40004300 74x90x10 AB SL LD MVQ 81-17539-50 N 2x 40004400 30x42x7 A SL RD FPM
2,0 831 B4.000 831 B5.000 831 C5.046 835 A7.000 835 A7.046 835 A8.000 835 A8.046	85-130 kW (115-177 PS)	DEDRA DEDRA Turbo DELTA PRISMA	04/86-07/99	01-31830-09 <sup>12 13</sup> 02-31830-11 <sup>12</sup> 5893002	61-31830-00 5891307 85 Ø 		71-31726-00 2x 4158656 	12-26058-02 4357028 (8x) 70-26058-00 7581344	71-35666-00 2x 7700197 8x 	71-21584-00 4177112 	71-12961-00 4331606 	81-35624-00 K ← 40004260 30x43x8 AB SL RD FPM 81-35881-00 K → 40004300 74x90x10 AB SL LD MVQ 81-34368-00 N 2x 32x47x10 A SL LD PTFE ACM
2,0 831 C5.000	133 kW (181 PS)	DELTA	10/87-02/89	01-31735-09 <sup>12 13</sup> 5891877 02-31735-09 <sup>12</sup> 5891876 08-31744-09 <sup>13</sup>	61-31735-00 4314165 85 Ø 	14-35742-01 60807357 (10x) 	71-31726-00 2x 4158656 	12-25837-01 7553637 (8x) 70-25837-00 5930415	71-35666-00 2x 7700197 8x 	71-21584-00 4177112 	71-31744-00 5959226 Gummi Kork 	81-35881-00 K → 40004300 74x90x10 AB SL LD MVQ 81-35883-00 N 40004940 30x52x7 AB SL RD FPM

LANCIA													
Ltr.													
2,0 831 E5.000 831 E5.046 834 B2.000 834 B2.246 834 C1.000 834 F1.000 834 F2.000	104-155 kW (141-211 PS) DELTA 16V THEMA THEMA 16V THEMA 16V Turbo	05/88-07/94	<b>01-31830-04</b> ⑫ ⑬ 5893401 <b>02-31830-02</b> ⑫ 5892352	<b>61-31830-00</b> 5891307 85 Ø 	<b>14-35737-01</b> 60807621 (10x) 	<b>15-31741-01</b> 	<b>12-26058-03</b> 4357028 (16x) <b>70-26058-00</b> 7581344	16x <b>71-35688-00</b> 7646020 	<b>71-35689-00</b> 7575386 	<b>71-31751-00</b> 7646248 	<b>81-35624-00</b> K ← 40004260 30x43x8 AB SL RD FPM <b>81-35881-00</b> K → 40004300 74x90x10 AB SL LD MVQ <b>81-17539-50</b> N 40004400 30x42x7 A SL RD FPM		
2,0 834 B.000	88 kW (120 PS) THEMA	11/84-09/88	<b>01-31735-01</b> ⑫ ⑬ 5882329 <b>02-31735-01</b> ⑫ 5882328 <b>08-31744-11</b> ⑬	<b>61-31735-00</b> 4314165 85 Ø 	<b>14-35742-01</b> 60807357 (10x) 	<b>71-31726-00</b> 2x 4158656 	<b>12-25837-01</b> 7553637 (8x) <b>70-25837-00</b> 5930415	8x <b>71-35666-00</b> 7700197 	<b>71-21584-00</b> 4177112 	<b>71-31744-00</b> 5959226 Gummi Kork 	<b>81-35624-00</b> K ← 40004260 30x43x8 AB SL RD FPM <b>81-35881-00</b> K → 40004300 74x90x10 AB SL LD MVQ <b>81-35883-00</b> N 40004940 30x52x7 AB SL RD FPM		
2,0 834 B1.000 834 B1.146 835 A5.000 835 A5.045	86 kW (117 PS) DEDRA THEMA	09/88-07/92	<b>01-31830-08</b> ⑫ ⑬ 5892008 <b>02-31830-10</b> ⑫ 5892007 <b>08-31751-04</b> ⑬	<b>61-31830-00</b> 5891307 85 Ø 	<b>14-35742-01</b> 60807357 (10x) 	<b>71-35677-00</b> 2x 7715789 	<b>12-25837-01</b> 7553637 (8x) <b>70-25837-00</b> 5930415	8x <b>71-35666-00</b> 7700197 	<b>71-21584-00</b> 4177112 	<b>71-31751-00</b> 7646248 			
2,0 834 B.146	85 kW (115 PS) THEMA	09/87-05/92	<b>01-31830-07</b> ⑫ ⑬ 5893003	<b>61-31830-00</b> 5891307 85 Ø 		<b>71-35677-00</b> 2x 7715789 	<b>12-25837-01</b> 7553637 (8x) <b>70-25837-00</b> 5930415	8x <b>71-35666-00</b> 7700197 	<b>71-21584-00</b> 4177112 	<b>71-31751-00</b> 7646248 	<b>81-35624-00</b> K ← 40004260 30x43x8 AB SL RD FPM <b>81-35881-00</b> K → 40004300 74x90x10 AB SL LD MVQ		
2,0 834 C.000 834 C.146	110-122 kW (150-166 PS) THEMA Turbo THEMA 16V Turbo	11/84-03/92	<b>01-31735-07</b> ⑫ ⑬ 5893330 <b>02-31735-02</b> ⑫ 5893329	<b>61-31735-00</b> 4314165 85 Ø 	<b>14-35742-01</b> 60807357 (10x) 	<b>71-31726-00</b> 2x 4158656 	<b>12-25837-01</b> 7553637 (8x) <b>70-25837-00</b> 5930415	8x <b>71-35666-00</b> 7700197 	<b>71-21584-00</b> 4177112 	<b>71-31744-00</b> 5959226 Gummi Kork 	<b>81-35881-00</b> K → 40004300 74x90x10 AB SL LD MVQ <b>81-35883-00</b> N 40004940 30x52x7 AB SL RD FPM		
2,0 835 A5.046	83 kW (113 PS) DEDRA	09/89-07/99	<b>01-31830-03</b> ⑫ ⑬ 5893330 <b>02-31830-04</b> ⑫ 5893326	<b>61-31830-00</b> 5891307 85 Ø 	<b>14-35742-01</b> 60807357 (10x) 		<b>12-26058-02</b> 4357028 (8x) <b>70-26058-00</b> 7581344	8x <b>71-35666-00</b> 7700197 	<b>71-21584-00</b> 4177112 	<b>71-31751-00</b> 7646248 	<b>81-35624-00</b> K ← 40004260 30x43x8 AB SL RD FPM <b>81-35881-00</b> K → 40004300 74x90x10 AB SL LD MVQ <b>81-35883-00</b> N 40004940 30x52x7 AB SL RD FPM		

LANCIA													
Ltr.													
2,0 836 A2.000	137 kW (186 PS) DELTA 16V Turbo	06/93-08/99	01-31735-06 <sup>12</sup> <sup>13</sup> 5893768 02-31735-07 <sup>12</sup> 5893767	61-31735-00 4314165 85 Ø	14-35742-01 60807357 (10x)	15-31741-01	12-26058-03 4357028 (16x) 70-26058-00 7581344	71-35688-00 7646020 16x		71-31751-00 7646248	81-35624-00 K ← 40004260 30x43x8 AB SL RD FPM 81-35881-00 K → 40004300 74x90x10 AB SL LD MVQ 81-17539-50 N 40004400 30x42x7 A SL RD FPM		
2,0 836 A3.000 838 A4.000	102-151 kW (139-205 PS) DEDRA DEDRA 16V DELTA 16V KAPPA 16V Turbo	06/93-10/01	01-31830-04 <sup>12</sup> <sup>13</sup> 5893401 02-31830-05 <sup>12</sup> 5893400	61-31830-00 5891307 85 Ø	14-35737-01 60807621 (10x)	15-31741-01	12-26058-03 4357028 (16x) 70-26058-00 7581344	71-35688-00 7646020 16x	71-35689-00 7575386	71-31751-00 7646248	81-35624-00 K ← 40004260 30x43x8 AB SL RD FPM 81-35881-00 K → 40004300 74x90x10 AB SL LD MVQ 81-17539-50 N 40004400 30x42x7 A SL RD FPM		
2,0 841 E.000	136 kW (185 PS) THESIS Turbo	07/02-07/09	02-36890-01 <sup>12</sup> 71737153 08-38367-01 <sup>13</sup> <sup>38</sup> 71730149	61-36890-00 55187705 MLS	14-32220-02 7710582 (12x)	71-38206-00 46464114	12-26058-04 4357028 (20x) 70-26058-00 7581344	71-35683-00 7765227 20x	71-35672-00 7772358	70-31414-10	81-35882-00 K ← 7628850 31x41x7 AB SL RD FPM 81-90027-00 K → 71718365 81-17539-50 N 40004400 30x42x7 A SL RD FPM 81-35723-00 N 6081144 55x68x8 AB SL RD FPM		
2,1 P 8 C	80 kW (109 PS) ZETA TD	05/96-09/99	01-33673-01 <sup>12</sup> <sup>13</sup> 95655248  02-33673-01 <sup>12</sup> 9400348969  08-25918-03 <sup>13</sup>	61-33655-00 9620480580 86 Ø 1,52 mm MLS 61-33655-10 9620480680 86 Ø 1,57 mm MLS 61-33655-20 9620480780 86 Ø 1,62 mm MLS 61-33655-30 9620480880 86 Ø 1,67 mm MLS 61-33655-40 9620480980 86 Ø 1,72 mm MLS		71-33673-00 9608064880	12-25837-03 70-25837-00 5930415	71-33671-00 9400348969 12x	71-33672-00 9400348969	71-25918-30 96042653	81-25926-10 K ← 9614194980 42x62x8 A RD FPM 81-34456-00 K → 9614379380 90x110x7 A SL LD FPM 81-21798-30 N 94002361 35x50x8 A SL WD ACM		



LANCIA												
Ltr.												
2,2 4HP 4HR 4HS 4HT	120-125 kW (163-170 PS) PHEDRA	04/06-11/10	02-39244-01 <sup>12</sup>  08-39246-01 <sup>13</sup>	61-35805-00 9655638580 85,9 Ø 1,25 mm 1 MLS 61-35805-10 9655638680 85,9 Ø 1,3 mm 2 MLS 61-35805-20 9655638780 85,9 Ø 1,35 mm 3 MLS 61-35805-30 9655638880 85,9 Ø 1,4 mm 4 MLS 	14-35774-01 9802033280 (10x) 	15-38554-01 9682131780 +9682131280 (2x) +9656742280 	12-38539-01 9400956639 (16x)	11-38553-01 9661413780 		71-35919-00 9653365180 	70-31414-10 	81-36557-00 K ← 9614194980 42x62x7 A SL RD PTFE 81-36556-00 K → 9400127459 90x110x7 A SL LD PTFE 81-34144-00 N 9400807289 27x47x7 A SL RD FPM
2,2 4HW (DW12ATED4) (128 PS)	94 kW PHEDRA JTD	09/02-11/10	01-34404-01 <sup>12</sup> <sup>13</sup> 9463378980   02-34404-01 <sup>12</sup> 9463380080 	61-34370-00 9644450580 86 Ø 1,25 mm 2 MLS 61-34370-10 9644450680 86 Ø 1,3 mm 3 MLS 61-34370-20 9644450780 86 Ø 1,35 mm 4 MLS 61-34370-30 9644450880 86 Ø 1,4 mm 5 MLS 	14-32233-01 9646397880 	71-34404-00 9463380380 	12-34399-02 9400956489 (16x) 70-34399-00 9400956489 16x			71-33223-00 9400349129 	70-31414-10 	81-25926-10 K ← 9614194980 42x62x8 A RD FPM 81-34456-00 K → 9614379380 90x110x7 A SL LD FPM 81-34144-00 N 9400807289 27x47x7 A SL RD FPM

LANCIA												
Ltr.												
2,4 AR 32501	99 kW (135 PS)	LYBRA JTD	07/99-02/01	<p><b>01-35699-02</b> <sup>12</sup> <sup>13</sup> 60814970 Mot.→1819831</p> <p></p> <p><b>02-35699-03</b> <sup>12</sup> 71717836 Mot.1819832→</p> <p></p> <p><b>08-38367-01</b> <sup>13</sup> <sup>38</sup> 71730149</p> <p></p>	<p><b>61-33760-00</b> 46442435 83 Ø 1,6 mm MLS Mot.→1819831</p> <p><b>61-33760-10</b> 46442436 83 Ø 1,7 mm 1 □ MLS Mot.→1819831</p> <p><b>61-33760-20</b> 46442437 83 Ø 1,8 mm 2 □ MLS Mot.→1819831</p> <p></p> <p><b>61-37315-00</b> 55190359 0,82 mm MLS Mot.1819832→</p> <p><b>61-37315-10</b> 55190360 0,92 mm 1 □ MLS Mot.1819832→</p> <p><b>61-37315-20</b> 55190361 1,02 mm 2 □ MLS Mot.1819832→</p> <p></p>	<p><b>14-35779-01</b> 7775920 (12x)</p> <p></p> <p>RIBE</p>	<p><b>71-35699-00</b> 46437256</p> <p></p>	<p><b>12-22737-02</b> 7553637 (10x) <b>70-22737-00</b> 5930415</p>	<p><b>71-35777-00</b> 7735415 Mot.→1819831</p> <p>10x </p> <p><b>71-35777-10</b> 46772390 Mot.1819832→</p> <p></p> <p><b>71-35598-00</b></p> <p></p>	<p><b>70-31414-10</b></p> <p></p>	<p><b>81-35882-00</b> K ← 7628850 31x41x7 AB SL RD FPM <b>81-90027-00</b> K → </p> <p>71718365 <b>81-17539-50</b> N 40004400 30x42x7 A SL RD FPM</p>	
2,4 AR 32501 838 A8.000 839 A5.000	99-100 kW (135-136 PS)	KAPPA JTD LYBRA JTD	06/98-10/01	<p><b>01-35699-02</b> <sup>12</sup> <sup>13</sup> 60814970 Mot.→1819831</p> <p></p> <p><b>02-35699-02</b> <sup>12</sup> 60814969 Mot.→1819831</p> <p></p> <p><b>08-35778-01</b> <sup>13</sup></p>	<p><b>61-33760-00</b> 46442435 83 Ø 1,6 mm MLS <b>61-33760-10</b> 46442436 83 Ø 1,7 mm 1 □ MLS <b>61-33760-20</b> 46442437 83 Ø 1,8 mm 2 □ MLS</p> <p></p>	<p><b>14-35779-01</b> 7775920 (12x)</p> <p></p> <p>RIBE</p>	<p><b>71-35699-00</b> 46437256</p> <p></p>	<p><b>12-25837-02</b> 5930415 (10x) <b>70-25837-00</b> 5930415</p>	<p><b>71-35777-00</b> 7735415 Mot.→1819831</p> <p>10x </p>	<p><b>71-35698-00</b> 46414437</p> <p></p>	<p><b>70-31414-10</b></p> <p></p>	<p><b>81-35882-00</b> K ← 7628850 31x41x7 AB SL RD FPM <b>81-90027-00</b> K → </p> <p>71718365 <b>81-17539-50</b> N 2x 40004400 30x42x7 A SL RD FPM</p>
2,4 EDG <b>[NEW]</b>	125-129 kW (170-175 PS)	FLAVIA Cabriolet (JS)	03/12-12/14	<p><b>02-10029-01</b> <b>08-54097-01</b> <sup>13</sup></p> <p></p>	<p><b>61-10029-00</b> 0,5 mm MLS</p> <p></p>		<p><b>15-10007-01</b></p> <p></p>	<p><b>12-54093-01</b></p>	<p><b>71-10196-00</b></p> <p></p>	<p><b>71-54096-00</b></p> <p></p>	<p><b>70-31414-10</b></p> <p></p>	<p><b>81-54097-00</b> K ← A SL RD FPM <b>81-54098-00</b> K → 85x103x8 A SL LD FPM</p>

LANCIA												
Ltr.												
2,4 192 A2.000 841 D.000	125 kW (170 PS)	THESIS	07/02→	<b>02-36915-01</b> <sup>12</sup> 71737154 <b>08-38367-01</b> <sup>13 38</sup> 71730149 	<b>61-36915-00</b> 55189964 MLS 	<b>14-32220-02</b> 7710582 (12x) 	<b>71-38206-00</b> 46464114 	<b>12-26058-04</b> 4357028 (20x) <b>70-26058-00</b> 7581344 20x	<b>71-35683-00</b> 7765227 	<b>71-35672-00</b> 7772358 	<b>70-31414-10</b> 	<b>81-35882-00 K</b> ← 7628850 31x41x7 AB SL RD FPM <b>81-90027-00 K</b> → 71718365 <b>81-17539-50 N</b> 40004400 30x42x7 A SL RD FPM <b>81-35723-00 N</b> 60811144 55x68x8 AB SL RD FPM
2,4 8144.91	74 kW (101 PS)	THEMA TD	11/84-09/90	<b>01-35708-01</b> <sup>12 13</sup> 5882403  <b>02-35708-01</b> <sup>12</sup> 5882402 	<b>61-35660-00</b> 4848253 95 Ø 1,65 mm <b>61-35660-10</b> 4848254 95 Ø 1,8 mm 	<b>14-32096-01</b> 4854648 (10x) +4828150 (12x) 	<b>71-35708-00</b> 7302624 	<b>12-34914-05</b> 40101573 (8x) <b>70-34914-00</b> 40101573 8x	<b>71-33621-00</b> 98425767 	<b>71-33654-00</b> 7303076 	<b>71-35706-00</b> 7302582 	<b>81-21798-30 K</b> ← 94002361 35x50x8 A SL WD ACM <b>81-35907-00 K</b> → 1227942L00 100x118x10 AB SL LD FPM <b>81-33627-00 N</b> 98454041 55x70x8 A SL RD FPM
2,4 838 A2.000 838 A2.027	129 kW (175 PS)	KAPPA 20V	08/94-10/01	<b>01-35615-03</b> <sup>12 13 35</sup> 5894854  <b>02-35615-03</b> <sup>12</sup> 5894853 	<b>61-35615-00</b> 7766268 83 Ø 	<b>14-32220-02</b> 7710582 (12x) 	<b>15-35673-01</b> 7766236 +7715492 (5x) 	<b>12-26058-04</b> 4357028 (20x) <b>70-26058-00</b> 7581344 20x	<b>71-35683-00</b> 7765227  <b>71-35782-00</b> 46435397 	<b>71-35672-00</b> 7772358 	<b>70-31414-10</b> 	<b>81-35882-00 K</b> ← 7628850 31x41x7 AB SL RD FPM <b>81-90027-00 K</b> → 71718365 <b>81-17539-50 N</b> 40004400 30x42x7 A SL RD FPM <b>81-35723-00 N</b> 60811144 55x68x8 AB SL RD FPM

LANCIA												
Ltr.												
2,4 838 A3.000 838 A7.000	91 kW (124 PS) KAPPA TD	08/94-10/01	<b>01-35699-01</b> ⑫ ⑬ <b>02-35699-01</b> ⑫ <b>08-35762-01</b> ⑬	<b>61-35655-00</b> 46468413 83 Ø 1,6 mm MLS <b>61-35655-10</b> 46468414 83 Ø 1,7 mm MLS <b>61-35655-20</b> 46468415 83 Ø 1,8 mm MLS 	<b>71-35699-00</b> 46437256 	<b>12-25837-02</b> 5930415 (10x) <b>70-25837-00</b> 5930415	<b>71-35697-00</b> 7775802 10x		<b>71-35698-00</b> 46414437 	<b>70-31414-10</b> 	<b>81-35882-00</b> K ← 7628850 31x41x7 AB SL RD FPM <b>81-90027-00</b> K → 71718365 <b>81-17539-50</b> N 2x 40004400 30x42x7 A SL RD FPM	
2,4 838 B2.000	129 kW (175 PS)		<b>01-35615-04</b> ⑫ ⑬ ⑮ 71714576  <b>02-35615-04</b> ⑫ 71714575	<b>61-35615-00</b> 7766268 83 Ø 	<b>14-32220-02</b> 7710582 (12x)  RIBE	<b>71-38206-00</b> 46464114 	<b>12-26058-04</b> 4357028 (20x) <b>70-26058-00</b> 7581344 20x		<b>71-35672-00</b> 7772358 	<b>70-31414-10</b> 	<b>81-35882-00</b> K ← 7628850 31x41x7 AB SL RD FPM <b>81-90027-00</b> K → 71718365 <b>81-17539-50</b> N 40004400 30x42x7 A SL RD FPM <b>81-35723-00</b> N 60811144 55x68x8 AB SL RD FPM	
2,4 839 A6.000 841 C.000	103-110 kW (140-150 PS) LYBRA JTD THESIS JTD	09/00-07/09	<b>02-38193-01</b> ⑫ 71718333  <b>08-38367-03</b> ⑬ ⑮ 71728831 	<b>61-37315-00</b> 55190359 0,82 mm MLS <b>61-37315-10</b> 55190360 0,92 mm 1 □ MLS <b>61-37315-20</b> 55190361 1,02 mm 2 □ MLS 	<b>14-35779-01</b> 7775920 (12x)  RIBE	<b>71-38193-00</b> 46739261 	<b>12-22737-02</b> 7553637 (10x) <b>70-22737-00</b> 5930415 10x		<b>71-35698-00</b> 46414437 	<b>70-31414-10</b> 	<b>81-35882-00</b> K ← 7628850 31x41x7 AB SL RD FPM <b>81-90027-00</b> K → 71718365 <b>81-17539-50</b> N 40004400 30x42x7 A SL RD FPM	

LANCIA													
2,4	841 G.000 841 H.000 841 M.000 841 N.000	120-129 kW (163-175 PS)	THESIS THESIS JTD	05/03→	<b>02-38313-02</b> <sup>12</sup> 71734259 Mot.→5192516  <b>02-38313-03</b> <sup>12</sup> Mot.5192517→  <b>08-38367-02</b> <sup>13 38</sup> 71734258 	<b>61-37310-00</b> 55190353 82 mm MLS <b>61-37310-10</b> 55190354 0,92 mm 1 <input type="checkbox"/> MLS <b>61-37310-20</b> 55190355 1,02 mm 2 <input type="checkbox"/> MLS 	<b>14-32321-02</b> 55214216 (12x)  RIBE	<b>71-38313-00</b> 46814175 	<b>12-36208-02</b> 46743167 (20x) Mot.→5192516 <b>12-38209-01</b> 55183812 (20x) Mot.5192517→ <b>70-36208-00</b> 46743167 Mot.→5192516 <b>70-38209-00</b> 55183812 Mot.5192517→ 20x 20x	<b>71-38348-00</b> 55190771 	<b>71-35672-00</b> 7772358 	<b>70-31414-10</b> 	<b>81-35882-00 K</b> ← 7628850 31x41x7 AB SL RD FPM <b>81-90027-00 K</b> → 71718365 <b>81-36229-00 N</b> 46802577 30x45x7 AB SL RD FPM
2,4	841 P.000	136 kW (185 PS)	THESIS	04/06-07/09	<b>02-38313-02</b> <sup>12</sup> 71734259 Mot.→5192516  <b>02-38313-03</b> <sup>12</sup> Mot.5192517→  <b>08-38367-02</b> <sup>13 38</sup> 71734258 	<b>61-37305-00</b> 55184740 0,95 mm MLS <b>61-37305-10</b> 55184741 1,05 mm 1 <input type="checkbox"/> MLS <b>61-37305-20</b> 55184742 1,15 mm 2 <input type="checkbox"/> MLS 	<b>14-32321-02</b> 55214216 (12x)  RIBE	<b>71-38313-00</b> 46814175 	<b>12-36208-02</b> 46743167 (20x) Mot.→5192516 <b>12-38209-01</b> 55183812 (20x) Mot.5192517→ <b>70-36208-00</b> 46743167 Mot.→5192516 <b>70-38209-00</b> 55183812 Mot.5192517→ 20x 20x	<b>71-38348-00</b> 55190771 	<b>71-35672-00</b> 7772358 	<b>70-31414-10</b> 	<b>81-35882-00 K</b> ← 7628850 31x41x7 AB SL RD FPM <b>81-90027-00 K</b> → 71718365 <b>81-36229-00 N</b> 46802577 30x45x7 AB SL RD FPM
2,5	8144.97	85 kW (115 PS)	THEMA TD	06/88-05/92	<b>01-35708-01</b> <sup>12 13</sup> 5882403  <b>02-35708-01</b> <sup>12</sup> 5882402 	<b>61-33610-00</b> 7701040179 95,2 Ø 1,65 mm <b>61-33610-10</b> 7701040180 95,2 Ø 1,7 mm <b>61-33610-20</b> 95,2 Ø 1,8 mm 	<b>14-32096-01</b> 4854648 (10x) +4828150 (12x)  RIBE	<b>71-35708-00</b> 7302624 	<b>12-34914-05</b> 40101573 (8x) <b>70-34914-00</b> 40101573 8x	<b>71-33621-00</b> 98425767 4x 8x 	<b>71-33654-00</b> 7303076 4x 	<b>71-35706-00</b> 7302582 	<b>81-21798-30 K</b> ← 94002361 35x50x8 A SL WD ACM <b>81-35907-00 K</b> → 1227942L00 100x118x10 AB SL LD FPM <b>81-33627-00 N</b> 98454041 55x70x8 A SL RD FPM
2,5	8144.97 Y	85 kW (116 PS)	THEMA TD	05/92-07/94	<b>02-33657-01</b> <sup>12</sup>  <b>08-35784-01</b> <sup>13</sup> 99478460	<b>61-33640-00</b> 95,2 Ø 1,65 mm <b>61-33640-10</b> 95,2 Ø 1,8 mm 	<b>14-32096-01</b> 4854648 (10x) +4828150 (12x)  RIBE	<b>71-33657-00</b> 	<b>12-31753-01</b> <b>70-34914-00</b> 40101573 8x	<b>71-33621-00</b> 98425767 4x 8x 	<b>71-33654-00</b> 7303076 4x 	<b>71-35784-00</b> 98414010 	<b>81-33627-00 K</b> ← 98454041 55x70x8 A SL RD FPM <b>81-20745-30 K</b> → 90x110x11 A SL LD FPM <b>81-33627-00 N</b> 98454041 55x70x8 A SL RD FPM

LANCIA												
Ltr.												
2,5 8144.97/1400 85 kW (116 PS)	1			<p><b>01-35708-01</b> <sup>12</sup> <sup>13</sup> 5882403 →12/91</p> <p></p> <p><b>01-35786-01</b> <sup>12</sup> <sup>13</sup> 01/92→</p> <p></p> <p><b>02-35708-01</b> <sup>12</sup> 5882402 →12/91</p> <p></p> <p><b>08-35784-01</b> <sup>13</sup> 99478460</p>	<p><b>61-33610-00</b> 7701040179 95,2 Ø 1,65 mm</p> <p><b>61-33610-10</b> 7701040180 95,2 Ø 1,7 mm</p> <p><b>61-33610-20</b> 95,2 Ø 1,8 mm</p>	<p><b>14-32096-01</b> 4854648 (10x) +4828150 (12x)</p>	<p><b>71-35708-00</b> 7302624</p>	<p><b>12-34914-05</b> 40101573 (8x)</p> <p><b>70-34914-00</b> 40101573</p>	<p><b>71-33621-00</b> 98425767</p> <p>8x</p>	<p><b>71-33654-00</b> 7303076</p> <p>4x</p>	<p><b>71-35706-00</b> 7302582</p>	<p><b>81-21798-30 K</b> ← 94002361 35x50x8 A SL WD ACM</p> <p><b>81-35907-00 K</b> → 1227942L00 100x118x10 AB SL LD FPM</p> <p><b>81-33627-00 N</b> 98454041 55x70x8 A SL RD FPM</p>
2,5 8144.97/24 85 kW (116 PS)				<p><b>01-35708-01</b> <sup>12</sup> <sup>13</sup> 5882403 →12/91</p> <p></p> <p><b>02-35708-01</b> <sup>12</sup> 5882402 →12/91</p> <p></p>	<p><b>61-33610-00</b> 7701040179 95,2 Ø 1,65 mm</p> <p><b>61-33610-10</b> 7701040180 95,2 Ø 1,7 mm</p> <p><b>61-33610-20</b> 95,2 Ø 1,8 mm</p>	<p><b>14-32096-01</b> 4854648 (10x) +4828150 (12x)</p>	<p><b>71-35708-00</b> 7302624</p>	<p><b>12-34914-05</b> 40101573 (8x)</p> <p><b>70-34914-00</b> 40101573</p>	<p><b>71-33621-00</b> 98425767</p> <p>8x</p>	<p><b>71-33654-00</b> 7303076</p> <p>4x</p>	<p><b>71-35706-00</b> 7302582</p>	<p><b>81-21798-30 K</b> ← 94002361 35x50x8 A SL WD ACM</p> <p><b>81-35907-00 K</b> → 1227942L00 100x118x10 AB SL LD FPM</p> <p><b>81-33627-00 N</b> 98454041 55x70x8 A SL RD FPM</p>
3,0 834 F.000 126 kW (171 PS) THEMA V6	08/92-07/94			<p><b>01-27470-01</b> <sup>12</sup> <sup>13</sup> 5892689</p> <p><b>02-27470-01</b> <sup>12</sup> 5892690</p>	<p><b>61-27470-10 R</b> 60569896 95 Ø 1,7 mm</p> <p><b>61-27475-20 L</b> 60548751 95 Ø 1,7 mm</p>		<p><b>71-35787-00 R</b> 60808412</p> <p><b>71-35788-00 L</b> 60808971</p>	<p><b>12-31052-01</b> 60507454 (12x)</p> <p><b>70-31052-00</b> 60507454</p>	<p><b>71-35791-00</b> 60807856</p> <p>2x</p>	<p><b>71-28333-00</b> 60630269</p> <p>6x</p>	<p><b>71-35789-00</b> 60807818</p>	<p><b>81-35631-00 K</b> ← 60807827 48x65x10 A RD ACM FPM</p> <p><b>81-35908-00 K</b> → 60811338 84x105x12 A LD MVQ</p> <p><b>81-35909-00 N</b> 2x 60610985 32x47x10 A RD NBR</p>
3,0 838 B.000 150 kW (204 PS) KAPPA 24V	08/94-10/01			<p><b>01-28805-01</b> <sup>12</sup> <sup>13</sup> 60778799</p> <p><b>02-28805-01</b> <sup>12</sup> 60778798</p> <p><b>08-35798-01</b> <sup>13</sup></p>	<p><b>61-28805-00 R</b> 60570352 95 Ø 17 mm</p> <p><b>61-28810-00 L</b> 60570351 95 Ø 17 mm</p>		<p><b>71-35793-00 R</b> 60568809</p> <p><b>71-35794-00 L</b> 60810603</p>	<p><b>12-26058-01</b> 4357028 (12x)</p> <p><b>70-26058-00</b> 7581344</p>	<p>2x</p> <p><b>71-35796-00</b> 60513869</p> <p>2x</p>	<p><b>71-35797-00</b> 60573536</p> <p>6x</p>	<p><b>81-35631-00 K</b> ← 60807827 48x65x10 A RD ACM FPM</p> <p><b>81-35908-00 K</b> → 60811338 84x105x12 A LD MVQ</p> <p><b>81-35909-00 N</b> 2x 60610985 32x47x10 A RD NBR</p>	

LANCIA												
Ltr.												
3,0 841 A.000	158 kW (215 PS)	THESIS V6	07/02-07/09	<b>01-27475-01</b> <sup>12</sup> <sup>13</sup> <sup>16</sup> 71713724  <b>02-27475-01</b> <sup>12</sup> 71713723	<b>61-27475-20 L</b> 60548751 95 Ø 1,7 mm  <b>61-37290-00 R</b> 60602071 95 Ø 1,7 mm 		<b>15-38207-01 R</b> 60609978 +60610548  <b>15-38208-01 L</b> 60609979 +60610548 	<b>12-26058-08</b> 60548495 (24) <b>70-26058-00</b> 7581344 24x	<b>71-35796-00</b> 60513869 2x  <b>71-38304-00</b> <sup>10</sup> 60513868 6x 	<b>71-35797-00</b> 60573536 6x 	<b>70-31414-10</b> 	<b>81-38088-00 K</b> ← 60601977 48x65x8 AB RD <b>81-38087-00 K</b> → 60567605 84x105x12 AB LD <b>81-35909-00 N</b> 4x 60610985 32x47x10 A RD NBR
3,2 841 L.000	169 kW (230 PS)	THESIS V6	05/03-07/09	<b>01-27475-01</b> <sup>12</sup> <sup>13</sup> <sup>16</sup> 71713724  <b>02-27475-01</b> <sup>12</sup> 71713723	<b>61-27475-20 L</b> 60548751 95 Ø 1,7 mm  <b>61-37290-00 R</b> 60602071 95 Ø 1,7 mm 		<b>15-38207-01 R</b> 60609978 +60610548  <b>15-38208-01 L</b> 60609979 +60610548 	<b>12-26058-08</b> 60548495 (24)	<b>71-35796-00</b> 60513869 2x  <b>71-38304-00</b> <sup>10</sup> 60513868 6x 	<b>71-35797-00</b> 60573536 6x 	<b>70-31414-10</b> 	<b>81-38088-00 K</b> ← 60601977 48x65x8 AB RD <b>81-38087-00 K</b> → 60567605 84x105x12 AB LD <b>81-35909-00 N</b> 4x 60610985 32x47x10 A RD NBR
3,6 ERB <b>[NEW]</b>	208-210 kW (283-286 PS)	THEMA (LX) V6 VOYAGER Großraumlimo- usine (RT)	09/11→	<b>02-10045-01</b> <b>08-26248-01</b> <sup>13</sup>	<b>61-10045-00 R</b> MLS  <b>61-10046-00 L</b> MLS 	<b>14-10415-01</b> 	<b>71-10358-00 R</b> ACM  <b>71-10359-00 L</b> ACM 	<b>12-31306-05</b> 4647334 (24x)	<b>71-10360-00</b> 6x 	<b>71-10413-00</b> 2x 	<b>70-31414-10</b> 	<b>81-26248-10 K</b> ← 45x67x8 A SL RD PTFE